



Rico 60 Auto Services Pte Ltd, Blk 8, Kallang Road, Singapore 410224
 Premier @ Kallang Road Singapore 410224, Email: claims@rico60.com
 Tel: 6286 6060, FAX: 6286 7060

VEHICLE NUM:
 MAKE & MODEL:
 MILEAGE:
 TYRE:
 CHASSIS NUM:

SLT 4768 U
HONDA SHUTTLE

ATTN	NO	DESCRIPTION	QTY	PRICE
	1	REAR WINDSCREEN MOULDING	1	\$486.90
	2	REAR TAILGATE	1	\$1,634.90
	3	REAR TAILGATE LAMP L+R @ 340.80	2	\$1,104.40
	4	REAR TAILGATE WIPER ARM	1	\$461.30
	5	REAR TAILGATE WIPER MOTOR	1	\$296.40
	6	REAR TAILGATE WIPER MOTOR COVER	1	\$191.60
	7	REAR TAILGATE LOGO 'HONDA'	1	\$99.70
	8	REAR TAILGATE CENTER CHROME	1	\$516.30
	9	REAR TAILGATE CENTER CHROME NUMBER PLATE LAMP L+R	2	\$246.40
	10	REAR TAILGATE CENTER CHROME SWITCH	1	\$193.70
	12	REAR TAILGATE EMBLEM 'SHUTTLE'	1	\$124.10
	13	REAR TAILGATE INNER TRIM TOP L+R	1	\$416.70
	14	REAR TAILGATE INNER TRIM BTM	1	\$670.10
	15	REAR TAILGATE INNER HANDLE	1	\$79.40
	16	REAR TAILGATE HINGE L+R	2	\$232.60
	17	REAR TAILGATE DAMPER L+R	2	\$684.40
	18	REAR TAILGATE WEATHERSTRIP	1	\$414.60
	19	TAILLAMP L+R	2	\$1,646.40
	20	TAILLAMP PANEL L+R	2	\$1,006.40
	21	REAR BUMPER	1	\$1,071.20
	22	REAR BUMPER RETAINER L+R	2	\$421.40
	23	REAR BUMPER BRACKET L+R	2	\$406.80
	24	REAR BUMPER SPONGE	1	\$329.70
	25	REAR BUMPER REFLECTOR L+R	1	\$274.40
	26	REAR BUMPER BUZZER	1	\$671.10
	27	REAR FENDER L+R	2	\$4,684.30
	28	REAR FENDER COWLING L+R	2	\$492.40
	29	REAR FENDER INNER TRIM TOP L+R	2	\$1,240.40
	30	REAR FENDER INNER TRIM BTM L+R	2	\$2,466.20
	31	END PANEL	1	\$1,075.90
	32	END PANEL TOP GARNISH	1	\$224.60
	33	SPARE WHEEL PANEL	1	\$2,411.70
	34	SPARE WHEEL PANEL TOP BOARD	1	\$643.60
	35	SPARE WHEEL PANEL ACCESSORIES BOX L+R	2	\$764.20
	36	REAR CHASSIS RH	1	REPAIR
	37	REAR EXHAUST PIPE	1	\$1,441.70
	38	REAR EXHAUST MOUNTING	1	
	39	REAR EXHAUST BRACKET	1	
	40	REAR EXHAUST HEAT SHIELD	1	
	41	HEADLAMP L+R	2	

29,461.30

42	HEADLAMP BRACKET L+R	X	2	
43	HEADLAMP CHROME L+R	X	2	
44	FRONT GRILLE	X	1	
45	FRONT GRILLE TOP	X	1	
46	FRONT GRILLE LOGO	X	1	
47	FRONT BUMPER	1050 del	1	41041.90
48	FRONT BUMPER RETAINER RH	110. ne	1	5368.40
49	FRONT BUMPER BRACKET RH	X	1	
50	FRONT BUMPER FOG LAMP RH	X	1	
51	FRONT BUMPER FOG LAMP GARNISH RH	X	1	
52	FRONT BUMPER FOG LAMP CHROME RH	X	1	
53	FRONT FENDER RH	RX	1	
54	FRONT FENDER COWLING RH	R	1	
55	FRONT DOOR RH	X	1	
56	FRONT DOOR SIDE MIRROR RH	X	1	
57	FRONT ABSORBER RH	X	1	
58	FRONT UPPER ARM RH	X	1	
59	FRONT LOWER ARM RH	R	1	
60	FRONT KNUCKLE RH	353.60 bl?	1	4619.40
61	FRONT KNUCKLE BEARING RH	270.85 bl?	1	7341.70
62	FRONT BEARING HUB RH	X	1	
P = \$14,244.40. 10697.55				2770.50
20% 8558.04 SUBTOTAL				\$ -
LESS 20%				\$ -
PARTS TOTAL				\$ -
SPECIAL NETT			QTY	PRICE
1	REAR NUMBER PLATE	wt 45	1	\$ 120.00
2	REVERSE SENSOR	nw 200	2	\$ 300.00
3	REVERSE CAM	nw X	1	\$ 1,000.00
4	REAR END PANEL SEALANT	new 40	1	\$ 120.00
5	SPARE WHEEL PANEL SEALANT	nw X	1	\$ 120.00
6	REAR BUMPER CLIPS	new 30	10	\$ 120.00
7	TAILLAMP CLIPS	30 new?	12	\$ 60.00
8	REAR FENDER COWLING CLIPS	new 10	10	\$ 120.00
9	REAR FENDER INNER TRIM CLIPS	new 20	10	\$ 120.00
10	BOOTLID INNER TRIM CLIPS	new 20	10	\$ 120.00
11	REAR END PANEL TOP GARNISH CLIPS	new 10	10	\$ 120.00
12	FRONT BUMPER CLIPS	new 30	10	\$ 120.00
13	FRONT FENDER COWLING CLIPS	new 20	10	\$ 120.00
14	FRONT RIM	dd 400	SET	\$ 8,000.00
15	FRONT TYRE	nw X	SET	\$ 4,000.00
SIN = 8885 855				
SPECIAL NETT TOTAL				\$ 14,560.00
LABOUR			QTY	PRICE
1	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN	1200	1	\$ 4,000.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1400	1	\$ 3,500.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	50	1	\$ 120.00



Rico 60 Auto Services Pte Ltd, Blk 8, Kaki Bukit Avenue 4, #02-24
Premier @ Kaki Bukit Singapore 415875, Email: claims@rico60.com
Tel: 6286 6060, FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SLT 4768 U
HONDA SHUTTLE

ATTN			
NO	DESCRIPTION - PARTS	QTY	PRICE
1	FRONT BUMPER LOWER PANEL 475.72 66✓	1	\$679.60
2	FRONT BUMPER REINFORCEMENT BAR BRACKET (RH) 66✓	1	\$190.70
3	TAILGATE LOCK 229.40 66✓	1	\$419.80
4	SPAREWHEEL PANEL TOP SIDE BOARD (L-R) 338.10 \$438.10. LH-2✓ RH-X	2	\$876.20.
5	SPAREWHEEL PANEL TOOL BOX (L+R) 236.40 \$336.40 LH✓ RH-X	2	\$672.80
6	REAR ABSORBER (LH) x ?	1	\$531.40 X
7	REAR KNUCKLE BEARING (LH) x x ?	1	\$490.70 X
8	REAR BEARING HUB (LH) x x ?	1	\$803.40 X
9	REAR AXLE x	1	\$2,148.40 X
	PB \$8599.10 1530.32		
	20% - 1224.25	SUBTOTAL	\$ -
		LESS 10%	\$ -
		PARTS TOTAL	\$ -
	SPECIAL NETT	QTY	PRICE
	SPECIAL NETT TOTAL	\$	-
	LABOUR	QTY	PRICE
	TOTAL	\$	-
	GRAND TOTAL COST	\$	-
			6139.80

PARTS TOTAL = \$17,843.50
- 20% = \$14,274.80.
SN = \$885
LABOUR = \$3,660
TOTAL = \$18,819.80
- 20% = \$15,100

Trifur 23/12/19

8558.04 + 1120
855
3660
1224.25

15417.29
4/5/12 300
14297.29
4/5/11400



Rico 60 Auto Services Pte Ltd. Blk 8, Kaki Bukit Avenue 4, #02-24
Premier @ Kaki Bukit Singapore 415875, Email: claims@rico60.com
Tel: 6286 6060, FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SLT 4768 U
HONDA SHUTTLE

ATTN			
NO.	DESCRIPTION - PARTS	QTY	PRICE
1	REAR SECONDARY BATTERY	1	\$2843.90
	✓shorted/400		
	20% - 1120		
	P: \$2843.90	SUBTOTAL	\$ -
	-20% = \$2275.10	LESS 10%	\$ -
		PARTS TOTAL	\$ -
	SPECIAL NETT	QTY	PRICE
	SPECIAL NETT TOTAL		\$ -
	LABOUR	QTY	PRICE
	TOTAL		\$ -
	GRAND TOTAL COST		\$ -

P: \$16,549.90

Q/N: \$885

L: \$3660

Total: \$21,094.90

-20% = \$16,900.00