

ASS. REC. BY:

REF: es/IC819022320/Avd3en Special Instruction:

Survivor
Merimen

Adrian

ASSIGNMENT (Office)

From (Person):

Crystabelle Tan

of

ICS

Date/Time:

19/12/19 @ 12.24pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBJ 5449E

Insured:

GN 2875Y

at Workshop m/s

Liu's Brother

Tel:

67411730

of

1 kaki Bukit Ave 6 #01-01 Autobay

Policy No:

Claim No:

DMCV19000714/02/CT

Sum Insured:

Excess:

Make of Veh:

D.O.A.

16/12/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12.36pm @ 19/12/19

Person Contacted:

Susan

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

GBJ 5449E-X

GN 2875Y-X

4/3/20

Adrian confirmed LS \$14,300 (Red 22,718.60, 61%)

5/3/20

Send preli revised via merimen

ASSIGNMENT

(U) / (P) / (W) / (P) RES / (O) RES / (E) VA / (M) V / (M) V
 To inspect vehicle No.
 at Workshop no.
 at
 Insured
 Policy No.
 Plate No.
 Gen. Insured Excess
 (Client's Record)
 Make of Vehicle

(Policy Condition)

Remarks: The veh had commenced its repair at the time of inspection.

N/S	O/S

Est. or Market Value

IDAC / Accident Report Consistent? Yes or No

GIA / PR Seen Consistent? Yes or No

Est. Repair: days Res: Yes or No

Lum Sum % S Val: Yes or No

CA / REV / REP / 24 HRS

Date: Person Contacted

Vehicle: IN / OUT

Make: **GBJS449E** 2019 May.
 Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Heavy Motor

Truck / Trailer or

Make: **Fiat Doblo** 1598

Colour: **white** A/C Insured / Std / Nil / NA

Sp Reading: **9970** T/Ratio Insured / Std / Nil / NA

Eng No:

C/Vo: **ZFA26300006H90642**

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: **Under** / Jammed / Leaked / Burnt or

Brake: **Under** / Jammed / Leaked / Burnt or

Mod: **Nil** / S/Rim / STD A/Rim or

Tyre Size F: **195/60R16C**

R: **195/60R16C**

BS / DUN / EXNOVA **GV** / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: **06** mm R/Bal: **06** mm

L/Bal: **06** mm L/Bal: **06** mm

D.O.A. D.O.I. **19/12/19**

Survey held at **Liu Brothers**

Des. of Damages: Frt / **Rear** / GIS / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

TP ECICS.

MV: **58K**

PV: **20.5K**

Nett: **37.5K**

RECEIVED 5 MAR 2020

Code/Time File Pass to



: Prel. Report



: Final Report

Code/Time File Status to

sl3 - typist

Merimen

L/S \$14,300/-

Days Of Repair: **10**

Resurvey No. of Trips: **2**

Survey Fee

Transportation

at 24 HRS

Other

Other

Other

050

11

461

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
10 Eunus Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 05 Mar 2020

Preliminary Advice

Insured Vehicle No : GN2875Y

TP Vehicle No : GBJ5449E

Accident Date : 16/12/2019

Make : FIAT NEW DOBLO SX

Assignment Date : 19/12/2019

Date of Inspection : 19/12/2019

Est. Duration of Repair : 10

Inspection At : LIU'S BROTHER AUTO ENGINEERING WORKSHOP

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	37,018.60
-----------------------------	------	-----------

Revised Amount	:S\$	17,959.38
----------------	------	-----------

Check Items (Estimated)	:S\$	0.00
-------------------------	------	------

Total	:S\$	17,959.38
-------	------	-----------

Lump Sum Repair (estimated)	:S\$	14,300.00
-----------------------------	------	-----------

Total Loss Consideration

New for Old Value	:S\$	
-------------------	------	--

Pre-Accident Value	:S\$	
--------------------	------	--

COE / PARF Rebate	:S\$	
-------------------	------	--

Salvage Value	:S\$	
---------------	------	--

Margin for Repair	:S\$	
-------------------	------	--

Remarks

☐ The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

☐ The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

☒ Other comments : The above survey was conducted on a 'Without Prejudice' basis.

Niwitha (LKK Auto)

From: Crystabelle Tan Gek Peng (ECICS, Claims) <Crystabelle_Tan@ecics.com.sg>
Sent: Thursday, 19 December 2019 12:24 PM
To: assignments
Cc: Susan Low
Subject: RE: Request for 3rd party claims survey GBJ5449E Claims against GN2875Y - Ref : DMCV1900071H/02/CT
Attachments: GBJ5449E191216.pdf

Dear LKK

Refer to below email and arrange PRI.

Best regards

Crystabelle Tan

Senior Associate | Claims



DID (65) 6303 0190

Tel (65) 6337 4779

Email crystabelle_tan@ecics.com.sg Web www.ecics.com.sg

Address 10 Eunus Road 8, Singapore Post Centre, #09-04A, Singapore 408500.

From: Susan Low [mailto:liusbro@gmail.com]
Sent: Thursday, 19 December, 2019 12:19 PM
To: Crystabelle Tan Gek Peng (ECICS, Claims)
Subject: Re: Request for 3rd party claims survey GBJ5449E Claims against GN2875Y - Ref : DMCV1900071H/02/CT

We did liked to chose as follow

LKK Auto Consultants Pte Ltd

Kindly arrange

Thank.

Best Regards,

Susan Low
M/s Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 67411730 Fax: 67445746

On Thursday, 19 December 2019, 11:21:58 am SGT, Crystabelle Tan Gek Peng (ECICS, Claims) <crystabelle_tan@ecics.com.sg> wrote:

Our Ref : DMCV1900071H/02/CT

Dear Susan

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert.

1. Ajax Inspection Services Pte Ltd
2. Appraisals Associates Pte Ltd
3. Infiniti Appraisal Services
4. LKK Auto Consultants

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Best regards

Crystabelle Tan

Senior Associate | Claims



DID (65) 6303 0190

Tel (65) 6337 4779

Email crystabelle_tan@ecics.com.sg Web www.ecics.com.sg

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

From: Susan Low [mailto:liusbro@ymail.com]
Sent: Thursday, 19 December, 2019 11:14 AM
To: ECICS Claims; Crystabelle Tan Gek Peng (ECICS, Claims)
Subject: Request for 3rd party claims survey GBJ5449E Claims against GN2875Y

Accident on 16/12/2019 Along PIE Towards Changi

Involving GBJ5449E and GN2875Y

We refer to the above accident and 3rd party claims.

We hereby write to request of 3rd party claims pre-repair inspection for our client's vehicle.

Please let us have your single joint expert motor surveyors list (SJE) to conduct a pre-repair survey of the damage to our client's vehicle jointly with our client/our motor workshop at No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883 as soon as possible.

Kindly arrange.

Thank you.

Best Regards

Susan Low
M/s Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 6741 1730
Fax: 6744 5746

Date of Survey:- _____

Name of Authorise Surveyor:- _____

Surveyor Email: _____

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Details Particulars	
Owner ID Type:	Company
Owner ID:	196N
Vehicle Details	
Vehicle No:	GBJ5449E
Vehicle to be Exported:	Yes
Intended Demolition Date:	19 Dec 2019
Vehicle Make:	FIAT
Vehicle Model:	NEW DOBLO SX 1.6MJ E6 GLAZED
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No:	263A80008234659
Chassis No:	ZFA26300006H90642
Maximum Power Output:	-
Open Market Value:	\$20,615.00
Original Registration Date:	22 May 2019
First Registration Date:	22 May 2019
Transfer Count:	0
Actual AWP Paid:	\$1,031.00
Import Duty Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Import GST Rebate Details	
COE Expiry Date:	21 May 2029
COE Category:	C - Goods Vehicle & Bus
COE Period Years:	10
PQP Paid:	\$25,610.00
COE Rebate Amount:	\$20,488.00
Total Rebate Amount:	\$20,488.00

The information contained herein is correct as at 19 Dec 2019

OK



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post Ad [15](#) Advertisements [1](#) Ways of Selling

Nissan Latio Auto 1.5 White.



Direct Owner, No Engine
Problems, Regular Servicing.
Direct Owner: StarAd



PRIME MOTOR & LEASING

SHENYI YONG CREDIT AND SERVICES PTE LTD. GROUP OF COMPANIES

With over 200 units of vehicles
to choose from, ranging from
all European to Japanese Makes.



Browse by Category

[Save Search](#)

[Print](#)

« Back (1 2) Next »

Sort by Date Posted

20 results/page

26 Vehicles

Search

Doblo

Advanced Search

Search

View All

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

Doblo

Any

Any

Any

Any

Any

Any

Available



☐ Fiat Doblo 1.3H

\$20,800

\$5,440 /yr

16-Oct-2013

1,248 cc

102,380 km

Van

Available

Fuel Type: Diesel

Please Call In Advance Before Viewing. Thanks!

[View](#) [Details](#) [Compare](#) [Add to Favourites](#) [Add to Compare](#) [Print](#) [Share](#) [Report](#)



☐ Fiat Doblo Cargo Maxi 1.6A

\$48,888

\$6,180 /yr

14-Nov-2017

1,598 cc

57,000 km

Van

Available

Fuel Type: Diesel

New Sets Of Tyres, 5 Years Agent Warranty, Paintwork Well Maintained, High Loans 90% Of The Car Price With Lowest Interest Rates From 2.28%. Trade In Welcome. Call Now To Book An Appointment To View This Beauty. Viewing Strictly Appointment Based.

[View](#) [Details](#) [Compare](#) [Add to Favourites](#) [Add to Compare](#) [Print](#) [Share](#) [Report](#)



☐ Fiat Doblo Cargo Maxi 1.6A

\$48,888

\$6,860 /yr

17-Oct-2016

1,598 cc

28,000 km

Van

Available

Fuel Type: Diesel

Servise And Warranty By Agent Motoriva Pte Ltd.

[View](#) [Details](#) [Compare](#) [Add to Favourites](#) [Add to Compare](#) [Print](#) [Share](#) [Report](#)



☐ Fiat Doblo 1.3H

\$30,888

\$6,780 /yr

09-Jul-2014

1,248 cc

-

Van

Available

Fuel Type: Diesel

Value For Money, In House Loan Is Available.

[View](#) [Details](#) [Compare](#) [Add to Favourites](#) [Add to Compare](#) [Print](#) [Share](#) [Report](#)



Fiat unveils its new Doblo

The new Fiat Doblo retains the outstanding versatility, practicality and dynamics of the current model but with improved refinement.

[Read this article](#)



☐ Fiat Doblo Cargo Maxi 1.6A

\$40,800

\$6,700 /yr

21-Jan-2016

1,598 cc

89,826 km

Van

Available

Fuel Type: Diesel

Cheapest In The Market, For Personal Usage Only, No Cargos Etc. Hence The Car Looks And Drive Like New. No Scratches Etc. Condition Is Like Brand New.

Prime Row Motors

[View](#) [Details](#) [Compare](#) [Add to Favourites](#) [Add to Compare](#) [Print](#) [Share](#) [Report](#)



☐ Fiat Doblo 1.6H Multijet Glaze

\$61,800

\$6,480 /yr

01-Jul-2019

1,598 cc

-

Van

Available

Fuel Type: Diesel

5 Years/160000 Warranty, 3 Times Servicing With Parts And Labour Included. Powerful Engine And Economical Model. Good Fuel Efficiency. Call Us Now And Find Out More On Our Package.

Ezy-1 Pte Ltd

[View](#) [Details](#) [Compare](#) [Add to Favourites](#) [Add to Compare](#) [Print](#) [Share](#) [Report](#)

Save this search criteria, to get email alerts whenever a match is found.

[Save Search](#)

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

view Expired ads

« Back (1 2) Next »

20 results/page

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/12/2019 10:44
Date Of Accident	16/12/2019 15:25
Exact Location Of Accident	PIE TOWARDS CHANGI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBJ5449E
Insured/Policyholder	
Name Of Registered Owner	GOLDBELL LEASING PTE LTD
Co Reg No	199001196N
Email Address	ISAACNGCL@GBL.COM.SG
Mobile Phone No	(LOCAL) +65-96348607
Alternative Phone No	OFFICE-64942897

Vehicle Particulars

Manufacturer	FIAT
Model	NEW DOBLO SX-1.6 MJ E6 GLA (A)
Exact Purpose for which vehicle was being used at time of accident	DELIVERY
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-19093298MFCV
Cover Note Number	

Driver

Name of Driver	JIMMY SIM WUI LENG
NRIC No	S7642322I
Date Of Birth	28/12/1976
Occupation	OUTDOOR
Date Of Driving Pass	10/05/1999
Driving Experience	20 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96348607
Fax Number	
Contact Number	
Email Address	WILLIAM.TAN@GARDENERDENVER.COM

Address	BLK 111 TAMPINES STREET 11 #08-217
Postcode	521111
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 16 DEC 2019, AT ABOUT 1525HRS, I WAS DRIVING MY VEHICLE GBJ5449E ALONG PIE TOWARDS CHANGI. I WAS TRAVELLING ALONG SECOND LANE. THE FRONT VEHICLE, GBF8059Z STOPPED HIS VEHICLE DUE TO SLOW MOVING TRAFFIC. I STOPPED MY VEHICLE. SUDDENLY I FELT AN IMPACT AT MY REAR PORTION, ALIGHTED FROM VEHICLE AND REALISED THERE WERE 2 VEHICLES BEHIND ME. REALISED THAT VEHICLE D - GX8558X DID NOT STOP HIS VEHICLE AND COLLIDED ONTO VEHICLE C - GN2875Y. BECAUSE OF THE IMPACT VEHICLE C - GN2875Y COLLIDED ONTO MY REAR PORTION. AND MY VEHICLE HIT FRONT VEHICLE GBF8059Z. EXCHANGED PARTICULARS. I WAS INJURED. MY NECK AND MY BACK WERE IN PAIN DUE TO THE ACCIDENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF8059Z
Vehicle Make/Model/Colour	TOYOTA HIACE
Details Of Properties	HONG DA SIANG ENGINEERING & CONSTRUCTION PTE LTD
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CHONG CHUN SUONG
NRIC/Passport Number	F7143872N
Contact Number	+6596223913
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

2

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

GN2875Y

Vehicle Make/Model/Colour

TOYOTA (LORRY)

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

KOH MUI BOON, ANDREAS

NRIC/Passport Number

S9021907C

Contact Number

+6582685449

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

2

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

GX8558X

Vehicle Make/Model/Colour

TOYOTA

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

TAMILSELVAM S/O UMPIGAPATHI

NRIC/Passport Number

S7903150Z

Contact Number

Address

BLK 223A SUMANG LANE #14-153

Postcode

821223

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

2

DETAILS OF INJURED PERSON 1

Name

JIMMY SIM WUI LENG

Approximate Age

Injuries Sustain

NECK AND BACK PAIN

Injured person in which vehicle?

GBJ5449E

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be **as truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information"), and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police, for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/an be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
(date & time)

Driver's Signature
(if driver is not the policyholder)
Date & Time 17/12/18 0841H

Reporting Centre Personnel's Signature
Name: Khumedy
NRIC/FIN No.

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 16 DEC 2016, at about 1031H, I was driving my vehicle GBJ 5441E along PIE towards Chang. I was travelling along second lane. The front vehicle GBF 80572 stopped his vehicle due to slow moving traffic. Suddenly I stopped my vehicle. Suddenly I felt an impact at my rear portion. Alighting from vehicle and realised that there was 2 vehicle behind me. Realised that vehicle D - GX 8558X was did not stop his vehicle and collided onto vehicle C - GN 2875Y. Because of the impact vehicle C - GN 2875Y collided onto my rear portion. And my vehicle hit front vehicle GBF 80572. Exchanged particulars. No body was injured I was injured. My neck and my back were injured due the accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policeholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policeholder)
Date & Time 17/12/16 - 0641H

Reporting Centre Personnel's Signature
Name: Khanna
NRIC/PPN No:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 196N

Vehicle Details

Vehicle No.: GBJ5449E
Vehicle to be Exported: No
Intended Deregistration Date: 18 Dec 2019
Vehicle Make: FIAT
Vehicle Model: NEW DOBLO SX 1.6MJ E6
GLAZED

Primary Colour: Grey
Manufacturing Year: 2017
Engine No.: 263A80008234659
Chassis No.: ZFA26300006H90642
Maximum Power Output: -
Open Market Value: \$20,615.00
Original Registration Date: 22 May 2019
First Registration Date: 22 May 2019
Transfer Count: 0
Actual ARF Paid: \$1,031.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 21 May 2029
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 10
PQP Paid: \$25,610.00
COE Rebate Amount: \$24,136.00
Total Rebate Amount: \$24,136.00

The information contained herein is correct as at 18 Dec 2019

OK



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-208595
Date of Request: 18/12/2019
Your Ref No: Online Purchase

LIU'S BROTHER AUTO WORKSHOP
1 Kaki Bukit Ave 6 #01-01
Auto Bay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date: 18/12/2019
Enquiry By: Susan Low Siew Yian
TP Vehicle No: GN2875Y
Accident Date: 16/12/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GN2875Y	ECICS Limited	01/04/2019-31/03/2020	63374779 /6303 0178

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-208595
Date of Request: 18/12/2019

Your Ref No: Online Purchase

LIU'S BROTHER AUTO WORKSHOP
1 Kaki Bukit Ave 6 #01-01
Auto Bay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date: 18/12/2019
Enquiry By: Susan Low Siew Yian
TP Vehicle No: GN2875Y
Accident Date: 16/12/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:
Date:
☒ GIRO ☐ Cash ☐ Cheque

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417881

ROB No: 53297931 Tel: 6741-7730 / 731 Fax: 6744-5746 Email: liusbrog@gmail.com

Invoice/Ref No: GBJ5449E191216

Estimate

Customer

Page 01 of 02

Name: ECICS Limited

Date: 18-12-19

Address: Motor Claims Department

Vehicle No: GBJ5449E

10 Eunos Road 8 #09-04A

Model/Make: Fiat Doblo Cargo

Singapore Post Centre Singapore 408600

SX 1.6 MJE 6

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Bumper <i>Replaced</i>	\$ 627.00	✓
2	Bumper Clips 1 set <i>m</i>	\$ 65.00	✓
3	Bumper Reflector 02 pcs (@ \$598.60) <i>LH included</i>	\$ 197.20	✓ 98.60
4	Bumper Reinforcement <i>Best</i>	\$ 475.30	✓
5	End Panel Outer <i>Replaced</i>	\$ 430.00	✓
6	End Panel Inner <i>Replaced</i>	\$ 295.00	✓
7	End Panel Top Garnish <i>Replaced</i>	\$ 347.70	✓
8	End Panel Top Garnish Clips 1 set <i>m</i>	\$ 58.00	✓ 20
9	Bumper Reverse Sensor 1 set <i>Replaced</i>	\$ 220.00	✓ SN 200 (320)
10	Bumper Bracket 02 pcs (@ \$583.70) <i>Replaced</i>	\$ 567.40	✓ 116.20
11	Spare Tyre Carrier <i>Replaced</i>	\$ 590.00	✓ 427
12	Floor Panel <i>Replaced</i>	\$ 2,450.00	✓
13	Floor Panel Outer Garnish <i>Replaced</i>	\$ 179.80	✓
14	Tail Lamp 02 pcs (@ \$5462.70) <i>LH included</i>	\$ 995.40	✓ 442.70 384.20
15	Rear Rh Tailgate <i>Replaced</i>	\$ 1,895.90	✓
16	Tailgate Weatherstrip <i>Replaced</i>	\$ 237.00	✓
17	Tailgate Inner Trim Board	\$ 297.80	✓
18	Tailgate Inner Trim Board Clips 1 set <i>Replaced</i>	\$ 127.30	✓
19	Tailgate Lock Top <i>Replaced</i>	\$ 189.30	✓
20	Tailgate Lock Upper <i>Replaced</i>	\$ 192.90	✓
21	Tailgate Hinge 02 pcs (@ 166.30) <i>Replaced</i>	\$ 332.60	✓
22	Tailgate Outer Garnish <i>Replaced</i>	\$ 279.00	✓
23	Tailgate Inner Handle <i>Replaced</i>	\$ 189.40	✓
24	Tailgate "Fiat Logo" Emblem	\$ 87.80	✓
25	Tailgate "Professional" Emblem	\$ 163.50	✓
26	Tailgate "6 PAX" Sticker	\$ 12.00	✓ SN 60 (320)
27	Tailgate Glass Sealant	\$ 80.00	✓
28	Tailgate "70 KM/H" Sticker	\$ 15.00	✓
29	Rear Lh Tailgate <i>Replaced</i>	\$ 2,156.30	✓
30	Tailgate Weatherstrip <i>Replaced</i>	\$ 279.00	✓
31	Tailgate Inner Trim Board <i>Replaced</i>	\$ 384.90	✓
32	Tailgate Inner Trim Board Clips 1 set <i>Replaced</i>	\$ 164.50	✓ SN 30 (50)
33	Tailgate Lock <i>Replaced</i>	\$ 331.00	✓
34	Tailgate Hinge 02 pcs (@ 166.30) <i>Replaced</i>	\$ 332.60	✓
35	Tailgate Outer Handle <i>Replaced</i>	\$ 556.30	✓ 115.20
	C/F Balance	\$ 15,731.90	



M/s Liu's Brother Auto Engrg Wks

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417881

ROB No: 53197931 Tel: 6741-1730 / 731 Fax: 6741-5746 Email: liusbroy@gmail.com

Invoice/Ref No: GBJ5449E191216

Estimate

Customer

Page 02 - 02

Name: ECICS Limited

Date: 18-12-19

Address: Motor Claims Department

Vehicle No: GBJ5449E

10 Eunos Road 8 #09-04A

Model/Make: Fiat Doblo Cargo

Singapore Post Centre

Singapore 408600

SX 1.6 MJE 6

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
	B/F Balance →	\$ 15,731.90	
36	Rear Lh Tailgate Outer Handle Garnish <i>Repaired</i>	\$ 369.80	
37	Tailgate Inner Handle <i>Ren</i>	\$ 189.40	
38	Tailgate Number Plate Outer Garnish <i>Del</i>	\$ 310.60	
39	Tailgate Number Plate Lamp 02 pcs (@\$1.50) <i>Ren</i>	\$ 103.00	
40	Tailgate Number Plate & Base <i>Ben</i>	\$ 48.00	
41	Tailgate Windscreen Glass <i>Shattered</i>	\$ 841.50	
42	Tailgate Glass Sealant <i>Ren</i>	\$ 80.00	
43	Tailgate Wiper Motor <i>Ren</i>	\$ 428.00	
44	Tailgate Wiper Link <i>Ren</i>	\$ 165.30	
45	Tailgate Wiper Blade <i>cut</i>	\$ 98.00	
46	Tail Lamp Panel <i>Ren</i>	\$ 989.30	
47	Fender (Body Panel) <i>Ren</i>	\$ 2,350.00	
48	Fender Cowling <i>Ren</i>	\$ 316.00	
49	Front Bumper <i>Ren</i>	\$ 1,245.50	
50	Bumper Clips 1 set <i>Ren</i>	\$ 58.00	
51	Bumper Reinforcement <i>Ren</i>	\$ 752.00	
52	Bumper Sponge <i>Ren</i>	\$ 117.60	
53	Bumper Bracket 02 pcs (@ \$517.80) <i>Ren</i>	\$ 343.60	
54	Grille <i>Ren</i>	\$ 484.70	
55	Grille "Fiat Logo" Motif <i>Ren</i>	\$ 142.10	
56	Bumper Lower Grille <i>Ren</i>	\$ 685.00	
57	Bumper Lower Grille Clips 1 set <i>Ren</i>	\$ 65.00	
58	Number Plate Garnish <i>Ren</i>	\$ 387.00	
59	Number Plate and Base <i>Ben</i>	\$ 48.00	
60	Head Lamp 02 pcs (@ \$862.40) <i>Ren</i>	\$ 1,724.80	
61	AirBag Control Unit <i>Ren</i>	\$ 2,876.50	
40	Tailgate Number Plate & Base <i>Ben</i>	\$ 48.00	
	"Corporate" Advertisement Sticker <i>Ren</i>	\$ 800.00	
	To check all wiring & electrical component for proper function	\$ 180.00	
	Remove and refix rear 2 tailgate components & wiper mechanism	\$ 180.00	
	Remove and refix rear bumper reverse sensor	\$ 100.00	
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 2,500.00	
	To putty & spray painting & including touch up paint on accident affected	\$ 1,800.00	
	Remove & reinstall Tailgate 2 Glass to facilitate repairs	\$ 180.00	
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 180.00	

Total Parts & Labour of estimate for damaged vehicle

\$ 37,018.60

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

Total 181138

L/S 14316

96893735

19/12/19

Adrian Lj

L/S 10 Days

3890

Veron Chen (LKKAUTO)

From: Susan Low <liusbro@ymail.com>
Sent: Monday, 2 March 2020 2:51 PM
To: Veron Chen (LKKAUTO)
Subject: Re: FINALISE (3 VEHICLES)

Confirmed and accepted as follow

1. YM 5120P-Offer Lump Sum \$950 @ 4 working days
2. YQ 188G-Offer Lump Sum \$5850 @ 6 working days
3. GBJ 5449E-Offer Lump Sum \$14,300 @ 10 working days

Thank.

Best Regards,

Susan Low
M/s Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 67411730 Fax: 67445746

On Monday, 2 March 2020, 1:44:52 pm SGT, Veron Chen (LKKAUTO) <veronchen@lkkauto.com> wrote:

Dear Susan,

WITHOUT PREJUDICE

Attach 3 vehicles for finalise.

1. YM 5120P-Offer Lump Sum \$950 @ 4 working days

2. YQ 188G-Offer Lump Sum \$5850 @ 6 working days
3. GBJ 5449E-Offer Lump Sum \$14,300 @ 10 working days

Please check and confirmed.

Any more outstanding cases survey by Adrian for him to finalise.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Mar 2020 11:00 Edit Reg		19 Dec 2019 00:00 Edit Adj Rpt	S\$14,300.00 Edit Estimates	S\$14,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: -, Co. Reg. No.: -, Email: EMAIL@EMAIL.COM									
Main Claimant: GOLDBELL LEASING PTE LTD , Co. Reg. No.: 199001196N									
Vehicle Reg. No.: GBJ5449E		Date of Loss: 16/12/2019 15:00 - :59 [6 Months and 24 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): GN2875Y		Policy No. (Claimant):							
		Excess:							
Repairer: Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ) Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit, 417883 Kaki Bukit - Tel:									
Handling Insurer: ECICS Limited (HQ) - Tel: 63374779 /6303 0178									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 31/12/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBJ5449E

[GN2875Y]

TP

GOLDBELL LEASING PTE LTD

Dec 16 2019 3:00PM

[-]

Liu's Brother Auto Engineering Workshop (kaki Bukit)

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	05/03/20 09:20	Adjuster Immediate Advice					1	Load HTM		
Photos/Images							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	05/03/20 08:52	General View					1	Load JPG	☒	
2	05/03/20 08:52	General View					1	Load JPG	☒	
3	05/03/20 08:52	General View					1	Load JPG	☒	
4	05/03/20 08:52	General View					1	Load JPG	☒	
5	05/03/20 08:52	General View					1	Load JPG	☒	
6	05/03/20 08:52	General View					1	Load JPG	☒	
7	05/03/20 08:52	General View					1	Load JPG	☒	
8	05/03/20 08:52	General View					1	Load JPG	☒	
9	05/03/20 08:52	General View					1	Load JPG	☒	
10	05/03/20 08:52	General View					1	Load JPG	☒	
11	05/03/20 08:52	General View					1	Load JPG	☒	
12	05/03/20 08:52	General View					1	Load JPG	☒	
13	05/03/20 08:52	General View					1	Load JPG	☒	
14	05/03/20 08:52	General View					1	Load JPG	☒	
15	05/03/20 08:52	General View					1	Load JPG	☒	
16	05/03/20 08:52	General View					1	Load JPG	☒	
17	05/03/20 08:52	General View					1	Load JPG	☒	
18	05/03/20 08:52	General View					1	Load JPG	☒	
19	05/03/20 08:52	General View					1	Load JPG	☒	
20	05/03/20 08:52	General View					1	Load JPG	☒	
21	05/03/20 08:52	General View					1	Load JPG	☒	
22	05/03/20 08:52	General View					1	Load JPG	☒	
23	05/03/20 08:52	General View					1	Load JPG	☒	
24	05/03/20 08:52	General View					1	Load JPG	☒	
25	05/03/20 08:52	General View					1	Load JPG	☒	
26	05/03/20 08:52	General View					1	Load JPG	☒	
27	05/03/20 08:52	General View					1	Load JPG	☒	
28	05/03/20 08:52	General View					1	Load JPG	☒	
29	05/03/20 08:52	General View					1	Load JPG	☒	
30	05/03/20 08:52	General View					1	Load JPG	☒	
31	05/03/20 08:52	General View					1	Load JPG	☒	
32	05/03/20 08:52	General View					1	Load JPG	☒	
33	05/03/20 08:52	General View					1	Load JPG	☒	
34	05/03/20 08:52	General View					1	Load JPG	☒	

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
35	05/03/20 08:52	General View	 Load JPG	☒
36	05/03/20 08:52	General View	 Load JPG	☒
37	05/03/20 08:52	General View	 Load JPG	☒
38	05/03/20 08:52	General View	 Load JPG	☒
39	05/03/20 08:52	General View	 Load JPG	☒
40	05/03/20 08:53	General View	 Load JPG	☒
41	05/03/20 08:53	General View	 Load JPG	☒
42	05/03/20 08:53	General View	 Load JPG	☒
43	05/03/20 08:53	General View	 Load JPG	☒
44	05/03/20 08:53	General View	 Load JPG	☒
45	05/03/20 08:53	General View	 Load JPG	☒
46	05/03/20 08:53	General View	 Load JPG	☒
47	05/03/20 08:53	General View	 Load JPG	☒
48	05/03/20 08:53	General View	 Load JPG	☒
49	05/03/20 08:53	General View	 Load JPG	☒
50	05/03/20 08:53	General View	 Load JPG	☒
51	05/03/20 08:53	General View	 Load JPG	☒
52	05/03/20 08:53	General View	 Load JPG	☒
53	05/03/20 08:53	General View	 Load JPG	☒
54	05/03/20 08:53	General View	 Load JPG	☒
55	05/03/20 08:53	General View	 Load JPG	☒
56	05/03/20 08:53	General View	 Load JPG	☒
57	05/03/20 08:53	General View	 Load JPG	☒
58	05/03/20 08:53	General View	 Load JPG	☒
59	05/03/20 08:53	General View	 Load JPG	☒
60	05/03/20 08:53	General View	 Load JPG	☒
61	05/03/20 08:53	General View	 Load JPG	☒
62	05/03/20 08:53	General View	 Load JPG	☒
63	05/03/20 08:53	General View	 Load JPG	☒
64	05/03/20 08:53	General View	 Load JPG	☒
65	05/03/20 08:53	General View	 Load JPG	☒
66	05/03/20 08:53	General View	 Load JPG	☒
67	05/03/20 08:53	General View	 Load JPG	☒
68	05/03/20 08:53	General View	 Load JPG	☒
69	05/03/20 08:53	General View	 Load JPG	☒
70	05/03/20 08:53	General View	 Load JPG	☒
71	05/03/20 08:53	General View	 Load JPG	☒
72	05/03/20 08:53	General View	 Load JPG	☒
73	05/03/20 08:53	General View	 Load JPG	☒
74	05/03/20 08:53	General View	 Load JPG	☒
75	05/03/20 08:53	General View	 Load JPG	☒
76	05/03/20 08:53	General View	 Load JPG	☒
77	05/03/20 08:53	General View	 Load JPG	☒
78	05/03/20 08:53	General View	 Load JPG	☒
79	05/03/20 08:53	General View	 Load JPG	☒
80	05/03/20 08:53	General View	 Load JPG	☒
81	05/03/20 08:53	General View	 Load JPG	☒
82	05/03/20 08:53	General View	 Load JPG	☒
83	05/03/20 08:53	General View	 Load JPG	☒

Assessment Reports			1 per page	☒	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
84	05/03/20 08:53	General View		Load JPG	☒
85	05/03/20 08:53	General View		Load JPG	☒
86	05/03/20 08:53	General View		Load JPG	☒
87	05/03/20 08:53	General View		Load JPG	☒
88	05/03/20 08:53	General View		Load JPG	☒
89	05/03/20 08:53	General View		Load JPG	☒
90	05/03/20 08:53	General View		Load JPG	☒
91	05/03/20 08:53	General View		Load JPG	☒
92	05/03/20 08:53	General View		Load JPG	☒
93	05/03/20 08:59	Reinspection Photo		Load JPG	☒
94	05/03/20 08:59	Reinspection Photo		Load JPG	☒
95	05/03/20 08:59	Reinspection Photo		Load JPG	☒
96	05/03/20 08:59	Reinspection Photo		Load JPG	☒
97	05/03/20 08:59	Reinspection Photo		Load JPG	☒
98	05/03/20 08:59	Reinspection Photo		Load JPG	☒
99	05/03/20 08:59	Reinspection Photo		Load JPG	☒
100	05/03/20 08:59	Reinspection Photo		Load JPG	☒
101	05/03/20 08:59	Reinspection Photo		Load JPG	☒
102	05/03/20 08:59	Reinspection Photo		Load JPG	☒
103	05/03/20 08:59	Reinspection Photo		Load JPG	☒
104	05/03/20 08:59	Reinspection Photo		Load JPG	☒
105	05/03/20 09:00	Reinspection Photo		Load JPG	☒
106	05/03/20 09:00	Reinspection Photo		Load JPG	☒
107	05/03/20 09:00	Reinspection Photo		Load JPG	☒
108	05/03/20 09:00	Reinspection Photo		Load JPG	☒
109	05/03/20 09:00	Reinspection Photo		Load JPG	☒
110	05/03/20 09:00	Reinspection Photo		Load JPG	☒
111	05/03/20 09:00	Reinspection Photo		Load JPG	☒
112	05/03/20 09:00	Reinspection Photo		Load JPG	☒
113	05/03/20 09:00	Reinspection Photo		Load JPG	☒
114	05/03/20 09:00	Reinspection Photo		Load JPG	☒
115	05/03/20 09:00	Reinspection Photo		Load JPG	☒
116	05/03/20 09:00	Reinspection Photo		Load JPG	☒
117	05/03/20 09:00	Reinspection Photo		Load JPG	☒
118	05/03/20 09:00	Reinspection Photo		Load JPG	☒
119	05/03/20 09:00	Reinspection Photo		Load JPG	☒
120	05/03/20 09:00	Reinspection Photo		Load JPG	☒
121	05/03/20 09:00	Reinspection Photo		Load JPG	☒
122	05/03/20 09:00	Reinspection Photo		Load JPG	☒
123	05/03/20 09:00	Reinspection Photo		Load JPG	☒
124	05/03/20 09:00	Reinspection Photo		Load JPG	☒
125	05/03/20 09:00	Reinspection Photo		Load JPG	☒
126	05/03/20 09:00	Reinspection Photo		Load JPG	☒
127	05/03/20 09:00	Reinspection Photo		Load JPG	☒
128	05/03/20 09:00	Reinspection Photo		Load JPG	☒
129	05/03/20 09:00	Reinspection Photo		Load JPG	☒
130	05/03/20 09:00	Reinspection Photo		Load JPG	☒
131	05/03/20 09:00	Reinspection Photo		Load JPG	☒
132	05/03/20 09:00	Reinspection Photo		Load JPG	☒
133	05/03/20 09:00	Reinspection Photo		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
134	05/03/20 09:00	Reinspection Photo		☒
135	05/03/20 09:00	Reinspection Photo		☒
136	05/03/20 09:00	Reinspection Photo		☒
137	05/03/20 09:00	Reinspection Photo		☒
138	05/03/20 09:00	Reinspection Photo		☒
139	05/03/20 09:00	Reinspection Photo		☒
140	05/03/20 09:00	Reinspection Photo		☒
141	05/03/20 09:00	Reinspection Photo		☒
142	05/03/20 09:00	Reinspection Photo		☒
143	05/03/20 09:00	Reinspection Photo		☒
144	05/03/20 09:00	Reinspection Photo		☒
145	05/03/20 09:00	Reinspection Photo		☒
146	05/03/20 09:00	Reinspection Photo		☒
147	05/03/20 09:00	Reinspection Photo		☒
148	05/03/20 09:00	Reinspection Photo		☒
149	05/03/20 09:00	Reinspection Photo		☒
150	05/03/20 09:00	Reinspection Photo		☒
151	05/03/20 09:00	Reinspection Photo		☒
152	05/03/20 09:00	Reinspection Photo		☒
153	05/03/20 09:00	Reinspection Photo		☒
154	05/03/20 09:02	Reinspection Photo		☒
155	05/03/20 09:02	Reinspection Photo		☒
156	05/03/20 09:02	Reinspection Photo		☒
157	05/03/20 09:02	Reinspection Photo		☒
158	05/03/20 09:02	Reinspection Photo		☒
159	05/03/20 09:02	Reinspection Photo		☒
160	05/03/20 09:02	Reinspection Photo		☒
161	05/03/20 09:02	Reinspection Photo		☒
162	05/03/20 09:02	Reinspection Photo		☒
163	05/03/20 09:02	Reinspection Photo		☒
164	05/03/20 09:02	Reinspection Photo		☒
165	05/03/20 09:02	Reinspection Photo		☒
166	05/03/20 09:02	Reinspection Photo		☒
167	05/03/20 09:02	Reinspection Photo		☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS19022320/AVD3E2

Date: 06/03/2020

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	GBJ5449E	Insured Vehicle No :	GN2875Y
Date of Loss:	16/12/2019	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ5449E	Engine No:	263A80008234659
Make & Model:	FIAT NEW DOBLO SX, 1.6 MJ E6 GLA (A)	Chassis No:	ZFA26300006H90642
Reg. Date:	22/05/2019 (Man. Year: 2017)	Odometer:	9970 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R16C	Rear Tyre Size:	195/60 R16C
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,798.60	14,619.38	17,179.22	54.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,220.00	3,340.00	1,880.00	36.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	37,018.60	17,959.38	19,059.22	51.49
Approved Total (Overridden) (S\$)		14,300.00		
(S\$)	37,018.60	14,300.00	22,718.60	61.37
+ GST 7.00/7.00% (S\$)	2,591.30	1,001.00	1,590.30	61.37
Nett Amount (S\$)	39,609.90	15,301.00	24,308.90	61.37

INSPECTION

Date of Assignment: 19/12/2019
Date Inspected: 19/12/2019 Inspected At:

Liu's Brother Auto Engineering Workshop
(kaki Bukit) (HQ)
Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @
Kaki Bt Singapore 417883, Kaki Bukit
Singapore 417883

Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 06 Mar 2020)	
Parts:	N/A	FIAT NEW DOBLO SX 1.6 MJ E6 GLA (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ5449E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Distorted	627.00 F	*627.00 FL
2	1	*SET REAR BUMPER CLIPS	Necessary	65.00 F	*30.00 FL
3	1	*REAR BUMPER REFLECTOR	N/S Cracked	197.20 F	*98.60 FL
4	1	*REAR BUMPER REINFORCEMENT	Bent	475.30 F	*475.30 FL
5	1	*REAR END PANEL OUTER	Dented	430.00 F	*430.00 FL
6	1	*REAR END PANEL INNER	Repair	295.00 F	*- FL
7	1	*REAR END PANEL TOP GARNISH	Cracked	347.70 F	*347.70 FL
8	1	*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	58.00 F	*20.00 FL
9	1	*SET REAR BUMPER REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
10	2	*REAR BUMPER BRACKET	Necessary	567.40 F	*116.20 FL
11	1	*REAR SPARE TYRE CARRIER	Damaged	590.00 F	*427.00 FL
12	1	*REAR FLOOR PANEL	Repair	2,450.00 F	*- FL
13	1	*REAR FLOOR PANEL OUTER GARNISH	Deformed	179.80 F	*179.80 FL
14	1	*REAR TAIL LAMP	N/S Cracked	925.40 F	*384.20 FL
15	1	*REAR RH TAILGATE	Buckled	1,895.90 F	*1,895.90 FL
16	1	*REAR RH TAILGATE WEATHERSTRIP	Not Necessary	237.00 F	*- FL
17	1	*REAR RH TAILGATE INNER TRIM BOARD	Not Necessary	297.80 F	*- FL
18	1	*SET REAR RH TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	127.20 F	*- FL
19	1	*REAR RH TAILGATE LOCK TOP	Not Necessary	189.30 F	*- FL
20	1	*REAR RH TAILGATE LOCK UPPER	Damaged	192.90 F	*192.90 FL
21	2	*REAR RH TAILGATE HINGE	Not Necessary	332.60 F	*- FL
22	1	*REAR RH TAILGATE OUTER GARNISH	Cracked	279.00 F	*279.00 FL
23	1	*REAR RH TAILGATE INNER HANDLE	Not Necessary	189.40 F	*- FL
24	1	*REAR RH TAILGATE FIAT LOGO EMBLEM	Necessary	87.80 F	*87.80 FL
25	1	*REAR RH TAILGATE PROFESSIONAL EMBLEM	Necessary	163.50 F	*163.50 FL
26	1	*REAR RH TAILGATE 6 PAX STICKER	Necessary	12.00 FS	*12.00 FS
27	1	*REAR RH TAILGATE GLASS SEALANT	Necessary	80.00 FS	*60.00 FS
28	1	*REAR RH TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*15.00 FS
29	1	*REAR LH TAILGATE	Distorted	2,156.30 F	*2,156.30 FL
30	1	*REAR LH TAILGATE WEATHERSTRIP	Cut	279.00 F	*279.00 FL
31	1	*REAR LH TAILGATE INNER TRIM BOARD	Deformed	384.90 F	*384.90 FL
32	1	*SET REAR LH TAILGATE INNER TRIM BOARD CLIPS	Necessary	164.50 FS	*30.00 FS
33	1	*REAR LH TAILGATE LOCK	Damaged	331.00 F	*331.00 FL
34	2	*REAR LH TAILGATE HINGE	Bent	332.60 F	*332.60 FL
35	1	*REAR LH TAILGATE OUTER HANDLE	Deformed	556.40 F	*115.20 FL
36	1	*REAR LH TAILGATE OUTER HANDLE GARNISH	Repeated	369.80 F	*- FL
37	1	*REAR LH TAILGATE INNER HANDLE	Not Necessary	189.40 F	*- FL
38	1	*REAR LH TAILGATE NUMBER PLATE OUTER GARNISH	Deformed	310.60 F	*310.60 FL
39	2	*REAR LH TAILGATE NUMBER PLATE LAMP	Not Necessary	103.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR LH TAILGATE NUMBER PLATE & BASE	Bent	48.00 FS	*48.00 FS
41	1		*REAR LH TAILGATE WINDSCREEN GLASS	Shattered	841.50 F	*841.50 FL
42	1		*REAR LH TAILGATE GLASS SEALANT	Necessary	80.00 FS	*60.00 FS
43	1		*REAR LH TAILGATE WIPER MOTOR	Damaged	428.00 F	*428.00 FL
44	1		*REAR LH TAILGATE WIPER LINK	Not Necessary	165.30 F	*- FL
45	1		*REAR LH TAILGATE WIPER BLADE	Cut	98.00 F	*98.00 FL
46	1		*REAR LH TAIL LAMP PANEL	Repair	989.30 F	*- FL
47	1		*REAR LH FENDER (BODY PANEL)	Repair	2,350.00 F	*- FL
48	1		*REAR LH FENDER COWLING	Not Necessary	316.00 F	*- FL
49	1		*FRONT BUMPER	Deformed	1,245.50 F	*864.00 FL
50	1		*SET FRONT BUMPER CLIPS	Necessary	58.00 FS	*30.00 FS
51	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	752.00 F	*- FL
52	1		*FRONT BUMPER SPONGE	Cracked	117.60 F	*117.60 FL
53	2		*FRONT BUMPER BRACKET	Not Necessary	343.60 F	*- FL
54	1		*FRONT GRILLE	Cracked	484.70 F	*484.70 FL
55	1		*FRONT GRILLE FIAT LOGO MOTIF	Necessary	142.10 F	*142.10 FL
56	1		*FRONT BUMPER LOWER GRILLE	Cracked	685.00 F	*488.00 FL
57	1		*SET FRONT BUMPER LOWER GRILLE CLIPS	Necessary	65.00 FS	*65.00 FS
58	1		*FRONT NUMBER PLATE GARNISH	Cracked	387.00 F	*95.00 FL
59	1		*FRONT NUMBER PLATE AND BASE	Bent	48.00 FS	*48.00 FS
60	2		*FRONT HEAD LAMP	Cracked	1,724.80 F	*1,724.80 FL
61	1		*FRONT AIRBAG CONTROL UNIT	Not Necessary	2,876.50 F	*- FL
62	1		*FRONT NUMBER PLATE & BASE	Bent	48.00 FS	*48.00 FS
63	1		*CORPORATE ADVERTISEMENT STICKER	Necessary	800.00 FS	*550.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 31,798.60 16,114.20

- List Item Discount on L Items 0.00/10.00% (\$\$) 0.00 1,494.82

Total Parts (\$\$) 31,798.60 14,619.38

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	180.00	60.00
2	REMOVE AND REFIX REAR 2 TAILGATE COMPONENTS & WIPER MECHANISM	New	180.00	120.00
3	REMOVE AND REFIX REAR BUMPER REVERSE SENSOR	New	100.00	60.00
4	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETC'S	New	2,500.00	1,500.00
5	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED	New	1,800.00	1,400.00
6	REMOVE & REINSTALL TAILGATE 2 GLASS TO FACILITATE REPAIRS	New	280.00	120.00
7	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	180.00	80.00
Gross Labour Cost (S\$)			5,220.00	3,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >