

TRANS-CAB AUTO SERVCIES PTE LTD

NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHB 7556L - AXA**ROEL**

Dole

Not Notionel
L/Sig &

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 7556L - ROEL

LK1LA69RJBB078379*

CHEVROLET

CHEVROLET EPICA 2.0

07.03.2014

AXA**PART****LIST**

1	1	Rear Bumper (Bumper A-RR)	\$	Bul/wt 1,202.00 ✓
2	1	Rear Bumper Side Retainer RH	\$	D17 68.76 ✓
3	1	Rear Fender RH	\$	R 1,145.00 ✓
4	1	Rear Fender Inner Cowling RH	\$	Bu Sin 76.60 X
5	1	Rear Door RH	\$	1,133.00 ✓
6	1	Rear door weatherstrip - Inner RH	\$	Sn 41.40 X
7	1	Rear door weatherstrip - 2nd Frame RH	\$	Sn 25.90 X
8	1	Rear door top hinge RH	\$	R 35.00 X
9	1	Rear door bottom hinge RH	\$	R 35.00 ✓
10	1	Rear door inner lock RH	\$	Tn 425.00 ✓
11	1	Rear door check / arrestor RH	\$	Sn 65.00 X
12	1	Rear door outer weatherstrip moulding RH	\$	Sn 85.00 X
13	1	Rear door outer handle RH	\$	Sn 60.00 X
14	1	Rear door outer handle - rubber seal RH	\$	Sn 25.00 X
15	1	Rear door inner opening handle RH	\$	Sn 45.50 X
16	1	Rear door inner trim board RH	\$	Sn 455.69 X
17	1	Rear door kicking plate / step garnish RH	\$	63.25 ?
18	1	Rear door channel weatherstrip / felt RH	\$	Sn 89.50 X
19	1	Rear door interior light switch RH	\$	Sn 139.20 X
20	1	Rear door power window motor (master)	\$	Tn 274.97 ✓
21	1	Rear door regulator gear RH	\$	R 55.30 ✓
22	1	Rear door regulator handle RH	\$	Bul/wt Sn 65.30 X
23	1	Side Rocker Panel Garnish RH	\$	R 236.40 ✓
24	1	Centre pillar outer RH	\$	R 446.00 ✓
25	1	Centre pillar inner RH	\$	R 460.00 X
26	1	Centre Pillar Reinforcement (Centre) RH	\$	R 596.00 X
27	1	Centre pillar inner garnish - top	\$	Sn 85.55 X
28	1	Centre pillar inner garnish - lower	\$	Sn 185.46 X
29	1	Side Rocker Panel Garnish RH	\$	Bul/wt R 236.40 X
30	1	Side Rocker Panel Outer RH	\$	R 600.00 X
31	1	Side Rocker Panel Inner RH	\$	R 519.30 X
32	1	Side Rocker Panel Center RH	\$	R 501.80 X
33	1	Rear shock absorber	\$	243.57 ?

TRANS-CAB AUTO SERVCIES PTE LTD**ROEL**

NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHB 7556L - AXA

34	1	Rear Axle Housing (Axle A-RR)	\$	711.00 ?
35	1	Parallel Link RR (Link A-Parallel RR)	\$	93.00 ?
36	1	Trailing Link RR RH	\$	90.00 ?
37	1	Upr Arm RH (Arm A-Upr RH)	\$	343.00 ?
38	1	Rear Knuckle Arm RH	\$	350.00 ?
39	1	Front Door RH	\$	1,133.00 ✓
40	1	Steering Wheel Air Bag	\$	1,681.48 —
41	1	Steering Wheel Air Bag Sensor	\$	680.00 —
42	1	Steering Wheel air bag control unit	\$	1,543.22 —
43	1	Front Seat Belt RH	\$	402.50 ✓
44	1	Front safety belt cover garnish	\$	125.00 X
45	1	Front Seat Belt LH	\$	402.50 ?
46	1	Front safety belt cover garnish	\$	125.00 X
47	1	Front Bumper	\$	1,202.00 X
48	1	Front Fender LH	\$	837.60 X
49	1	Front Shock Absorber Assy LH	\$	216.17 ?
50	1	Front Shock Absorber Top Mounting LH	\$	48.32 ?
51	1	Front Lower Arm LH	\$	283.00 ?
52	1	Front Knuckle Arm LH	\$	230.00 ✓
53	1	Steering Rack End (Spring A-Clock)	\$	88.56 ?

TOTAL	\$	20,307.20
10%	\$	2,030.72
	\$	18,276.48

Specical Nett

1Set	Rear Fender Inner Cowling Clip	\$	30.00 X
1Set	Rear Bumper Fastener Clip	\$	24.00 —
1	Door Sticker "6555-3333"	\$	80.00 60SA
1	Door Sticker "Trans-cab"	\$	80.00 60SA
2	Rear Windscreen Sealant	\$	100.00 40SA
1	Rear Windscreen Inner Sponge Seal	\$	100.00 30SA
1	Rear windscreen inner top garnish	\$	80.00 X
1	Rear Tyre RH	\$	180.00 40SA
1	Rear Tyre Rim RH	\$	126.00 50SA
2	Tyre hub cap RH	\$	70.00 X
1set	Side Rocker Panel Garnish Clip RH	\$	30.00 —
1	Front Tyre LH	\$	360.00 60SA
1	Front Wheel Rim LH	\$	254.00 50SA
1	Rear door inner trim board Clip	\$	45.00 X

TRANS-CAB AUTO SERVCIES PTE LTD**ROEL**

NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHB 7556L - AXA

TOTAL		\$	1,559.00
TOTAL PARTS		\$	19,835.48
To Rust-Proofing Of The Affected Areas.	\$	220.00	1201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00	14001
Putty and Spray Painting Of The Affected Portion.	\$	2,700.00	14001
To Check Electrical Lighting Concerned.	\$	170.00	401
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	?
To transfer of tire, rim and on wheel balancing.	\$	170.00	401
To check steering geometry and computer wheel alignment	\$	220.00	601
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	380.00	?
To dismantle and refit rear axle housing assy, remove and renewal of parts, final checking and testing.	\$	380.00	~ 1
To drop rear axle assy, remove and renewal of the necessary parts	\$	380.00	?
To Remove And Refit Rear W/ Screen Glass To Facilitate Bodywork Repair.	\$	170.00	1201
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	1001

TRANS-CAB AUTO SERVCIES PTE LTD

ROEL

NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHB 7556L - AXA

To dismantle and refit rear seat, backrest,
trimings, garnish, roof-lining, speaker
shelfboard, carpeting and other to enable
body work repair.

\$

380.00 10d

Towing fees

\$

120.00 5d

To Transfer Of Fender Fittings, Attachments
And Perform Water Seepage Test.

\$

330.00 X

TOTAL \$ 8,970.00**Over All Total** \$ 28,805.48**REPAIR DAYS****~~10~~ DAYS**