JAS TAN

# CC3/AXA14014454/Kga3s2-1

LKK: IDAC:

ASSIGNMENT

	200	
	J.,	
Surve	yons	

KENNETH

DOI: 30/07/2014

30/07/2014 Date / Time :

Registered in Merimen:

#### Pre-assign / CCU / FTE



Insured Vehicle No.

**SDZ 980L** 

Claim No.

C0311787

Name of Insured

SUNG LI LING

Policy No.

VPA/P0906969

Insured Tel No.

HP: +65-98775610

Make / Model :

HONDA JAZZ-1.5 S (A)

Excess Sec II :S\$ Is driver the owner?

VES / NO )

D.O.A: 28/07/2014

Place of Accident:

BEACH ROAD / OPHIR ROAD JUNCTION TO ECP

Nature of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

If NO. Driver Name / Age

Driver Tel No. :

(V/L: YES / NO )

Insured Liability:

Final? Yes/No

SHD 9409E



WSP: TRANS-CAB Tel: AUTO

Liability:

Payee 3: (Strike if N.A.)

RMKS:



INSRS: WSP: Tel: Liability:

RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date/ Time			T000 (198928	W - 200 - 200 -
			STAGE	DATE / PIC
			Non-Reporting ltr (1st):	
***	REFER CC3/AX/	\14014454/Kja3s2	Non-Reporting ltr (2nd):	
18113	DA COMMENTAL A	aim sussessibile 85%.	Non-Reporting ltr (Final Notification ltr (if non-pi	
14/15 -	AXA INSTRUCT	to VIIII to clows	Call OI:	Supply 2
	1201014000 000	to vijelt to claim.	After call ltr to Ol:	
	HELECULA, WAY	our serve p	Documentation Check	List: Handler Typist
4/2 -	File pass mix to	tlose -	Notification ltr (if non-pi	ckup)
4/7	III horas IIII- in	District Control	After call ltr to Ol:	
		0.713	Authorisation To Act:	
		Ceculà	Release Voucher:	
		Approved by 5 Per	Final Repair Bill;	
		04/03/20	Car Rental Invoice:	
			Towing Invoice	
			LTA / GIA :	
			Medical Bill:	
			PIR:	
			Mandate/Reject Instru	ction:
			LOD	
			Payment Breakdown F	orm:
PRELIMINARY ADVICE	Date/Time:	Sent By:	Post-Repair Photos:	
			Others:	
INALIZATION	Date/Time:	Confirm with:	Confirm by:	- 10 N N N
Repair Cost:	SS (	days) Reduction: %	En	ail Call
INAL SETTLEMENT	Date/Time:	Confirm with	Email Call	
Final Liability:	% (Agree	d / Assessed) BOLA S/N No. :	If NO or B 28, Ass. Li	
Repair Cost:	SS		-70 5	can & chos
oss of Rental (LOR):	SS (	days)	- mad	armsi .
.oss of Use (LOU):	SS (S	x days)		222
Loss of Income (LOI):	SS (\$	x days)	81	2
LOR only LOU only	LOR + LOU	1.OR + LOI [Tick only one]		· Hid on
GIA/LTA Search	SS	resource to the first of the fi		
Medical:	SS			al/Reject/Private Settle
Disbursement:	SS	(e.g. Tow/ Independent )	2) Report Format:	11-10
.egal Cost	SS		3) Survey fee:	94770
Fotal:	S\$	Global Sum S\$:		4
FINAL PAYMENT	Date/Time:	Confirm with:	Email Call	
Payee 1:	SS	Name 1:		
Payee 2: (Strike if N.A.)	SS	Name 2:		
	ge.	Nama 2:		

Name 3:

REF: AVA ASS. REC. BY: Kenneth ASSIGNMENT From: Date: SHO 940 PEYREGN: 02, 12 Estimated Cost: OD TTP/WS/TP RES/OD RES/EVA/INV/MV Type: M.Car / M.Cycle / Bus / Van / Lorry (Tax) / Prime Mover / To Inspect Vehicle No: Truck / Trailer or at Workshop m/s Make: Colour A/C: Insured / Std / NI / NA Insured: Sp.Reading T/Radio: Insured / Std / NI / NA Policy No. Eng/No: Claims No. ALILA 69RTBB 064733 C/No: Sum Insured: Gen. Cond. Good / Fair / Poor / Burnt Excess: (Client's Record) Steering: Inorder / Jammed / Leaked / Burnt or Make of Veh; Brake: Inorder / Jammed / Leaked / Burnt or Modi: NIL / S/Rim / STD A/Rim or (Policy Condition) Tyre Size: F: 195/85R15 Remark: The veh had commenced its repair at the time of inspection. N/S 0/\$ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / Bal. or Market Value: TOYO / YOKO or IDAC Accident Rport Front Consistent? : Yes or No GIA / PR Seen: R/Bal Consistent?: Yes or No R/Bal Est. Repairs: 0 4 days Res.: Yes or No L/Bal L/Bal D.O.A. 3 Val.: Yes or No D.O.I. Survey held at CA / REV / REP. / 24 HRS Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Vehicle: IN / OUT Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision. Date / Time Action / Instruction Days Of Repair: Date/Time, File Pass to? Preli. Report Resurvey No. of Trip: Survey Fee: Final Report Transportation: Date/Time, File Return to? Add Fee: : Site Insp (\$ S+RS\_\_SI : Interview (\$ Photos Tech. Invs (\$ Others Report Format: Weekend (\$ Lump Sum / I.B.I: (\$ TOTAL

# TRANS-CAB AUTO SERVICES PTE LTD

NO 466-468 Tagore industrial avenue singapore 787835 FAX NO.6366 8862 TEL NO.6287 6666 CO/GST REG NO 201019626G

SHD 9409E - AXA

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer:

SHD 9409E - Andrea KL1LA69RJBB064733

CHEVROLET

Nor Arthorn B3100%

CHEVROLET EPICA 2.0

Andrea

28.07.2014 AXA LIST PART

		PART			LIST
		Front Fender LH		\$	₹ 837.60 ×
1	1			\$	1,133.00
2	1	Front Door LH Front Door Guide LH Chrome Mouldi		\$	
3	1	Front Door Guide Life Chronic Moulding LH	****	\$	<sup>R</sup> 220.00 ×
4	1	Front Door Outer Moulding LH		\$	3.00 X
5	1	Front Door Handle Support LH	Н	\$	√ 89.15 X
6	1	Front Door outer handle inner seal L		\$	₹ 65.00×
7	1	Front Door Hinge Upper LH		\$	€5.00 ×
8	1	Front Door Hinge Lower LH		\$	√ 138.79 X
9	1	Front Door Weatherstrip LH		\$	72 939.00 ×
10	1	Front Side View Mirror LH			₹ 698.15 ×
11	1	Front Door Center Pillar Panel LH		\$	236.40 ×
12	1	Side Rocker Panel Garnish LH		\$	By 1,133.00
13	1	Rear Door LH		\$	1- 41.40×
14	1	Rear Door weatherstrip - Inner LH		\$	n 35.00 ×
15	1	Rear Door top hinge LH		\$	₹ 35.00 X
16	1	Rear Door bottom hinge LH		\$	55.00 ×
17	1	Rear Door check / arrestor LH			1,145.00 ×
18	1	Rear Fender LH		\$	Sec 76.60×
19	1	Rear Fender Inner Cowling LH		\$	M 298.00
20	1	Rear Fender Inner Trim LH		\$	n 1,202.00 ×
21	1	Rear Bumper		\$	68.76 x
22	1	Rear Bumper Side Retainer LH		\$	
			<b>***</b>		7,747.25 8584.85 774.73 6,972.53 7726-36
			TOTAL	managed a comment	774 73
			10%	\$	6 972 53 7726-36
				<u> </u>	0,912.00
		Specical Nett			
				d:	Ma 80.00 GOIN-
	1	Door Sticker "TRANS-CAB"		\$	ne 80.00 6612
	1	Door Sticker "6555-3333"			n 60.00 ×
	1se	t Side Rocker Panel Garnish Clip LH		\$	1~ 35.00 X
	1Se	et Rear Bumper Fastener Clip		\$	30.007

#### Andrea TRANS-CAB AUTO SERVICES PTE LTD NO 466-468 Tagore industrial avenue singapore 787835 FAX NO.6366 8862 TEL NO 6287 6666 CO/GST REG NO.201019626G SHD 9409E - AXA 80.00 X \$ Rear Windscreen Sealant 100.00 X \$ Rear Windscreen Inner Sponge Seal 435.00 TOTAL \$ 7,407.53 TOTAL PARTS \$ Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal 1,400.00 567 Of Parts, Adjust And Realign The Same \$ 220.00 64 To Rust-Proofing Of The Affected Areas. \$ Putty and Spray Painting Of The Affected 1,350.00 900 \$ Portion. 170.00 201 To Check Electrical Lighting Concerned. \$ To transfer of door fittings, attachment and 170.00 1201 \$ perform water seepage test. To Remove And Refit Rear W/Screen Glass 170.00 X To Facilitate Bodywork Repair. To Transfer Of Fender Fittings, Attachments 170.00 601 \$ And Perform Water Seepage Test. To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. 380.00 X 4,030.00 TOTAL \$ LKK Auto Consultants hence notify the Repairer of the following: 11,437.53

the Repairer of the following:

The Repairer of the following:

To resurvey beforelatter spray painting

To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No lifegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

10 DAYS 12191.364

Acknowledged by Repairer Signature:

Date:

Text size + -

# Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

200303878K

Vehicle Details

Vehicle No.

SHD9409E

Vehicle to be Exported: Yes

Intended De-registration 29 Jul 2014

Date

Vehicle Make:

CHEVROLET

Vehicle Model:

EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO

Primary Colour.

Red

Manufacturing Year

2011

Engine No.:

Z20S1443975K

Chassis No.:

KL1LA69RJBB064733

Maximum Power Output: 110.0 kW (147 bhp)

Open Market Value:

\$13,834.00

Original Registration

28 Feb 2012

Date:

First Registration Date: 28 Feb 2012

Transfer Count:

Actual ARF Paid:

\$13,834.00

#### Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry

27 Feb 2020

PARF Rebate Amount: \$10,375.00

#### Intended COE Rebate Details

COE Expiry Date:

27 Feb 2020

COE Category:

A - Car (1600cc & below)

COE Period (Years):

OP Paid:

\$37,512.00

COE Rebate Amount:

\$26,178.00

Total Rebate Amount: \$36,553.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier

The information contained herein is correct as at 29 Jul 2014

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer Please do not use the Back or Forward buttons on your browser as this may after the results of the transactions Best viewed with € 6:0 SP3 and above 1024 X 768 resolution Copyright © 2014 LTA 1 Privacy Statement 1 Terms of Use 1 Disclaimer 1 Rate the Alebada

#### Joy Irene (LKK Auto)

From:

Joy Irene (LKK Auto)

Sent:

Thursday, 12 November, 2015 4:50 PM

To:

Lynn Khong

Cc: Subject: Admin A DS / P0906969 / C0311787 / OD SDZ980L / DOA: 28.07.2014 / TRANS-CAB SHD 9409E

Dear Ms. Lynn,

We refer to the above-subject.

We have surveyed TP vehicle on 30.07.2014 and have adjusted the cost of repairs to lump sum \$3,100.00 with 4 working days recommendation to repair after inspection.

As insured strongly disputed the claim, we provided a copy of the voice recording from the insured to TP on 27.11.2014.

It was recorded that TP driver admitted fault and we sent our enquiry to TP if their client is still to pursue TP claim however, to this date we receive no response from them.

Since there is no development from TP with regards to their TP claim, we will temporarily close this more than one (1) year outstanding file and submit our report to your good-office.

In future, if there is any development from TP, we will update and inform you for our further handling.

Thank you.

Best Regards,

Joy Irene | Case Handler

#### LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: <u>joyirene@lkkauto.com</u>| fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Vale Oh [mailto:Vale.Oh@axa.com.sg] Sent: Wednesday, 20 August, 2014 11:24 AM

To: Sharon Yee <sharonyee@lkkauto.com>; Hsiao Tong <chewht@lkkauto.com>; Vic <vicalpeh@lkkauto.com>

Subject: FW: Direct Settlement - Accident Involving SDZ980L (OI: AXA - TBA) & SHD9409E (TP: LKK REF -

CC3/AXA14014454/Ksa3) on 28.07.2014

Importance: High

Hi all

Please note we had forwarded you the CCTV from Insured!

Please check and keep us posted on the above matter.

Fax: 6741 4108

Email: sharonyee@lkkauto.com

From: Vale Oh [mailto:Vale.Oh@axa.com.sg] Sent: Monday, 18 August, 2014 11:04 AM To: Admin-A (LKK Auto); Vic; Hsiao Tong

Subject: FW: Direct Settlement - Accident Involving SDZ980L (OI : AXA - TBA) & SHD9409E (TP : LKK REF -

CC3/AXA14014454/Ksa3) on 28.07.2014

Hi all

Further to Winnie's email of 06.08.14.

Please note insured has a copy of the video footage where TP admitted at fault. Please liaise with Insured before admitting any liability towards the TP's claim, tks.

#### **Best Regards**

Vale Oh

A.Manager - Motor Claims AXA Insurance Singapore Pte Ltd 8 Shenton Way, #27-01 AXA Tower, Singapore 068811 vale.oh@axa.com.sg

DID: (65) 6880 4897 Website: www.axa.com.sg



#### redefining / insurance

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorised disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.



#### Please consider the environment before printing this email

From: Admin-A (LKK Auto) [mailto:admin-a@lkkauto.com]

Sent: Friday, August 01, 2014 8:48 AM

To: Winnie Ho Ping Ping; Tan Tiong Beng; Kitty Teo Poh Guek

Cc: KKLau; Sharon Yee

Subject: Direct Settlement - Accident Involving SDZ980L (OI: AXA - TBA) & SHD9409E (TP: LKK REF -

CC3/AXA14014454/Ksa3) on 28.07.2014

#### WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHD 9409E at M/s Trans-cab Auto Services Pte Ltd on 30.07.2014.

Enclosed herewith a copy of TP's GIA report, estimated cost of repair and preliminary advice for your perusal.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Please take note that the case handler in-charge is Sharon and she can be contacted at DID: 6749 4274

#### Cecilia Chong (LKK Auto)

From:

Mei Kwan (LKKAuto)

Sent:

Thursday, 19 December 2019 4:55 PM

To:

TAN Jas

Cc:

Cecilia Chong (LKK Auto)

Subject:

RE: C0311787MC/VO FW: Our Ref: D14/8881/TC/JT, Letter of Demand for Uninsured

Loss claim for vehicle no: SDZ980L

Dear Jas,

Noted with thanks.

Thank you.

Best Regards,

Mei Kwan | Admin

#### LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: TAN Jas < jas.tan@axa.com.sg>

Sent: Thursday, 19 December, 2019 4:51 PM
To: Mei Kwan (LKKAuto) < Meikwan@lkkauto.com>

Subject: RE: C0311787MC/VO FW: Our Ref: D14/8881/TC/JT, Letter of Demand for Uninsured Loss claim for vehicle no:

SDZ980L

Hi Mei Kwan,

Please proceed to reject TP claim .thanks.

#### Regards

\*Please note we have terminated our fax-line. Hence, please send in your correspondences to our two common mail boxes instead. For OD/TP survey, send it to <a href="mailto:motor.survey@axa.com.sg">motor.survey@axa.com.sg</a> and other correspondences send it to <a href="mailto:motor.doc@axa.com.sg">motor.doc@axa.com.sg</a>.

Jas Tan | Snr Specialist, Motor Claims Department

AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg

Email: jas.tan@axa.com.sg

Customer Care No. 1800 8804741







Please consider the environment before printing this message

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: TAN Jas

Sent: Thursday, December 19, 2019 4:49 PM
To: Mei Kwan (LKKAuto) < Meikwan@lkkauto.com >

Subject: FW: C0311787MC/VO FW: Our Ref: D14/8881/TC/JT, Letter of Demand for Uninsured Loss claim for vehicle no:

SDZ980L

fya

#### Regards

\*Please note we have terminated our fax-line. Hence, please send in your correspondences to our two common mail boxes instead. For OD/TP survey, send it to <a href="mailto:motor.survey@axa.com.sg">motor.survey@axa.com.sg</a> and other correspondences send it to <a href="mailto:motor.doc@axa.com.sg">motor.doc@axa.com.sg</a>,

Jas Tan | Snr Specialist, Motor Claims Department

AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg

Email: jas.tan@axa.com.sg

Customer Care No. 1800 8804741







Please consider the environment before printing this message

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

#### Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Our Ref

: AAD1407-305

Your Ref

: SDZ980L

Date

: 16.December 2019

#### **AXA INSURANCE S PTE LTD**

Dear Sir/Madam,

# ACCIDENT INVOLVING SHD9409E AND SDZ980L ON 28/07/14 01:40 PM ALONG BEACH ROAD

It appears that the above accident was caused by your insured's negligence. We, therefore seeking compensation from you for our financial loss as itemized below :-

1.	Cost of Repair (inclusive of 7% GST)	\$ 3,317.00
2.	Loss of Rental for days @ \$ per day	\$ 483.64
3.	Loss of Income for 4 days @ \$so per day	\$ 200.00
4.	LTA Search Fee	\$ 6.00
5.	Survey Fee	\$ 0.00
	Total	\$ 4,006.64

We enclose a copy of the following documents for your consideration :-

GIA report lodged by our driver

Rental rate and mileage records

Certificate of Insurance

Authorization To Act

Original final repair bill

LTA Search Fee

Kindly let us have the discharge voucher within the next 14 days, failing which we shall proceed to hand over the conduct of this matter to our solicitors without further reference to you.

Yours Faithfully

Trans-Cab Services Pte Ltd

Jasmine Tan

General Manager

Tel No.: 6603 1250 (DID)

Note: Please email any further correspondence to claims@transcab.com.sg (6603 1259)

# TRANS 得運私人有限公司 COID TRANS-CAB SERVICES PTE LTD

Co. Reg. No: 200303878K

29. July 2014

To Whom It May Concern

Dear Sir. / Madam,

#### Accident on 28/07/14 01:40 PM at BEACH ROAD

- We refer to the above-mentioned accident and wish to inform that Trans-Cab Services Pte Ltd is
  the registered owner of the taxi bearing vehicle registration no. SHD9409E. The taxi was hired to
  HO BOON KHENG a registered hirer-operator of Trans-Cab Services Pte Ltd at the time of
  occurrence of the aforementioned accident at a rental rate \$120.91 per day (inclusive of GST).
- Please be advised that the Taxi is insured with First Capital Insurance Ltd on a third party basis at the material time of the accident.
- 3. Please liaise with us directly far any settlement of claims in respect of the said accident.

Yours faithfully,

Jasmine Tan General Manager

This is a computer generated print-out. No signature is required.

No. 58 Defu Lane 1, Singapore 539498 Tel: 6287 6666 Fax: 6281 1400

#### Trans-Cab Auto Services Pte Ltd

58 Defu Lane 1 Singapore 539498

Tel: 6287 6666 Fax: 6287 7764

Co. Reg. No.: 201019626G GST Reg. No.: 201019626G

Tax Invoice

TO:

AXA INSURANCE (S) PTE LTD 8 SHENTON WAY,#27-01

AXA TOWER

068811 SINGAPORE

ATTENTION:

INVOICE NO. : INV1408-169

DATE

: 31. August 2014

REFERENCE N: AAD1407-305

TERMS DUE DATE

: 31. August 2014

PAGE

: 1

NIO	CODE	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
NO.	CODE		4	3,317.00	3.317.00
1.	6050101	REPAIR-SHD9409E;DOA 28.07.14 (LUMP SUM-14)	1	3,517.00	3,01.100

Total SGD Excl. GST:

3,100.00

7% GST:

217.00

\*\*\*\* THREE THOUSAND THREE HUNDRED SEVENTEEN AND 0/100 SGD

Total SGD Incl. GST:

3,317.00

<sup>1)</sup> All cheques should be crossed and made payable to "Trans-Cab Auto Services Pte Ltd"

<sup>2)</sup> Please quote our Invoice Number during payment.

<sup>3)</sup> We reserve the right to change interest @ 1.5% per month on overdue invoice.

<sup>4)</sup> Any dispute as to the accuracy, charges etc of this invoice must be communicated within 10 days from the date hereof falling which it shall be deemed to have been unconditionally accepted.

#### Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

#### **Authorization To Act**

We, Trans-cab Services Pte Ltd of Company Registration No. 200303878K hereby authorize Trans-cab Auto Services Pte Ltd to act on behalf to claim for all losses incurred for the accident involving SHD9409E and SDZ980L along BEACH ROAD on 28/07/14 01:40 PM.

In addition, we also hereby authorize the above payment to be made in favour of Trans-cab Auto Services Pte Ltd upon settlement.

Dated this 16 (day) of December 2019

Yours Faithfully

Trans-Cab-Services Pte Ltd

Jasmine Tan

General Manager





SHD 9409 E

E . TT	LIMIT OF DOUGED	COLUM		DEA	DING	MILEAGE		
DATE	NAME OF DRIVER	MILL	MGE	KEA	DING	TRAVELLED (KM)	FROM	то
	Acrident on 28.07	1.10.a	B	110	1125			
	Sant in Dr. 29.07							
	Discharged Ox 02	AUG 20	44	20	has			
	lanowi nasono ispetanje se sak							
2018-11								
							5 10 55 - 21 17 14 15 William	
								٠
3 4 4								



### Enquire Vehicle & Owner Information ( Vehicle No. SDZ980L As At 28 Jul 2014 / 13:40:00)

Law Firm Search Details

Search Reason:

Insurance claim in relation to traffic accident

Law Firm Case No.:

TCS(ANDREA)SHD9409E

Current Owner Details

Owner ID Type:

Singapore NRIC

Owner ID:

S1804646F

Owner Name:

SUNG LI LING

Registered Block/House 54

Registered Address Type: Private Residential (non-Condo Apt / non-House)

Registered Street Name: TERANG BULAN AVENUE

Registered Unit No.:

Registered Building Name: -

Registered Postal Code: 455577

Current Vehicle Details

Vehicle No.:

((

SDZ980L

Make Description/Model: HONDA / JAZZ 1.5L AT ABS D/AB HID 2WD 5DR

Insurance Company Name: AXA INSURANCE SINGAPORE PTE LTD

Please reed through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the Back or Forward buttons on your browser as this may after the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 769 resolution

Copyright © 2014 LTA 1 Privacy Statement 1 Terms of Use 1 Disclaimer 1 Rate the Website

#### Cecilia Chong (LKK Auto)

From:

Cecilia Chong (LKK Auto)

Sent:

Thursday, 19 December 2019 5:04 PM

To:

'Ng Wai Yin'

Cc:

'Jasmine Tan'

Subject:

RE: TCS REF AAD1407-305 [SHD9409E] , DOA: 28.07.14; YOUR REF: CC3/AXA14014454

(SDZ980L - AXA)

Attachments:

OI VIDEO.MOV

Your Ref: AAD1407-305 (SHD 9409E)

Without Prejudice

Our Ref: CC3/AXA14014454/Kga3s2-1

Dear Sirs/Madam,

#### ACCIDENT INVOLVING SDZ 980L (AXA) & SHD 9409E ON 28/07/2014

We refer to the above matter.

Attached is a copy of our insured car video footage for your easy reference. We have reviewed the matter and we are of the view that our driver is not liable for the accident.

Your client has admitted her fault for this case.

In view of the above, we have our principal instruction to deny liability and unable to look into your client's matter.

Thank you.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,

Cecilia Chong | Case Handler

#### LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth Print only when necessary

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>

Sent: Tuesday, 17 December, 2019 5:45 PM

To: Mei Kwan (LKKAuto) < Meikwan@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

THE PROPERTY.	Affiliated to Federation Interna	ationale Des Experts En Autom	obile
AXA INSURANCE PTE	LTD	Ref: CC3/AXA14014	454/Kga3s2-1
3 SHENTON WAY #24 AXA TOWERSINGAPO ATTN: JAS TAN	-01 DRE 068811	Date: 06-03-2020 Code: AXA2	
1. 1032 10 10	Policy Particula	rs :- THIRD PARTY CLAI	M
Insured Veh.	SDZ 980L	Veh. Inspected	SHD 9409E
Policy No.	VPA/P0906969	Coverage (\$)	0.00
Claim No.	C0311787	Excess (\$)	0.00
Assign From	Application of the Co.	Assign Date	19/12/2019
2.	Vehicle Pa	rticulars & Condition	
Make & Model	CHEVROLET EPICA (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	KL1LA69RJBB064733	Colour	WHITE / RED
Odometer	341337	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3.	Con	ditions of Tyres	
	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	4 mm
L/H Front Tyre	195/65 R15	FALKEN	4 mm
R/H Rear Tyre	195/65 R15	FALKEN	3 mm
L/H Rear Tyre	195/65 R15	FALKEN	3 mm
4.	Descr	iption of Damages	
THE VEHICLE SU	ISTAINED DAMAGES AT THE	N/S BODY.	
DAMAGES SEE I	520 YV 141 702 2 2		
5.	NAME AND DESCRIPTION OF THE PARTY OF THE PAR	eral Information	30/07/2014
Accident Date	28/07/2014	Inspection Date	30/07/2014
Survey held at	TRANS-CAB AUTO SERVIC		DE 707035
	NO. 466-468 TAGORE INDI	JSTRIAL AVENUE SINGAPO	JKE 101033
5a.		Remarks	eie
A)THE INSPECTI B)IN ACCORDAN	ON WAS CONDUCTED ON A'	S, WE HAVE NOT AUTHORIS	SED REPAIRS.
5b.		ate Days of Repair	
ESTIMATED NO	RMAL PERIOD FOR REPAIR:	4 Working Da	iys



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9409E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT FENDER LH (CONSISTENT)	TO REPAIR SEE LABOUR	837.60	
1	FRONT DOOR LH (CONSISTENT)	BENT	1,133.00	1,133.00
	FRONT DOOR GUIDE LH CHROME MOULDING (CONSISTENT)	SERVICEABLE	60.00	
1	FRONT DOOR OUTER MOULDING LH (CONSISTENT)	SERVICEABLE	220.00	( )
	FRONT DOOR HANDLE SUPPORT LH (CONSISTENT)	SERVICEABLE	3.00	
	FRONT DOOR OUTER HANDLE INNER SEAL LH (CONSISTENT)	SERVICEABLE	89.15	-
1	FRONT DOOR HINGE UPPER LH (CONSISTENT)	TO REPAIR SEE LABOUR	65.00	
1	FRONT DOOR HINGE LOWER LH (CONSISTENT)	TO REPAIR SEE LABOUR	65.00	-
1	FRONT DOOR WEATHERSTRIP LH (CONSISTENT)	SERVICEABLE	138.79	-
	FRONT SIDE VIEW MIRROR LH (CONSISTENT)	TO REPAIR SEE LABOUR	939.00	
1	FRONT DOOR CENTER PILLAR PANEL LH (CONSISTENT)	TO REPAIR SEE LABOUR	698.15	
1	SIDE ROCKER PANEL GARNISH LH (CONSISTENT)	TO REPAIR SEE LABOUR	236.40	)
1	REAR DOOR LH (CONSISTENT)	BENT	1,133.00	1,133.00
	REAR DOOR WEATHERSTRIP -INNER LH (CONSISTENT)	SERVICEABLE	41.40	)
	REAR DOOR TOP HINGE LH (CONSISTENT)	TO REPAIR SEE LABOUR	35.00	
1	REAR DOOR BOTTOM HINGE LH (CONSISTENT)	TO REPAIR SEE LABOUR	35.00	
125	REAR DOOR CHECK/ARRESTOR LH (CONSISTENT)	SERVICEABLE	65.00	
	REAR FENDER LH (CONSISTENT)	TO REPAIR SEE LABOUR	1,145.00	
- 3	REAR FENDER INNER COWLING LH (CONSISTENT)	SERVICEABLE	76.60	
88	REAR FENDER INNER TRIM LH (CONSISTENT)	SERVICEABLE	298.00	
	REAR BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	1,202.00	
-	REAR BUMPER SIDE RETAINER LH (CONSISTENT)	SERVICEABLE	68.76	3

Report Ref No. CC3/AXA14014454/Kja3s2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
plism	LESS 10% DISCOUNT	45	-858.49	-226.60
	LESS 10% DISCOUNT		7,726.36	2,039.40
	SPECIAL NETT ITEMS			university and
1	DOOR STICKER "TRANS-CAB" (SN) (CONSISTENT)	NECESSARY	80.00	60.00
	DOOR STICKER "6555-3333" (SN) (CONSISTENT)	NECESSARY	80.00	60.00
	SET SIDE ROCKER PANEL GARNISH CLIP LH (SN) (CONSISTENT)	NOT NECESSARY	60.00	й <del>е</del>
1	SET REAR BUMPER FASTENER CLIP (SN) (CONSISTENT)	NOT NECESSARY	35.00	-
2	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	E-
	(CONSISTENT)		435.00	120.00
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FRONT FENDER LH, FRONT DOOR HINGE UPPER LH, FRONT DOOR HINGE LOWER LH, FRONT SIDE VIEW MIRROR LH, FRONT DOOR CENTER PILLAR PANEL LH, SIDE ROCKER PANEL GARNISH LH, REAR DOOR TOP HINGE LH, REAR DOOR BOTTOM HINGE LH, REAR FENDER LH AND REAR BUMPER.		1,400.00	
	TO RUST-PROOFING OF THE AFFECTED AREAS.		220.00	
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,350.00	900.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	
	TO TRANSFER OF DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	120.00
	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	170.00	
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.0	60,00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH,	NOT NECESSARY	380.0	
	FITTINGS AND OTHER, TO ENABLE REPAIR.		4,030.0	1,700.00
$\vdash$	GRAND TOTAL		12,191.3	6 3,859.40

Report Ref No. CC3/AXA14014454/Kja3s2



Page No.:3 of 3

RECOMMENDED COST OF LUMP SUM REPAIRS		3,100.00
(TO ITS PRE-ACCIDENT CONDITION)	THE RESIDENCE OF THE RESIDENCE OF THE PERSON	

Report Ref No. CC3/AXA14014454/Kja3s2

KSC

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.