

TRANS-CAB AUTO SERVICES PTE LTD

NO.466-468 Tagore industrial avenue singapore 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD 9409E - AXA**Andrea***Not Authorised
L1 Reg B3100h*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHD 9409E - Andrea
KL1LA69RJBB064733
CHEVROLET
CHEVROLET EPICA 2.0
28.07.2014
AXA

PART**LIST**

1	1	Front Fender LH	\$	<i>R</i> 837.60 X
2	1	Front Door LH	\$	<i>R</i> 1,133.00 ✓
3	1	Front Door Guide LH Chrome Moulding	\$	<i>Sm</i> 60.00 X
4	1	Front Door Outer Moulding LH	\$	<i>R</i> 220.00 X
5	1	Front Door Handle Support LH	\$	<i>Sm</i> 3.00 X
6	1	Front Door outer handle inner seal LH	\$	<i>Sm</i> 89.15 X
7	1	Front Door Hinge Upper LH	\$	<i>R</i> 65.00 X
8	1	Front Door Hinge Lower LH	\$	<i>R</i> 65.00 X
9	1	Front Door Weatherstrip LH	\$	<i>Sm</i> 138.79 X
10	1	Front Side View Mirror LH	\$	<i>R</i> 939.00 X
11	1	Front Door Center Pillar Panel LH	\$	<i>R</i> 698.15 X
12	1	Side Rocker Panel Garnish LH	\$	<i>R</i> 236.40 X
13	1	Rear Door LH	\$	<i>R</i> 1,133.00 ✓
14	1	Rear Door weatherstrip - Inner LH	\$	<i>Sm</i> 41.40 X
15	1	Rear Door top hinge LH	\$	<i>R</i> 35.00 X
16	1	Rear Door bottom hinge LH	\$	<i>R</i> 35.00 X
17	1	Rear Door check / arrestor LH	\$	<i>Sm</i> 65.00 X
18	1	Rear Fender LH	\$	<i>R</i> 1,145.00 X
19	1	Rear Fender Inner Cowling LH	\$	<i>Sm</i> 76.60 X
20	1	Rear Fender Inner Trim LH	\$	<i>Sm</i> 298.00 X
21	1	Rear Bumper	\$	<i>R</i> 1,202.00 X
22	1	Rear Bumper Side Retainer LH	\$	<i>Sm</i> 68.76 X

TOTAL	\$	7,747.25
10%	\$	774.73
	\$	6,972.53

Special Nett

1	Door Sticker "TRANS-CAB"	\$	<i>R</i> 80.00 <i>60.00</i>
1	Door Sticker "6555-3333"	\$	<i>R</i> 80.00 <i>60.00</i>
1set	Side Rocker Panel Garnish Clip LH	\$	<i>R</i> 60.00 X
1Set	Rear Bumper Fastener Clip	\$	<i>R</i> 35.00 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.466-468 Tagore industrial avenue singapore 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD 9409E - AXA**Andrea**

2	Rear Windscreen Sealant	\$	<i>~ 80.00</i> X
1	Rear Windscreen Inner Sponge Seal	\$	<i>~ 100.00</i> X

TOTAL	\$	435.00
TOTAL PARTS	\$	7,407.53

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,400.00	<i>540</i>
To Rust-Proofing Of The Affected Areas.	\$	220.00	<i>60</i>
Putty and Spray Painting Of The Affected Portion.	\$	1,350.00	<i>900</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>20</i>
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	<i>120</i>
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>~ 170.00</i> X	
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	<i>60</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>~ 380.00</i> X	

TOTAL	\$	4,030.00
Over All Total	\$	11,437.53

REPAIR DAYS**10 DAYS**
4 days