

NS. CASE OWNER: Jacqueline

CC 3 / AXA140 16319 / KW b3 a39

LKK:
IDAC:Surveyor: KennethDOI: 26/08/14Assg Date: 26/08/14

Pre-assign / CCU / FTE

Insured Vehicle No.: SKM 7612P

Claim No.: _____

Name of Insured: De Ferrari Wicki ElisabettaPolicy No.: GA 000095Insured Tel No.: Angela maria HP: 9720 7229Make / Model: ToyotaExcess Sec II: SS NIL D.O.A.: 26/08/14Place of Accident: Bukit Timah Saddle Club CarparkIs driver the owner? (YES / NO) (YES)

Nature of Accident: _____

If NO, Driver Name / Age: _____

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO (YES)

Driver Tel No.: _____

(V/L: YES / NO Insured Liability: _____

% Final? Yes / No



INSRS:

WSP: Trans-cab

Tel: _____

Liability: _____

RMKS: _____



INSRS:

WSP: _____

Tel: _____

Liability: _____

RMKS: _____



INSRS:

WSP: _____

Tel: _____

Liability: _____

RMKS: _____



INSRS:

WSP: _____

Tel: _____

Liability: _____

RMKS: _____

Date/ Time

02/09/14 -

FOR CSO ONLY:

Is driver the owner? (YES / NO)

If NO, Driver Name / Age:

Driver's Own Vehicle Number: _____ Insurance Company: _____

SHB 9948B - CS / LIP 08012579 / Kv6; DOA: 18/04/08
SKM 7612P - X

STAGE

DATE / PIC

Finalisation:

Email AIG for OI GIA:

Apt letter to OI:

Call OI:

After call ltr to OI: 11/06/15 - vic EWM/ANW

Type Report:

Prepare Invoice: 17/6

Others:

Documentation Check List: Handler Typist

OI Apt Ltr: ☐Authorisation To Act: ☐Release Voucher: ☐Final Repair Bill: ☐Car Rental Invoice: ☐LTA / GIA: ☐Medical Bill: ☐Approval Email: ☐Payment Breakdown Form: ☐Others: ☐

11/06/15 @ 10:30AM

all OI. OVERSEAS TONE.

SEND LETTER TO OI TO NOTIFY TP CLAIM IN
NCD ISSUES.

REVIEW LIABILITY AFTER LETTER SENT OUT.

12/06/16

RECEIVED LETTER FROM OI. REBAGGED APPROX.

TO GET TP OWN IF ANY.

12/5/16

Email to AXA to temporary close.

COPY SENT
12/5/16

FINAL SETTLEMENT

Date:

Confirm with

Repair Cost:

SS

Final Liability

50 % (Agreed / Assessed)

BOLA S/N No.: NIL

Loss of Rental:

SS

(days)

If NO or B 28, Ass. Lia:

Loss of Use:

SS

(\$ x days)

Format Type:

w/p temporary dock
b.m.m



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE SINGAPORE PTE LTD		Ref : CC3/AXA14016319/Kwb3		
8 SHENTON WAY #27-01 SINGAPORE 068811		Date : 27-08-2014		
		Code : AXA2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKM 7612P	Veh. Inspected	SHB 9948B	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	27/08/2014	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	26/08/2014	Inspection Date	26/08/2014	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO. 466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHB 9844S -

Not Authented

RIZA

1-B1

89221.63

Resumy B4 part

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHB 9844S - RIZA
 VF1ABL15AUC273402
 RENAULT
 LATITUDE
 08.07.2015
MG

PART

LIST

1	1	BUMPER COVER FRT	\$	968.78 X
2	1	BUMPER ABSORBER FRT	\$	303.60 X
3	1	BUMPER BEAM FRT	\$	703.14 X
4	1	BUMPER SPOILER FRT	\$	139.81 X
5	1	BUMPER FOG LAMP GRILLE LH	\$	159.40 X
6	1	BUMPER RETAINER FRT LH	\$	116.47 X
7	1	BUMPER SUPPORT FRT LH	\$	18.37 X
8	1	BUMPER UNDERTRAY FRT	\$	363.71 X
9	1	LOWER ARM LH	\$	527.51 X
10	1	KUNCKLE ARM LH	\$	651.53 X
11	1	ABSORBER FRT LH	\$	277.34 X
12	1	ABSORBER DUST COVER	\$	175.93 X
13	1	BONNET	\$	1,493.56 X
14	1	WIPER RESERVOIR	\$	173.60 X
15	1	WIPER RESERVOIR MOTOR	\$	91.78 X
16	1	HEADLALMP LH	\$	911.10 X
17	1	FENDER PANEL FRT LH	\$	602.95 X
18	1	FENDER WHEELARCH FRT LH	\$	107.33 X
19	1	DOOR MIRROR LH	\$	1,141.08 X
20	1	DOOR PANEL FRT LH	\$	2,188.20 X
21	1	DOOR HINGE UPPER LH	\$	211.15 X
22	1	DOOR HINGE LOWER	\$	231.19 X
23	1	DOOR CHECK FRT LH	\$	149.83 X
24	1	DOOR LOCK FRT LH	\$	699.04 X
25	1	DOOR CATCH FRT LH	\$	100.94 X
26	1	DOOR HANDLE OUTER FRT LH	\$	198.55 X
27	1	DOOR HANDLE CAP FRT LH	\$	20.34 X
28	1	DOOR HANDLE SEAL FRT LH	\$	6.07 X
29	1	DOOR HANDLE COVER FRT LH	\$	10.18 X
30	1	DOOR HANDLE MODULE FRT LH	\$	102.77 X
31	1	DOOR REGULATOR FRT LH	\$	388.61 X
32	1	DOOR REGUALTOR MOTOR FRT LH	\$	612.66 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHB 9844S -**RIZA**

33	1	ROCKER PANEL OUTER LH	\$	127 759.61 ✓
34	1	DOOR PANEL REAR LH	\$	127 2,188.20 ✓
35	1	DOOR HINGE UPPER LH	\$	127 242.88 X
36	1	DOOR HINGE LOWER LH	\$	127 231.19 X
37	1	DOOR LOCK REAR LH	\$	127 699.04 X
38	1	DOOR HANDLE OUTER REAR LH	\$	127 97.31 X
39	1	DOOR HANDLE MODULE REAR LH	\$	127 102.77 X
40	1	DOOR REGULATOR REAR LH	\$	127 512.02 X
41	1	DOOR REGULATOR MOTOR REAR LH	\$	127 687.50 X
42	1	DOOR FINISHER REAR LH	\$	127 325.46 X
43	1	DOOR MOULDING REAR LH	\$	127 136.01 X
44	1	FENDER PANEL REAR LH	\$	127 2,537.80 X
45	1	BUMPER COVER REAR	\$	127 852.66 X

TOTAL	\$	16,143.34
10%	\$	1,614.33
	\$	14,529.00

Specical Nett

1SET	FRONT BUMPER CLIP	\$	127 66.00 X
1SET	WHEELARCH CLIP LH	\$	127 66.00 ✓
1	CAP HUB LH FRT	\$	127 35.00 X
1	RIM LH FRT	\$	127 385.00 X
1	TYRE LH FRT	\$	127 330.00 X
1	CAP HUB LH RR	\$	127 35.00 ✓
1	RIM LH RR	\$	127 385.00 X
1	TYRE LH RR	\$	127 330.00 X
1	DOOR STICKER "Trans-cab"	\$	127 80.00 60.00
1	DOOR STICKER "Classic"	\$	127 30.00 15.00
1	DOOR STICKER "6555-3333"	\$	127 80.00 60.00
2	Rear Windscreen Sealant	\$	127 100.00 X
1	Rear Windscreen Inner Sponge Seal	\$	127 150.00 X
1SET	REAR BUMPER CLIP	\$	127 66.00 X
1SET	BUMPER SUPPORT FRT LH	\$	127 9.80 X
1SET	BUMPER RETAINER FRT LH	\$	127 12.50 X

TOTAL	\$	2,160.30
--------------	----	-----------------

TOTAL PARTS	\$	16,689.30
--------------------	----	------------------

TRANS-CAB AUTO SERVICES PTE LTD
NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
TEL NO.6287 6666 FAX NO.6366 8862
CO/GST REG NO.201019626G
SHB 9844S -

RIZA

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,800.00	800
To Check Electrical Lighting Concerned.	\$	170.00	300
Putty and spray painting of the affected portion.	\$	3,000.00	13200
To check steering geometry and computer wheel alignment	\$	220.00	600
To transfer of tire, rim and on wheel balancing.	\$	170.00	na X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	1200
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00	na X
To transfer of fender fittings and conduct water seepage test.	\$	380.00	800
To rust-proofing of the affected areas.	\$	170.00	900

TOTAL \$ 7,250.00

Over All Total \$ 23,939.30

(PARTS BY PARTS) Repair Days

-10 Days

6 days

Jojo Ngai

From: Winnie Ho Ping Ping [winnie.ho@axa.com.sg]
Sent: Monday, 1 September, 2014 10:10 AM
To: assignments@lkkauto.com; Admin-A (LKK Auto); sur@lkkauto.com
Cc: Jacqueline Leong Kin Mun
Subject: DIRECT SETTLEMENT / TRANS-CAB AUTO / GA000095 / OD- SKM7612P / TP-SHB9948B / DOA: 26.08.2014 / EST: TBA / NO XS / JL
Attachments: TP GIA REPORT.pdf; Full page photo.pdf; SKM7612P - 260714.PDF

RISK 1 - GA000095
CLAIM RECEIVE : 29.08.2014
SKM7612P (INSD) C/W SHB9948B
IMP HOV
VTP
LKK : 01.09.2014
NCD : Y
CH : JL

Thanks & Regards

Winnie Ho
Claims Assistant – Claims Services
AXA Insurance Singapore Pte Ltd
8 Shenton Way, #27-01 AXA Tower, Singapore 068811
winnie.ho@axa.com.sg
DID: (65) 6880 4833
Website: www.axa.com.sg



This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorised disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

 Please consider the environment before printing this email

From: Jojo Ngai [mailto:admin-b@lkkauto.com]
Sent: 29 August, 2014 5:40 PM
To: Winnie Ho Ping Ping; Kitty Teo Poh Guek; Tan Tiong Beng
Cc: KKLau; Vivian Lau
Subject: Direct Settlement - Acc Invl SKM 7612P (OI : AXA - TBA) & SHB 9948B (TP : LKK - CC3/AXA14016319/Kwb3) on 26.08.2014

Dear Sir/Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHB 9948B AT M/s Trans-Cab Auto Services Pte Ltd.

Enclosed herewith a copy of TP's GIA report & photo for your perusal.

Please be informed that our estimated cost of repair is not ready yet.

Kindly take note that the case handler in-charge is Vivian and she can be contacted at DID: 6841 8625.

Thanks & Regards

Jojo Ngai

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1,

#01-25 Paya Ubi Industrial Park,

Singapore 408933

DID : 6742 8617

Fax : 6741 4108



Save the trees - Do you really need to print this e-mail?

Vic

From: Vic
Sent: Thursday, 11 June, 2015 11:00 AM
To: edeferrari@bluewin.ch
Cc: Admin A; Vivian Lau; Vic
Subject: Your Ref: SKM 7612P_ACCIDENT INVOLVING SKM 7612P AND SHB 9948B ON 26/08/2014

Your Ref: SKM 7612P
Our Ref: CC3/AXA14016319/Kwb3
AXA Policy No.: GA000095

Dear Madam,

ACCIDENT INVOLVING SKM 7612P AND SHB 9948B ON 26/08/2014 ALONG BUKIT TIMAH SADDLE CLUB CAR PARK

We refer to the above accident where we are acting for AXA Insurance Singapore Pte Ltd (AXA) to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We tried to contact you at your mobile but to no avail.

Kindly note that we have reviewed this matter and would like to advise that you and/or your authorized driver may not be absolved from blame for this accident.

If you have evidence/information to prove that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by **22/06/2015**, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Accordingly your No Claim Discount (NCD – if applicable) may not be preserved. However, if you are making a claim against third party and successful with 80% in your favour, our principal will re-instate your NCD.

You may call us if you have further queries.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth. Print only when necessary.

This email may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

Vic

From: Elisabetta [edeferrari@bluewin.ch]
Sent: Saturday, 13 June, 2015 3:27 AM
To: Vic
Cc: Admin A; Vivian Lau; Francesco de Ferrari
Subject: Re: Your Ref: SKM 7612P_ACCIDENT INVOLVING SKM 7612P AND SHB 9948B ON 26/08/2014

Dear Mr. Alpeh,

I am unfortunately abroad for the summer vacation period and will be back in Singapore only in the last days of July. I am surprised by your email below as in my previous discussions with AXA's claim department on this case, I was informed that the accident was closed without claims from the other party, at which point I decided not to make any claims from my end, given the limited nature of the accident.

I had already given all the details of what happened in the particular event to Mova at the time and I hope you can find them and use them to fight the claim below.

Let me reiterate that there is no way that the accident can be considered my fault and I sincerely hope you can succeed to stop this unjustified claim.

I was parking my vehicle at the Bukit Timah Saddle club parking, reversing into a parking space when the taxi driver in question, without waiting for me to complete my maneuver, simply tried to squeeze past my car. As there was no space to fit two cars, he hit with his car my front bumper as I swung around to complete my parking. When someone is reversing into a parking slot, it would be normal practice to wait for the car to complete the maneuver.

He might be describing the claim differently but my car was in front and the taxi was behind. If he had remained in position with his car and I would have reversed into his car, I would have hit it with my rear bumper. The fact that the collision happened with my front bumper as I was reversing clearly points to him moving his car forward to squeeze through without waiting for me to complete my maneuver.

I was in a parking space and I was already parking when he came, so there was absolutely non need to put the hazard lights, since my car had the white reversing lights on.

I'm sure you will do your best to solve the case in my favour.

Elisabetta de Ferrari

Sent from my iPad

On 11 Jun 2015, at 5:00 am, Vic <vicalpeh@lkkauto.com> wrote:

Your Ref: SKM 7612P
Our Ref: CC3/AXA14016319/Kwb3
AXA Policy No.: GA000095

Dear Madam,

ACCIDENT INVOLVING SKM 7612P AND SHB 9948B ON 26/08/2014 ALONG BUKIT TIMAH SADDLE CLUB CAR PARK

We refer to the above accident where we are acting for AXA Insurance Singapore Pte Ltd (AXA) to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We tried to contact you at your mobile but to no avail.

Kindly note that we have reviewed this matter and would like to advise that you and/or your authorized driver may not be absolved from blame for this accident.

If you have evidence/information to prove that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by **22/06/2015**, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Accordingly your No Claim Discount (NCD – if applicable) may not be preserved. However, if you are making a claim against third party and successful with 80% in your favour, our principal will re-instate your NCD.

You may call us if you have further queries.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth. Print only when necessary.

This email may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

Vivian Lau

From: Vivian Lau
Sent: Thursday, 12 May, 2016 5:14 PM
To: 'Chen Xinyou'
Cc: Olivia Lau; Hsiao Tong; Zayyer; Admin A
Subject: RE: C0314940: Direct Settlement - Acc Invl SKM 7612P (OI : AXA - TBA) & SHB 9948B (TP : LKK - CC3/AXA14016319/Kwb3) on 26.08.2014

Your Ref: C0314940
Our Ref: CC3/AXA14016319/Kwb3

Dear Xinyou

Accident Involving SKM 7612P & SHB 9948B on 26/08/2014

We refer to the above matter.

Be informed that our surveyor had finalised above matter with TP's repairer since 18/06/2015

TP's repairer did not submit the LOD & Evidence until now. In view of no further development, we will proceed to temporary close the file and submit the report to your office.

If any new development in future, we will keep you informed for an update and follow up the matter accordingly.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters."

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE SINGAPORE PTE LTD			Ref : CC3/AXA14016319/Kwa3q2	
8 SHENTON WAY #27-01 SINGAPORE 068811			Date : 18-05-2016	
ATTN: CHEN XINYOU			Code : AXA2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKM 7612P	Veh. Inspected	SHB 9948B	
Policy No.	GA00095	Coverage (\$)	0.00	
Claim No.	C0314940	Excess (\$)	0.00	
Assign From		Assign Date	26/08/2014	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	VF1ABL15AUC273376	Colour	METALLIC WHITE/RED	
Odometer	144547	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	FIRENZA	7 mm	
L/H Front Tyre	215/60 R16	FIRENZA	7 mm	
R/H Rear Tyre	215/60 R16	GOODYEAR	4 mm	
L/H Rear Tyre	215/60 R16	GOODYEAR	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/08/2014	Inspection Date	26/08/2014	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO. 466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 9948B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER COVER FRT (CONSISTENT)	SERVICEABLE	968.78	-
1	BUMPER ABSORBER FRT (CONSISTENT)	SERVICEABLE	303.60	-
1	BUMPER BEAM FRT (CONSISTENT)	TO REPAIR SEE LABOUR	703.14	-
1	BUMPER SPOILER FRT (CONSISTENT)	SERVICEABLE	139.81	-
1	BUMPER FOG LAMP GRILLE LH (CONSISTENT)	SERVICEABLE	159.40	-
1	BUMPER RETAINER FRT LH (CONSISTENT)	SERVICEABLE	116.47	-
1	BUMPER SUPPORT FRT LH (CONSISTENT)	SERVICEABLE	18.37	-
1	BUMPER UNDERTRAY FRT (CONSISTENT)	SERVICEABLE	363.71	-
1	LOWER ARM LH (CONSISTENT)	SERVICEABLE	527.51	-
1	KUNCKLE ARM LH (CONSISTENT)	SERVICEABLE	651.53	-
1	ABSORBER FRT LH (CONSISTENT)	SERVICEABLE	277.34	-
1	ABSORBER DUST COVER (CONSISTENT)	SERVICEABLE	175.93	-
1	BONNET (CONSISTENT)	TO REPAIR SEE LABOUR	1,493.56	-
1	WIPER RESERVOIR (CONSISTENT)	SERVICEABLE	173.60	-
1	WIPER RESERVOIR MOTOR (CONSISTENT)	SERVICEABLE	91.78	-
1	HEADLAMP LH (CUT)	NOT CONSISTENT WITH THE IMPACT	911.10	-
1	FENDER PANEL FRT LH (CONSISTENT)	BENT	602.95	602.95
1	FENDER WHEELARCH FRT LH (CONSISTENT)	DISTORTED	107.33	107.33
1	DOOR MIRROR LH (CONSISTENT)	CRACKED	1,141.08	1,141.08
1	DOOR PANEL FRT LH (CONSISTENT)	BENT	2,188.20	2,188.20
1	DOOR HINGE UPPER LH (CONSISTENT)	TO REPAIR SEE LABOUR	211.15	-
1	DOOR HINGE LOWER (CONSISTENT)	TO REPAIR SEE LABOUR	231.19	-
1	DOOR CHECK FRT LH (CONSISTENT)	SERVICEABLE	149.83	-
1	DOOR LOCK FRT LH (CONSISTENT)	TO REPAIR SEE LABOUR	699.04	-
1	DOOR CATCH FRT LH (CONSISTENT)	TO REPAIR SEE LABOUR	100.94	-
1	DOOR HANDLE OUTER FRT LH (CONSISTENT)	DENTED	198.55	198.55

Report Ref No. CC3/AXA14016319/Kwa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR HANDLE CAP FRT LH (CONSISTENT)	DENTED	20.34	20.34
1	DOOR HANDLE SEAL FRT LH (CONSISTENT)	NOT NECESSARY	6.07	-
1	DOOR HANDLE COVER FRT LH (CONSISTENT)	SERVICEABLE	10.18	-
1	DOOR HANDLE MODULE FRT LH (CONSISTENT)	SERVICEABLE	102.77	-
1	DOOR REGULATOR FRT LH (CONSISTENT)	TO REPAIR SEE LABOUR	388.61	-
1	DOOR REGULATOR MOTOR FRT LH (CONSISTENT)	SERVICEABLE	612.66	-
1	ROCKER PANEL OUTER LH (CONSISTENT)	BENT	759.61	759.61
1	DOOR PANEL REAR LH (CONSISTENT)	BENT	2,188.20	2,188.20
1	DOOR HINGE UPPER LH (CONSISTENT)	TO REPAIR SEE LABOUR	242.88	-
1	DOOR HINGE LOWER LH (CONSISTENT)	TO REPAIR SEE LABOUR	231.19	-
1	DOOR LOCK REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	699.04	-
1	DOOR HANDLE OUTER REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	97.31	-
1	DOOR HANDLE MODULE REAR LH (CONSISTENT)	SERVICEABLE	102.77	-
1	DOOR REGULATOR REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	512.02	-
1	DOOR REGULATOR MOTOR REAR LH (CONSISTENT)	SERVICEABLE	687.50	-
1	DOOR FINISHER REAR LH (CONSISTENT)	SERVICEABLE	325.46	-
1	DOOR MOULDING REAR LH (CONSISTENT)	SERVICEABLE	136.01	-
1	FENDER PANEL REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	2,537.80	-
1	BUMPER COVER REAR (CONSISTENT)	TO REPAIR SEE LABOUR	852.66	-
	LESS 10% DISCOUNT		-2,321.90	-720.63
			20,897.07	6,485.63
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIP (SN) (CONSISTENT)	NOT NECESSARY	66.00	-
1	SET WHEELARCH CLIP LH (SN) (CONSISTENT)	NECESSARY	66.00	66.00
1	CAP HUB LH FRT (SN) (CONSISTENT)	SERVICEABLE	35.00	-
1	RIM LH FRT (SN) (CONSISTENT)	SERVICEABLE	385.00	-
1	TYRE LH FRT (SN) (CONSISTENT)	SERVICEABLE	330.00	-

Report Ref No. CC3/AXA14016319/Kwa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	CAP HUB LH RR (SN) (CONSISTENT)	DENTED	35.00	35.00
1	RIM LH RR (SN) (CONSISTENT)	SERVICEABLE	385.00	-
1	TYRE LH RR (SN) (CONSISTENT)	SERVICEABLE	330.00	-
1	DOOR STICKER 'TRANS-CAB' (SN) (CONSISTENT)	NECESSARY	80.00	60.00
1	DOOR STICKER 'CLASSIC' (SN) (CONSISTENT)	NECESSARY	30.00	15.00
1	DOOR STICKER '6555-3333' (SN) (CONSISTENT)	NECESSARY	80.00	60.00
2	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN) (CONSISTENT)	NOT NECESSARY	150.00	-
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NOT NECESSARY	66.00	-
1	SET BUMPER SUPPORT FRT LH (SN) (CONSISTENT)	SERVICEABLE	9.80	-
1	SET BUMPER RETAINER FRT LH (SN) (CONSISTENT)	SERVICEABLE	12.50	-
			2,160.30	236.00
	LABOUR			
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM FRT,BONNET,DOOR HINGE UPPER LH,DOOR HINGE LOWER,DOOR LOCK FRT LH ,DOOR CATCH FRT LH,DOOR REGULATOR FRT LH ,)		2,800.00	800.00
	DOOR HINGE UPPER LH ,DOOR HINGE LOWER LH ,DOOR LOCK REAR LH,DOOR HANDLE OUTER REAR LH ,DOOR REGULATOR REAR LH ,FENDER PANEL REAR LH AND BUMPER COVER REAR.)		-	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	30.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	1,320.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	120.00
	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FENDER FITTINGS AND CONDUCT WATER SEEPAGE TEST.		380.00	80.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	90.00
			7,250.00	2,500.00
GRAND TOTAL			30,307.37	9,221.63
RECOMMENDED COST OF REPAIRS				9,221.63

Report Ref No. CC3/AXA14016319/Kwa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.