

SHB9948B-DOA 26.8.2014

AA1408-280

SHB9948B - AXA - DOA 26.8.2014

	AMOUNT	
PARTS	\$	633.01
	\$	1,823.50
	\$	2,456.51
10%	\$	245.65
	\$	2,210.86
SPECICAL NETT		
	\$	60.00
	\$	60.00
LABOUR		
	\$	600.00
	\$	20.00
	\$	880.00
	\$	60.00
	\$	60.00
	\$	1,620.00
	\$	3,890.86
0%	\$	-
	\$	3,890.86
Part-by-Part after GST	\$	4,163.22

TRANS-CAB AUTO SERVICES PTE LTD

NO.466-468 Tagore industrial avenue singapore 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHB 9948B - AXAdone - Kunteta
AndreaNot Authorized
1-B.1

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHB 9948B - Andrea
VF1AB115AUC273376
RENAULT
LATITUDE
26.08.2014
AXA

PART**LIST**

1	1	DOOR PANEL FRT RH	\$	R B 1,823.50 X
2	1	ROCKER PANEL OUTER RH	\$	B 633.01 ✓
3	1	DOOR PANEL REAR RH	\$	B 1,823.50 ✓
4	1	DOOR HINGE UPPER RH	\$	R 202.40 X
5	1	DOOR HINGE LOWER RH	\$	R 192.66 X
6	1	DOOR HANDLE OUTER REAR RH	\$	sm 81.09 X
7	1	DOOR SEAL REAR RH 车门黑塑胶条	\$	SVC 119.44 X
8	1	DOOR REGUALTOR MOTOR REAR RH	\$	R 572.92 X
9	1	BUMPER COVER REAR	\$	R 710.55 X
10	1	BUMPER BRACKET SIDE RH REAR	\$	th 87.16 X
11	1	BUMPER RETAINER RH REAR	\$	sm 28.84 X
12	1	FENDER PANEL REAR RH	\$	R 2,114.83 X

TOTAL	\$	8,389.90
--------------	----	-----------------

10%	\$	838.99
------------	----	---------------

	\$	7,550.91
--	----	-----------------

Specical Nett

1	1	DOOR STICKER "Trans-cab"	\$	nn As 80.00 X
2	1	DOOR STICKER "Classic"	\$	nn 30.00 X
3	1	DOOR STICKER "6555-3333"	\$	nn 80.00 60mm ✓
4	2	Rear Windscreen Sealant	\$	nn 80.00 X
5	1	Rear Windscreen Inner Sponge Seal	\$	nn 150.00 X

TOTAL	\$	420.00
--------------	----	---------------

TOTAL PARTS	\$	7,970.91
--------------------	----	-----------------

Panel beating, knocking and straightening
the necessary portion, remove and renewal
of parts, adjust and realign the same

\$

2,800.00 600

TRANS CAB AUTO SERVICES PTE LTD

NO.466-458 Tagore industrial avenue singapore 787836

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHB 9948B - AXA**Andrea**

To Check Electrical Lighting Concerned.	\$	170.00 <i>20/</i>
Putty and spray painting of the affected portion.	\$	3,000.00 <i>880/✓</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	220.00 <i>60/</i>
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00 <i>60/</i>
TOTAL	\$	6,700.00
Over All Total	\$	14,670.91
(PARTS BY PARTS) Repair Days		10 Days