

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

**WIP : 22532**

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/1469/2019/NS  
**Date** : 12-Dec-19

**Vehicle NOT IN workshop. Kindly arrange for survey.**

## ~~NTUC Income Insurance Co -~~ Claims Department

73 Bras Basah Road

#05-01 NTUC Trade Union House

Singapore 189556

*AlG.*

**Attn: Motor Claims Dept**

**Tel: Fax 6338 1504**

**Owner's Name** : Professor Phee Soo Jay Louis  
**Address** : 33 Jalan Limau Bali  
Singapore 468504  
**Telephone** : HP +65 97968155  
**Type of Claim** : Own Damage Claim  
**Policy No.** : 2100503552-02  
**Vehicle No** : **SLL 8108 R**  
**Model Code** : Audi A6 1.8 TFSI S tronic  
**Model / Year** : Mar-17  
**Engine No** : CYG 015125  
**Chassis No** : WAUZZZ4G8HN009761  
**Mileage** : -  
**Date In** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 8-Dec-19  
**Place of Accident** : Junction of Tanah Merah Kechil Rd South

*7038*

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLL 8108 R

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function.	S/N \$	360.00	✓
2	To renew rear windscreen and rhs 1/4 glass to facilitate fender renewal.	S/N \$	600.00	✓
3	To install rear windscreen solar film.	S/N \$	400.00	✓
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$	1,400.00	✓
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$	1,400.00	✓
<b>SUB TOTAL LABOUR CHARGES</b>		:	<b>\$ 4,160.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLL 8108 R

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
6	To remove and transfer rhs rear door's multi-lock system and power window devices. Check function and renew if necessary.	S/N \$ 280.00	X
7	To dismantle rear bumper, rear lid and rhs rear door. Cut out and weld rhs rear fender. To renew rhs rear door and rear bumper. Re-organise crash management components. Reinstall all parts removed.	\$ <del>7,200.00</del>	3000
8	To respray rear bumper, rhs rear door, door handles, rhs rear fender, rhs sill panel, door entrances, roof channel, drain panel and end paneling. To carry out stone chip treatment and joint sealer works.	\$ <del>6,200.00</del>	5 x 550 = 2750
9	To renew rhs rear rim and carry out wheel alignment.	S/N \$ 280.00	✓
10	To carry out diagnostic check.	S/N \$ 192.00	✓
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 18,312.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLL 8108 R

S/N	Parts Description	<u>Damaged Parts &amp; Prices</u>	
		S/Nett	Remarks
1	REAR BUMPER <i>Repis</i>	\$ 2,676.00	<i>+</i>
2	REAR BUMPER FIXING PARTS	\$ 247.00	<i>+</i>
3	REAR BUMPER SECURING STRIP	\$ 203.00	<i>+</i>
4	REAR BUMPER GUIDE SECTION - RH	\$ 48.00	<i>+</i>
5	SIDE PANEL - RH <i>Dented</i>	\$ 2,850.00	<i>✓</i>
6	REAR WINDSCREEN <i>me</i>	\$ 1,069.00	<i>✓</i>
7	PRIMER <i>3 per</i>	\$ 19.00	<i>✓</i>
8	SIDE WINDOW - RH	\$ 356.00	<i>✓</i>
9	REAR WHEEL HOUSING LINER - RH	\$ 256.00	<i>+</i>
10	WHEEL HOUSING LINER ATTACHMENT PARTS <i>2 per</i>	\$ 66.00	<i>+</i>
11	REAR DOOR - RH <i>Repis</i>	\$ 3,374.00	<i>+</i>
12	REAR DOOR ATTACHMENT PARTS <i>3</i>	\$ 76.00	<i>+</i>
13	REAR DOOR OUTER SEAL	NEC \$ 212.00	<i>+</i>
14	BONDING AGENT	NEC \$ 45.00	<i>+</i>
15	CLEANING SOLUTION	NEC \$ 65.00	<i>+</i>
16	REAR DOOR CATCH <i>1 set</i>	\$ 109.00	<i>+</i>
17	EXTERIOR DOOR HANDLE - RH <i>me</i>	\$ 537.00	<i>+</i>
18	DOOR HANDLE CAP - RH	\$ 102.00	<i>+</i>
19	REAR ALUMINIUM RIM - RH <i>cit</i>	\$ 733.00	<i>✓</i>
20	ALUMINIUM RIM RUBBER VALVE <i>me</i>	4 \$ 13.00	<i>+</i>
<b>SUB TOTAL SPARE PARTS</b>		<b>: \$ 13,056.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLL 8108 R

S/N	Parts Description	<u>Damaged Parts &amp; Prices</u>	
		S/Nett	Remarks
21	ACRYLIC SEALANT	S/N \$ 180.00	✓
22	CAVITY WAX	S/N \$ 140.00	✓
23	STONE CHIP	S/N \$ 180.00	✓
24	METAL FILLER POWDER	S/N \$ 280.00	✓
25	REAR WINDSCREEN SEALANT	S/N \$ 200.00	✓
26	1/4 GLASS SEALANT	\$ 100.00	✓
27	SUNDRIES ?	\$ 400.00	?

**TOTAL SPARE PARTS : \$ 14,536.00**

**TOTAL LABOUR CHARGES \$ 18,312.00**

**GRAND TOTAL \$ 32,848.00**

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : *Adrian Lj*  
Surveyed Date : *19/12/19*  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : *not authorised, 13 days.*

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the  
progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant