

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

JTDGJ20W005002703

OH CHOON KIAT
BLK 469 PASIR RIS DRIVE 6
#12-436
S 510469

TPAXA
Xiao Tong

Date :14.02.2020
Vehicle No :SJW 8996 J
Make/Model :TOYOTA WISH
Accident date :17.12.2019

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Rear windscreen rubber <i>new</i>	1	\$ 92.70 ✓
2	Rear tailgate <i>Distorted</i>	1	\$ 1403.50 1273
3	Rear tailgate hinges @ \$94.50 <i>the new</i>	2	\$ 139.00 X
4	Rear tailgate upper lock <i>Damaged</i>	1	\$ 81.50 ✓
5	Rear tailgate lower lock <i>the new</i>	1	\$ 38.30 X
6	Rear tailgate shock absorber @ \$252.60 <i>the new</i>	2	\$ 505.20 X
7	Rear tailgate inner board <i>cracked</i>	1	\$ 391.50 ✓
8	Rear tailgate weather strip <i>cut</i>	1	\$ 351.90 ✓
9	Rear tailgate inner handle <i>cracked</i>	1	\$ 30.90 ✓
10	Rear tailgate wiper motor <i>Damaged</i>	1	\$ 969.60 611
11	Rear tailgate centre emblem <i>3 new</i>	1	\$ 61.20 ✓
12	Rear tailgate Deluxe emblem	1	\$ 60.50 ✓
13	Rear tailgate Borneo Motor emblem <i>new</i>	1	\$ 38.50 ✓
14	Rear tailgate reflector @ \$161.00 <i>cracked</i>	2	\$ 322.00 ✓
15	Rear tailgate handle <i>cracked</i>	1	\$ 240.80 ✓
16	Rear number plate lamp @ \$58.20 <i>cracked</i>	2	\$ 116.40 ✓
17	Rear end panel <i>Dented</i>	1	\$ 571.80 ✓
18	Rear end panel top garnish <i>cracked</i>	1	\$ 295.70 ✓
19	Rear lamp @ \$612.60 <i>cracked</i>	2	\$ 1225.20 ✓
20	Rear lamp housing @ \$136.90 <i>the new</i>	2	\$ 273.80 X
21	Rear bumper <i>Damaged</i>	1	\$ 941.50 585
22	Rear bumper side holder @ \$61.20 <i>new</i>	2	\$ 122.40 ✓
23	Rear bumper reflector @ \$68.20 <i>cracked</i>	2	\$ 126.40 ✓
24	Rear bumper bracket @ \$48.50 <i>the new</i>	2	\$ 97.00 X
25	Rear bumper clips (1 set) <i>the new</i>	1	\$ 66.00 30
26	Rear bumper holder @ \$108.80 <i>Replaced</i>	2	\$ 217.60 X
27	Rear Fender Inner Trim Board @ 643 <i>RH cracked</i>	1296	\$ 8780.90
Less 25% Disc			\$ 2195.23
Total			\$ 6585.67

7271.40

5453.55

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

OH CHOON KIAT

BLK 469 PASIR RIS DRIVE 6

#12-436

S 510469

Date :14.02.2020

Vehicle No :SIW 8996 J

Make/Model :TOYOTA WISH

Accident date :17.12.2019

No	DESCRIPTION	Qty	Amount (\$\$)
----	-------------	-----	---------------

Special Nett Items

1	Rear number plate	200	\$ 50.00 ✓
2	Rear number plate holder		\$ 50.00 ✓
3	Rear bumper reverse sensor (1 set) Danyd		\$ 380.00 100
Total			\$ 480.00

Labour Cost

1	To supply rear windscreen sealant		\$ 50.00 ✓
2	To supply rear end panel sealant		\$ 200.00 60
3	Remove & reinstall rear windscreen		\$ 150.00 120
4	Remove & reinstall reverse sensor		\$ 150.00 60
5	Remove & reinstall bootlid inner garnish	2100	\$ 200.00 80
6	Remove & reinstall petrol tank		\$ 200.00 x
7	Remove & reinstall exhaust pipe		\$ 200.00 x
8	Remove ,replace & repair consistent to the accident		\$ 1800.00 850
9	Respray painting		\$ 1400.00 800
10	Remove and Replace upholstery 2x60 80		\$ 4350.00
Total			\$ 4350.00
Grand Total			\$ 11415.67

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total : 7753.55

L/S 6.2K

6days

total : 7753.55