



Asher

TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475
E-mail : claims@teamworkgarage.com
ROC number : 201015366H

AIG INSURANCE

REPAIR PERFORMANCE INVOICE

Vehicle number	SKA4300Y
Make / Model	MAZDA 3
Chassis number	JM6BL10Z1A0159287 (2011)
Accident date	12/12/19
Reference	1912-20

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR BUMPER de ✓	880.00 ✓
1	REAR BUMPER RETAINER ne (LH) ✓	84.00 42 (1pc)
1	REAR BUMPER LOWER GARNISH X su ✓	461.50 X
1	REAR BUMPER REFORCEMENT 7bf ✓	412.00 ✓
1	REAR BUMPER SPONGE ? X su ✓	261.30 X
1	REAR BUMPER REFLECTOR cm (1pc) ✓	236.00 118 (1pc)
1	REAR END PANEL X su ✓	693.00 X
1	REAR END PANEL TOP GARNISH X su ✓	236.50 X
1	REAR EXHAUST SILENCER X su ✓	1050.00 X
2	REAR EXHAUST MOUNTING X su ✓	92.00 X
1	BOOTLID X su ✓	1092.00 X
1	BOOTLID LOCK X su ✓	303.00 X
1	BOOTLID LOCK STRIKER X su ✓	65.00 X
1	BOOTLID WEATHERSTRIP X su ✓	107.50 X
1	BOOTLID LAMP LH X su ✓	365.60 X
1	TAILLAMP LH ? cr ✓	719.60 ✓
		2171.60
		20%
		1737.28
		7059.00
	Less 20%	1411.80
		5647.20
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1 SET	REAR BUMPER CLIP ha ✓	60.00 30
1 SET	END PANEL TOP GARNISH CLIP X nn ✓	50.00 X X
1 SET	REVERSE SENSOR ? X su ✓	400.00 200? X
1	BOOTLID STICKER X nn ✓	100.00 X
		30
		610.00
	Subtotal	610.00
	Balance C/F	6257.20
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	6257.20
1	CHECK WIRING AND LIGHTNING SYSTEM	60.00 30
2	REMOVE, RENEW & REFIT OLD BOOTLID TO NEW	150.00 X nn
2	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	150.00 X nn
4	PANEL BEATING ON AFFECTED AREAS	1000.00 300
5	SPRAY PAINTING ON AFFECTED AREAS	1000.00 200
6	APPLY ANTI RUST ON AFFECTED AREAS	150.00 X nn
		530
		2510.00
	Subtotal	2510.00
	Grand total	8767.20

Rashid
Hp 90010068
3 days
4/5
17/12/19 @ 1635
Resy after repair

PARIS: 1737.28
S/N: 30100
L: 530100
T: 2297.28
20%
1837.82
4/5 - 1,800
3 days