

NGS AUTOMOTIVE

Blk 10 Ang Mo Kio Ind. Pk 2a #02-01 AMK AutoPoint Singapore 568047
Tel: 64815727 Fax: 64815772 Email: evelyn191ngsautomotive@gmail.com
Reg No.:53405718K

QUOTATION

No. : AQT-0007

INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOU BLDG
SINGAPORE 049711

TEL : 6347 6100

FAX :

Your Ref. :

Our Ref : AQT-007/SGN5242

C. C. :

Date : 18-12-2019

Page : 1 of 2

Description	Qty	U/ Price S\$	Amount S\$
ACCIDENT ON 11/12/2019@12:10 INVOLVING SGN5242D & SHA4332R ALONG 13 STAMFORD RD CAPITOL PIAZZA TAXI STAND CLAIMS AGAINST SHA4332R (INDIA INT'L) REPLACEMENT PART: HONDA CIVIC <i>Not Authorized claim 820000 Running after claim 4 days</i>			
FRT FENDER RH	1	450.80	450.80
FRT DOOR OUTER PILLAR RH	1	609.90	609.90
FRT DOOR RH	1	949.20	949.20
SIDE MIRROR RH	1	659.40	659.40
FRT OUTER HANDLE RH	1	175.40	175.40
REAR DOOR RH	1	687.40	687.40
FRT DOOR WINDOW MOULDING TOP CHANNEL RH	1	90.50	90.50
FRT DOOR OUTER MOULDING	1	99.20	99.20
FRT DOOR TAPE	1	54.90	54.90
SubTotal			3,776.70
LESS 20%	1	-755.34	-755.34
TO REMOVE ALL DAMAGED PART WITH ALL NECESSARY COMPONENT/ATTACHMENT. STRAIGHTEN CHASSIS MEMBER, REPAIR/RESHAPE DENTED BODY PANEL REPLACE DAMAGED PART. REFIT INTO POSITION.	1	1,200.00	1,200.00
TO SPRAY PAINTING	1	1,000.00	1,000.00
TRANSFER DOOR MECHANISM	1	150.00	150.00
CHECK WIRING & LIGHT FUNCTION	1	50.00	50.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: