

Trust Autoworks

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
H/p 91082728

Giam Kia Kit
48 Canberra Drive #13-16
Singapore 768437

Vehicle No : SCN 66 B
Make/Model : Subaru Forester 2.0 X
Year : 2018

Not Authorized
1/1 Sep @ 7
Pressure After Paint
Today

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear tail-gate assy	<i>By</i> \$1,450.10	✓
1 pc	Rear tail-gate glass moulding	<i>ru</i> \$75.10	✓
1 pc	Rear tail-gate outer garnish	<i>ru</i> \$255.70	X
1 pc	Rear tail-gate inner lock	<i>ru</i> \$185.60	X
1 pc	Rear tail-gate emblem : " Subaru "	<i>ru</i> \$40.20	—
1 pc	Rear tail-gate emblem " Forester "	<i>ru</i> \$55.10	—
1 pc	Rear tail-gate emblem " Logo "	<i>ru</i> \$48.10	—
1 pc	Rear tail-gate emblem " AWD "	<i>ru</i> \$35.20	—
1 pc	Rear tail-gate emblem " Badge "	<i>ru</i> \$32.60	—
1 pc	Rear tail-gate inner trim board	<i>ru</i> \$405.10	X
1 pc	Rear n/s tail-lamp assy	<i>cm</i> \$625.10	?
1 pc	Rear n/s tail-lamp lower bracket	<i>cm</i> \$44.60	—
1 pc	Rear n/s tail-lamp panel	<i>ru</i> \$205.30	?
1 pc	Rear boot rubber	<i>ru</i> \$197.40	X
1 pc	Rear n/s fender	<i>ru</i> \$987.20	✓
1 pc	Rear n/s fender inner trim board	<i>cm</i> \$455.60	?
1 pc	Rear n/s fender air duct	<i>cm</i> \$205.30	—
1 pc	Rear n/s fender air duct sponge	<i>cm</i> \$36.10	?
1 pc	Rear n/s fender inner shield	<i>cm</i> \$210.20	✓
1 pc	Rear end panel	<i>ru</i> \$725.70	✓
1 pc	Rear end panel inner garnish	<i>ru</i> \$192.60	?
1 pc	Rear bumper	<i>ru</i> \$885.70	—
1 pc	Rear bumper reinforcement	<i>ru</i> \$455.70	?
1 pc	Rear n/s bumper reflector	<i>ru</i> \$65.90	—
1 pc	Rear n/s bumper side retainer	<i>cm</i> \$57.10	—
1 pc	Rear n/s bumper bracket	<i>ru</i> \$95.60	?
1 pc	Rear bumper tow cover	<i>ru</i> \$40.10	—
1 pc	Rear n/s boot panel side sponge	<i>ru</i> \$105.20	?
1 pc	Rear spare tyre cover board	<i>ru</i> \$195.70	?
1 pc	Rear n/s exhaust silencer cover	<i>ru</i> \$95.70	?
		<i>20%</i> \$8,464.60	
		Less 45%	\$1,269.69
		balance c/f	\$7,194.91

SCN 66 B

balance b/f \$7,194.91

S Nett

2 pcs Rear tail-gate glass sealant
1 pc Rear reverse sensor
15 pcs Bumper clip

\$35.00	<i>neu</i>	\$70.00	<i>neu</i>
	<i>neu</i>	\$200.00	<i>✓</i>
\$2.00	<i>neu</i>	\$30.00	<i>✓</i>
		<u>\$300.00</u>	

Labour Charges

Remove/renew the above accident parts including knocking, welding & cutting.

\$1,800.00 *1200*

To putty and spray paint on rear portion.

\$1,500.00 *800*

Check & reconnect wiring.

\$40.00 *20*

To respray anti-rust proofing treatment

\$150.00 *90*

Remove/refit rear tail-gate glass & n/s fender glass to facilitate repair.

\$150.00 *60*

Remove/refit rear tail-gate mechanism, inner trim to new door.

\$120.00 *60*

Remove/refit & boot upholstery, conduct water leakage test.

\$100.00 *60*

Remove/refit roof lining to facilitate repair.

\$200.00 *100*

Total

\$11,554.91

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: