

K/K

# Trust Autoworks

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225  
H/p 91082728

Giam Kia Kit  
48 Canberra Drive #13-16  
Singapore 768437

Vehicle No : SCN 66 B  
Make/Model : Subaru Forester 2.0 X  
Year : 2018

Not Authorised  
C/Sing @ 645ph  
Recovery After Paint  
8 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

## Estimate Cost Of Repair

1 pc	Rear tail-gate assy	1272.00	Rt \$1,450.10 ✓
1 pc	Rear tail-gate glass moulding		rt \$75.10 ✓
1 pc	Rear tail-gate outer garnish		rt <del>\$255.70</del> X
1 pc	Rear tail-gate inner lock		rt <del>\$185.60</del> X
1 pc	Rear tail-gate emblem " Subaru "		rt \$40.20 ✓
1 pc	Rear tail-gate emblem " Forester "		rt \$55.10 ✓
1 pc	Rear tail-gate emblem " Logo "		rt \$48.10 ✓
1 pc	Rear tail-gate emblem " AWD "		rt \$35.20 ✓
1 pc	Rear tail-gate emblem " Badge "		rt \$32.60 ✓
1 pc	Rear tail-gate inner trim board		rt <del>\$405.10</del> X
1 pc	Rear n/s tail-lamp assy	photo 518.40	cm \$625.10 ✓
1 pc	Rear n/s tail-lamp lower bracket		cm \$44.60 ✓
1 pc	Rear n/s tail-lamp panel	photo	Rt \$205.30 ✓
1 pc	Rear boot rubber		rt <del>\$197.40</del> X
1 pc	Rear n/s fender	960	Rt \$987.20 ✓
1 pc	Rear n/s fender inner trim board	photo	cm \$455.60 ✓
1 pc	Rear n/s fender air duct		cm \$205.30 ✓
1 pc	Rear n/s fender air duct sponge	photo	cm \$36.10 ✓
1 pc	Rear n/s fender inner shield		cm \$210.20 ✓
1 pc	Rear end panel	684.00	Rt \$725.70 ✓
1 pc	Rear end panel inner garnish	photo 179.00	mycm \$192.60 ✓
1 pc	Rear bumper	540.	Ti \$885.70 ✓
1 pc	Rear bumper reinforcement	photo	Rt \$455.70 ✓
1 pc	Rear n/s bumper reflector		Rt \$65.90 ✓
1 pc	Rear n/s bumper side retainer		cm \$57.10 ✓
1 pc	Rear n/s bumper bracket	photo	Rt \$95.60 ✓
1 pc	Rear bumper tow cover		Rt \$40.10 ✓
1 pc	Rear n/s boot panel side sponge	photo	cm \$105.20 ✓
1 pc	Rear spare tyre cover board		rt <del>\$195.70</del> X
1 pc	Rear n/s exhaust silencer cover	photo	rt \$95.70 ✓
1 pc	Rear n/s boot side panel	275.80	20% \$8,464.60 7500.90
			Less 45% \$1,269.69 1500.18
			balance c/f \$7,194.91 6000.72

SCN 66 B

balance b/f \$7,194.91

S Nett

2 pcs Rear tail-gate glass sealant  
1 pc Rear reverse sensor  
15 pcs Bumper clip

\$35.00 *neu* \$70.00 *kosu*  
\$2.00 *neu* \$200.00 *—*  
\$30.00 *—*  
\$300.00 *270.00*

Labour Charges

Remove/renew the above accident parts including knocking, welding & cutting.

\$1,800.00 *1200*

To putty and spray paint on rear portion.

\$1,500.00 *800*

Check & reconnect wiring.

\$40.00 *20*

To respray anti-rust proofing treatment

\$150.00 *90*

Remove/refit rear tail-gate glass & n/s fender glass to facilitate repair.

\$150.00 *60*

Remove/refit rear tail-gate mechanism, inner trim to new door.

\$120.00 *60*

Remove/refit & boot upholstery, conduct water leakage test.

\$100.00 *60*

Remove/refit roof lining to facilitate repair.

\$200.00 *100*

Total

\$11,554.91 *2390.0*

*Hi Kenneth*

*Paint - 6000.72*  
*S Nett - 270.00*  
*Labour - 8390.00*  
*8,660.72*

*dump fee*

*6,900.00 - 8 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: