

15/9/2010

INS. CASE OWNER: StaceyCC 3 / AXA140 06734 / KS<sup>3</sup> y3LKK:  
IDAC:

## ASSIGNMENT

Surveyor: KennethDOI: 7.4.14Assg Date: 7.4.14

Pre-assign / CCU / FTE

Insured Vehicle No.: SGM 8938 R


Claim No.: \_\_\_\_\_

Name of Insured: James Wai YungPolicy No.: 9116855

Insured Tel No.: \_\_\_\_\_ HP: \_\_\_\_\_

Make / Model: NissanExcess Sec II: SS Nil D.O.A.: 4.4.14Place of Accident: Along Jln Buroh After West Coast HighwayIs driver the owner? (YES / NO) Nature of Accident: \_\_\_\_\_If NO, Driver Name / Age: Org Henry Soon DesmondOI GIA REPORT: YES / NO; TP GIA REPORT: YES / NODriver Tel No.: 9668 1157(V/L: YES / NO Insured Liability: \_\_\_\_\_ % Final? Yes / No

SHC 52097

INSRS:  
WSP: Trans - cab  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_INSRS:  
WSP: \_\_\_\_\_  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_INSRS:  
WSP: \_\_\_\_\_  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_INSRS:  
WSP: \_\_\_\_\_  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_

Date/ Time

## FOR CSO ONLY:

Is driver the owner? (YES / NO)

If NO, Driver Name / Age: \_\_\_\_\_

Driver's Own Vehicle Number: \_\_\_\_\_ Insurance Company: \_\_\_\_\_

SHC 52097 - (SS/FCI/14006451/Pam2d1) 4.4.14.  
SGM 8938 R - " "

17.4  
Zupper

21/4/14 5:43 called OSD spoke to Mr Desmond. Inform about the claim. Confirm the accident. OI said he was driving straight all the way. Video footage was forwarded to his wife (Nissan car).

Inform OI we will be held due to third party claim.

letter out / email to OI

22-05-15 I THINK BASED ON DAMAGE PROFILE WHICH IS A SMALL DENT THE REAR RIGHT BUMPER & FENDER. NO SCRATCHLINE WAS SEEN. SO HIS PERSON IS QUITE RELIABLE. IF ANOTHER VEHICLE MENTIONED COULD BE CONFIRMED INVOLVING IN THE COLLISION. THEN THIS IS A CASE OF CHAIN COLLISION, CHARGES OF REJECTION IS HIGH.

Pending accident.

01-10-15 To send reminder to AXA FOR INSTRUCTION

## STAGE

DATE / PIC

Finalisation:

Email AIG for OI GIA:

Apt letter to OI:

Call OI:

After call ltr to OI:

Type Report:

Prepare Invoice:

Others:

Documentation Check List: Handler Typist

OI Apt Ltr:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

LTA / GIA:

Medical Bill:

Approval Email:

Payment Breakdown Form:

Others:

## FINAL SETTLEMENT

Date:

Confirm with

Repair Cost:

S\$

Final Liability

S\$ % (Agreed / Assessed)

BOLA S/N No.: IVL

Loss of Rental:

S\$

( days)

If NO or B 28, Ass. Lia:

Loss of Use:

S\$

(\$ x days)

Format Type: Re-direct claim

Disbursement:

S\$

Total:

S\$

Global Sum: S\$

88350

ASS. REC. BY:

REF:

AA/

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

<input type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 63 days Res.: Yes or NoLum Sum: 1.13 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHC 52094 Yr Ragn: 01, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or TAMake: Renault Latitude C.C. 1995Colour: M. White / RW A/C: Insured / Std / NI / NASp. Reading: 31835 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VF1AB215AUC 276788

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm R/Bal. 7 mmL/Bal. 6 mm L/Bal. 7 mmD.O.A. 4/4/14 D.O.I. 7/4/14

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

T.B.I \$ 2776.88, 3 days

Paid (\$ 8145.30, 750/6)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE SINGAPORE PTE LTD		Ref : CC3/AXA14006734/Ksy3	
8 SHENTON WAY #27-01 SINGAPORE 068811		Date : 10-04-2014	
		Code : AXA2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SGM 8938R	Veh. Inspected	SHC 5209Y
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	07/04/2014
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	04/04/2014	Inspection Date	07/04/2014
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO. 466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To be advised  
Our ref: CC3/AXA14006734/Ksy3

Date: 10/04/2014

The Motor Claims Department  
M/s AXA Insurance Singapore Pte Ltd

Dear Sir/Madam

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SHC 5209Y**


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 07/04/2014 at the premises of M/s Trans-Cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	10,922.18
Revised Estimate Amount	: S\$	2,776.88
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

**Description of Damage:**

The vehicle sustained damages at the  
N/S Frt portion.



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 3 days

Yours faithfully,

Kenneth Kong  
Licensed Appraiser

**TRANS-CAB AUTO SERVCIES PTE LTD**

NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHC 5209Y - AXA

done  
Andrea

parts by parts

*Not Authental*  
*1-B-1*  
*82776-88*Vehicle No.:  
Chassis No.:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :**SHC5209Y - Andrea**  
VF1ABL15AUC276798  
RENAULT  
LATITUDE  
04.04.2014  
**AXA**

		PART			LIST
1	1	BUMPER COVER FRT	\$	<i>Bar</i>	702.02 ✓
2	1	BUMPER RETAINER FRT LH	\$	<i>D/I</i>	84.04 ✓
3	1	BUMPER RETAINER FRT RH	\$	<i>See</i>	84.04 X
4	1	HEADLALMP LH	\$	<i>mg/12A</i>	660.22 ✓
5	1	FENDER PANEL FRT LH	\$	<i>As</i>	436.92 ✓
6	1	FENDER BRACKET LOWER LH	\$	<i>See</i>	8.80 X
7	1	FENDER BRACKET FRT TOP LH	\$	<i>See</i>	19.30 X
8	1	FENDER BRACKET FRT LH	\$	<i>R</i>	84.81 X
9	1	WHEELARCH FRT LH	\$	<i>See</i>	77.77 X
10	1	LOWER ARM LH	\$	<i>See</i>	382.25 X
11	1	KUNCKLE ARM LH	\$	<i>See</i>	472.12 X
12	1	ABSORBER FRT LH	\$	<i>See</i>	200.97 X

<b>TOTAL</b>	<b>\$</b>	<b>3,213.26</b>
<b>10%</b>	<b>\$</b>	<b>321.33</b>
	<b>\$</b>	<b>2,891.93</b>

**Specical Nett**

1SET	HEADLALMP SCREW L70Y	\$	<i>nn</i>	35.20 X
1SET	FRONT BUMPER CLIP	\$	<i>nn</i>	66.00 ✓
1SET	WHEELARCH CLIP (Necessary)	\$	<i>nn</i>	66.00 ✓
1SET	WHEELRACH SCREW	\$	<i>nn</i>	27.50 X
1SET	HEX NUT WITH WASHER	\$	<i>See</i>	4.95 X
1	CAP HUB LH FRT	\$	<i>nn</i>	35.60 X
1	RIM (ROUE 7J 16H 2547) LH FRT	\$	<i>See</i>	385.00 X
1	TYRE LH FRT	\$	<i>See</i>	330.00 X

<b>TOTAL</b>	<b>\$</b>	<b>950.25</b>
--------------	-----------	---------------

<b>TOTAL PARTS</b>	<b>\$</b>	<b>3,842.18</b>
--------------------	-----------	-----------------

**TRANS-CAB AUTO SERVCIES PTE LTD**

NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHC 5209Y - AXA

**Andrea**  
**parts by parts**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,800.00 <i>400</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>20</i>
Putty and spray painting of the affected portion.	\$	3,000.00 <i>400</i>
To transfer of Fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	220.00 <i>60</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>nn</i> 380.00 <i>X</i>
To rust-proofing of the affected areas.	\$	170.00 <i>30</i>

**TOTAL \$ 7,080.00****Over All Total \$ 10,922.18****(PARTS BY PARTS) Repair Days*****10* Days**

## Admin-B (LKK Auto)

**From:** Kitty Teo Poh Guek [Kitty.Teo@axa.com.sg]  
**Sent:** Monday, 14 April, 2014 3:42 PM  
**To:** 'Admin-B (LKK Auto)'; Jeffrey Ng Say Kiat  
**Cc:** 'Sharon Yee'; 'KKLau'; Stacey Ng Pei Sze; Ong Eng Hong (PSC); Tan Chia Ling (PSC)  
**Subject:** DS / TRANS-CAB / P1116955 / OD-SGM8938R / TP-SHC5209Y / 04.04.2014 / EST \$10,922.18 / NPS  
**Attachments:** Full page photo.pdf; POLICE REPORT.PDF; Preliminary Advice - SHC 5209Y.PDF; TP ESTIMATE.PDF; TP GIA REPORT.PDF; SGM8938R - 040414.pdf; FileNETImage.tif

RISK 1-P1116955

Claim received on 10/04/2014.

SGM8938R(INSR) C/W SHC5209Y

**VAT VTP**

SITF 14.04.14

NCD-Y

NPS 14.04.14

### Kitty TEO

Executive Assistant – Motor Claims

**AXA Insurance Singapore Pte Ltd**

8 Shenton Way #27-01 AXA Tower Singapore 068811

[kitty.teo@axa.com.sg](mailto:kitty.teo@axa.com.sg)

DID: (65) 6880 4602 Fax: (65) 6880 4838

Website: [www.axa.com.sg](http://www.axa.com.sg)



redefining / standards

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorised disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Please consider the environment before printing this email

**From:** Admin-B (LKK Auto) [mailto:admin-b@lkkauto.com]  
**Sent:** Thursday, April 10, 2014 8:06 PM  
**To:** Winnie Ho Ping Ping; Tan Tiong Beng; Kitty Teo Poh Guek  
**Cc:** 'Sharon Yee'; 'KKLau'  
**Subject:** Direct Settlement - Acc Invl SGM 8938R (OI : AXA - TBA) & SHC 5209Y (TP : LKK - CC3/AXA14006734/Ksy3) on 04.04.2014

Dear Sir/Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHC 5209Y AT M/S Trans-Cab Auto Services Pte Ltd

Enclosed herewith a copy of TP's GIA report, police report, estimated cost of repair and preliminary advice for your perusal.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Sharon and she can be contacted at DID: 6749 4274.



Zayyer

From:  
Sent:  
To:  
Cc:  
Subject:

Zayyer  
Tuesday, 22 April, 2014 10:34 AM  
'doks72@hotmail.com'  
Sharon Yee  
ACCIDENT INVOLVING SGM 8938R / SHC 5209Y / OTHER ON 4/4/2014



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: SGM 8938R

Our Ref: CC3/AXA14006734/Ksy3

Dear Sir/Madam,

**ACCIDENT INVOLVING SGM 8938R / SHC 5209Y / OTHER ON 4/4/2014**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

This also refers to our telephone conversation.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be withheld for the time being pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,

Thanks and Best Regards

Zayyer

LKK Auto Consultants Pte Ltd

51 Ubi Avenue 1

#01-25

Paya Ubi Industrial Park

Singapore 408933

MOB: 6749 9635

Fax: 6741 4108



email to AXA

**Zayyer**

**From:** Stacey Ng Pei Sze <stacey.ng@axa.com.sg>  
**Sent:** Thursday, 19 November, 2015 4:13 PM  
**To:** Zayyer  
**Subject:** FW: request approval to redirect the claim for Date of accident on 4/4/2014 involving vehicles SGM 8938R & SHC 5209Y C0301208MC/NPS  
**Attachments:** TP statement.pdf; OI statement.pdf; BOLA 28g.pdf; ATT00001.txt

Hi Zayyer

Please redirect the claim.

Thanks.

**Stacey Ng**  
Senior Executive – Motor Claims  
**AXA Insurance Singapore Pte Ltd**  
8 Shenton Way #27-01 Singapore 068811  
[stacey.ng@axa.com.sg](mailto:stacey.ng@axa.com.sg)  
Contact: 1800-8804741 (Option 3)  
Website: [www.axa.com.sg](http://www.axa.com.sg)

**We are all born to protect, but for me it's a calling.**  
Discover our stories on [www.borntoprotect.sg](http://www.borntoprotect.sg)

redefining / insurance



This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorised disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

 Please consider the environment before printing this email

**From:** Zayyer [mailto:[zayyer@lkkauto.com](mailto:zayyer@lkkauto.com)]  
**Sent:** Wednesday, November 11, 2015 8:31 PM  
**To:** Stacey Ng Pei Sze  
**Cc:** Zayyer  
**Subject:** request approval to redirect the claim for Date of accident on 4/4/2014 involving vehicles SGM 8938R & SHC 5209Y

Your Ref: P1116955

Dear Stacey,

**Date of accident on 4/4/2014 involving vehicles SGM 8938R & SHC 5209Y**

We refer to the below email.

Third Party reported that he was travelling on the 2<sup>nd</sup> lane along West Coast Highway towards City. While travelling, the insured vehicle from 3<sup>rd</sup> lane tried to cut into his lane and hit onto the left front of taxi. Then

another vehicle (SGY 5065R) came from the the 1<sup>st</sup> lane and collided into the rear portion of vehicle. Please find the attached statement.

The insured reported that he was travelling along Jalan Buroh on the extreme left lane of 3 lanes. After West Coast Highway, out of a sudden, he felt a strong impact from rear right portion of vehicle. After he alighted, it was 3 vehicles involved in the accident as a chain collision. Please see attached OI's statement.

We did call OID to verify the nature of accident. OID mentioned that he was travelling straight all the way and was hit by TP's from the 2<sup>nd</sup> lane. Total of 3 vehicles chain collision.

We have reviewed both reports. Basing on the reports from both parties and circumstances of accident, the scenario falls under BOLA 28g. Refer to the attached.

As above mentioned, we are of opinion that third party should claim against to the insurer of SGY 5065R and our insured is not liable for the accident.

As such, we will inform the TP to redirect the claim to the insurer of SGY 5065R in view of BOAL 28g. Kindly let us have your approval / instruction.

Best Regards,

Zayer | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841 2409, email: [zayyer@lkkauto.com](mailto:zayyer@lkkauto.com) | fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Email to w/r2ap

**Zayyer**

**From:** Zayyer  
**Sent:** Wednesday, 25 November, 2015 4:42 PM  
**To:** tzeyong.lui; 'Zhe Wei'  
**Cc:** Zayyer; claims@transcabservices.com.sg; 'JasmineTan'  
**Subject:** Date of accident on 4/4/2014 involving vehicles SGM 8938R & SHC 5209Y  
**Attachments:** our insured statement.pdf; your client statement.pdf; BOLA 28g.pdf

**WITHOUT PREJUDICE**

**Your Ref: SHC 5209Y**

Dear Mr Lui / Zhe Wei,

**Date of accident on 4/4/2014 involving vehicles SGM 8938R & SHC 5209Y**

We refer to the above matter.

Your Client reported that he was travelling on the 2<sup>nd</sup> lane along West Coast Highway towards City. While travelling, our insured vehicle from 3<sup>rd</sup> lane tried to cut into his lane and hit onto the left front of taxi. Then another vehicle (SGY 5065R) came from the 1<sup>st</sup> lane and collided into the rear portion of his taxi. Please find the attached statement.

Our insured reported that he was travelling along Jalan Buroh on the extreme left lane of 3 lanes. After West Coast Highway, out of a sudden, he felt a strong impact from rear right portion of vehicle.

After he alighted, it was 3 vehicles involved in the accident as a chain collision. Please see attached OI's statement.

We have reviewed both reports. Basing on the reports from both parties and circumstances of accident, the scenario falls under BOLA 28g. Refer to the attached.

As above mentioned, in view of BOAL 28g, our principal has given the instruction to inform you that our insured is not liable for the accident and kindly re-direct your claim against to the insurer of **SGY 5065R**.

Best Regards,

Zayyer | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841 2409, email: [zayyer@lkkauto.com](mailto:zayyer@lkkauto.com) | fax: 6741 4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

<b>Affiliated to Federation Internationale Des Experts En Automobile</b>			
AXA INSURANCE SINGAPORE PTE LTD		Ref : CC3/AXA14006734/Kza3q2	
8 SHENTON WAY #27-01 SINGAPORE 068811		Date : 26-11-2015	
ATTN: STACEY NG		Code : AXA2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SGM 8938R	Veh. Inspected	SHC 5209Y
Policy No.	P1116955	Coverage (\$)	0.00
Claim No.	C0301208MC	Excess (\$)	0.00
Assign From		Assign Date	07/04/2014
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC276798	Colour	METALLIC WHITE/RED
Odometer	31835	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	GOODYEAR	6 mm
L/H Front Tyre	215/60 R16	GOODYEAR	6 mm
R/H Rear Tyre	215/60 R16	GOODYEAR	7 mm
L/H Rear Tyre	215/60 R16	GOODYEAR	7 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	04/04/2014	Inspection Date	07/04/2014
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO. 466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5209Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BUMPER COVER FRT (CONSISTENT)	BUCKLED	702.02	702.02
1	BUMPER RETAINER FRT LH (CONSISTENT)	DISTORTED	84.04	84.04
1	BUMPER RETAINER FRT RH (CONSISTENT)	SERVICEABLE	84.04	-
1	HEADLAMP LH (CONSISTENT)	MTG CRACKED	660.22	660.22
1	FENDER PANEL FRT LH (CONSISTENT)	BENT	436.92	436.92
1	FENDER BRACKET LOWER LH (CONSISTENT)	SERVICEABLE	8.80	-
1	FENDER BRACKET TOP LH (CONSISTENT)	SERVICEABLE	19.30	-
1	FENDER BRACKET FRT LH (CONSISTENT)	TO REPAIR SEE LABOUR	84.61	-
1	WHEELARCH FRT LH (CONSISTENT)	SERVICEABLE	77.77	-
1	LOWER ARM LH (CONSISTENT)	SERVICEABLE	382.25	-
1	KUCKLE ARM LH (CONSISTENT)	SERVICEABLE	472.12	-
1	ABSORBER FRT LH (CONSISTENT)	SERVICEABLE	200.97	-
	LESS 10% DISCOUNT		-321.33	-188.32
			2,891.93	1,694.88
<b>SPECIAL NETT ITEMS</b>				
1	SET HEADLAMP SCREW L70Y (SN) (CONSISTENT)	NOT NECESSARY	35.20	-
1	SET FRONT BUMPE CLIP (SN) (CONSISTENT)	NECESSARY	66.00	66.00
1	SET WHEELARCH CLIP (NECESSARY) (SN) (CONSISTENT)	NECESSARY	66.00	66.00
1	SET WHEELARCH SCREW (SN) (CONSISTENT)	NOT NECESSARY	27.50	-
1	SET EXHAUST WITH WASHER (SN) (CONSISTENT)	SERVICEABLE	4.95	-
1	CAP HUB LH FRT (SN) (CONSISTENT)	NOT NECESSARY	35.60	-
1	RIM (ROUE 7J 2547) LH FRT (SN) (CONSISTENT)	SERVICEABLE	385.00	-
1	TYRE LH FRT (SN) (CONSISTENT)	SERVICEABLE	330.00	-
			950.25	132.00
<b>LABOUR</b>				
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME, INCLUSIVE OF THE REPAIR OF FENDER BRACKET FRT LH.		2,800.00	400.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00

Report Ref No. CC3/AXA14006734/Kza3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	440.00
	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	NOT NECESSARY	170.00	-
	TO DISMANTLE AND REFIT FRONT END SUSPENSION ,UNDERCARRIAGE PARTS ,FINAL CHECKING AND TESTING	NOT NECESSARY	380.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
			7,080.00	950.00
GRAND TOTAL			10,922.18	2,776.88
RECOMMENDED COST OF REPAIRS				2,776.88

Report Ref No. CC3/AXA14006734/Kza3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.