CC3/1M1 1902361/ Fsf352

ASSIGNMENT

* From: Date:	Veh No: SHA 3473Z Yr Regn: 22/10 / 19
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Hyundai ronia (G3) ac 1580
at Workshop m/s	Colour Blue A/C: Insured / Std / NI / NA
of	Sp.Reading 18 321 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No: -
Policy No.	C/No: 1 <mhc851cvlv186580< td=""></mhc851cvlv186580<>
Claims No.	Gen. Cond. Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering Morder Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil (S/Rim) STD A/Rim or
	Tyre Size: F: 195 (65 R15
(Policy Condition)	R: —
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal, or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 8 mm R/Bal. 9 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 8 mm L/Bal. 9 mm
Est Repairs: days Res.: Yes or No	D.O.A. 18/12/19 D.O.I. 19/102/19
Lum Sum: % 3 Val.: Yes or No	Survey held at comfortdely co (Leyang)
CA / REV / REP. / 24 HRS	Des. of Damages : Frt (Reary O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	near
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	24.12
SHA 34732 - CS3/10 17008411/ JA	
GBB 7553R-(53/5MO 17001630)	171+65x-1 (TM) (P/P) 0.013-10/11/207
adiale @ 1000 BA	1 7/2 1
20/12/19 @ 15:01 pm revind PA	40 0000 Marine V/9 ens.
P/p: \$5375.18/= with 4 mpair	der 3
confirm on \$17/1/2020 with	n LIM KNOKERS.
C\$ 1.785.68 Red - 25%	
Date/Time. File Pass to? : Prell. Report	Days Of Repair: 4
1) Typict : Final Report	Resurvey No. of Trip: Survey Fee: 250
Date/Time, File Reium Io?	Transportation:
2) Add Fed	9: :Site Insp (\$)3+R\$3(
	: Interview (\$) Photos
Fleport Format	: Tech, Invs (\$) olies
Emp 200 (18) 1 5,34518 P/P	Mesterd (8
	101/0
	William Co.

OMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

Service Advisor

umed to Service Reception upon collection.

ComfortDelGro Engineering Pte Ltd 205 Brandel Fload Singapore 579701 Mainline + 65 6363 6280 Facsimile - 65 6280 9755

24 Senoko Lopo Singapore 758156 7 Sunger Kadut Way Singapore 728791 503 Yehun Industrial Park 4 Singapore 768732 142 Page: 1

Date/Time 00 00 1903 120 20019 09:42

Team: ARC Repair TP(CLSO)1	JOB CARD	Sales Order:	JC NO.: 305368163
OMER		REGN NO.: SHA3473Z	MILEAGE
S COMFORT TRANSPORTATION OMER NO. 7010045 ESS 383 SIN MING DRIVE	ON PTE LTD	MAKE: HYUNDAI	FUEL 1/2F
SINGAPOLA SINGAPORE	575717	MODEL IONIQ(G3)	18.12.2019 16:45
(R) 65508755 (O)	7111	YR OF MANU. 22.10.2019	TARGET DATE
OUNT CARD NO.	Cokio Marin	CHASSIS CODE KMHC851CVLU18	6580 COMPLETION DATE/TIME:
Accident Date: 18.12.2019 NATURE: 3P 18.12.2019	JOB DESCRIPTION		
S/NO LABOR CODE	DESC	CRIPTION	FRONT CONTROL OF THE
		LEFT SIDE	SIGHT SOE
×		REAR	
KED & PASSED OUT BY:			
SERVICE ADVISOR		CUSTOMER	R'S SIGNATURE
edgement Slip	Exit Pass	•	
o.: SHA3473Z LKE	Vehicle No.:	SHA3473Z	

Name of Service Advisor

To be kept by Security Guard

Signature/Date

Date

Shirley Hiew (LKK Auto)

From:

Shirley Hiew (LKK Auto)

Sent: To: Friday, 20 December 2019 3:01 pm motorclaims@tokiomarine.com.sg

Cc:

SUR

Subject:

DIRECT SURVEY INSPECTION ON WORKSHOP -COMFORTDELGRO ENGINEERING PTE

LTD, DOA: 18/12/2019, SHA 3473Z (TP VEHICLE), GBB 7553R (OI VEHICLE)

Attachments:

TP GIA REPORT.pdf; ESTIMATE.pdf; PRELI ADVISE - SHA 3473Z.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHA 3473Z at M/s: COMFORTDELGRO ENGINEERING PTE LTD,59 LOYANG DRIVE SINGAPORE 508969 on 19/12/2019

Enclosed herewith a copy of TP's GIA report, estimated cost of repair and preliminary revised.

Kindly create claim in merimen for our necessary action.

"Best Wishes for Merry Christmas & Happy New Year 2020"

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 20 December 2019

Our Ref: CC3/TMI19022361/Fsf3

The Motor Claims Department
TOKIO MARINE INSURANCE SINGAPORE LTD

Dear Sir/Madam,

PRELIMINARY ADVISE REPORT OF VEHICLE NO. SHA 3473Z .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 19/12/2019 at the premises of M/s ComfortDelGro Engineering Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	7,160.86	
Revised Estimate Amount	: <u>S</u> \$	5,437.74	
"Check" Items Amount	: <u>S\$</u>		
Market Value	: <u>S</u> \$	2 4 3	
LTA Reimbursement Value	: <u>S\$</u>	-	
Nett Value	: <u>S\$</u>	-	

Description of Damage:


The vehicle sustained damages at the rear portion.

Comments/ Present Status:

Damages Consistent. Repair days: 4 days

Yours faithfully

Parasuram S/O Shanmugam Automotive Assessor



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aioresaio.		
	ACCIDENT STATEMENT	
Date Of Report	19/12/2019 08:57	
Date Of Accident	18/12/2019 16:05	
Exact Location Of Accident	BEACH RD TWDS CRAWFORD RD	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHA3473Z	
Insured/Policyholder		
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD	
Co Reg No	199303821R	
Email Address	FLEETSAFETY@CDGTAXI.COM.SG	

OFFICE-65508768

Alternative Phone No Vehicle Particulars

Mobile Phone No

Manufacturer HYUNDAI Model IONIQ

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY

NO

Vehicle Category TAXI

Insurance Company

Name of Insurance Company INDIA INTERNATIONAL INSURANCE PTE LTD

Type Of Coverage THIRD PARTY FIRE AND/OR THEFT

Fleet Policy YES

Policy Number MCOM0015

Cover Note Number

Driver

 Name of Driver
 HIA KENG CHUE

 NRIC No
 S0218149E

 Date Of Birth
 10/03/1952

 Occupation
 OUTDOOR

 Date Of Driving Pass
 18/11/2011

Driving Experience 8 YEARS AND 1 MONTH

Gender MALE

Mobile Number (LOCAL) +65-90223113

Fax Number

Contact Number

EMail Address HIAKC@GOODLINKS.COM.SG

Address

BLK 3 TANAH MERAH KECHIL ROAD #09-06

Postcode

466664

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

OTHER - TAXI DRIVER

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance.

2

Number of Passengers (Including Driver) Passenger 1

NAME:

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLS REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBB7553R

Vehicle Make/Model/Colour Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

KALIMUTHU KALAIMARAN

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

TOKIO MARINE INSURANCE SINGAPORE LTD

Nature Of Damage

FRT

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (Iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTF LTD

4 8

Policyholder's Signature
Date & Time

Driver's Chature

(If driver s not the policyholder)

Date & Time

Reporting Centre Personnel's Signature

M. 18/12

Name

NRIC/FIN No.

Sketch Plan Pg. 2

SKETCH PLAN	7	
	of the L	
SH4	Chause	
A) 3473 Z.	1	3 3
	ন্ত্ৰ	X
B) GRR FYYZR	3	
	på	

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 18 Dec 2019 @ 1605 hu .T.
VCH A CLOW down are ctop Sudde
WEH B from the Rear hot well (A
Rev @ the point of acciden
ret (ferry a nume par we
Book to a Location

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION FTE LTDY

COLUMN TO 199303821K

Policyholder's Signature

Driver's Little of the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Sil81 Mil

vame.

NRIC/FIN No.







ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive Singapore 508969 Tel: 6214 8300

TP INSURER:

Tokio Marine Insurance Singapore Ltd (HQ)

CTPL

Singapore

, RAN

	PAR	TICUL/	ARS OF	CLAIM
--	-----	--------	--------	-------

Claim Type:

THIRD PARTY

Ref. No:

18/12/2019

Policy No:

SHA3473Z

Date of Loss: Driveable?

YES

Vehicle Reg. No.: Party At Fault:

UNKNOWN

HYUNDAI IONIQ HYBRID, 1.6 GLS

Vehicle Reg. Date:

22/10/2019

Vehicle Colour:

Make/Model:

DCT (A) BLUE

Gen Condition:

GOOD

Engine No:

G4LEKU397952

Chassis No:

KMHC851CVLU186580

Odometer:

0 KM

Paint Type:

List Item Discount:

20.00 %

Total Loss?

NO

Est. Duration of Repair

(day)

5

Present Location:

COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS		Amount
Parts		5,249.86
Miscellaneous Items		11.00
Labour		1,900.00
Paintwork Labour		0.00
Towing		0.00
	Gross Total (S\$)	7,160.86
	+ GST 7.00% (S\$)	501.26
	Nett Amount (S\$)	7,662.12

This claim is handled by: LIM KWOK ENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Estimates on Miscellaneous Items

No	Qty	Particulars		Amount
<u>Mis</u> 1	cella 1	OD/TP Case (Insurer)		11.00
			Sub Total (S\$)	11.00

	stimates on Labour		
No	Particulars	Lab.Type	Amount
Lat	bour Items		
1	PANEL BEATING (\$320 1d my)	New	900.00
2	SPRAY PAINTING CHARGE	New	700.00\$60℃
3	WIRING CHARGE	New	50.00\$ 3€
4	TUFF KOTE	New	50.00 × ₩
5	REMOVE/REFIX REVERSE SENSOR	New	850 80.00
6	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00

ComfortDelGro Engineering Pte Ltd/SHA3473Z/19/12/2019 14:52. Not valid without Reference section.

Generated using Merimen e-Claims IEAS < END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting.
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis.
- . No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ram (LK&)
19/12/19 15/5/12/19
19/12/19 15/5/12/19
Pavasovan a Lkrawtorom
Pavasovan a Lkrawtorom
Pavasovan a John Photo
PIP Bert Paint photo
PIP Bert Paint photo

Gross Labour Cost (S\$)

1,900.00

Ou	ır Job R	ef No	305368163			OMFORTDELGRO ENGINEERING
Da		:_	16.01.20	- 5	5	omfortDelGro Engineering Pte L 9 Loyang Drive Singapore 5089
FI	NALIZA	TION FOR	м		F	ex: 6546 8156
To	: -		LKK		Fax	1
Att	n : M	//r	RAM			
Ve	hicle Re	g No.	SHA3473Z CT	PL		18.12.19
The	e survey	and estim	nates of the repairs of the above	e-mentioned veh	icle are as follo	ws:-
1.	The	repair job	shall bill to:	OKIO MARINE		GBB7553R
2.	The	finalized a	mount shall be:			
	(a)	Spare P	arts after List discount			\$3,664.18
	(b)	Labour	Charges	5		\$1,711.00
		Total fo	r Part-By-Part Repair Cost			\$5,375.18
	(c.)	Total for	m Repair (if applicable) Lumpsum repair cost after Le mpsum Repair cost	ss: 20	0%	
			al period for repairs:	4	working days.	
4.	We si work	hall treat t ing days	the above amount as Correctour assistance.	t and Confirmed	if there is no i	estimates and
4.	We si worki Thank	hall treat or ing days	the above amount as Correctour assistance.	t and Confirmed	if there is no in the finalized amount is signature:	estimates and
4.	We si worki Thank Signa Name	hall treat of ing days k you for you	our assistance. KWOK ENG	t and Confirmed	We confirm the finalized amour	estimates and
4.	We si worki Thank Signal Name Tel	ture: LIN	the above amount as Correctour assistance. I KWOK ENG	t and Confirmed	if there is no in the finalized amount is signature:	estimates and
4.	We si worki Thank Signa Name Tel Fax	ture: LIN 62	our assistance. KWOK ENG	t and Confirmed	We confirm the finalized amour	estimates and
4.	We si worki Thank Signa Name Tel Fax	ture: LIN	the above amount as Correctour assistance. I KWOK ENG	t and Confirmed	We confirm the finalized amour	estimates and at
4.	We si worki Thank Signa Name Tel Fax	ture: LIN 62	the above amount as Correctour assistance. I KWOK ENG	t and Confirmed	We confirm the finalized amour	estimates and at
4. 5.	We si worki Thank Signa Name Tel Fax Official I	ture: : LIN : 62 : 656 Use Only	the above amount as Correctour assistance. I KWOK ENG 148316 468156 Amount	Documen Attached	We confirm the finalized amour	Ram
4. Or (We si worki Thank Signal Name Tel Fax Official I	ture: : LIM : 62 : 654 Use Only tem	the above amount as Correctour assistance. I KWOK ENG 148316 468156 Amount	Documen Attached Yes or No	We confirm the finalized amour	Ram
or (We si worki Thank Signa Name Tel Fax Official I	ture: LIN 62 565 Use Only tem te P/Day come Paid	the above amount as Correctour assistance. I KWOK ENG 148316 468156 Amount	Documen Attached Yes or No	We confirm the finalized amour	Ram
. Ro	We si worki Thank Signa Name Tel Fax Official I	ture: LIN 62 565 Use Only tem te P/Day come Paid	1 KWOK ENG 148316 Amount \$7,49	Documen Attached Yes or No	We confirm the finalized amour	Ram

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 19 Dec 2019)

Parts:

192

HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHA3473Z/19/12/2019 14:52

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BOOTLID 00	20.00	0.00	*2,480.40 FI
2	1		*BOOTLID LOCK UPPER XMM	20.00	0.00	*224.00 FI
3	1		*BOOTLID LOCK LOWER XXX	20.00	0.00	*51.30 Ft
4	1		*BOOTLID H EMBLEM MEC	20.00	0.00	*28.00 FI
5	1		*BOOTLID EMBLEM -HYBRIDINGC	20.00	0.00	*24.30 Ft
6	1		*BOOTLID EMBLEM -IONIQ /PC	20.00	0.00	*31.30 FL
	1		*BOOTLID WINDSCREEN GLASS UPPER PEL	20.00	0.00	*607.20 FL
8	1		*BOOTLID GLASS LOWER NEC	20.00	0.00	*384.90 FL
9	1		*BOOTLID WINDSCREEN GLASS MOULDING	20.00	0.00	*28.20 FL
10	1		*REAR BUMPER X(R)	20.00	0.00	*459.40 FL
11	1		*REAR BUMPER REINFORCEMENT ×(R)	20.00	0.00	*294.80 FL
12	1		*REAR BUMPER REINFORCEMENT BRACKET LH XVV	20.00	0.00	*138.10 FL
13	1		*REAR BUMPER REINFORCEMENT BRACKET RH > N	20.00	0.00	*138.10 FL
14	1		*REAR BUMPER CENTRE MOULDING ASSYCVA	20.00	0.00	*451.25 FL
15	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY	20.00	0.00	*155.00 FL
16	1		*REAR BUMPER SIDE BRACKET LH > ~	20.00	0.00	*33.10 FL
17	1		*REAR BUMPER SIDE BRACKET RH Xn^	20.00	0.00	*33.10 FL
18	10		*REAR BUMPER COVER CLIPS Mec	20.00	0.00	*22.00 FL
19	1		*REAR PANEL X (K)	20.00	0.00	*532.00 FL
20	1		*BOOTLID COMFORT LOGO INC	0.00	0.00	*20.00 F
21	1		*BOOTLID TEL NO. STICKER (ACC	0.00	0.00	*10.00 F
22	1		*BOOTLID APPS STICKER MEG	0.00	0.00	*40.00 F
23	2		*BOOTLID WINDSCREEN GLASS SEALANTMEC	0.00	0.00	*46.00 F
24	1		*REAR NO. PLATE CHA	0.00	0.00	*25.00 F
5	1		*REAR NO. PLATE TRIN COVER CVA	0.00	0.00	*30.00 F
26	1		*REAR BUMPER REVERSE SENSOR SC	0.00	0.00	*135.70 F
7	1		*REAR BUMPER RUBBER MAT NEC	0.00	0.00	*50.00 F
=Fran	chise par	rt. L=ListItemI	Disc.	10.40-cm/m/.		
			Sub Total (S\$)			6,473.15
			- List Item Discount on L Items (S\$)			1,223.29
			Total Parts (S\$)	-		5,249.86

ComfortDelGro Engineering Pte Ltd/SHA3473Z/19/12/2019 14:52. Not valid without Reference section. Generated using Merimen e-Claims IEAS

3

4

5

6

WIRING CHARGE

REMOVE/REFIX REVERSE SENSOR

REMOVE/REFIX REAR WINDSCREEN GLASS

TUFF KOTE

Estimates on Miscellaneous Items

	aty Farticulars		Amount
<u>M</u>	iscellaneous Items		
1	1 OD/TP Case (Insurer)		
			11.00
		Sub Total (S\$)	11.00
Es	stimates on Labour		
No	Particulars	Lab Type	120000000000000000000000000000000000000
l al	pour Items	Lab.Type	Amount
1	PANEL BEATING		
2	SPRAY PAINTING CHARGE	\$1.00 New	900.00-

ComfortDelGro Engineering Pte Ltd/SHA3473Z/19/12/2019 14:52. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Ram (LKt)

19/12/19 15/5/N/5

19/12/19 15/5/N/5

Pavasovan @Lkrowtown

Pavasovan @Lkrowtown

88622718 NP

88622718 NP

Akpair days

PIP Bert Paint photo

\$600 New

430 New

Gross Labour Cost (S\$)

New

New

New

700.00\$

50.00%

50.00>

120.00 \$

\$50 80.00€

1,900.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 16.01.2020 Time: 19:31:01

Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO : 305368163
REGN NO : SHA3473Z
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 22.10.2019
DATE/TIME IN : 18.12.2019 16:45
ACCIDENT DATE : 18.12.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2270-G IONIQ EMBLEM-HYBRID 1 L 24.30 20.00 19.44 pec
0002 04-01-0104-2271-G IONIQ EMBLEM-IONIQ 1 L 31.30 20.00 25.04 NEC
0003 04-01-0104-2533-G IONIQV2 MOULDING ASSY-RR 1 L 451.25 20.00 361.00 CFA
0004 04-01-0104-2256-G IONIQVC PANEL ASSY-TAIL G 1 L 2,480.40 20.00 1,984.32 DD
0005 04-01-0104-2257-G IONIQ GLASS ASSY-TAIL GAT 1 L 384.90 20.00 307.92
0006 FNPS NO PLATE(S) WITH TRIM COV 1 N 55.00 2.00- 55.00 Crq
0007 28-01-0103-0005-A (I40/SONATA)REAR BOOT LOG 1 N 20.00 0.20 20.00 NEL
0008 28-01-0103-0006-A (I40/SONATA)REAR BOOT TEL 1 N 10.00 0.02- 10.00 vel
0009 28-01-9999-2025-A APP LOGO REAR BONNET CTPL 1 N 40.00 0.00 40.00 NEC
0010 04-01-0104-2258-G IONIQ GLASS ASSY-TAIL GAT 1 L 607.20 20.00 485.76 PC
0011 05-01-0199-0032-A (ALL)WINDSCREEN AHESIVE-3 2 N 46.00 2.00- 46.00 NEC
0012 04-01-0104-2545-G IONIQVC MOULDING-REAR BUM 1 L 155.00 20.00 124.00 QVA
0013 09-01-9999-0068-A HYUNDAI REVERSE SENSOR AS 1 N 135.70 2.00- 135.70 SC

3307.48

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 16.01.2020 Time: 19:31:01

Page: 2

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO

: 305368163

REGN NO : SHA3473Z

MILEAGE : 0000000000

MAKE : HYUNDAI

MODEL : IONIQ(G3)

DATE OF REGN : 22.10.2019

DATE/TIME IN : 18.12.2019 16.

ACCIDENT DATE : 18.12.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0014 04-01-0104-1150-A IONIQVC PROTECTOR MAT

1 N 50.00 0.20 50.00 rec

SUB-TOTAL : 3,664.18

JOB NATURE

0000 L	MERIMEN CHARGE	11.00	
0001 L	PANEL BEATING	900.00	
0002 23-502	SPRAYPAINT ON AFFECTED AREA	600.00	
0003 17-01	CHECK ALL LIGHTING	30.00	
0004 20-22	REMOVE/REFIX REVERSE SENSOR	50.00	
0005 20-20	REMOVE/REFIX RR W/SCREEN TO ASST R/P	120.00	

SUB-TOTAL : 1,711.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 16.01.2020 Time: 19:31:01

Page: 3

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

: 18.12.2019 16:4

ACCIDENT DATE : 18.12.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 5,375.18

MVA NAME & SIGNATURE

DATE:

DATE:

AUTHORISED: YES / NO SURVEYOR NAME & SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Su	bmitted	Ins Auth'ed	Status	
Main	19 Dec 2019 Sendback Est	19 Dec 2019 14:52 \$\$7,160.86	23 Dec 2019 08:58 Edit Adj Rpt	S\$5,375.18 Edit Estimat	2.4000000000000000000000000000000000000	75.18 Rpt		Pending for Su Report Cancel Case	irvey
	Main	Ref	erence	Cla	im Details		Document	s	Show All
CLAIM S	UBFOLDER DET	AILS	Interested to the second of						
Insured:	торсного	FOOD INDUST	RIES (S) PTE L	TD, Co. Reg.	No.: 200003	107W			
Main Claimant:	CTPL			2					
Vehicle Reg. SHA3473Z			Date of Loss:	[1 Month		m LTA Reg Date (M	an Yr)]		
Claim Type: TP / M1909898 Policy/Cover Note No.: MS001245 (Comprehensive) Coverage: 09/02/2019 - 08/02/2020									
Vehicle Re No. (Insured):	GBB7553R				Policy No. (Claimant):	1 1 132	30.27		
					Excess:	S\$2,500.	00		
Repairer:	ComfortDe	Gro Engineerin	g Pte Ltd (Loya	ng) 59 Loyan	g Drive, 5089	69 Loyang	- Tel: 6214 8300		
Handling Insurer:	The Carly House His						g Kwai Kay Fran		
Adjuster:	03/01/202	consultants Pte 20]	Ltd (HQ) - Tel: 6	6256-3561	[Handled by	PARASURA	AM SHANMUGAM] [Final Rpt o	lue
ASSOCIA	TED MAIL REC	EIVED					V	/iew All Compose	e Case Ma
There are	no mail for this c	ase.							
ALL ASS	OCIATED TASK	(SE				View All	Search Tasks	Create New Task	Complet
Due Da	3.75.65.55	Type Task (iroup Subje	ect Handle	er Assigi	ned By	Completed On	Created On	Done

Claim Documents

SHA3473Z (M1909898)

[GBB7553R]

TP

CTPL

Dec 18 2019 12:00AM

[TOPCHOICE FOOD INDUSTRIES (S) PTE LTD]

ComfortDelGro Engineering Pte Ltd

Up	load Documents Uplo	ad Photos Compose New Letter	View	View in Brow	ser 🔻
Ass	essment Reports	ALCO SECULIAR STATE OF THE SECULIAR SECU	1 per	The state of the s	•
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	19/12/19 14:52	Repairer Estimates	0	Load HTM	_
Pho	otos/Images		3 per	page ▼	•
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/01/20 16:13	General View	0	Load JPG	•
2	20/01/20 16:13	General View	0	Load JPG	
3	20/01/20 16:13	General View	0	Load JPG	•
4	20/01/20 16:13	General View	0	Load JPG	
5	20/01/20 16:13	General View	0	Load JPG	•
6	20/01/20 16:13	General View	0	Load JPG	•
7	20/01/20 16:13	General View	0	Load JPG	•
8	20/01/20 16:13	General View	0	Load JPG	•
9	20/01/20 16:13	General View	0	Load JPG	€
10	20/01/20 16:13	General View	0	Load JPG	•
11	20/01/20 16:13	General View	0	Load JPG	•
12	20/01/20 16:13	General View	0	Load JPG	•
13	20/01/20 16:13	General View	0	Load JPG	•
14	20/01/20 16:13	General View	0	Load JPG	•
15	20/01/20 16:13	General View	0	Load JPG	•
16	20/01/20 16:13	General View	0	Load JPG	•
17	20/01/20 16:13	General View	0	Load JPG	•
18	20/01/20 16:13	General View	0	Load JPG	•
19	20/01/20 16:13	General View	0	Load JPG	•
20	20/01/20 16:13	General View	0	Load JPG	•
21	20/01/20 16:13	General View	0	Load JPG	
22	20/01/20 16:13	General View	0	Load JPG	
23	20/01/20 16:13	General View	0	Load JPG	✓
24	20/01/20 16:13	General View	0	Load JPG	€
25	20/01/20 16:13	General View	0	Load JPG	•
26	20/01/20 16:13	General View	0	Load JPG	€
27	20/01/20 16:13	General View	0	Load JPG	•
28	20/01/20 16:13	General View	0	Load JPG	Ø
29	20/01/20 16:13	General View	0	Load JPG	✓
30	20/01/20 16:13	General View	0	Load JPG	Ø
31	20/01/20 16:13	General View	0	Load JPG	•
32	20/01/20 16:13	General View	0	Load JPG	•

Asse	essment Reports		1 per	1 per page 🔻	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	
33	20/01/20 16:13	General View	0	Load JPG	•
34	20/01/20 16:13	General View	0	Load JPG	•
35	20/01/20 16:13	General View	0	Load JPG	•
36	20/01/20 16:14	General View	0	Load JPG	2
		\$3550 S0000 V 30000	0	Load JPG	•
37	20/01/20 16:14	General View	0	Load JPG	•
38	20/01/20 16:14	General View	o	Load JPG	•
39	20/01/20 16:14	General View		(-) (1) (1) (1) (1) (1) (1) (1) (1) (1) (1	
40	20/01/20 16:14	General View	0	Load JPG	•
41	20/01/20 16:14	General View	0	Load JPG	•
42	20/01/20 16:14	General View	0	Load JPG	•
43	20/01/20 16:14	General View	0	Load JPG	•
44	20/01/20 16:14	General View	0	Load JPG	•
45	20/01/20 16:14	General View	0	Load JPG	•
	20/01/20 16:14	General View	0	Load JPG	•
46		General View	0	Load JPG	•
47	20/01/20 16:14	Security Control of the Control of Control o	0	Load JPG	•
48	20/01/20 16:14	General View	0	Load JPG	•
49	20/01/20 16:14	General View	0	Load JPG	•
50	20/01/20 16:14	General View			•
51	20/01/20 16:14	General View	0	Load JPG	-
52	20/01/20 16:14	Reinspection Photo	0	Load JPG	•
53	20/01/20 16:14	Reinspection Photo	0	Load JPG	•
54	20/01/20 16:14	Reinspection Photo	0	Load JPG	•
55	20/01/20 16:14	Reinspection Photo	0	Load JPG	•
56	20/01/20 16:14	Reinspection Photo	0	Load JPG	•
57	20/01/20 16:14	Reinspection Photo	0	Load JPG	•
58	20/01/20 16:14	Photo After Spray	0	Load JPG	•
59	20/01/20 16:14	Photo After Spray	0	Load JPG	•
60	20/01/20 16:14	Photo After Spray	0	Load JPG	•
61	20/01/20 16:14	Photo After Spray	0	Load JPG	•
01	20/01/20 10:14	Priorio Arter Spray			
Do	cumentation		1 pe	r page 🔻	•
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)		Thumbnail	Prin
1	22/01/20 12:10	LOD, Invoice, LOR, Mileage Record, LA, LTA Search Fee	0	Load PDF	-
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Prin
1	19/12/19 14:54	E-filed GIA report	0		
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ) 19.12.2019 - EMAIL AGENT NON REPORTING	0	Load PDF	Prin

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Repairer Handling Insurer	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/TMI19022361/FSF3S2

Date:

23/01/2020

REFERENCE

Handling Insurer:

Tokio Marine Insurance Singapore Ltd

Policy No:

MS001245

Claimant Vehicle No:

SHA3473Z

Insured Vehicle No:

GBB7553R

Date of Loss:

18/12/2019

Nature of Claim:

TP

M1909898 Claim No:

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHA3473Z

Make & Model:

HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)

Engine No:

G4LEKU397952

Reg. Date:

22/10/2019 (Man. Year: 2019)

Chassis No:

KMHC851CVLU186580

Colour: Engine Capacity:

Sum Insured (S\$):

Blue 1580 cc Odometer:

18321 km

Market Value/New Car Price:

N/A

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Good Yes

Steering (Serviceable): Engine Modification:

No

Footbrake (Serviceable): Pre-accident Condition:

Yes Good

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

195/65R15

Rear Tyre Size:

195/65R15

Front Left Side:

Michelin 8 mm Michelin 8 mm Rear Left Side: Rear Right Side: Michelin 9 mm Michelin 9 mm

Front Right Side: The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,249.86	3,664.18	1,585.68	30.20
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,900.00	1,700.00	200.00	10.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,160.86	5,375.18	1,785.68	24.94
+ GST 7.00/7.00% (S\$)	501.26	376.26	125.00	24.94
Nett Amount (S\$)	7,662.12	5,751.44	1,910.68	24.94

INSPECTION

Date of Assignment:

23/12/2019

Present Location:

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang) ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected:

19/12/2019

59 Loyang Drive

Singapore 508969

Estimated Period of Repair:

4.0 days

Adjuster: PARASURAM SHANMUGAM Manager:

Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Validity:

REPAIR DETAILS

Reference

Version: 1.0 (Last Synchronised: 23 Jan 2020) Part Source: MRM-SG

HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0) 192 Parts:

(Price-denominated Standard List) Repairer's Labour:

Print Code: (Unsubmitted, no print-code for SHA3473Z) These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

			ed Parts Particulars	Condition	Repairer's	Reference	Amount
300	55.50		*BOOTLID	Dented	2,480.40 FL	2 5	*2,480.40 FL
1	1		*BOOTLID LOCK UPPER	Not Necessary	224.00 FL	8 5	*-FL
2	1		*BOOTLID LOCK LOWER	Not Necessary	51,30 FL		*-Fl
3 4	1		*BOOTLID H EMBLEM	Not Necessary	28.00 FL		*- Fl
-	1		*BOOTLID EMBLEM -HYBRID	Necessary	24.30 FL	2	*24.30 FL
5 6	1		*BOOTLID EMBLEM -IONIQ	Necessary	31.30 FL	-	*31.30 FL
-	1		*BOOTLID WINDSCREEN GLASS UPPER	Necessary	607.20 FL		*607.20 FI
7	1		*BOOTLID GLASS LOWER	Necessary	384.90 FL		*384.90 FI
8			*BOOTLID WINDSCREEN GLASS MOULDING	Not Necessary	28.20 FL		*- FI
9	1		*REAR BUMPER	Repair	459.40 FL		*- FI
			*REAR BUMPER REINFORCEMENT	Repair	294.80 FL	-	*-FI
11	1		*REAR BUMPER REINFORCEMENT BRACKET LH	Not Necessary	138.10 FL	=	*-F
12	1		*REAR BUMPER REINFORCEMENT BRACKET RH	Not Necessary	138.10 FL		*-F
13	1		*REAR BUMPER CENTRE MOULDING ASSY	Cracked	451.25 FL		*451.25 F
14			*REAR BUMPER LOWER CENTRE MOULDING ASSY	Cracked	155.00 FL	-	*155.00 F
15	1		*REAR BUMPER SIDE BRACKET LH	Not Necessary	33.10 FL		*-F
16	- 27		*REAR BUMPER SIDE BRACKET RH	Not Necessary	33.10 FL		*-F
17	1		*REAR BUMPER COVER CLIPS	Not Necessary	22.00 FL		*-F
18	10		*REAR PANEL	Repair	532.00 FL	141	*-F
19	1		*BOOTLID COMFORT LOGO	Necessary	20.00 F		*20.00 F
20	1		*BOOTLID TEL NO. STICKER	Necessary	10.00 F		*10.00 F
21	1		*BOOTLID APPS STICKER	Necessary	40.00 F	-	*40.00 F
22	1		*BOOTLID WINDSCREEN GLASS SEALANT	Necessary	46.00 F	(+)	*46.00 F
23	2		*REAR NO. PLATE	Cracked	25.00 F	(a n)	*25.00 F
24	1		*REAR NO. PLATE TRIN COVER	Cracked	30.00 F	-	*30.00 F
25	1		*REAR BUMPER REVERSE SENSOR	Short Circuit	135.70 F	-	*135.70 F
26	1			Necessary	50.00 F	323	*50.00 F
27	1	se part. L=Lis	*REAR BUMPER RUBBER MAT	1.000000.j			
F=FI	ranchis	se part. L=Lis	memorac.	Sub Total (S\$	6,473.15	4,491.05	
			- List Item Discount on L Items 2	0.00/20.00% (S\$	1,223.29	826.87	
				Total Parts (S\$	5,249.86		3,664.18

Report was unsubmitted during this print-out.

	mmended Miscellaneous Items y Particulars		Repairer's	Amount
Miscella	oneous Items OD/TP Case (Insurer)		11.00	11.00
	400 KDH 1 - 1 MIN 400 KDH 1 MIN 1 MI	Sub Total (S\$)	11.00	11.00

No	commended Labour Particulars	Lab.Type	Repairer's	Amount
Lab	our Items		909020	000.00
1	PANEL BEATING	New	900.00	900.00
2	SPRAY PAINTING CHARGE	New	700.00	600.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	50.00	0.00
5	REMOVE/REFIX REVERSE SENSOR	New	80.00	50.00
6	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
		Gross Labour Cost (S\$)	1,900.00	1,700.00

< END OF ESTIMATES >