

CVR Accident Photos





VEHICLE DETAIL

Vehicle No	PC3362E	Date Of accident	
Date Booked In		Date of Submission	


REPAIR DESCRIPTIONS

1. Remove LHS Door Pillar (Pic 1-4)
2. Remove LHS Sliding Door (Pic 5-9)
3. Remove LHS Sliding Door Accessories (eg: Window Glass, Outer & Inner Door Lock & Door Handle, Central Locking etc.)
4. Remove Front LH Rim (Pic 11)
5. Remove Rear RH Rim (Pic 14)
6. Replace LHS Door Pillar (Pic 1-4)
7. Replace LHS Sliding Door (Pic 5-9)
8. Re-Install LHS Sliding Door Accessories (eg: Window Glass, Outer & Inner Door Lock & Door Handle, Central Locking etc.) onto new Sliding Door
9. Replace Front LH Rim Cover (Pic 10)
10. Replace Front LH Rim (Pic 11)
11. Replace Rear RH Rim (Pic 14)
12. Replace Front LH Mud Guard (Pic 15)
13. Panel Beating for Rear RH Body Panel (Pic 12-13)
14. Putty & Spray Paint for LHS Door Pillar (Pic 1-4)
15. Putty & Spray Paint for LHS Sliding Door (Pic 5-9)
16. Putty & Spray Paint for Rear RH Body Panel (Pic 12-13)

PHOTOS OF DAMAGED PARTS

LHS Door Pillar Dented (Pic 1)	LHS Door Pillar Dented (Pic 2)
	
LHS Door Pillar Dented (Pic 3)	LHS Door Pillar Dented (Pic 4)
	
LHS Sliding Door Dented & Scratched (Pic 5)	LHS Sliding Door Dented (Pic 6)

CVR Accident Photos

	
LHS Sliding Door Dented (Pic 7)	LHS Sliding Door Dented (Pic 8)
	
LHS Sliding Door Dented (Pic 9)	Front LH Rim Cover Missing (Pic 10)
	
Front LH Rim Dented (Pic 11)	Rear RH Body Panel Dented & Scratched (Pic 12)
	
Rear RH Body Panel Dented & Scratched (Pic 13)	Rear RH Rim Dented (Pic 14)
	
Front LH Mud Guard Missing (Pic 15)	Odometer Reading (Pic 16)
	
PC3362E (Pic 17)	
	