

INS. CASE OWNER: **Meenachi**

CC4/III19022366/Upa3

LKK:
IDAC:

ASSIGNMENT

Surveyor: **MARCUS**

DOI: **26/12/2019**

Date / Time: **19/12/2019**

Registered in Merimen: **/12/2019**

Pre-assign / CCU / FTE



Insured Vehicle No.: **GBH 8719S**
Name of Insured: **PAN PACIFIC VAN & TRUCK LEASING PTE LTD**
Insured Tel No.: _____ HP: _____
Excess Sec II :SS _____ D.O.A: **15/12/2019**

Claim No.: **MFL2019D0001641** ×
Policy No.: **D19MFL0005549**
Make / Model: **NISSAN NV200-1.6 DX (A)**
Place of Accident: **JLN BENAAN KAPAL TWDS STADIUM WAY (OPP NO 28)**

Is driver the owner? (YES / ☒ NO) Nature of Accident: _____

If NO, Driver Name / Age: **VEERAPPAN**
Driver Tel No.: **+65-92310932** (V/L: YES / NO)

OI GIA REPORT: ☒ YES / NO : TP GIA REPORT: ☒ YES / NO
Insured Liability: % **Final ? Yes / No**

GBC 7944R



INSRS:
WSP: **CAR CITY**
Tel: **AUTO**
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

URGENT

Date/ Time		STAGE	DATE / PIC
	GBC 7944R - CS/CTI19008306/Uqd3n2; DOA: 04.05.19	Non-Reporting ltr (1st):	
	- CS/CTI19011680/R1td3n2; DOA: 13/06/19	Non-Reporting ltr (2nd):	
	GBH 8719S - X	Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	
		Documentation Check List: Handler	Typist
		Notification ltr (if non-pickup)	<input type="checkbox"/>
		After call ltr to OI:	<input type="checkbox"/>
		Authorisation To Act:	<input checked="" type="checkbox"/>
		Release Voucher:	<input checked="" type="checkbox"/>
		Final Repair Bill:	<input checked="" type="checkbox"/>
		Car Rental Invoice:	<input type="checkbox"/>
		Towing Invoice:	<input type="checkbox"/>
		LTA / GIA:	<input checked="" type="checkbox"/>
		Medical Bill:	<input type="checkbox"/>
		PIR:	<input type="checkbox"/>
		Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
		LOI:	<input type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/>
		Post-Repair Photos:	<input type="checkbox"/>
		Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____

Repair Cost: S\$ _____ (days) Reduction: % _____ Email ☐ Call ☐

FINAL SETTLEMENT Date/Time: **18/1/2020** Confirm with: **Mr FHJ** Email ☒ Call ☐

Final Liability: % _____ (Agreed / Assessed) BOLA S/N No.: **14**

Repair Cost: **W/GP** S\$ **7597.00**

Loss of Rental (LOR): S\$ _____ (days)

Loss of Use (LOU): S\$ **600.00** (**5** x **6** days)

Loss of Income (LOI): S\$ _____ (**5** x _____ days)

LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search: S\$ **7.45**

Medical: S\$ _____

Disbursement: S\$ _____ (e.g. Tow/ Independent)

Legal Cost: S\$ _____

Total: S\$ **8204.45** Global Sum S\$: **8200.00**

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email ☒ Call ☐

Payee 1: S\$ **8200.00** Name 1: **Car City Auto Centre Pte Ltd.**

Payee 2: (Strike if N.A.) S\$ _____ Name 2: _____

Payee 3: (Strike if N.A.) S\$ _____ Name 3: _____

COPY SENT

1) Claim status: Normal/Reject/Private Settle
2) Report Format: **7P**
3) Survey fee: **600.00**

08/11/13) • waf

ASS. REC. BY: Marcus

REF:

(19/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

20

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

2yrs 10mth freezer lorry.

21/1/20 Confirmed H/S #7100 with MR Ho.

(Recd 580713/454)

Veh No: GBC 7944R Yr Regn: 10/13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (m/

Make:

Toyota Dyna

C.C. 2982

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

279477

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFAT35Y70K202597

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195-215-

R:

155-R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

GST

Front

Rear

R/Bal.

6

mm

R/Bal.

6/6

mm

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

15/12/19

D.O.I.

26/12/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

frt n/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) \$ + RS \$

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL



CAR CITY AUTO CENTRE PTE LTD

Car City Always

Blk 9006 Tampines st93 #01-198 S'pore 528840

TEL: 6781 0300

FAX: 6782 0300

Get Price 2007199500

E-mail: ccacpl@singnet.com.sg

TO: INDIA INTERNATIONAL INSURANCE

ATTN: MOTOR CLAIMS DEPT

ESTIMATE REPORT

OWNER'S PARTICULAR

NAME:

ADDRESS:

CONTACT NO H/P:

TEL:

OWNERS INSURER: CHINA TAIPIING INSURANCE

POLICY NO: MMCVSN3073741902

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Approved by Repairer
Signature:
Date:

QUOTATION SUMMARY

CLAIM DETAIL: PARTS

not attached 1 OF 4
2/5 \$7100/-
6 by
26/12/19
Whaphc. Affluence

DATE: 26-Dec-19

JOB TYPE: 3RD PARTY CLAIM

VEH NO: GBC7944R

MODEL: TOYOTA / DYNA
150 MANUAL

CHASSIS NO: JTFAT35Y70K202

ENGINE NO:

ACCIDENT DATE: 15/12/2019

REQUESTOR CONTACT:

HO / 67810300

S/NO	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Get ✓</i>	1	396.20	396.20
2	FRONT HEADLAMP ASSY <i>1/5 cre ✓</i>	1	623.30	623.30
3	FRONT GRILLE <i>cre ✓</i>	1	510.30	510.30
4	FRONT GRILLE GARNISH CLIP <i>rec ✓</i>	6	4.90	29.40
5	FRONT PANEL <i>3 dy ✓</i>	1	1229.70	1229.70
6	FRONT PANEL LOGO <i>rec ✓</i>	1	69.27	69.27
7	FRONT PANEL EMBLEM " DYNA " <i>rec ✓</i>	1	64.70	64.70
8	FRONT SIDE PANEL <i>1/5 m ✓</i>	1	282.20	282.20
9	FRONT GARNISH CENTRE <i>garn ✓</i>	1	368.50	368.50
10	FRONT SIDE GARNISH LH <i>cre ✓</i>	1	153.95	153.95
11	FRONT TOP PANEL <i>do ✓</i>	1	347.70	347.70
12	FRONT TOP PANEL MOULDING <i>17 X ✓</i>	1	86.80	86.80
13	FRONT SIDE TOP PANEL <i>cre ✓</i>	2	180.00	360.00
14	FRONT SIDE MIRROR LH <i>SUC X</i>	1	478.70	478.70

1491120

15	FRONT SIDE MIRROR LH (ROUND)	11X	1	160.00	160.00	X
16	FRONT SIDE MIRROR STAND LH	BU ✓ 289.20	1	289.20	289.20	✓
17	FRONT SIDE MIRROR STAND LH BRACKET	complete X	1			✓
18	FRONT WINDSCREEN RUBBER	7m1 ✓	1	303.70	303.70	✓
19	FRONT INNER PANEL	12X	1	188.75	188.75	X
20	FRONT DOOR FRAME OUTER FRT	12X	2	426.75	426.75	X
21	FRONT DOOR FRAME LH OUTER RR	12X	1	621.75	621.75	X
22	FRONT DOOR FRAME CENTER FRT	11X	2	363.75	363.75	X
23	FRONT DOOR FRAME INNER FRT	12X	2	414.70	414.70	X
24	FRONT DOOR FRAME TOP INNER	12X	2	269.75	269.75	X
25	FRONT DOOR FRAME LH INNER RR	12X	1	298.75	298.75	X
26	FRONT DOOR FRAME WEATHER STRIP	12X	2	145.80	145.80	X
27	FRONT DOOR PILLAR TRIM LH	11X	1	137.42	137.42	X
28	FRONT DOOR LH	BU ✓	1	1649.70	1649.70	✓
29	FRONT DOOR HINGE LH	11X	2	79.25	79.25	X
30	FRONT DOOR CHECKER LH	12X	1	131.75	131.75	X
31	FRONT DOOR WEATHER STRIP LH	12X	1	195.40	195.40	X
32	FRONT DOOR GLASS OUTER RUBBER STRIP LH	12X	1	157.44	157.44	X
33	FRONT DOOR TRIM BOARD LH	12X	1	721.40	721.40	X
34	FRONT STEP PANEL	SPRINKLE H ✓	1	348.50	348.50	✓
35	FRONT Wiper Nozzles + Linkage	12X ✓	1	389.70	389.70	✓
36	FRONT Wiper Nozzles + Linkage	12X	1			
37			1			

PARTS PRICE :

LESS 25%

SUB TOTAL PRICE :

11,802.47 7411.52
 - 2974.04 -1852.88
 8828.12 5558.64

Supplement

- 1 Condenser fan assy
- 2 Condenser Assy
- 3 Bracket condenser

complete.

LIST PRICE

DISK 1082.95 ✓

1082.95
 LESS 25% - 270.74
 812.21

7416.02
 4488.57
 6374.2
 4538.2
 7151

S/NO	DESCRIPTION	QTY	UNIT S/Nett PRICE	TOTAL S/Nett PRICE
1	FRONT BUMPER NUMBER PLATE <i>304 15</i>	1	\$35.00	\$35.00 <i>15</i>
2	WINDSCREEN GLASS SEALANT <i>11 X</i>	2	\$35.00	\$70.00 <i>X</i>
3	LH DOOR STICKER <i>121 ✓</i>	1	\$30.00	\$30.00

S/N PARTS PRICE :

\$135.00 *45*

TOTAL PARTS PRICE :

No	CLAIM DETAIL : LABOURS & SPRAY PAINTING			
	JOBS DESCRIPTION	PRICE	REVISED PRICE	APPR.
1	TO REMOVE & REFIT AFFECTED PARTS; PANEL BEATING ON DAMAGED AREAS, CUT, WELD, KNOCK STRAIGHTEN, REALIGN & RESHAPE. FRONT PANEL OUTER & INNER, FRONT BUMPER, FRONT SUPPORT PANEL, FRONT HEADLAMP RH & LH, FRONT DOOR LH, DOOR FRAME, FLOOR PANEL & OTHER.	\$1,400.00	<i>1000</i>	
2	TO PUTTY, CLEANING, SANDING, POLISHING, WAXING & SPRAY PAINT ON ALL NECESSARY PARTS AND AREAS. FRONT BUMPER, FRONT PANEL, FRONT SUPPORT PANEL, FRONT DOOR LH, DOOR PILLAR LH, FLOOR PANELETC.	\$1,500.00	<i>1000</i>	
3	CHECK WIRING	\$80.00	<i>20</i>	
4	TO REMOVE & REFIT FRONT DOOR LH. DOOR GLASS, DOOR GLASS MOTOR, REGULATOR, DOOR CHANNEL, DOOR LOCK INNER & OUTER, DOOR HANDLE INNER & OUTER.....ETC.	\$150.00	<i>60</i>	
5	TO REMOVE & REFIT FRONT WINDSCREEN GLASS FOR ALL NECESSARY REPAIRS.	\$120.00	<i>80</i>	
6	TO REMOVE & VACUUM AIR-CON SYSTEM & CHARGE UP AIR-CON GAS.	\$150.00	<i>100</i>	
7	TO REMOVE & REFIT INTERIOR SEAT & TRIM BOARD, ROOF LINING, CARPET & OTHER FOR NECESSARY REPAIR WORK.	\$200.00	<i>60</i>	
8	TO REMOVE & REFIT DASHBOARD ASSEMBLY.	\$250.00	<i>200</i>	
9				
		\$3,850.00	<i>2520 ✓</i>	

VEHICLE NO : GBC7944R

ESTIMATE REPORT

TOTAL LABOUR COST : \$3,850.00 ✓

TOTAL PARTS COST : *9057 13*

TOTAL REPAIR COST :

\$12,907 13 .

4 OF 4

APPROVAL DETAILS

EXCESS :

NO. OF DAY :

RE-SURVEY :

SURVEY BY :

CONTACT NO :

FAX NO. :

NOTE :

LUMP-SUM AMOUNT OR COST OF REPAIR WOULD BE
REVISED IF SUPPLEMENT REPAIR IS REQUIRED



CAR CITY AUTO CENTRE PTE LTD

Car City Always

Blk 9006 Tampines st93 #01-198 S'pore 528840

TEL: 6781 0300

FAX: 6782 0300

612 2/3 2007199502

E-mail: ccacpl@singnet.com.sg

TO: INDIA INTERNATIONAL INSURANCE

ATTN: MOTOR CLAIMS DEPT

ESTIMATE REPORT

OWNER'S PARTICULAR

NAME:


ADDRESS:

CONTACT NO H/P:

TEL:

OWNERS INSURER : CHINA TAIPING INSURANCE

POLICY NO: MMCVSN3073741902



not attached
1 OF 4
2/5
6/12/19
26/12/19
Whp. Aff. 14/19

DATE : 26-Dec-19

JOB TYPE : 3RD PARTY CLAIM

VEH NO : GBC7944R

MODEL : TOYOTA / DYNA
150 MANUAL

CHASSIS NO : JTFAT35Y70K202!

ENGINE NO:

ACCIDENT DATE : 15/12/2019

QUOTATION SUMMARY

CLAIM DETAIL: PARTS

REQUESTOR CONTACT :

HO / 67810300

S/NO	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Best ✓</i>	1	\$386.17	\$386.17
2	FRONT HEADLAMP ASSY <i>1/2 one 17C</i>	1	\$577.50	\$577.50
3	FRONT GRILLE <i>one ✓</i>	1	\$363.17	\$363.17
4	FRONT GRILLE GARNISH CLIP <i>new ✓</i>	6	\$4.90	\$29.40
5	FRONT PANEL <i>body ID ✓</i>	1	\$835.50	\$835.50
6	FRONT PANEL LOGO <i>new ✓</i>	1	\$65.00	\$65.00
7	FRONT PANEL EMBLEM " DYNA " <i>new ✓</i>	1	\$54.19	\$54.19
8	FRONT SIDE PANEL <i>1/2 ID</i>	1	\$299.55	\$299.55
9	FRONT GARNISH CENTRE <i>garnish ✓</i>	1	\$-	\$-
10	FRONT SIDE GARNISH LH <i>one ✓</i>	1	\$-	\$-
11	FRONT TOP PANEL <i>DD ✓</i>	1	\$-	\$-
12	FRONT TOP PANEL MOULDING <i>fasten up ?</i>	1	\$85.00	\$85.00
13	FRONT SIDE TOP PANEL <i>one ✓</i>	2	\$-	\$-
14	FRONT SIDE MIRROR LH <i>?</i>	1	\$-	\$-

15	FRONT SIDE MIRROR LH (ROUND)	11 X	1	\$-	\$-
16	FRONT SIDE MIRROR STAND LH	bu ✓	1	\$-	\$-
17	FRONT SIDE MIRROR STAND LH BRACKET	complete X	1	\$-	\$-
18	FRONT WINDSCREEN RUBBER	1 unit ✓	1	\$190.00	\$190.00
19	FRONT INNER PANEL	12 X	1		
20	FRONT DOOR FRAME OUTER FRT	12 X	2	\$-	\$-
21	FRONT DOOR FRAME LH OUTER RR	12 X	1	\$-	\$-
22	FRONT DOOR FRAME CENTER FRT	11 X	2	\$-	\$-
23	FRONT DOOR FRAME INNER FRT	12 X	2	\$-	\$-
24	FRONT DOOR FRAME TOP INNER	12 X	2	\$-	\$-
25	FRONT DOOR FRAME LH INNER RR	?	1	\$-	\$-
26	FRONT DOOR FRAME WEATHER STRIP	?	2	\$-	\$-
27	FRONT DOOR PILLAR TRIM LH	11 X	1	\$-	\$-
28	FRONT DOOR LH	bu ✓	1	\$1,110.20	\$1,110.20
29	FRONT DOOR HINGE LH	?	2	\$-	\$-
30	FRONT DOOR CHECKER LH	?	1	\$-	\$-
31	FRONT DOOR WEATHER STRIP LH	?	1	\$-	\$-
32	FRONT DOOR GLASS OUTER RUBBER STRIP LH	?	1	\$-	\$-
33	FRONT DOOR TRIM BOARD LH	?	1	\$-	\$-
34	FRONT STEP PANEL LH	?	1	\$428.50	\$428.50
35	Front Wiper Nozzle + Linkage	?	1	\$-	\$-
36	Air-con Not working (include 14 box)	?	1	\$-	\$-
37			1	\$-	\$-

PARTS PRICE :

\$4,424.18

LESS 25%

SUB TOTAL PRICE :

S/NO	DESCRIPTION	QTY	UNIT S/Nett PRICE	TOTAL S/Nett PRICE
1	FRONT BUMPER NUMBER PLATE <i>304 15'</i>	1	\$35.00	\$35.00
2	WINDSCREEN GLASS SEALANT <i>11 X</i>	2	\$35.00	\$70.00
3	LH DOOR STICKER <i>121 ✓</i>	1	\$30.00	\$30.00
S/N PARTS PRICE :			\$135.00	
TOTAL PARTS PRICE :				

No	CLAIM DETAIL : LABOURS & SPRAY PAINTING			
	JOBS DESCRIPTION	PRICE	REVISED PRICE	APPR.
1	TO REMOVE & REFIT AFFECTED PARTS; PANEL BEATING ON DAMAGED AREAS, CUT, WELD, KNOCK STRAIGHTEN, REALIGN & RESHAPE. FRONT PANEL OUTER & INNER, FRONT BUMPER, FRONT SUPPORT PANEL, FRONT HEADLAMP RH & LH, FRONT DOOR LH, DOOR FRAME, FLOOR PANEL & OTHER.	\$1,400.00	<i>1000</i>	
2	TO PUTTY, CLEANING, SANDING, POLISHING, WAXING & SPRAY PAINT ON ALL NECESSARY PARTS AND AREAS. FRONT BUMPER, FRONT PANEL, FRONT SUPPORT PANEL, FRONT DOOR LH, DOOR PILLAR LH, FLOOR PANELETC.	\$1,500.00	<i>1000</i>	
3	CHECK WIRING	\$80.00	<i>20</i>	
4	TO REMOVE & REFIT FRONT DOOR LH. DOOR GLASS, DOOR GLASS MOTOR, REGULATOR, DOOR CHANNEL, DOOR LOCK INNER & OUTER, DOOR HANDLE INNER & OUTER.....ETC.	\$150.00	<i>60</i>	
5	TO REMOVE & REFIT FRONT WINDSCREEN GLASS FOR ALL NECESSARY REPAIRS.	\$120.00	<i>80</i>	
6	TO REMOVE & VACUUM AIR-CON SYSTEM & CHARGE UP AIR-CON GAS.	\$150.00	<i>100</i>	
7	TO REMOVE & REFIT INTERIOR SEAT & TRIM BOARD, ROOF LINNING, CARPET & OTHER FOR NECESSARY REPAIR WORK.	\$200.00	<i>60</i>	
8	TO REMOVE & REFIT DASHBOARD ASSEMBLY.	\$250.00	<i>200</i>	
9				
		\$3,850.00		

VEHICLE NO : GBC7944R

ESTIMATE REPORT

TOTAL LABOUR COST : \$3,850.00

TOTAL PARTS COST :

TOTAL REPAIR COST :

APPROVAL DETAILS

EXCESS :

NO. OF DAY :

RE-SURVEY :

SURVEY BY :

CONTACT NO :

FAX NO. :

NOTE :

**LUMP-SUM AMOUNT OR COST OF REPAIR WOULD BE
REVISED IF SUPPLEMENT REPAIR IS REQUIRED**

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

For

We're big on certified pre-owned cars.

Da
Used

toyota dyna

Price Range

Depreciation

2013

Vehicle Type



Home » Used Cars » QiFei Auto Pte Ltd » Toyota Dyna 150 3.0M

Toyota Dyna 150 3.0M

Overview

Financial

Accessories

Similar

Research

Photos

Map



Making the Difference

Price	\$33,800	Lifespan	07-Jul-2033
Depreciation ⓘ	\$9,580 /yr View models with similar depre	Reg Date	08-Jul-2013 (3yrs 6mths 10days COE left)
Mileage	N.A.	Manufactured ⓘ	2013
Road Tax ⓘ	N.A.	Transmission	Manual
Dereg Value ⓘ	\$20,075 as of today (change)	OMV ⓘ	\$24,970
COE ⓘ	\$56,889	ARF ⓘ	\$1,249
Engine Cap	2,982 cc	No. of Owners ⓘ	1
Curb Weight ⓘ	1,760 kg		
Type of Vehicle	Truck		

Features

View specs of the Toyota Dyna 150 (2014)

Description

Superb Condition 10FT Lorry With Canopy. New Paint Job Done, Wear And Tear All Done Up. 100% LOAN Available, High Trade In Guaranteed. 6 Months Warranty. See To Believe, Call For More Information.

Category

Premium Ad Car

Status


Available

Ref

Compare

https://www.sgcarmart.com/used_cars/info.php?ID=826631&DL=3492


Price Chart



Click on the point to view the vehi

Shortlist

Compare

Report Error

More Acti

Seller Information

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	189N

Vehicle Details

Vehicle No.:	GBC7944R
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 MANUAL
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	1KD2333516
Chassis No.:	JTFAT35Y70K202597
Maximum Power Output:	-
Open Market Value:	\$24,970.00
Original Registration Date:	25 Oct 2013
First Registration Date:	25 Oct 2013
Transfer Count:	0
Actual ARF Paid:	\$1,249.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	24 Oct 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$76,001.00
COE Rebate Amount:	\$29,054.00
Total Rebate Amount:	\$29,054.00

The information contained herein is correct as at 27 Dec 2019

OK

20366/P
Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Thursday, 19 December 2019 11:41 AM
To: ccacpl@singnet.com.sg; 'sur@lkkauto.com'; Nivitha (LKK Auto)
Cc: C Meenachi - III
Subject: RE: NOTICE OF ACCIDENT: 3RD PARTY CLAIM: GBC7944R AGAINST YOUR INSURED GBH8719S (Pan pac) POLICY DOA: 15/12/2019
Attachments: GBC7944RSAS.PDF

Dear Sir / Mdm,

Please conduct a survey on TP vehicle GBC7944R and let us have your report urgently.

This claim will be handled by Ms Meena.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee

p. Severe
T: 11:50 AM 19.12.19
v: Out
E: ✓



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: ccacpl@singnet.com.sg [mailto:ccacpl@singnet.com.sg]
Sent: 19 December, 2019 10:45 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: RE: NOTICE OF ACCIDENT: 3RD PARTY CLAIM: GBC7944R AGAINST YOUR INSURED GBH8719S (Pan pac) POLICY DOA: 15/12/2019

Dear Mr Gabriel,

We select LKK.

Can you please help to check is this a Direct Settlement with liability in favour of our customer?

Regards,

Ho Too Boon
CAR CITY AUTO CENTRE PTE LTD
TEL: 67810300 FAX: 67820300
EMAIL: ccacpl@singnet.com.sg

On Thu Dec 19 2019 08:56:36 GMT+0800 (Singapore Standard Time) Motor Claim - III

<motorclaim@iii.com.sg> wrote:

----- Original Message -----

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From:

ccacpl@singnet.com.sg [mailto:ccacpl@singnet.com.sg]

Sent: 18 December, 2019 5:33 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: NOTICE OF ACCIDENT: 3RD PARTY CLAIM: GBC7944R AGAINST YOUR INSURED GBH8719S 'S
POLICY DOA: 15/12/2019

Dear Sir,

Attached is our customer, GBC7944R accident report doing a 3rd party claim against your insured GBH8719S policy.

Please provide us with a list of surveyor for PRI.

Please also help to check is the liability in favour of our customer.

Regards,

Ho Too Boon
CAR CITY AUTO CENTRE PTE LTD
TEL: 67810300 FAX: 67820300

EMAIL: ccacpl@singnet.com.sg

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Hsiao Tong (LKKAuto)

From: ccacpl@singnet.com.sg
Sent: Saturday, 15 February 2020 10:12 AM
To: Hsiao Tong (LKKAuto)
Subject: RE: Your Ref: GBC7944R *Our Ref: CC4/III19022366/Upa3 [ACCIDENT INVOLVING GBH 8719S(III) AND GBC 7944R ON 15/12/2019]

Without Prejudice to any Personal Injuries claim

Dear Miss Chew,

Ok accept global sum \$8200.00.

Regards,

Ho Too Boon
CAR CITY AUTO CENTRE PTE LTD
TEL: 67810300 FAX: 67820300
EMAIL: ccacpl@singnet.com.sg

On Fri Feb 14 2020 16:48:37 GMT+0800 (Singapore Standard Time) Hsiao Tong (LKKAuto) <chewht@lkkauto.com> wrote:

----- Original Message -----

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement at a global sum of **\$8,200.00(all-in)**.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,
Hsiao Tong, Chew (Ms)
| Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | email: chewht@lkkauto.com
| fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From:

Hsiao Tong (LKKAuto)

Sent: Friday, 10 January 2020 9:41 AM

To: ccacpl@singnet.com.sg

Cc: Admin A <admin-a@lkkauto.com>

Subject: Your Ref: GBC7944R *Our Ref: CC4/III19022366/Upa3 [ACCIDENT INVOLVING GBH 8719S(III) AND GBC 7944R ON 15/12/2019]

Your Ref: **GBC7944R**

Without Prejudice

Our Ref: CC4/III19022366/Upa3

Dear Sirs/Mdm,

ACCIDENT INVOLVING GBH 8719S(III) AND GBC 7944R ON 15/12/2019

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle and admission of any liability to our Insured's part. The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor and approved by our principal.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

"Wishing you a Happy and Prosperous New Year"



Best Regards,

Hsiao Tong, Chew (Ms)

| Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com

| fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)












































Direct Settlement




















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Dec 2019 Edit Reg		19 Dec 2019 00:00 Edit Adj Rpt	\$57,100.00 Edit Estimates	\$57,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	PAN PACIFIC VAN & TRUCK LEASING PTE LTD, Co. Reg. No.: 201511635R								
Main Claimant:	XIANG REFRESHMENT PTE LTD, Co. Reg. No.: 200207189N								
Vehicle Reg. No.:	GBC7944R	Date of Loss:	15/12/2019 00:00 - :59 [73 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MFL2019D0001641	Policy/Cover Note No.:	D19MFL0005549						
Vehicle Reg. No. (Insured):	GBH8719S	Policy No. (Claimant):	DMCVSN3073741902						
		Excess:							
Repairer:	Car City Auto Centre Pte Ltd (HQ) Blk 9006 #01-198, Tampines Street 93, 528840 Tampines - Tel: 6781 0300								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by C. Meenachi - 6347 6073]								
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 07/01/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (13/02/2020): Alert - Adj Mandate Approved (\$8204.45) - GBC7944R - Claim Handler: C. Meenachi III_SG (07/01/2020): Alert - Adj Mandate Approved (\$0.00) - GBC7944R - Claim Handler: C. Meenachi 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBC7944R (MFL2019D0001641)
 [GBH8719S]
 TP
 XIANG REFRESHMENT PTE LTD
 Dec 15 2019 12:00AM
 [PAN PACIFIC VAN & TRUCK LEASING PTE LTD]
 Car City Auto Centre Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	23/01/20 09:00	Chassis Number							 Load JPG	<input checked="" type="checkbox"/>	
2	23/01/20 09:00	Odometer Reading							 Load JPG	<input checked="" type="checkbox"/>	
3	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
4	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
5	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
6	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
7	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
8	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
9	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
10	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
11	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
12	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
13	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
14	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
15	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
16	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
17	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
18	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
19	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
20	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
21	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
22	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
23	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
24	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
25	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
26	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
27	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
28	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
29	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
30	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
31	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
32	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
33	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
34	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
35	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
36	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
37	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
38	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
39	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
40	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
41	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
42	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	
43	23/01/20 09:00	General View							 Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	23/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
45	23/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
46	23/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
47	23/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
48	23/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
49	23/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
50	23/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
51	23/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
52	23/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
53	23/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
54	23/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
55	23/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
56	23/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
57	23/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
58	23/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
59	23/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
60	23/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
61	23/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
62	23/01/20 09:00	General View	 Load JPG	<input checked="" type="checkbox"/>
63	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	23/01/20 09:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	23/01/20 09:00	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
96	23/01/20 09:00	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
97	23/01/20 09:00	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
98	23/01/20 09:00	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
99	23/01/20 09:00	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
100	23/01/20 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
101	23/01/20 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
102	23/01/20 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
103	23/01/20 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
104	23/01/20 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
105	23/01/20 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
106	23/01/20 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
107	23/01/20 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
108	23/01/20 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
109	23/01/20 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
110	23/01/20 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
111	23/01/20 09:00	Reinspection Photo		<input checked="" type="checkbox"/>
112	23/01/20 09:01	Reinspection Photo		<input checked="" type="checkbox"/>
113	23/01/20 09:01	Reinspection Photo		<input checked="" type="checkbox"/>
114	23/01/20 09:01	Reinspection Photo		<input checked="" type="checkbox"/>
115	23/01/20 09:01	Reinspection Photo		<input checked="" type="checkbox"/>
116	23/01/20 09:01	Reinspection Photo		<input checked="" type="checkbox"/>
117	23/01/20 09:01	Reinspection Photo		<input checked="" type="checkbox"/>
118	23/01/20 09:01	Reinspection Photo		<input checked="" type="checkbox"/>
119	23/01/20 09:01	Reinspection Photo		<input checked="" type="checkbox"/>
120	23/01/20 09:01	Reinspection Photo		<input checked="" type="checkbox"/>
121	23/01/20 09:01	Reinspection Photo		<input checked="" type="checkbox"/>
122	23/01/20 09:01	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/12/19 15:41	ACKNOWLEDGEMENT EMAIL TO III DD 19.12.19		<input type="checkbox"/>
2	27/12/19 14:27	TP GIA REPORT		<input type="checkbox"/>
3	23/01/20 09:10	TP ESTIMATE_MARKED		<input type="checkbox"/>
4	04/02/20 14:22	LTA SEARCH		<input type="checkbox"/>
5	25/02/20 11:34	WORKSHOP INVOICE		<input type="checkbox"/>
6	25/02/20 11:34	AUTHORISATION TO ACT FORM		<input type="checkbox"/>
7	25/02/20 11:34	DISCHARGE VOUCHER		<input type="checkbox"/>
8	25/02/20 11:34	LOD		<input type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	30/12/19 11:55	Singapore Accident Statement		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19022386/UPA3Q2

Date: 25/02/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549
Claimant Vehicle No :	GBC7944R	Insured Vehicle No :	GBH8719S
Date of Loss:	15/12/2019	Nature of Claim:	TP
		Claim No:	MFL2019D0001641

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC7944R	Engine No:	1KD2333516
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	JTFAT35Y70K202597
Reg. Date:	25/10/2013 (Man. Year: 2013)	Odometer:	279477 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R12 (D)
Front Left Side:	GST 6 mm	Rear Left Side:	GST 6/6 mm
Front Right Side:	GST 6 mm	Rear Right Side:	GST 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,513.34	6,419.23	7,094.11	52.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,850.00	2,520.00	1,330.00	34.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,363.34	8,939.23	8,424.11	48.52
Approved Total (Overridden) (S\$)		7,100.00		
(S\$)	17,363.34	7,100.00	10,263.34	59.11
+ GST 7.00/7.00% (S\$)	1,215.43	497.00	718.43	59.11
Nett Amount (S\$)	18,578.77	7,597.00	10,981.77	59.11
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,204.45		
Global Sum Settlement (S\$)		8,200.00		

INSPECTION

Date of Assignment: 19/12/2019
Date Inspected: 26/12/2019 Inspected At:

Car City Auto Centre Pte Ltd (HQ)
Blk 9006 #01-198, Tampines Street 93
Singapore 528840

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 04 Feb 2020)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC7944R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	396.20 F	*396.20 FL
2	1		*FRONT HEADLAMP ASSY	N/S Cracked	623.30 F	*623.30 FL
3	1		*FRONT GRILLE	Cracked	510.30 F	*510.30 FL
4	6		*FRONT GRILLE GARNISH CLIP	Necessary	29.40 F	*29.40 FL
5	1		*FRONT PANEL	Badly Dented	1,229.70 F	*1,229.70 FL
6	1		*FRONT PANEL LOGO	Necessary	69.27 F	*69.27 FL
7	1		*FRONT PANEL EMBLEM DYNA	Necessary	64.70 F	*64.70 FL
8	1		*FRONT SIDE PANEL N/S	Dented	282.20 F	*282.20 FL
9	1		*FRONT GARNISH CENTRE	Grazed	368.50 F	*368.50 FL
10	1		*FRONT SIDE GARNISH LH	Cracked	153.95 F	*153.95 FL
11	1		*FRONT TOP PANEL	Dented	347.70 F	*347.70 FL
12	1		*FRONT TOP PANEL MOULDING	Not Necessary	86.80 F	*- FL
13	2		*FRONT SIDE TOP PANEL	Cracked	360.00 F	*360.00 FL
14	1		*FRONT SIDE MIRROR LH	Service item	478.70 F	*- FL
15	1		*FRONT SIDE MIRROR LH (ROUND)	Not Necessary	160.00 F	*- FL
16	1		*FRONT SIDE MIRROR STAND LH }	Bent	289.20 F	*289.20 FL
17	1		*FRONT SIDE MIRROR STAND LH BRACKET }		0.00 F	*- FL
18	1		*FRONT WINDSCREEN RUBBER	Twisted	303.70 F	*303.70 FL
19	1		*FRONT INNER PANEL	Repair	188.75 F	*- FL
20	2		*FRONT DOOR FRAME OUTER FRT	Repair	426.95 F	*- FL
21	1		*FRONT DOOR FRAME LH OUTER RR	Repair	621.75 F	*- FL
22	2		*FRONT DOOR FRAME CENTER FRT	Not Necessary	363.75 F	*- FL
23	2		*FRONT DOOR FRAME INNER FRT	Repair	414.70 F	*- FL
24	2		*FRONT DOOR FRAME TOP INNER	Repair	269.75 F	*- FL
25	1		*FRONT DOOR FRAME LH INNER RR	Not Necessary	298.75 F	*- FL
26	2		*FRONT DOOR FRAME WEATHER STRIP	Not Necessary	146.80 F	*- FL
27	1		*FRONT DOOR PILLAR TRIM LH	Not Necessary	137.43 F	*- FL
28	1		*FRONT DOOR LH	Buckled	1,649.70 F	*1,649.70 FL
29	2		*FRONT DOOR HINGE LH	Not Necessary	79.25 F	*- FL
30	1		*FRONT DOOR CHECKER LH	Not Necessary	131.75 F	*- FL
31	1		*FRONT DOOR WEATHER STRIP LH	Not Necessary	195.40 F	*- FL
32	1		*FRONT DOOR GLASS OUTER RUBBER STRIP LH	Not Necessary	157.44 F	*- FL
33	1		*FRONT DOOR TRIM BOARD LH	Not Necessary	721.40 F	*- FL
34	1		*FRONT STEP PANEL GARNISH LH	Cracked	348.50 F	*348.50 FL
35	1		*FRONT WIPER NOZZLE & LINKAGE	Twisted	389.70 F	*389.70 FL
36	1		*CONDENSER FOR ASSY }	Distorted / Cracked	1,082.95 F	*1,082.95 FL
37	1		*CONDENSER ASSY }		0.00 F	*- FL
38	1		*BRACKET CONDENSER }		0.00 F	*- FL
39	1		*FRONT BUMPER NUMBER PLATE	Bent	35.00 FS	*15.00 FS
40	2		*WINDSCREEN GLASS SEALANT	Not Necessary	70.00 FS	*- FS
41	1		*LH DOOR STICKER	Necessary	30.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc						
Sub Total (S\$)					13,513.34	8,543.97
- List Item Discount on L Items 0.00/25.00% (S\$)					0.00	2,124.74
Total Parts (S\$)					13,513.34	6,419.23

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT AFFECTED PARTS ,PANEL BEATING ON DAMAGED AREAS,CUT ,WELD ,KNOCK STRAIGHTEN ,REALIGN & RESHAPE ,FRONT PANEL OUTER & INNER ,FRONT BUMPER ,FRONT SUPPORT PANEL ,FRONT HEADLAMP RH & LH,FRONT DOOR LH ,DOOR FRAME ,FLOOR PANEL & OTHER	New	1,400.00	1,000.00
2	TO PUTTY ,CLEANING SANDING ,POLISHING WAXING & SPRAY PAINT ON ALL NECESSARY PARTS AND AREAS ,FRONT BUMPER ,FRONT PANEL,FRONT SUPPORT PANEL ,FRONT DOOR LH ,DOOR PILLAR LH ,FLOOR PANEL ...ETC	New	1,500.00	1,000.00
3	CHECK WIRING	New	80.00	20.00
4	TO REMOVE & REFIT FRONT DOOR LH, DOOR GLASS ,DOOR GLASS MOTOR,REGULATOR ,DOOR CHANNEL ,DOOR LOCK INNER & OUTER ,DOOR HANDLE INNER & OUTER ...ETC	New	150.00	60.00
5	TO REMOVE & REFIT FRONT WINDSCREEN GLASS FOR ALL NECESSARY REPAIRS	New	120.00	80.00
6	TO REMOVE & VACUUM AIR-CON SYSTEM & CHARGE UP AIR-CON GAS	New	150.00	100.00
7	TO REMOVE & REFIT INTERIOR SEAT & TRIM BOARD ,ROOF LINING ,CARPET & OTHER FOR NECESSARY REPAIR WORK	New	200.00	60.00
8	TO REMOVE & REFIT DASHBOARD ASSEMBLY	New	250.00	200.00
Gross Labour Cost (S\$)			3,850.00	2,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >