



CAR CITY AUTO CENTRE PTE LTD

Car City Always

Blk 9006 Tampines st93 #01-198 S'pore 528840

TEL: 6781 0300

FAX: 6782 0300

451 Reg 2007199802

E-mail : ccacpl@singnet.com.sg

TO: INDIA INTERNATIONAL INSURANCE
ATTN: MOTOR CLAIMS DEPT

ESTIMATE REPORT

OWNER'S PARTICULAR

NAME:

ADDRESS:

CONTACT NO H/P:

TEL:

OWNERS INSURER : CHINA TAIPING INSURANCE

POLICY NO: MMCVSN3073741902

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not attached
2/5/19
6 by
26/12/19
Whphc. Affluence

1 OF 4

DATE : 26-Dec-19

JOB TYPE : 3RD PARTY CLAIM

VEH NO : GBC7944R

MODEL : TOYOTA / DYNA
150 MANUAL

CHASSIS NO : JTFAT35Y70K202!

ENGINE NO:

ACCIDENT DATE : 15/12/2019

QUOTATION SUMMARY

CLAIM DETAIL: PARTS

REQUESTOR CONTACT :

HO / 67810300

S/NO	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Best ✓</i>	1	\$386.17	\$386.17
2	FRONT HEADLAMP ASSY <i>MS one 1PC</i>	1	\$577.50	\$577.50
3	FRONT GRILLE <i>one ✓</i>	1	\$363.17	\$363.17
4	FRONT GRILLE GARNISH CLIP <i>new ✓</i>	6	\$4.90	\$29.40
5	FRONT PANEL <i>body ID ✓</i>	1	\$835.50	\$835.50
6	FRONT PANEL LOGO <i>new ✓</i>	1	\$65.00	\$65.00
7	FRONT PANEL EMBLEM " DYNA " <i>new ✓</i>	1	\$54.19	\$54.19
8	FRONT SIDE PANEL <i>MS ID ✓</i>	1	\$299.55	\$299.55
9	FRONT GARNISH CENTRE <i>garnish ✓</i>	1	\$-	\$-
10	FRONT SIDE GARNISH LH <i>one ✓</i>	1	\$-	\$-
11	FRONT TOP PANEL <i>DD ✓</i>	1	\$-	\$-
12	FRONT TOP PANEL MOULDING <i>. Fats with ?</i>	1	\$85.00	\$85.00
13	FRONT SIDE TOP PANEL <i>one ✓</i>	2	\$-	\$-
14	FRONT SIDE MIRROR LH <i>?</i>	1	\$-	\$-

15	FRONT SIDE MIRROR LH (ROUND)	11X	1	\$-	\$-
16	FRONT SIDE MIRROR STAND LH	Buc ✓	1	\$-	\$-
17	FRONT SIDE MIRROR STAND LH BRACKET	complete X	1	\$-	\$-
18	FRONT WINDSCREEN RUBBER	1m1 ✓	1	\$190.00	\$190.00
19	FRONT INNER PANEL	12X	1		
20	FRONT DOOR FRAME OUTER FRT	12X	2	\$-	\$-
21	FRONT DOOR FRAME LH OUTER RR	12X	1	\$-	\$-
22	FRONT DOOR FRAME CENTER FRT	11X	2	\$-	\$-
23	FRONT DOOR FRAME INNER FRT	12X	2	\$-	\$-
24	FRONT DOOR FRAME TOP INNER	12X	2	\$-	\$-
25	FRONT DOOR FRAME LH INNER RR	12X	1	\$-	\$-
26	FRONT DOOR FRAME WEATHER STRIP	?	2	\$-	\$-
27	FRONT DOOR PILLAR TRIM LH	11X	1	\$-	\$-
28	FRONT DOOR LH	Buc ✓	1	\$1,110.20	\$1,110.20
29	FRONT DOOR HINGE LH	?	2	\$-	\$-
30	FRONT DOOR CHECKER LH	?	1	\$-	\$-
31	FRONT DOOR WEATHER STRIP LH	?	1	\$-	\$-
32	FRONT DOOR GLASS OUTER RUBBER STRIP LH	?	1	\$-	\$-
33	FRONT DOOR TRIM BOARD LH	?	1	\$-	\$-
34	FRONT STEP PANEL LH	?	1	\$428.50	\$428.50
35	FRONT Wipe Nozzle + Linkage.	?	1	\$-	\$-
36	Air-gun Not working (include 14 box)	?	1	\$-	\$-
37			1	\$-	\$-

PARTS PRICE :

\$4,424.18

LESS 25%

SUB TOTAL PRICE :

S/NO	DESCRIPTION	QTY	UNIT S/Nett PRICE	TOTAL S/Nett PRICE
1	FRONT BUMPER NUMBER PLATE <i>304 15'</i>	1	\$35.00	\$35.00
2	WINDSCREEN GLASS SEALANT <i>11 X</i>	2	\$35.00	\$70.00
3	LH DOOR STICKER <i>111 ✓</i>	1	\$30.00	\$30.00

S/N PARTS PRICE :

\$135.00

TOTAL PARTS PRICE :

No	CLAIM DETAIL : LABOURS & SPRAY PAINTING			
	JOBS DESCRIPTION	PRICE	REVISED PRICE	APPR.
1	TO REMOVE & REFIT AFFECTED PARTS; PANEL BEATING ON DAMAGED AREAS, CUT, WELD, KNOCK STRAIGHTEN, REALIGN & RESHAPE. FRONT PANEL OUTER & INNER, FRONT BUMPER, FRONT SUPPORT PANEL, FRONT HEADLAMP RH & LH, FRONT DOOR LH, DOOR FRAME, FLOOR PANEL & OTHER.	\$1,400.00	<i>1000</i>	
2	TO PUTTY, CLEANING, SANDING, POLISHING, WAXING & SPRAY PAINT ON ALL NECESSARY PARTS AND AREAS. FRONT BUMPER, FRONT PANEL, FRONT SUPPORT PANEL, FRONT DOOR LH, DOOR PILLAR LH, FLOOR PANELETC.	\$1,500.00	<i>1000</i>	
3	CHECK WIRING	\$80.00	<i>20</i>	
4	TO REMOVE & REFIT FRONT DOOR LH. DOOR GLASS, DOOR GLASS MOTOR, REGULATOR, DOOR CHANNEL, DOOR LOCK INNER & OUTER, DOOR HANDLE INNER & OUTER.....ETC.	\$150.00	<i>60</i>	
5	TO REMOVE & REFIT FRONT WINDSCREEN GLASS FOR ALL NECESSARY REPAIRS.	\$120.00	<i>80</i>	
6	TO REMOVE & VACUUM AIR-CON SYSTEM & CHARGE UP AIR-CON GAS.	\$150.00	<i>100</i>	
7	TO REMOVE & REFIT INTERIOR SEAT & TRIM BOARD, ROOF LINING, CARPET & OTHER FOR NECESSARY REPAIR WORK.	\$200.00	<i>60</i>	
8	TO REMOVE & REFIT DASHBOARD ASSEMBLY.	\$250.00	<i>200</i>	
9				
		\$3,850.00		

VEHICLE NO : GBC7944R

ESTIMATE REPORT

TOTAL LABOUR COST : \$3,850.00

TOTAL PARTS COST :

TOTAL REPAIR COST :

APPROVAL DETAILS

EXCESS :

NO. OF DAY :

RE-SURVEY :

SURVEY BY :

CONTACT NO :

FAX NO. :

NOTE :

**LUMP-SUM AMOUNT OR COST OF REPAIR WOULD BE
REVISED IF SUPPLEMENT REPAIR IS REQUIRED**