



**Diplomat Parts Pte. Ltd.**

Company Reg No. 196400304H  
GST Reg No. MR-8500111-X

**ESTIMATE**

Invoice Name & Address

Owner Name & Vehicle Info

Cycle & Carriage Leasing Pte. Ltd.

239 Alexandra Road  
Singapore 159930

Reg No/Reg Date SMH2820R / 29/09/2016

Date In/Mileage / 0

Chassis No RU11204580

Engine No

Contact No

Make/Model Veze1

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
PC000162		14/12/2019/ 11:24	QUK	282 / Kevin Leong	23691			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
PNT88000					875	1600.00		
TO RENEW REAR TAILGATE, REAR RH BUMPER, REAR BUMPER, REAR RH WHEEL								
SHIELD TRIM, RH ROCKER COVER & AFFECTED AREA					420	800.00		
PNT98000					80	120.00		
PAINT WORK ON REAR TAILGATE & REAR RH BUMPER					150	240.00		
PNT88000					60	80.00		
TO REMOVE & INSTALL REAR PARKING ASSIST					40	80.00		
PNT88000								
TO REMOVE & INSTALL REAR WINDSCREEN GLASS								
SUNDRY								
TO APPLY SEALANT ON REAR WINDSCREEN								
SUNDRY								
PERFORM RUST PREVENTION								
SUNDRY								
TO APPLY BODY SEALANT								
PNT88000								
TO REMOVE & INSTALL REAR BOOT COMPARTMENT								
PNT88000					80	120.00		
TO REMOVE & INSTALL REAR TAILGATE TRIM & OTHERS ATTACHMENTS								
TO NEW PANEL								
54900099								
CHECK ELECTRICAL SYSTEM								
10028901								
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST					20	50.00		
SUNDRY								
SUNDRIES								
SUNDRY								
REAR TAILGATE								
SUNDRY								
REAR BRAKE LAMP RH (BODY)								
SUNDRY								
REAR BRAKE LAMP RH (TAILGATE)								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

**Diplomat Parts Pte. Ltd.**Company Reg No. 196400304H  
GST Reg No. MR-8500111-X**ESTIMATE**

Invoice Name &amp; Address

Owner Name &amp; Vehicle Info

Cycle &amp; Carriage Leasing Pte. Ltd.

239 Alexandra Road  
Singapore 159930

Reg No/Reg Date SMH2820R / 29/09/2016

Date In/Mileage / 0

Chassis No RU11204580

Engine No

Contact No

Make/Model Veze1

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
PC000162		14/12/2019/ 11:24	QUK	282 / Kevin Leong	23691

Description of Goods / Services

Qty

Unit Price

Disc%

Amount

M	SUNDRY				465.00
	REAR BUMPER de -				
M	SUNDRY				151.00
	REFLECTOR REAR RH can -				
M	SUNDRY				46.00
	EMBLEM 'VEZEL' neu -				
M	SUNDRY				162.00
	REAR BUMPER RH su -				
M	SUNDRY				155.00
	REAR RH WHEEL ARCH TRIM ?				
M	SUNDRY				175.00
	REAR RH WHEEL SHIELD X				
M	SUNDRY				280.00
	RH SIDE PANEL COVER X				
M	SUNDRY				75.00
	RAER RH WHEEL SHIELD S X				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date:

SURVEYOR NAME:

Rasul - Hp 90010068

SURVEYOR SIGNATURE:

Rul

DATE:

10/02/2020 @ 11:50

REMARKS:

Reng bahr pint  
S days

Confirm &amp; accepted by

Nett

6,958.00

Authorized signatory and company stamp

Total Payable

6,958.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.