


Cecilia



DPS

Diplomat Parts Pte. Ltd.

Company Reg No. 196400304H
GST Reg No. MR-8500111-X

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
Cycle & Carriage Leasing Pte. Ltd.	Reg No/Reg Date SMH2820R / 29/09/2016
239 Alexandra Road	Date In/Mileage / 0
Singapore 159930	Chassis No RU11204580
	Engine No
Contact No	Make/Model Vezel

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
C000162		14/12/2019/ 11:24	QUK	282 / Kevin Leong	23691		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
PNT88000 TO RENEW REAR TAILGATE, REAR RH BUMPER, REAR BUMPER, REAR RH WHEEL SHIELD TRIM, RH ROCKER COVER & AFFECTED AREA				875	1600.00		
PNT98000 PAINT WORK ON REAR TAILGATE & REAR RH BUMPER				420	800.00		
PNT88000 TO REMOVE & INSTALL REAR PARKING ASSIST				80	120.00		
PNT88000 TO REMOVE & INSTALL REAR WINDSCREEN GLASS				150	240.00		
SUNDRY TO APPLY SEALANT ON REAR WINDSCREEN				60	80.00		
SUNDRY PERFORM RUST PREVENTION				40	80.00		
SUNDRY TO APPLY BODY SEALANT					80.00		Xm
PNT88000 TO REMOVE & INSTALL REAR BOOT COMPARTMENT					120.00		Xm
PNT88000 TO REMOVE & INSTALL REAR TAILGATE TRIM & OTHERS ATTACHMENTS TO NEW PANEL				80	120.00		
54900099 CHECK ELECTRICAL SYSTEM					50.00		
10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST					180.00		
SUNDRY SUNDRIES				20	50.00		
SUNDRY REAR TAILGATE					972.00		
SUNDRY REAR BRAKE LAMP RH (BODY)					650.00		
SUNDRY REAR BRAKE LAMP RH (TAILGATE)					267.00		

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Diplomat Parts Pte. Ltd.

Company Reg No. 196400304H
GST Reg No. MR-8500111-X

ESTIMATE

Invoice Name & Address		Owner Name & Vehicle Info	
Cycle & Carriage Leasing Pte. Ltd.		Reg No/Reg Date	SMH2820R / 29/09/2016
239 Alexandra Road		Date In/Mileage	/ 0
Singapore 159930		Chassis No	RU11204580
		Engine No	
Contact No		Make/Model	Vezel

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
RC000162		14/12/2019/ 11:24	QUK	282 / Kevin Leong	23691			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	SUNDRY							465.00 ✓
	REAR BUMPER de -							151.00 ✓
M	SUNDRY							46.00 ✓
	REFLECTOR REAR RH can -							162.00
A	SUNDRY							155.00
	EMBLEM 'VEZEL' neu /							175.00
M	SUNDRY							280.00
	REAR BUMPER RH sea x snc							75.00
A	SUNDRY							
	REAR RH WHEEL ARCH TRIM ? de /							
M	SUNDRY							
	REAR RH WHEEL SHIELD x snc							
M	SUNDRY							
	RH SIDE PANEL COVER x snc							
M	SUNDRY							
	RAER RH WHEEL SHIELD S x snc							

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Estimate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Rasul - Hp 90010068

SURVEYOR SIGNATURE: [Signature]

DATE: 10/02/2020 @ 11:50

REMARKS: Reay bahr pint
3 days

Confirm & accepted by

Nett 6,958.00

Total Payable 6,958.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Surveyor : NASUL (LKK)
Company : LKK
DOA : 25/11/19
CSE : KEVIN

VEHICLE NO : SMH 2820R
MODEL : HONDA / VEZEL
WIP : 23691

Email :

Material : \$ 1,789.00
Labour : \$ 1,955.00
Sub-Total : \$ 3,744.00
Less Excess : \$ —
Total : \$ 3,744.00
GST 7% : \$ 262.08
Grand Total : \$ 4,006.08
Finalise By/Date : Wany on 25/03/20

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 05 WORKING DAYS + 02 Days (1) Weekends
+ Days () Public Holiday
TOTAL DAYS REPAIR TOOK = 07

☐ ~~OD~~ Claim TP CLAIM (SHA7995H)

☐ Claim GIA / LTA fee

☐ Claim Loss ☐ Use ☒ Rental

☐ Claim Medical Fee / Others

**PRO-FORMA INVOICE****THIS IS NOT AN OFFICIAL TAX INVOICE****Diplomat Parts Pte. Ltd.**Company Reg No. 196400304H
GST Reg No. MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
CYCLE & CARRIAGE LEASING PTE LTD		Reg No/Reg Date	SMH2820R / 29/09/2016
239 ALEXANDRA ROAD		Date In/Mileage	10/02/2020/ 81076
SINGAPORE 159930		Chassis No	RU11204580
Contact No Mobile: 85188668		Engine No	
		Make/Model	Veze1

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
CTP00060	Cash	25/03/2020/ 17:09	TLK	884 / Lauro Songcuan	23691				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
E	PNT88000	RENEW REAR TAILGATE, REAR RH BUMPER, REAR BUMPER & AFFECTED AREAS							875.00✓
E	PNT98000	SPRAY PAINT ON REAR TAILGATE & REAR RH BUMPER							420.00✓
E	PNT88000	REMOVE & INSTALL REAR PARKING ASSIST							80.00✓
E	PNT88000	REMOVE & INSTALL REAR WINDSCREEN GLASS							150.00✓
M	SUNDRY	APPLY SEALANT ON REAR WINDSCREEN							60.00✓
M	SUNDRY	PERFORM RUST PREVENTION ON AFFECTED PORTIONS							40.00✓
E	PNT88000	REMOVE & INSTALL REAR TAILGATE TRIM & OTHER ATTACHMENT TO NEW PANEL							80.00✓
A	54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							50.00✓
A	10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							180.00✓
M	SUNDRY	SUNDRIES							20.00✓
X	WHD68100T8PU10	REAR TAIL GATE ✓				1.00	972.00	00.00	972.00✓
X	WHD71501T8NT00	REAR BUMPER ✓				1.00	465.00	00.00	465.00✓
X	WHD33505T7AJ01	RHR BUMPER REFLECTOR ✓				1.00	151.00	00.00	151.00✓
X	WHD71502T7JH00ZZ	RHR BUMPER SIDE PAD ✓	(REAR RH WHEEL ARCH TRIM)			1.00	155.00	00.00	155.00✓
X	WHD75722T7A003	RR VEZEL EMBLEM ✓				1.00	46.00	00.00	46.00✓
Z	TEXT	TP CLAIM INDIA - SHA2820R							

This is not an official tax invoice. This is a computer generated document, no signature is required.

**PRO-FORMA INVOICE****THIS IS NOT AN OFFICIAL TAX INVOICE****Diplomat Parts Pte. Ltd.**Company Reg No. 196400304H
GST Reg No. MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
CYCLE & CARRIAGE LEASING PTE LTD		Reg No/Reg Date	SMH2820R / 29/09/2016
239 ALEXANDRA ROAD		Date In/Mileage	10/02/2020/ 81076
SINGAPORE 159930		Chassis No	RU11204580
Contact No		Engine No	
Mobile: 85188668		Make/Model	Veze1

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
CTP00060	Cash	25/03/2020/ 17:09	TLK	884 / Lauro Songcuan	23691	
		Description of Goods / Services	Qty	Unit Price	Disc%	Amount

DOA: 25.11.2019
SURVEYOR: RASUL LKK
05 DAYS

10/02/2020

Pro Forma

Parts	1,789.00			
Labour	1,835.00			
Standard Menu	0.00			
Specialist Job	0.00			
Others(Lub,etc)	0.00			
Sundry	120.00			
Total(w/o GST)	3,744.00			
		7% GST on	3744.00	
			Nett	3,744.00
				262.08
			Total Payable	4,006.08

This is not an official tax invoice. This is a computer generated document, no signature is required.

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4558 Fax: (65) 6567 5258