

ASSIGNMENT

Surveyor:

KENNETH

DOI: 19/12/2019

Date / Time: 19/12/2019

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.: SHC 7121C

Claim No.: D19007966MFSH

Name of Insured: CITYCAB PTE LTD

Policy No.: D-19092579MFSH

Insured Tel No.: HP:

Make / Model: HYUNDAI I40

Excess Sec II :SS D.O.A: 15/12/2019 13:10

Place of Accident: ALONG GRANGE RD TOWARDS PATERSON HILL AND ORCHARD

Is driver the owner? (YES / NO) Nature of Accident:

If NO, Driver Name / Age: YAP THIAM SEN

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.: +65-96702888

(V/L: YES / NO)

Insured Liability: % Final ? Yes / No

EY 668H

INSRS:
WSP: ALAN'S UNITEDTel:
Liability:
RMKS:INSRS:
WSP:Tel:
Liability:
RMKS:INSRS:
WSP:Tel:
Liability:
RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC
	SHC 7121C - CS/FCI19000669/Asd3n2; DOA: 08.01.19	Non-Reporting ltr (1st):	
	- CS/FCI19001632/R1sd3e2; DOA: 24.01.19	Non-Reporting ltr (2nd):	
	- NA/LIP19004060/k4; DOA: 26.2.19	Non-Reporting ltr (Final):	
	EY 668H - CC3/AIG18016304/Avd3n2; DOA: 2.9.18	Notification ltr (if non-pickup):	
	- CC6/AIG18016150/Keb3q2; DOA: 2.9.18	Call OI:	
14/1/20	FILE PASD TO TYPE MANDATE	After call ltr to OI:	
5/3/2020	FILE RMKS TO HMM TO WORK	Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	☐
		After call ltr to OI:	☐
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☐
		Towing Invoice:	☐
		LTA / GIA:	☐
		Medical Bill:	☐
		PIR:	☐
		Mandate/Reject Instruction:	☒
		LOD	☒
		Payment Breakdown Form:	☐
		Post-Repair Photos:	☐
		Others:	☐

PRELIMINARY ADVICE		Date/Time:	Sent By:	
FINALIZATION		Date/Time:	Confirm with:	Confirm by:
Repair Cost:	SS	(days) Reduction:	%	Email ☐ Call ☐
FINAL SETTLEMENT		Date/Time: 24/2/2020	Confirm with: Kenny	Email ☒ Call ☐
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.: 28		If NO or B 28, Ass. Lia: 100%
Repair Cost: (w/415)	SS 10914.00			Reh C.C. 02 was last
Loss of Rental (LOR):	SS -	(days)		
Loss of Use (LOU):	SS 800.00	(5 80 x 10 days)		
Loss of Income (LOI):	SS -	(5 x days)		
LOR only ☐ LOU only ☒	LOR + LOU ☐ LOR + LOI ☐	[Tick only one]		
GIA/LTA Search	SS -			
Medical:	SS -			
Disbursement:	SS -	(e.g. Tow/ Independent)		
Legal Cost	SS -			
Total:	SS 11714.00	Global Sum SS:		
FINAL PAYMENT		Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	SS 11714.00	Name 1:	Alan's United Auto Pte Ltd	
Payee 2: (Strike if N.A.)	SS	Name 2:		
Payee 3: (Strike if N.A.)	SS	Name 3:		

ASS. REC. BY:

REF: 1021

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 36k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

/ File pass to

L/S - \$10200 (Red \$6174.10 / 381.)

MV: \$36000

LTA Rebate: \$25622

NV: \$10378

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: _____

Site Insp (\$ _____)

Interview (\$ _____)

Tech Invs (\$ _____)

Weekend (\$ _____)

S + RS \$ _____

Fees

Other

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Veh No: 54684 Yr Regn: 11, 10

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A5 cc 1798

Colour: M. Black AC: Insured / Std / NI / NA

Sp. Reading: 97.478 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAU 2288T 2BA 009373

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 15/12/19

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 19/12/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

& 1st

The U/C / Chassis frame / Body Structure affected due to collision.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19007967MFSH
Our ref: CC4/FCI19022359/Kka3

Date: 23/12/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

EY 668H

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on SCN 66B at the premises of M/s Trust Autoworks and have the following to report:-

Workshop Estimate Amount	: S\$	11,554.91
Revised Estimate Amount	: S\$	6,626.56
"Check" Items Amount	: S\$	1,970.08
Total (Including Check Items)	: S\$	8,596.64
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
Rear N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 8.0 day

Yours faithfully,

KENNETH KONG
Licensed Appraiser

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06113

Vehicle Insured : SHC7121C

Accident Date : 15-Dec-2019

Date : 16-Dec-2019

Our Ref : 219210 (FIRST) / CHAN

PAGE : 1

LEE SIANG KHENG BERT
22 LORONG PUNTONG
#10-01 COUNTRY GRANDEUR
Singapore 576439

Not Notarized

61 Sep 810,200.

Recovery After Pain Today

ESTIMATED COST OF REPAIR FOR AUDI A5 SPORTBACK 1.8TSIMU EY668H

1 pc	Tail gate	B ₁	1,700.00	✓
1 pc	Tail gate inner seal	na	110.00	✓
1 pc	Tail gate inner lock	oil	185.00	✓
1 pc	Tail gate rubber	oil	220.00	50% 110 SN
1 pc	Tail gate logo	na	115.00	✓
1 pc	Tail gate "A5" emblem	na	70.00	✓
2 pcs	Tail gate lamp	ats lca ^{cm}	@ S\$550.00	1,100.00
2 pcs	Taillamp	ats lca	@ \$1100.00	2,200.00
1 pc	Rear end panel	B ₁	680.00	✓
1 pc	Rear end panel top garnish	oil	175.00	✓
1 pc	Rear bumper fascia	B ₁	1,330.00	✓
1 pc	Rear bumper lower garnish	A ₁	277.00	✓
2 pcs	Rear bumper parking sensor	shot @ S\$190.00	380.00	✓
1 pc	Rear bumper reinforcement	A ₁	490.00	✓
1 pc	Rear bumper sponge	SL	128.00	7 X
1 pc	Spare tyre panel		2,950.00	7 ✓
1 pc	Front bumper fascia		1,600.00	7 ✓
1 pc	Radiator grille	CM	595.00	✓
pc	Front bumper sponge	SL	185.00	7 X
1 pc	Front bumper reinforcement	R	659.00	7 X

15,149.00
Less 10% : 1,514.90

*13957.00
1395.70
12561.30*

1 pc	Rear w/s glass sealant	na	13,634.10	
1 pc	Rear no.plate with box	CM	45sn	60.00 sn
1 pc	Front no.plate with box	CM	45sn	50.00 sn

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SHC7121C

Page : 2

To remove & refix rear windscreen
glass and conduct water leak test.

150.00 1201

To remove roof lining, front and
rear seats, trim board and carpet

120.00 601

To apply undersealing

60.00 ✓

To remove and renew exhaust
silencer box

50.00 ✓

To putty and spray replaced parts

1,200.00 10001

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

1,000.00 8001

Total : S\$16,374.10

Singapore Dollars Sixteen Thousand Three Hundred
and Seventy Four and Cents Ten Only

4/sum
12400.00
A Kenneth
pls Company
7/15

P 12561.30
S.P. 651.60
SN 240.00
L 2090.00

18542.90
3108.58

12434.32

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SHC7121C (FIRST)

Date : 20-12-2019

Accident Date : 15-12-2019

Our Ref : 219210 / CHAN

LEE SIANG KHENG BERT

C/O ALAN'S UNITED AUTO PTE LTD

SUPPLEMENTARY ITEM PRICE FOR AUDI A5 SPORTBACK 1.8TSI MU EY668H

2 PCS	REAR BUMPER REINFORCEMENT BRACKET @ \$192.00	<i>DT</i>	\$384.00	✓
1 PC	REAR FLOOR PANEL SPEAKER BOX	<i>CM</i>	\$340.00	✓
			<u>\$724.00</u>	
		LESS 10%	<u>\$72.40</u>	
			<u>\$651.60</u>	

Singapore Dollars Six Hundred Fifty One And Cents Sixty Only

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06113

Vehicle Insured : SHC7121C
Accident Date : 15-Dec-2019

Date : 16-Dec-2019

Our Ref : 219210 (FIRST) / CHAN

PAGE : 1

LEE SIANG KHENG BERT
22 LORONG PUNTONG
#10-01 COUNTRY GRANDEUR
Singapore 576439

Not Attached
11 Sep 20?
Recovery After PAM Today,

ESTIMATED COST OF REPAIR FOR AUDI A5 SPORTBACK 1.8TSIMU EY668H

1 pc	Tail gate	R1	1,700.00	✓
1 pc	Tail gate inner seal	RM	110.00	✓
1 pc	Tail gate inner lock		185.00	✓
1 pc	Tail gate rubber	D171R	220.00	506m
1 pc	Tail gate logo	RM	115.00	✓
1 pc	Tail gate "A5" emblem	RM	70.00	✓
2 pcs	Tail gate lamp	old car @ S\$550.00	1,100.00	✓
2 pcs	Taillamp	old car @ \$1100.00	2,200.00	✓
1 pc	Rear end panel	R1	680.00	✓
1 pc	Rear end panel top garnish	D17	175.00	✓
1 pc	Rear bumper fascia	R1	1,330.00	✓
1 pc	Rear bumper lower garnish	R1	277.00	✓
2 pcs	Rear bumper parking sensor	shot @ S\$190.00	380.00	✓
1 pc	Rear bumper reinforcement	R1	490.00	✓
1 pc	Rear bumper sponge		128.00	✓
1 pc	Spare tyre panel		2,950.00	✓
1 pc	Front bumper fascia		1,600.00	✓
1 pc	Radiator grille	CM	595.00	✓
1 pc	Front bumper sponge		185.00	✓
1 pc	Front bumper reinforcement		659.00	✓
			15,149.00	
			Less 10% :	1,514.90
			13,634.10	
1 pc	Rear w/s glass sealant	RM	40.00	60.00 sn
1 pc	Rear no.plate with box	CM	45.00	50.00 sn
1 pc	Front no.plate with box	CM	45.00	50.00 sn

LKK Auto Consultants hence notify the Repairer of the following:

- To recovery before/after spray painting
- To display damage claim(s) during recovery
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be recovered and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature
Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Page : 2

Vehicle Insured : SHC7121C

To remove & refix rear windscreen
glass and conduct water leak test.

150.00 *1201*

To remove roof lining, front and
rear seats, trim board and carpet

120.00 *601*

To apply undersealing

60.00 ✓

To remove and renew exhaust
silencer box

50.00 ✓

To putty and spray replaced parts

1,200.00 *10001*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

1,000.00 *8001*

Total : S\$16,374.10

=====

Singapore Dollars Sixteen Thousand Three Hundred
and Seventy Four and Cents Ten Only

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	010I
Vehicle Details	
Vehicle No.:	EY668H
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Dec 2019
Vehicle Make:	AUDI
Vehicle Model:	A5 SPORTBACK 1.8 TFSI MU
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	CDH101824
Chassis No.:	WAUZZZ8T2BA009373
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$43,316.00
Original Registration Date:	04 Nov 2010
First Registration Date:	04 Nov 2010
Transfer Count:	2
Actual ARF Paid:	\$43,316.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Nov 2020
PARF Rebate Amount:	\$21,658.00
Intended COE Rebate Details	
COE Expiry Date:	03 Nov 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$45,501.00
COE Rebate Amount:	\$3,964.00
Total Rebate Amount:	\$25,622.00

The information contained herein is correct as at 20 Dec 2019.

OK



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CC4/FC119022384/Kda3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 11-03-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7121C	Veh. Inspected	EY 668H	
Policy No.	D-19092579MFSH	Coverage (\$)	0.00	
Claim No.	D19007966MFSH	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	19/12/2019	
2. Vehicle Particulars & Condition				
Make & Model	AUDI A5 (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WAUZZZ8T2BA009373	Colour	METALLIC BLACK	
Odometer	97478	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 R18	GOODYEAR	7 mm	
L/H Front Tyre	245/40 R18	GOODYEAR	7 mm	
R/H Rear Tyre	245/40 R18	GOODYEAR	7 mm	
L/H Rear Tyre	245/40 R18	GOODYEAR	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/12/2019	Inspection Date	19/12/2019	
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. EY 668H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAIL GATE	BENT	1,700.00	1,700.00
1	TAIL GATE INNER SEAL	NECESSARY	110.00	110.00
1	TAIL GATE INNER LOCK	DISTORTED	185.00	185.00
1	TAIL GATE LOGO	NECESSARY	115.00	115.00
1	TAIL GATE 'A5' EMBLEM	NECESSARY	70.00	70.00
2	TAIL GATE LAMP @\$550.00	CRACKED	1,100.00	1,100.00
2	TAILLAMP @\$1100.00	CUT	2,200.00	2,200.00
1	REAR END PANEL	BENT	680.00	680.00
1	REAR END PANEL TOP GARNISH	DISTORTED	175.00	175.00
1	REAR BUMPER FASCIA	BENT	1,330.00	1,330.00
1	REAR BUMPER LOWER GARNISH	BENT	277.00	277.00
2	REAR BUMPER PARKING SENSOR @\$190.00	SHORTED	380.00	380.00
1	REAR BUMPER REINFORCEMENT	BENT	490.00	490.00
1	REAR BUMPER SPONGE	SERVICEABLE	128.00	-
1	SPARE TYRE PANEL	DAMAGED	2,950.00	2,950.00
1	FRONT BUMPER FASCIA	DAMAGED	1,600.00	1,600.00
1	RADIATOR GRILLE	CRACKED	595.00	595.00
1	FRONT BUMPER SPONGE	SERVICEABLE	185.00	-
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	659.00	-
2	REAR BUMPER REINFORCEMENT BRACKET @\$192.00 (ADDITIONAL)	DISTORTED	384.00	384.00
1	REAR FLOOR PANEL SPEAKER BOX (ADDITIONAL)	CRACKED	340.00	340.00
	LESS 10% DISCOUNT		-1,565.30	-1,468.10
			14,087.70	13,212.90
1	TAIL GATE RUBBER (50%)	DISTORTED / DENTED	220.00	110.00
	LESS 10% DISCOUNT		-22.00	-
			198.00	110.00

Report Ref No. CC4/FCI19022384/Kda3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	REAR W/S GLASS SEALANT (SN)	NECESSARY	60.00	40.00
1	REAR NO.PLATE WITH BOX (SN)	CRACKED	50.00	45.00
1	FRONT NO.PLATE WITH BOX (SN)	CRACKED	50.00	45.00
			160.00	130.00
	<u>LABOUR</u>			
	TO REMOVE & REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		150.00	120.00
	TO REMOVE ROOF LINING ,FRONT AND REAR SEATS ,TRIM BOARD AND CARPET.		120.00	60.00
	TO APPLY UNDERSEALING.		60.00	60.00
	TO REMOVE AND RENEW EXHAUST SILENCER BOX.		50.00	50.00
	TO PUTTY AND SPRAY REPLACED PARTS.		1,200.00	1,000.00
	TO REMOVE,CUT-OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ABOVE PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT .		1,000.00	800.00
			2,580.00	2,090.00
	GRAND TOTAL		17,025.70	15,542.90
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			10,200.00

Report Ref No. CC4/FCI19022384/Kda3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.