

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06113

Vehicle Insured : SHC7121C
Accident Date : 15-Dec-2019

Date : 16-Dec-2019

Our Ref : 219210 (FIRST) / CHAN

PAGE : 1

LEE SIANG KHENG BERT
22 LORONG PUNTONG
#10-01 COUNTRY GRANDEUR
Singapore 576439

Not Attached

11 Sep 2019

Resurvey After Paint Today

ESTIMATED COST OF REPAIR FOR AUDI A5 SPORTBACK 1.8TSIMU EY668H

1 pc Tail gate
1 pc Tail gate inner seal
1 pc Tail gate inner lock
1 pc Tail gate rubber
1 pc Tail gate logo
1 pc Tail gate "A5" emblem
2 pcs Tail gate lamp
2 pcs Taillamp
1 pc Rear end panel
1 pc Rear end panel top garnish
1 pc Rear bumper fascia
1 pc Rear bumper lower garnish
2 pcs Rear bumper parking sensor
1 pc Rear bumper reinforcement
1 pc Rear bumper sponge
1 pc Spare tyre panel
1 pc Front bumper fascia
1 pc Radiator grille
1 pc Front bumper sponge
1 pc Front bumper reinforcement

ols car @ S\$550.00

ols car @ \$1100.00

shot @ S\$190.00

B1 1,700.00 ✓
na 110.00 ✓
na 185.00 ✓
na 220.00 ✓
na 115.00 ✓
na 70.00 ✓
ols car 1,100.00 ✓
ols car 2,200.00 ✓
B1 680.00 ✓
na 175.00 ✓
B1 1,330.00 ✓
B1 277.00 ✓
B1 380.00 ✓
B1 490.00 ✓
na 128.00 ✓
na 2,950.00 ✓
na 1,600.00 ✓
CM 595.00 ✓
na 185.00 ✓
na 659.00 ✓

15,149.00

Less 10% : 1,514.90

1 pc Rear w/s glass sealant
1 pc Rear no.plate with box
1 pc Front no.plate with box

na 13,634.10
CM 40sn 60.00 sn
CM 45sn 50.00 sn
CM 45sn 50.00 sn

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Page : 2

Vehicle Insured : SHC7121C

To remove & refix rear windscreen
glass and conduct water leak test.

150.00 1201

To remove roof lining, front and
rear seats, trim board and carpet

120.00 601

To apply undersealing

60.00 ✓

To remove and renew exhaust
silencer box

50.00 ✓

To putty and spray replaced parts

1,200.00 10001

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

1,000.00 8001

Total : S\$16,374.10

=====

Singapore Dollars Sixteen Thousand Three Hundred
and Seventy Four and Cents Ten Only