

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06113

Vehicle Insured : SHC7121C  
Accident Date : 15-Dec-2019

Date : 16-Dec-2019

Our Ref : 219210 (FIRST) / CHAN

PAGE : 1

LEE SIANG KHENG BERT  
22 LORONG PUNTONG  
#10-01 COUNTRY GRANDEUR  
Singapore 576439

*Not Attached*

*Call by 810, 2001*

*Resurvey After Paint Today*

## ESTIMATED COST OF REPAIR FOR AUDI A5 SPORTBACK 1.8TSIMU EY668H

|                                  |                                  |
|----------------------------------|----------------------------------|
| 1 pc Tail gate                   | R <sub>1</sub> 1,700.00 ✓        |
| 1 pc Tail gate inner seal        | na 110.00 ✓                      |
| 1 pc Tail gate inner lock        | oil 185.00 ✓                     |
| 1 pc Tail gate rubber            | oil/na 220.00 50% 110 SN         |
| 1 pc Tail gate logo              | na 115.00 ✓                      |
| 1 pc Tail gate "A5" emblem       | na 70.00 ✓                       |
| 2 pcs Tail gate lamp             | oil/na @ S\$550.00 1,100.00 47 ✓ |
| 2 pcs Taillamp                   | oil/na @ \$1100.00 2,200.00 47 ✓ |
| 1 pc Rear end panel              | R <sub>1</sub> 680.00 ✓          |
| 1 pc Rear end panel top garnish  | oil 175.00 ✓                     |
| 1 pc Rear bumper fascia          | R <sub>1</sub> 1,330.00 ✓        |
| 1 pc Rear bumper lower garnish   | R <sub>1</sub> 277.00 ✓          |
| 2 pcs Rear bumper parking sensor | shot @ S\$190.00 380.00 ✓        |
| 1 pc Rear bumper reinforcement   | R <sub>1</sub> 490.00 ✓          |
| 1 pc Rear bumper sponge          | SL 128.00 7 X                    |
| 1 pc Spare tyre panel            | 2,950.00 7 ✓                     |
| 1 pc Front bumper fascia         | 1,600.00 7 ✓                     |
| 1 pc Radiator grille             | CM 595.00 ✓                      |
| pc Front bumper sponge           | SL 185.00 7 X                    |
| 1 pc Front bumper reinforcement  | R 659.00 7 X                     |
|                                  | 15,149.00                        |
| Less 10% :                       | 1,514.90                         |
|                                  | 13,634.10                        |
| 1 pc Rear w/s glass sealant      | na 40% 60.00 sn                  |
| 1 pc Rear no.plate with box      | CM 45% 50.00 sn                  |
| 1 pc Front no.plate with box     | CM 45% 50.00 sn                  |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SHC7121C

Page : 2

To remove & refix rear windscreen  
glass and conduct water leak test.

150.00 1201

To remove roof lining, front and  
rear seats, trim board and carpet

120.00 601

To apply undersealing

60.00 ✓

To remove and renew exhaust  
silencer box

50.00 ✓

To putty and spray replaced parts

1,200.00 10001

To remove, cut-out damaged parts,  
panel beating, welding, align,  
refix and to renew above parts

1,000.00 8001

Total : S\$16,374.10  
=====

Singapore Dollars Sixteen Thousand Three Hundred  
and Seventy Four and Cents Ten Only

4/sum  
12400.00  
A Kenneth  
pls confirm  
TKS

P 12561.30  
S.P. 651.60  
SN 240.00  
L 2090.00  
-----  
15542.90  
3108.58  
-----  
12434.32

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SHC7121C (FIRST)

Date : 20-12-2019

Accident Date : 15-12-2019

Our Ref : 219210 / CHAN

LEE SIANG KHENG BERT  
C/O ALAN'S UNITED AUTO PTE LTD

## SUPPLEMENTARY ITEM PRICE FOR AUDI A5 SPORTBACK 1.8TSI MU EY668H

|       |                                              |           |                 |   |
|-------|----------------------------------------------|-----------|-----------------|---|
| 2 PCS | REAR BUMPER REINFORCEMENT BRACKET @ \$192.00 | <i>my</i> | \$384.00        | ✓ |
| 1 PC  | REAR FLOOR PANEL SPEAKER BOX                 | <i>cm</i> | \$340.00        | ✓ |
|       |                                              |           | <u>\$724.00</u> |   |
|       |                                              | LESS 10%  | <u>\$72.40</u>  |   |
|       |                                              |           | <u>\$651.60</u> |   |

Singapore Dollars Six Hundred Fifty One And Cents Sixty Only