

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9787M**AAD1912-137***Not Authorized*
C/Sing & 62501

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

19 DEC 2019

SHD 9787M

VF1ABL15AUC277266

RENAULT

LATITUDE

18.12.19

III

14/4/2014

PART	LIST
1 BUMPER COVER REAR	\$ Bu 561.70 ✓
1 BUMPER LOWER REAR	\$ Di 411.90 ✓
1 BUMPER BRACKET CTR REAR	\$ SL 98.10 X
1 BUMPER BRACKET SIDE RH REAR	\$ SL 82.10 X
1 BUMPER RETAINER RH REAR	\$ SL 59.80 X
1 BUMPER REFLECTOR RH	\$ Bu 16.60 ✓
1 BUMPER BRACKET SIDE LH REAR	\$ SL 80.80 X
1 BUMPER RETAINER LH REAR	\$ SL 54.20 X
1 BUMPER REFLECTOR LH	\$ SL 16.60 X
1 BUMPER BEAM REAR	\$ B 547.80 ✓
1 BUMPER BEAM BRACKET LH REAR	\$ H 114.50 X
1 BUMPER BEAM BRACKET RH REAR	\$ Di 100.90 ✓
1 BUMPER BLOCK LH REAR	\$ SL 75.70 X
1 BUMPER BLOCK RH REAR	\$ SL 76.50 X
1 BUMPER HARNESS REAR	\$ SL 301.10 X
1 BOOT REAR	\$ B 1,677.20 ✓
1 BOOT FINISHER	\$ SL 344.70 X
1 BOOT WHEATERSTRIP	\$ SL 178.20 X
1 BOOT REFLECTOR LAMP LH	\$ SL 277.70 X
1 BOOT REFLECTOR LAMP RH	\$ SL 277.70 X
1 BOOT BADGE 'RENAULT'	\$ M 82.40 —
1 BOOT BADGE	\$ M 95.80 —
1 BOOT STRUT LH	\$ SL 145.10
1 BOOT STRUT RH	\$ SL 145.10
1 BOOT HINGE LH	\$ H 254.20
1 BOOT HINGE RH	\$ H 253.80
1 BOOT INNER TRIM BOARD	\$ SL 611.00 } X
1 BOOT SWITCH	\$ SL 113.00
1 BOOT LOCK	\$ H 246.60
1 BOOT LOCK CATCH	\$ H 41.70
2 LICENCE PLATE LAMP	\$ SL 26.30 }

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9787M**AAD1912-137**

2	BOOT RUBBER PLUG	\$	Per 139.30	
1	BOOT LOCK LINKAGE	\$	SL 20.60	
1	BOOT LOCK LINKAGE HOLDER	\$	SL 99.50	
1	FENDER PANEL INNER TRIM REAR RH	\$	SL 671.45	
1	FENDER PANEL REAR RH	\$	N 1,933.20	
1	WHEELARCH REAR RH	\$	SL 275.40	
1	TAILLAMP RH	\$	SL 313.10	
1	TAILLAMP PANEL RH	\$	N 401.40	
1	TAILLAMP LH	\$	SL 401.40	
1	TAILLAMP PANEL LH	\$	N 401.40	
1	AIR VENT LH	\$	SL 59.40	
1	AIR VENT RH	\$	SL 59.40	
1	OUTER PANEL REAR (End Panel)	\$	N 745.80	
1	OUTER PANEL REAR (End Panel)TRIM	\$	SL 404.56	X
1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	N 1,229.40	X
1	SPARE WHEEL PANEL TRIM	\$	SL 612.21	X
1	SPARE TYRE BOARD	\$	SL 680.90	X
1	EXHAUST REAR	\$	N 5,263.60	X
1	EXHAUST CAP REAR	\$	MIS 125.40	✓
1	BUMPER COVER FRT	\$	Bu 747.20	✓
1	BUMPER SPOILER FRT	\$	SL 344.70	X
1	BUMPER ABSORBER FRT	\$	SL 394.68	X
1	BUMPER RETAINER FRT LH	\$	SL 101.40	X
1	BUMPER SUPPORT FRT	\$	SL 10.70	X
1	BUMPER RETAINER FRT RH	\$	MIS 101.40	✓
1	BUMPER SUPPORT FRT	\$	SL 10.70	
1	BUMPER UNDERTRAY FRT	\$	SL 292.50	
1	BUMPER GRILLE LOWER FRT	\$	SL 147.00	
1	BUMPER FOG LAMP GRILLE LH	\$	SL 207.21	
1	BUMPER FOG LAMP GRILLE RH	\$	SL 207.21	
1	BUMPER BEAM FRT	\$	N 663.70	
1	TOW COVER FRT	\$	SL 60.90	
1	RADIATOR GRILLE	\$	MIS 969.90	—
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	N 225.36	—
1	RADIATOR GRILLE FRAME	\$	CM 686.00	✓
1	FRAME FULL SUPPORT PANEL	\$	N 592.70	X
1	FRAME FULL SUPPORT BRACKET	\$	N 41.60	X
1	FRONT BRACE PANEL	\$	N 177.22	X
1	HORN	\$	SL 449.90	X

Trans-cab Auto Services Pte Ltd**AAD1912-137**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9787M

1	HORN BRACKET	\$	21.90
1	HEADLAMP LH	\$	743.60
1	HEADLAMP RH	\$	743.60
1	HEADLAMP PANEL FRT LH	\$	127.70
1	HEADLAMP PANEL FRT RH	\$	128.30
1	BONNET	\$	1,312.70
1	BONNET INSULATOR	\$	294.30
1	BONNET STRUT LH	\$	53.30
1	BONNET STRUT RH	\$	53.30
1	BONNET HINGE LH	\$	236.50
1	BONNET HINGE RH	\$	237.40
1	BONNET LOCK	\$	152.80
1	BONNET CABLE	\$	55.20
1	BONNET CABLE COVER	\$	80.60
1	BONNET SEAL OUTER	\$	83.20
1	BONNET SEAL INNER	\$	70.10
1	FENDER PANEL FRT LH	\$	414.40
1	WHEELARCH FRT LH	\$	112.30
1	FENDER BRACKET LOWER LH	\$	11.80
1	FENDER INSULATOR LH	\$	65.50
1	FENDER BRACKET FRT LH	\$	38.90
1	FENDER INSULATOR RH	\$	66.30
1	FENDER PANEL FRT RH	\$	437.10
1	WHEELARCH FRT RH	\$	191.40
1	FENDER BRACKET LOWER RH	\$	11.80
1	FENDER BRACKET FRT RH	\$	106.40
1	WIPER RESERVOIR	\$	179.60
1	WIPER RESERVOIR NECK	\$	29.30
1	WIPER RESERVOIR MOTOR	\$	82.60
1	AIR CLEANER LOWER	\$	271.26
1	AIR CLEANER HOSE	\$	76.14
1	AIR CLEANER BOX	\$	464.20
1	SUBFRAME OUTER FRT	\$	1,094.20
1	SUBFRAME BRACKET OUTER LH	\$	49.00
1	SUBFRAME BRACKET OUTER RH	\$	49.00
1	A/C CONDENSER	\$	1,537.80
1	A/C PIPE CONDENSER TO COMPRESSOR	\$	187.20
1	A/C PIPE CONDENSER TO EXPANSION VALVE	\$	380.20
1	A/C PIPE COMPRESSOR	\$	222.70

pu
X

Trans-cab Auto Services Pte Ltd**AAD1912-137**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9787M

1 A/C PIPE	\$	486.50	} <i>Svc X</i>
1 LOWER ARM LH L70Y	\$	192.70	
1 KNUCKLE ARM LH L70Y	\$	481.50	
1 ABSORBER FRT LH L70Y	\$	274.10	
1 KNUCKLE HUB+BEARING LH/RH	\$	272.30	
1 DRIVESHAFT LH	\$	1,355.70	
1 STEERING PINION RACK	\$	3,765.30	
1 STABILIZER BAR FRT	\$	427.90	
1 LOWER ARM RH L70Y	\$	192.70	
1 KNUCKLE ARM RH L70Y	\$	481.50	
1 ABSORBER FRT RH L70Y	\$	203.50	
1 DRIVESHAFT RH	\$	1,355.70	
TOTAL	\$	47,601.21	
10%	\$	4,760.12	
	\$	42,841.09	

Special Nett

1SET PARKING AID	\$	<i>Sm</i> 700.00 <i>X</i>	
1SET REAR BUMPER CLIP	\$	<i>na</i> 66.00	
1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00	
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00 <i>X</i>	
1SET BUMPER RETAINER RH CLIP RR	\$	<i>na</i> 20.00 <i>X</i>	
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00 <i>X</i>	
1SET BUMPER RETAINER CLIP LH RR	\$	<i>na</i> 20.00 <i>X</i>	
1SET BUMPER LOWER REAR RIVET	\$	<i>na</i> 22.00 <i>X</i>	
1SET BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00	
1 EXHAUST MOUNTING REAR	\$	<i>na</i> 16.00	} <i>X</i>
1 EXHAUST BRACKET REAR	\$	<i>R</i> 24.80	
1SET Rear licence plate with holder	\$	<i>Sm</i> 80.00	
1SET BOOT FINISHER CLIP	\$	<i>na</i> 24.20	
1 BOOT INNER TRIM CLIP	\$	<i>na</i> 45.00	
1 TAILLAMP CLIP RH	\$	<i>na</i> 5.00	
1 TAILLAMP CLIP LH	\$	<i>na</i> 5.00	
1SET FENDER WHEELARCH REAR RH CLIP	\$	<i>na</i> 35.00	
1 FENDER INNER TRIM CLIP RH	\$	<i>na</i> 28.00	
1 Rear Bumper Protector	\$	<i>na</i> 100.00	
2 REAR WINDSCREEN SEALANT	\$	<i>na</i> 80.00	
1 WINDSCREEN MOULDING	\$	<i>na</i> 100.00	
1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i> 100.00	

Trans-cab Auto Services Pte Ltd**AAD1912-137**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9787M

1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sn	385.00	X
1 SPARE TYRE	\$	Sn	330.00	X
1 BOOT STICKER "Trans-cab"	\$	na	30.00	—
1 BOOT STICKER "6555-3333"	\$	na	30.00	—
1SET RADIATOR GRILLE FRAME CLIP	\$	na	52.00	—
1SET BUMPER CLIP FRT	\$	na	66.00	—
1 BUMPER BRACKET CLIP FRT LH	\$	na	12.00	} X
1 BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	
1 BUMPER BRACKET CLIP FRT RH	\$	na	12.00	
1 BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	
1SET RADIATOR GRILLE SCREW	\$	na	16.00	
1SET BUMPER GRILLE LOWER CLIP	\$	na	69.00	} X
1SET FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
2 FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	
2 FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	} 45sn
1SET Front licence plate with holder	\$	na	80.00	
1 WHEELARCH CLIP FRT LH	\$	na	30.50	} X
1 WHEELARCH CLIP FRT RH	\$	na	30.50	
2 BONNET CABLE COVER SCREW L70Y	\$	Sn	10.85	
2 BONNET CABLE CLIP L70Y	\$	na	6.31	
1 FRONT RH RENAULT TYRE RIM	\$	Sn	385.00	
1 FRONT RH RENAULT TYRE	\$	Sn	330.00	} X
1 FRONT LH RENAULT TYRE RIM	\$	Sn	385.00	
1 FRONT LH RENAULT TYRE	\$	Sn	330.00	
1 REAR LH RENAULT TYRE RIM	\$	Sn	385.00	
1 REAR LH RENAULT TYRE	\$	Sn	330.00	
1 REAR RH RENAULT TYRE RIM	\$	Sn	385.00	} X
1 REAR RH RENAULT TYRE	\$	Sn	330.00	
TOTAL	\$		5,751.17	
TOTAL PARTS	\$		48,592.26	

LABOURTo transfer of rear luggage floor panel fittings,
attachment and perform water seepage test.

\$ 170.00 X

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts,
Adjust And Realign The Same

\$ 9,000.00 600/

Trans-cab Auto Services Pte Ltd**AAD1912-137**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9787M

To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	nn	380.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$		170.00	601
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn	170.00	X
Putty And Spray Painting Of The Affected Portion.	\$		9,000.00	8801
To reinstall rear bumper parking sensor.	\$		170.00	601
To Rust-Proofing Of The Affected Areas.	\$		170.00	301
To Check Electrical Lighting Concerned.	\$		170.00	301
To transfer of bootlid fittings, attachments and perform water seepage test.	\$		170.00	601
To supply and re-do rear luggage floor panel insulation padding.	\$	nn	380.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	↪	170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	↪	380.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	↪	380.00	X
To check steering geometry and computer wheel alignment	\$	↪	220.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	↪	380.00	X
To repair and realign rear exhaust pipe.	\$	↪	170.00	X

Trans-cab Auto Services Pte Ltd**AAD1912-137**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9787M

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 340.00	<i>X</i>
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	<i>5</i> 180.00	<i>X</i>
To transfer of front bonnet fittings, attachment and perform water seepage test.	\$	<i>5</i> 180.00	<i>X</i>
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>5</i> 180.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>5</i> 170.00	<i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>5</i> 380.00	<i>X</i>
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>5</i> 380.00	<i>X</i>
To check ABS and brake efficiency, final checking and testing.	\$	<i>5</i> 380.00	<i>X</i>
To vacuum, replace, refix and recharge air condenser	\$	<i>L</i> 380.00	<i>X</i>
TOTAL	\$	24,220.00	
Over All Total	\$	72,812.26	

Repair Days (LUMP SUM)~~30 DAYS~~*7 days*

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--