

00000000

ASS. REF. 190223861

REF: CS/CT1 190223861 kvf36

Special Instruction:

SA/VEH/ Kenneth

ASSIGNMENT (Office)

From (Person) Tan Kah Leong

of CT1

Date/Time 20.12.19 13.18p.m

Estimated Cost

Bill to:

OD / TP / WS / TP RES / OD RES / RYA / INV / MV / C5

to Inspect Vehicle No SFV 398R

Insured:

at Workshop no. Chng Hoe

Tel: 67556142 / 64812001

of BIK 1019 # 01-374/302

Policy No DMPISV 3075291901

Claim No: SNM1912 205931

Sum Insured:

Amount: \$50000

Make of Vch

D.O.A. 10.12.2019

(Client's Branch)

CA / REV / REP. / REV 24 HRS

MV: \$48K

H.O.D. Endorsement

Date/Time 20.12.19 1.45pm

Person Contacted Shawn

Vehicle IN/OUT

Date/Time	Action/Instruction
	(✓) Estimate Insured: 10 ANK Insured (Park on #101-04 SPV 398R - CS/CT1 18/1544/Tikhu DCA-06/01/2013
20/12/19	@ 4.46 pm Spoken to Efeeda vehicle likely TLH, will let insurance to offer
20/12/19	Revert via merimen
27/12/19	Reve approved not exceeding \$7887 from Alfred by merimen

ASS. REC. BY:

REF:

271 / CS/CT#19022386/kvf3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

500

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$ 48k

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

16

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SFV398R

Yr Regn:

08, 05

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Lexus GS300 c.c. 2995

Colour:

m. Silver

A/C: Insured / Std / NI / NA

Sp. Reading

113.438

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JT1HBG 96S105003721

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

215/50R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Habited

Front

Rear

R/Bal.

4 mm

R/Bal.

4 mm

L/Bal.

4 mm

L/Bal.

4 mm

D.O.A.

10/12/19

D.O.A.

20/12/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt, O/S body & U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

27/12/19 Informed Ebeeda c/A LS not exceeding \$7800 ex \$500 by email
 30/12/19 @305pm Doreen said they are unable to repair, informed her will recommend Total Loss
 30/12/19 Submit Uneconomical T/L - mv: \$48K LTA: \$40,113 NV: \$7887

RECEIVED 31 DEC 2019

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

30/12 - typist

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

220

Transportation:

S - RS \$

Fuel

Others

TOTAL

220

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Dec 2019 Sendback Est	18 Dec 2019 13:41 \$21,836.30	20 Dec 2019 13:18 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	SONG JUNSHIK, ID: G0615277K		
Vehicle Reg. No.:	SFV398R	Date of Loss:	10/12/2019 23:00 - :59 [171 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM19D205971/SFV398R/TKL	Policy/Cover Note No.:	DMPCSN3075291901 (Comprehensive)
		Excess:	S\$500.00
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/01/2020]		
Driver/Custodian:	SONG JUNSHIK (/ Male) , NRIC: G0615277K Email:		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 27 December 2019 4:07 PM
To: Cheng Hoe Motor Pte Ltd (Yishun-June); SUR
Subject: SFV 398R-DOA: 10/12/2019

Dear Efeeda,

As instructed by our client , please proceed to repair the **insured vehicle SFV 398R Not Exceeding Lump Sum \$7800/-, (Excess \$500/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SFV398R (SNM19D205971/SFV398R/TKL)

OD

Dec 10 2019 11:00PM

[SONG JUNSHIK]

Cheng Hoe Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on **27/12/2019 15:45 PM**.

To LKK_HQ

Subject Alert - Adj Mandate Approved (\$\$19862.08) - SFV398R - Claim Handler: Tan Kah Leong

Approved:19862.08;Please authorize repairs NO MORE THAN \$7,887.00 (margin for repairs) BEFORE Excess of \$500.00. Proceed as CTL claim if offer is not accepted by Insured.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Tan Kah Leong	Date:	20 Dec 2019

Preliminary Advice

Vehicle No	: SFV398R	Accident Date	: 10/12/2019
Make	: TOYOTA LEXUS GS300 AUTO	Policy No.	: DMPCSN3075291901
Assignment Date	: 20/12/2019	Excess	: S\$500.00
Date of Inspection	: 20/12/2019	Est. Duration of Repair	: 16
Inspection At	: CHENG HOE MOTOR PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion, o/s body and undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	21,836.30
Revised Amount	:S\$	17,057.08
Check Items (Estimated)	:S\$	2,805.00
Total	:S\$	19,862.08

Lump Sum Repair (estimated)	:S\$	15,900.00
-----------------------------	------	-----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	48,000.00
COE / PARF Rebate	:S\$	40,113.00
Salvage Value	:S\$	
Margin for Repair	:S\$	7,887.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Kindly advice on offer repair cost to repairer. Please note the margin repair cost is \$7,887.00

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Foreign Identification Number
Owner ID:	277K
Vehicle Details	
Vehicle No.:	SFV398R
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS GS300
Primary Colour:	Silver
Manufacturing Year:	2005
Engine No.:	3GR0083438
Chassis No.:	JTHBG96S105003721
Maximum Power Output:	170.0 kW (227 bhp)
Open Market Value:	\$53,389.00
Original Registration Date:	30 Aug 2005
First Registration Date:	30 Aug 2005
Transfer Count:	2
Actual ARF Paid:	\$58,728.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Aug 2025
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$70,454.00
COE Rebate Amount:	\$40,113.00
Total Rebate Amount:	\$40,113.00

The information contained herein is correct as at 20 Dec 2019

OK

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Foreign Identification Number
Owner ID:	277K
Vehicle Details	
Vehicle No.:	SFV398R
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS GS300
Primary Colour:	Silver
Manufacturing Year:	2005
Engine No.:	3GR0083438
Chassis No.:	JTHBG96S105003721
Maximum Power Output:	170.0 kW (227 bhp)
Open Market Value:	\$53,389.00
Original Registration Date:	30 Aug 2005
First Registration Date:	30 Aug 2005
Transfer Count:	2
Actual ARF Paid:	\$58,728.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Aug 2025
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$70,454.00
COE Rebate Amount:	\$40,246.00
Total Rebate Amount:	\$40,246.00

The information contained herein is correct as at 13 Dec 2019

OK



lexus gs300

Price Range

Depreciation

> 10 year

Vehicle Type



Submit

Advanced Search

Home > Used Cars > Mr Benz Traders > Lexus GS300 (COE till 11/2025)

Lexus GS300 (COE till 11/2025)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

PREMIUM AD

Price \$49,800

Depreciation ⓘ

N.A.

Reg Date

11-Nov-2005
(5yrs 10mths 28days COE left)

Mileage

140,000 km (9.9k /yr)

Manufactured ⓘ

2005

Road Tax ⓘ

\$3,332 /yr

Transmission

Auto

Dereg Value ⓘ

N.A.

OMV ⓘ

\$49,294

COE ⓘ

\$60,519

ARF ⓘ

\$54,224

Engine Cap

2,994 cc

Power

170.0 kW (227 bhp)

Curb Weight ⓘ

1,660 kg

No. of Owners ⓘ

2

Type of Vehicle

Luxury Sedan

Features

3.0L V6 Engine, 6 Speed Auto With Shift Tronic Transmission, ABS, SRS Airbags, Multi Function Steering Control, Cruise Control, Keyless Entry.

Accessories

Dual Memory Leather Seats, 18" Sports Rims, Factory Fitted Audio System, Reverse Sensors, Fog Lights.

Description

100% Loan Approval! Regularly Service! Accident Free, No Repairs Needed. 6 Months Warranty On Engine & Gearbox! View To Believe! Trade In/Bank/In House Loan Available.

Category

COE Car, Premium Ad Car, Low Mileage Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Mr Benz Traders

77 vehicles for sale, 55 sold in past 3 mths

210 Turf Club Road Lot A6
Car Mall @ The Grandstand
Tel: 63461282
Search cars nearby

Ansai Tan	98607949 ⓘ
Aaron	98797788 ⓘ
Stanley	90012123 ⓘ
Chester Lee	90676766 ⓘ

Posted on: 17-Nov-2019 | Last Updated on: 07-Dec-2019

Upfront Payment
Compare

→ more Financial info

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/12/2019 16:50
Date Of Accident	10/12/2019 23:30
Exact Location Of Accident	CTE TOWARDS SLE (AFTER TUNNEL)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFV398R
Insured/Policyholder	
Name Of Registered Owner	SONG JUNSHIK
Passport No/FIN	G0615277K
Email Address	JUNSHIK2@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-90105900
Alternative Phone No	OTHERS-90105900

Vehicle Particulars

Manufacturer	LEXUS
Model	GS300-3.0 (A)
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3075291901
Cover Note Number	24/11/2019 - 23/11/2020

Driver

Name of Driver	SONG JUNSHIK
Passport No/FIN	G0615277K
Date Of Birth	18/05/1982
Occupation	INDOOR
Date Of Driving Pass	16/04/2015
Driving Experience	4 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90105900
Fax Number	
Contact Number	OTHERS-90105900
Email Address	JUNSHIK2@HOTMAIL.COM

Address	BLK 3 SIN MING WALK #14-28 THE GARDENS AT BISHAN
Postcode	575575
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	UBI AVE 3
Police Station Address	ROAD: 10 UBI AVE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT NO.: T/20191212/2099.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	UNKNOWN
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

Before

After

Exit 6

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle No: SFV398R (China)

Date & Time: 10/12/19 @ 2330

Refer to police report no: T/20191212/2099.

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: (AMK)
NRIC/FIN No.:

GARMC Sketch Pad Form 3/20

☒ Claim Own Policy ☐ Claim Third Party ☐ Reporting Only
☐ Claim OD/TP at other workshop ()

SKETCH PLAN

VEHICLE NO.: SFV398R
INSURER: Ching
DATE & TIME: 10/12/2019 @ 2.30

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

13/Dec/2019

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Sunyn (AMK)
NRIC/FIN No.:

13/12/2019



SINGAPORE POLICE FORCE



T/20191212/2099

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20191212/2099

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 12/12/2019 14:37		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: SONG JUNSHIK			Address: APT BLK 3 SIN MING WALK #14-28 THE GARDENS AT BISHAN SINGAPORE 575575		
ID Type / ID No.: FIN NO / G0615277K			Contact No.: Home/Office: Mobile: 90105900		
Nationality: KOREAN, SOUTH			Email:		
Sex: Male	Age: 37	Date of Birth: 18/05/1982	Type of Informant: Driver		
Race:			Language:		Institution / School Name:
Occupation: OTHERS			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 10/12/2019 23:30	Type of Location:
Location: Along Road 1 CENTRAL EXPRESSWAY CTE TOWARDS SLE AT THE TUNNEL				
Weather: Raining		Road Surface:		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Moderate
Type of Collision:				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SFV398R	Car	TOYOTA	LEXUS GS300	Silver		0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SFV398R	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	DMPCSN30752919 011	24/11/2019	23/11/2020



Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	SONG JUNSHIK	ID No.	G0615277K
Related Vehicle	SFV398R (Car)	Contact No.	90105900
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	SONG JUNSHIK	ID No.	G0615277K
Related Vehicle	NIL	Contact No.	90105900
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

ON THE ABOVE MENTIONED DATE AND TIME,

I WAS DRIVING TOWARDS SLE WHEN ANOTHER CAR SUDDENLY CUT INTO MY LANE, I NOTICED THAT THIS CAR'S REAR LIGHTS WERE EITHER NOT WORKING OR NOT SWITCHED ON, THE DRIVER ALSO DID NOT SIGNAL, AFTER THE OTHER DRIVER COLLIDED INTO MY VEHICLE, THE IMPACT CAUSED MY VEHICLE TO COLLIDE INTO THE CENTRAL DIVIDER, RESULTING IN SOME DAMAGES TO THE SIDE OF MY VEHICLE. I STOPPED MY CAR ABOUT 5 - 10 METERS AHEAD AND TRIED TO LOOK FOR THE OTHER CAR, HOWEVER AS THE COMCOMING TRAFFIC WAS TOO FAST, I WAS UNABLE TO SPOT IT AND I THINK THAT THE OTHER DRIVER HAD ALREADY DROVE OFF. AFTERWRDS I LEFT THE SCENE AND MY AGENT TOLD ME TO GO TO THE POLICE STATION TO LODGE A POLICE REPORT AS SOON AS POSSIBLE.

THAT IS ALL



**SINGAPORE
POLICE FORCE**



T/20191212/2099

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20191212/2099

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
TP /
LEE CHEN EN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIA /
Staff Sgt WONG SIEU LUI
Contact No.: 65476151

Signature Of Informant:

Date/Time:
12/12/2019 14:37

Classification Of Case:

Authentication Stamp
NP168



Efficient Towing Services

403 Sin Ming Avenue #13-307, Sin Ming Garden, Singapore 570403

Ah Di Mobile: 8588 8877

Email: efficienttowing.sg@gmail.com

Business Reg. No.: 53349344K

NO. 42725

CASH SALE / JOB ORDER

Date: 13/12/18

Messrs: Cheng Hoe.
车牌 SPV398N 车型 Lexus
Vehicle No. SPV398N Model No: Lexus
时间 (日/夜) Time (day/night): 联络号码 Contact No:
由 3 Sing Ming Walk
Location: 3 Sing Ming Walk
到 Autoport #88 - Cheng Hoe.
To: Autoport #88 - Cheng Hoe.
报额 \$100 其他 Others:
Cash \$ \$100
经手人 AH02 Tow Truck Driver Name: Vay
Authorised By: AH02

- ☐ Jump Start/Changing of battery
- ☐ Tyre Replacement
- ☐ Accident/Breakdown
- ☒ Multi Basement
- ☐ With Load/Cargo Box
- ☒ King Dolly
- ☐ Transport Charge
- ☐ Low Body Kit
- ☐ Door Opening Service
- ☐ Crane Up/Winch Out
- ☐ Collect Doc/Key
- ☐ Repo
- ☐ Woodlands and Tuas Checkpoint

注意: 本公司对所拖之车辆, 在运行中如有任何损失或破坏, 一概由车主自行负责。

Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

E. & O. E.

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Insurer Reference: DMPCSN3075291901
Repairer Reference: A0074
Date calculated: 18/12/2019 8:56 AM

Full Report
Registration: SFV398R
Printed: 18/12/2019 12:26 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	CHENG HOE	Currency:	SGD
Claim Reference:	DMPCSN3075291901	Date of Incident:	10/12/19
Estimated Repair Time:	14	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	LEXUS
Model:	GS (S19)
Sub Model:	300
Model Sheet Number:	24 15 62
Registration:	SFV398R
VIN number:	JTHBG96S105003721
Odometer:	0

Model Specs

FROM 05/2005	LUXURY
AUTO GEARBOX 6 SPEED	2 WD

PARK PILOT SYSTEM	3.0 LTR 183 KW
PREPARE OFF VEHICLE	TWO COAT PEARL/MICA

Not for body & u/c Not Not make
6/1 Day @?
Perman After Pain
16 days
Ex 8500


Vehicle Condition

Vehicle Status

Pre-Accident Damage:	VEHICLE IN AMK.
Date of Inspection:	

Damage Areas

All ☐
Underbody ☐



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after any painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is only required if required
- No further work to be done
- Single survey report must be completed and submitted to the appropriate insurance company

PRINT DATE 18/12/2019

Admin/Quality Manager
Signature
Date

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
B040)	ADJUST HEADLAMPS		3.0	12.60
NO NUMBER	R + R ENGINE AND GEARBOX		41.0	172.20
B100	R + R L/F WING		4.0	16.80
B130)	RENEW LEFT FRONT PANEL		5.0	21.00
B110)	RENEW LEFT FRONT WING		3.0	12.60
	INCLUDES: TRANSFER ATTACHED PARTS			
B100	R + R LEFT SILL RAIL		5.0	21.00
B100	R + R RIGHT SILL RAIL		5.0	21.00
B110)	RENEW L/SILL MOULDING		3.0	12.60
B010	R + R FRONT BUMPER		7.0	29.40
	(WITH HEADLIGHT CLEANING SYSTEM)			
B020)	RENEW FRONT BUMPER (REMOVED)		13.0	54.60
NO NUMBER	RENEW R/F BUMPER BRACKET		1.0	4.20
B040)	RENEW LEFT HEADLAMP		3.0	12.60
B040)	R + R LEFT HEADLAMP		1.0	4.20
B060	R + R BONNET		3.0	12.60
190011)	R + R BATTERY		2.0	8.40
851091)	R + R WASHER RESERVOIR		7.0	29.40
B125	RENEW LOCK CARRIER		7.0	29.40
B085	R + R COWL GRILLE		2.0	8.40
	INCLUDES: R + R WIPER ARMS			
B210	RENEW LEFT FRONT DOOR		28.0	117.60
	INCLUDES: R + R AND ALIGN LEFT FRONT DOOR,			
	CONVERT ATTACHED PARTS, RENEW IF NECESSARY			
B210	RENEW RIGHT FRONT DOOR		28.0	117.60
	INCLUDES: R + R AND ALIGN RIGHT FRONT DOOR,			
	CONVERT ATTACHED PARTS, RENEW IF NECESSARY			
B210	RENEW RIGHT REAR DOOR		28.0	117.60
	INCLUDES: R + R AND ALIGN RIGHT REAR DOOR,			
	CONVERT ATTACHED PARTS, RENEW IF NECESSARY			
B270	RENEW R/R SIDE PANEL		72.0	302.40
	INCLUDES: R + R BOOT CARPET AND ALL TRIMS IN THE REPAIR SECTION			
	DOES NOT INCLUDE: R + R REAR SCREEN, SEAT CUSHION AND REAR BUMPER			
B350	R + R BOOTLID		5.0	21.00
B370	R + R BOOTLID HINGES		1.0	4.20
NO NUMBER	R + R REAR NO-PLATE		1.0	4.20
G020	R + R REAR SCREEN		33.0	138.60
	INCLUDES: R + R REAR PARCEL SHELF TRIM, REAR SEAT AND SIDE TRIMS			
B410	R + R REAR BUMPER		6.0	25.20
	INCLUDES: R + R BOOT TRIMS			
B420)	RENEW REAR BUMPER (REMOVED)		1.0	4.20
B410)	R + R REAR BUMPER REINFORCEMENT		1.0	4.20
B407)	RENEW RIGHT TAILLAMP		1.0	4.20

Code	Description	WU	Price SGD
B450	R + R REAR SEAT	3.0	12.60
M010	CONDENSER AND ADD RADIATOR R + R INCLUDES: REFILL COOLANT	15.0	63.00
111261)	R + R LEFT ENGINE BEARING	3.0	12.60
NO NUMBER	R + R EXHAUST SYSTEM ATTACHED PARTS	4.0	16.80
444401)	R + R POWER STEERING INCLUDES: DETACH + REFIT SUPPORTING JOINTS, BLEED POWER STEERING DOES NOT INCLUDE: ALIGN FRONT	6.0	25.20
420018)	R + R L/F FRONT WHEEL	1.0	4.20
420018)	R + R R/F FRONT WHEEL	1.0	4.20
420018)	R + R WHEEL/S (ADD/WORK)	1.0	4.20
420091A	R + R L/F TYRE AND WHEEL	3.0	12.60
420091A	R + R R/F TYRE AND WHEEL	3.0	12.60
430011)	DETACH + REFIT R/F FRONT UPPER CONTROL ARM	1.0	4.20
NO NUMBER	R + R FRONT HEADLAMP LEVELLING SENSOR	1.0	4.20
430201)	R + R FRONT STABILIZER	3.0	12.60
NO NUMBER	R + R FRONT AXLE CARRIER	4.0	16.80
430051)	R + R L/F LOWER CONTROL ARM	1.0	4.20
430011)	RENEW L/F UPPER SWINGING ARM	2.0	8.40
434211)	R + R LEFT FRONT STEERING KNUCKLE	6.0	25.20
434211)	RENEW LEFT FRONT STEERING KNUCKLE DOES NOT INCLUDE: VEHICLE ALIGNMENT	5.0	21.00
450251)	R + R STEERING ROD HEAD	4.0	16.80
420018)	R + R L/REAR WHEEL	1.0	4.20
420018)	R + R R/REAR WHEEL	1.0	4.20
420091A)	R + R L/R TYRE AND WHEEL	2.0	8.40
420091A)	R + R R/R TYRE AND WHEEL	2.0	8.40
370021)	R + R PROPELLER SHAFT CPL	5.0	21.00
1477	L/SIDE PANEL WORK	30 40.0*	168.00
1167	L/F UP W-HOUSE REINF REPAIR	20.0*	7 84.00
1207	L/F OUT S-MEMBER PNL REPAIR	20.0*	7 84.00
2227	LEFT A-PILLAR REPAIR	40.0*	7 168.00
2280	RIGHT B-PILLAR REPAIR	20.0*	7 84.00
2711	REAR PANEL REPAIR	15 20.0*	84.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		55.80	558.0
Total of Labour			2,343.60

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT PEARL/MICA	WU Price SGD
	L/F WING NEW PART PAINTING	11.0
	FRT LOCK CARRIER SURFACE PAINT	4.0
	L/F PANEL SURFACE PAINT	4.0
	LEFT FRONT DOOR NEW PART PAINTING	17.0
	RIGHT FRONT DOOR NEW PART PAINTING	17.0
	R/R DOOR NEW PART PAINTING	15.0
	R/R SIDE PANEL NEW PART PAINTING	30.0
	L/F OUT PARK AID SEN NEW PART PAINT K1R	3.0
	FRONT BUMPER NEW PART PAINT K1R	12.0

Paint Work

SYSTEM AZT

Time Basis 10 WU/h

Code	Description - TWO COAT PEARL/MICA	WU	Price SGD
	R/F DOOR OUT HANDLE NEW PART PAINT K1R	3.0	
	R/F HANDLE TRIM NEW PART PAINT K1R	3.0	
	L/F DOOR MOULDING NEW PART PAINT K1R	3.0	
	R/F DOOR MOULDING NEW PART PAINT K1R	3.0	
	L/DOOR MIRROR ASSY NEW PART PAINT K1R	3.0	
	R/DOOR MIRROR ASSY NEW PART PAINT K1R	3.0	
	R/R DOOR OUT HANDLE NEW PART PAINT K1R	3.0	
	R/R DOOR MOULDING NEW PART PAINT K1R	3.0	
	L/F SILL MOULDING NEW PART PAINT K1R	7.0	
	REAR BUMPER NEW PART PAINT K1R	13.0	
	R/R OUT PARKING SENS NEW PART PAINT K1R	3.0	
	R/OUTER SILL PANEL REPAIR PAINTING <50%	10.0	
	BONNET REPAIR PAINTING >50%	40.0	
	LEFT A-PILLAR REPAIR PAINTING >50%	11.0	
	RIGHT B-PILLAR REPAIR PAINTING >50%	14.0	
	REAR PANEL REPAIR PAINTING >50%	17.0	
	R/F OUT PARK AID SEN SURFACE PAINT PLAST.	3.0	
	L/F INNER SENSOR SURFACE PAINT PLAST.	3.0	
	R/F INNER SENSOR SURFACE PAINT PLAST.	3.0	
	R/F WING SURFACE PAINT	6.0	
	L/F UP W-HOUSE REINF SURFACE PAINT	4.0	
	L/F OUT S-MEMBER PNL SURFACE PAINT	4.0	
	L/F DOOR OUT HANDLE SURFACE PAINT PLAST.	3.0	
	L/F HANDLE TRIM SURFACE PAINT PLAST.	3.0	
	L/R DOOR SURFACE PAINT	7.0	
	L/R OUT PARKING SENS SURFACE PAINT PLAST.	3.0	
	L/R CTR PARK SENSOR SURFACE PAINT PLAST.	3.0	
	R/R CTR PARK SENSOR SURFACE PAINT PLAST.	3.0	
	L/R SIDE PANEL SURFACE PAINT	7.0	

Paint Material Per Part

Code	Description	Price SGD
0741	L/F WING NEW PART PAINTING	23.22
1017	FRT LOCK CARRIER SURFACE PAINT	4.48
1187	L/F PANEL SURFACE PAINT	1.25
1481	LEFT FRONT DOOR NEW PART PAINTING	49.02
1482	RIGHT FRONT DOOR NEW PART PAINTING	49.02
1782	R/R DOOR NEW PART PAINTING	39.73
3482	R/R SIDE PANEL NEW PART PAINTING	41.25
0269	L/F OUT PARK AID SEN NEW PART PAINT K1R	0.49
0283	FRONT BUMPER NEW PART PAINT K1R	58.06
1566	R/F DOOR OUT HANDLE NEW PART PAINT K1R	0.98
1586	R/F HANDLE TRIM NEW PART PAINT K1R	0.49
1685	L/F DOOR MOULDING NEW PART PAINT K1R	3.94
1686	R/F DOOR MOULDING NEW PART PAINT K1R	3.94
1737	L/DOOR MIRROR ASSY NEW PART PAINT K1R	3.94
1738	R/DOOR MIRROR ASSY NEW PART PAINT K1R	3.94
1866	R/R DOOR OUT HANDLE NEW PART PAINT K1R	0.98
1986	R/R DOOR MOULDING NEW PART PAINT K1R	2.46
2207	L/F SILL MOULDING NEW PART PAINT K1R	28.04
2583	REAR BUMPER NEW PART PAINT K1R	64.45
2670	R/R OUT PARKING SENS NEW PART PAINT K1R	0.49

Paint Material Per Part

Code	Description	Price SGD
2116	R/OUTER SILL PANEL REPAIR PAINTING <50%	8.72
0471	BONNET REPAIR PAINTING >50%	65.57
2227	LEFT A-PILLAR REPAIR PAINTING >50%	5.14
2280	RIGHT B-PILLAR REPAIR PAINTING >50%	10.67
2711	REAR PANEL REPAIR PAINTING >50%	18.17
0270	R/F OUT PARK AID SEN SURFACE PAINT PLAST.	0.37
0271	L/F INNER SENSOR SURFACE PAINT PLAST.	0.37
0272	R/F INNER SENSOR SURFACE PAINT PLAST.	0.37
0742	R/F WING SURFACE PAINT	11.21
1167	L/F UP W-HOUSE REINF SURFACE PAINT	1.74
1207	L/F OUT S-MEMBER PNL SURFACE PAINT	2.74
1565	L/F DOOR OUT HANDLE SURFACE PAINT PLAST.	0.73
1585	L/F HANDLE TRIM SURFACE PAINT PLAST.	0.37
1781	L/R DOOR SURFACE PAINT	19.17
2669	L/R OUT PARKING SENS SURFACE PAINT PLAST.	0.37
2671	L/R CTR PARK SENSOR SURFACE PAINT PLAST.	0.37
2672	R/R CTR PARK SENSOR SURFACE PAINT PLAST.	0.37
3481	L/R SIDE PANEL SURFACE PAINT	18.68

Labour Cost - Paint

Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint			304.0	
Preparation Main Work Metal		2.50	25.0	105.00
Preparation Comp. Work Plastic		0.50	5.0	21.00
Total	10 WU/h	33.40	334.0	1,402.80

Material Cost - Paint

	Price SGD
New Part Painting	202.24
New Part Painting - Plastic K1R	172.20
Repair Painting	108.27
Surface-/Blend Paint	59.27
Surface Painting Plastic	3.32
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	582.90

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
0269	L/F OUT PARK AID SEN	89341 44150A1			155.00
0283	FRONT BUMPER	52119 30964		CM	350.00
0321	L/INN BUMPER BRACKET	52116 30070	HILAMP bracket	PII	65.00
0323	L/F BUMPER SUPPORT	52536 30190	SIDE Retainer	CM	30.00
0324	R/F BUMPER SUPPORT	52535 30210		SM	30.00
0344	FRT IMPACT ABSORBER	52611 30300	Sponge	CM	55.00
0410	GRILLE	53111 30870			220.00
0420	RADIATOR GRILLE TRIM	52711 30231	CHROME	CM	180.00
0423	UPP RAD GRILLE SEAL	53119 30210	top rubber	CM	22.00
0431	GRILLE BADGE	90975 02082			55.00

Code	Description	Part Number	Supplier	Price SGD	
0561	LEFT HEADLAMP ASSY	81185 30B91		CM 670.00	✓
0617	H/LAMP WASHER VALVE	85208 30031		MT 155.00	✓
0637	L/F FOG LAMP	81221 30282		200.00	?
0707	L/F INDICATOR LAMP	81730 30131		R 26.00	✓
0741	L/F WING	53802 30A00		R 310.00	✓
0767	L/F UPPER WING MLDG	53806 30100		MT 55.00	✓
0841	L/WHEELHOUSE SHELL	53806 30090		CM 105.00	✓
0843	L/WING COVER PANEL	53828 30060		MT 45.00	✓
0883	L/F WHEELARCH MLDG	75872 30370		MT 55.00	✓
1015	UPPER AIR GUIDE	53295 30090		R 90.00	X
1017	FRT LOCK CARRIER	53205 30080		R 115.00	✓
1187	L/F PANEL	53203 30903	H/LAMP PANEL	150.00	?
1481	LEFT FRONT DOOR	67002 30A11		R 590.00	X
1482	RIGHT FRONT DOOR	67001 30841		R 590.00	✓
1509	L/F DOOR SEAL	67862 30280		R 140.00	X
1553	L/DOOR MOULDING	67866 30040	SEAL	R 35.00	✓
1566	R/F DOOR OUT HANDLE	69210 30300A0		MT 190.00	✓
1586	R/F HANDLE TRIM	69217 28010A4		R 15.00	✓
1685	L/F DOOR MOULDING	75072 30080	PROTECTOR	MT 140.00	✓
1686	R/F DOOR MOULDING	75071 30080		R 140.00	✓
1737	L/DOOR MIRROR ASSY	87906 30310B0		CM 500.00	✓
1738	R/DOOR MIRROR ASSY	87901 30250B0		R 500.00	✓
1782	R/R DOOR	67003 30620		R 460.00	✓
1810	R/R DOOR SEAL	67871 30290		140.00	?
1816	R/DOOR MOULDING	67895 30020		R 30.00	✓
1866	R/R DOOR OUT HANDLE	69210 30300A0		CM 190.00	✓
1878	R/R DOOR LOCK	69050 30491		MT 350.00	✓
1986	R/R DOOR MOULDING	75075 30080	PROTECTOR	R 115.00	✓
2207	L/F SILL MOULDING	75852 30902	SIDE SKIRT	MT 320.00	✓
2583	REAR BUMPER	52159 30935		B 310.00	✓
2670	R/R OUT PARKING SENS	89341 30010A1		MT 170.00	✓
3160	REAR SCREEN BOND KIT	P2491 00C1131		R 40.00	✓
3161	LWR REAR SCREEN SEAL	64813 52010		0.00	✓
3163	REAR SCREEN FIX SET	USE SINGLE PARTS			
3167	UPP REAR WINDOW MLDG	75571 30380		R 18.00	✓
3171	L/R WINDOW SEAL	56117 52040		R 18.00	✓
3172	R/R WINDOW SEAL	56117 52040		R 18.00	✓
3173	REAR SCREEN SUPPORTS	56115 30120		0.00	✓
3174	REAR SCREEN SUPPORTS	56116 22050		0.00	✓
3282	R/R MARKER LAMP	81551 30A41		CA 310.00	✓
3482	R/R SIDE PANEL	61611 30881		R 500.00	✓
3688	R/R WHEELARCH MLDG	75873 30370		R 115.00	✓
7049	L/UPPER CONTROL ARM	48630 39085		R 190.00	✓
7063	L/F CONTROL ARM BUSH	48076 30030		R 55.00	✓
7065	L/CARRIER JOINT	43340 39505		90.00	?
7071	L/LWR AXLE STEERING	48640 30290		R 195.00	✓
7077	L/F SHOCK ABSORBER	48520 80174		R 210.00	✓
7081	L/F STEERING KNUCKLE	43202 30020		R 190.00	✓
7085	FRT H-LAMP ADJ SENS	89406 30140		155.00	?
7105	L/F STRUT BEARING	48680 30300		R 90.00	✓
7131	L/F WHEEL HUB CPL	43560 30011		R 130.00	✓
7201	L/F WHEEL	42611 30C80		R 750.00	✓
7202	R/F WHEEL	42611 30C80		R 750.00	X

Code	Description	Part Number	Supplier	88	Price SGD	60 W.
7227	L/F TYRE	225/50 R 17 .. W		Tn	220.00	?
7245	L/F ABS SENSOR	89516 30030			150.00	?
7261	FRONT STABILISER	48811 30661			145.00	?
7269	L/F STABILISER BUSH	48815 30571			20.00	?
7270	R/F STABILISER BUSH	48815 30571			20.00	?
7271	L/F STABI ROD	48810 30070			55.00	?
7300	POWER STEERING CPL	44200 30460		Ad/Tn	2,100.00	✓
8623	L/ENGINE MOUNTING	12361 31101			110.00	?
8780	FRONT ENGINE COVER	51410 30161			240.00	?
8911	FRT AXLE CARRIER	51201 30140			650.00	?
9551	L/R WHEEL	42611 30C80		Ad	750.00	✓
9552	R/R WHEEL	42611 30C80		Ad	750.00	✓

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings	0.00
Subtotal	17,097.00
Fixed Sundry Parts Price	100.00
Total	17,197.00

Extras

Code	Description	Price SGD
1000	COMP WHEEL ALIGNMENT	60.00*
1001	MOUNT ON CAR O LINER	250.00*
	Total Extras	310.00

Final Calculation

	SGD	SGD
Parts		
Fixed Sundry Parts Price	17,097.00	
Total Parts	100.00	17,197.00
Labour Time Base 10 WU/h		
Total 558.0 WU X 42.00 SGD/h	2,343.60	2,343.60
Total of Labour		2,343.60
Total Of Extras		310.00
Paint Work Time Base 10 WU/h		
Labour Cost 334.0 WU X 42.00 SGD/h	1,402.80	1,402.80
Material Cost	582.90	582.90
Total Paint Including Material		1,985.70
Repair Cost Excludes GST		21,836.30
GST (+7.0%)		1,528.54
Repair Cost Included GST		23,364.84

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Report

Insurer Reference: DMPCSN3075291901
Repairer Reference: A0074
Date calculated: 20/12/2019 4:23 PM

Full Report
Registration: SFV398R
Printed: 20/12/2019 4:24 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	DMPCSN3075291901	Date of Incident:	10/12/19
Estimated Repair Time:	14	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details


Vehicle			
Manufacturer:	LEXUS		
Model:	GS (S19)		
Sub Model:	300		
Model Sheet Number:	24 15 62		
Registration:	SFV398R		
VIN number:	JTHBG96S105003721		
Odometer:	0		
Model Specs			
FROM 05/2005	LUXURY	PARK PILOT SYSTEM	3.0 LTR 183 KW
AUTO GEARBOX 6 SPEED	2 WD	PREPARE OFF VEHICLE	TWO COAT PEARL/MICA

Vehicle Condition

Vehicle Status
Pre-Accident Damage: VEHICLE IN AMK.
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
B040)	ADJUST HEADLAMPS		3.0	12.60
NO NUMBER	R + R ENGINE AND GEARBOX		41.0	172.20
B100	R + R L/F WING		4.0	16.80
B130)	RENEW LEFT FRONT PANEL		5.0	21.00
B110)	RENEW LEFT FRONT WING		3.0	12.60
	INCLUDES: TRANSFER ATTACHED PARTS			
B100	R + R LEFT SILL RAIL		5.0	21.00
B100	R + R RIGHT SILL RAIL		5.0	21.00
B110)	RENEW L/SILL MOULDING		3.0	12.60
B010	R + R FRONT BUMPER		7.0	29.40
	(WITH HEADLIGHT CLEANING SYSTEM)			
B020)	RENEW FRONT BUMPER (REMOVED)		13.0	54.60
B040)	RENEW LEFT HEADLAMP		3.0	12.60
B040)	R + R LEFT HEADLAMP		1.0	4.20
B060	R + R BONNET		3.0	12.60
190011)	R + R BATTERY		2.0	8.40
851091)	R + R WASHER RESERVOIR		7.0	29.40
B125	RENEW LOCK CARRIER		7.0	29.40
B085	R + R COWL GRILLE		2.0	8.40
	INCLUDES: R + R WIPER ARMS			
670301)	R + R L/F DOOR TRIM		2.0	8.40
672191	R + R LEFT FRONT OUTER DOOR HANDLE		2.0	8.40
	(DOOR TRIM REMOVED)			
	INCLUDES: R + R DOOR LOCK			
675131)	R + R LEFT FRONT DOOR WINDOW LIFTER		6.0	25.20
	(DOOR TRIM REMOVED)			
751371	R + R L/F OUTER DOOR MOULDING		3.0	12.60
752051)	R + R LEFT MIRROR		1.0	4.20
NO NUMBER	RENEW LEFT FRONT DOOR SEAL		1.0	4.20
B210	RENEW RIGHT FRONT DOOR		28.0	117.60
	INCLUDES: R + R AND ALIGN RIGHT FRONT DOOR,			
	CONVERT ATTACHED PARTS, RENEW IF NECESSARY			
B210	RENEW RIGHT REAR DOOR		28.0	117.60
	INCLUDES: R + R AND ALIGN RIGHT REAR DOOR,			
	CONVERT ATTACHED PARTS, RENEW IF NECESSARY			
B270	RENEW R/R SIDE PANEL		72.0	302.40
	INCLUDES: R + R BOOT CARPET AND ALL TRIMS IN THE REPAIR SECTION			
	DOES NOT INCLUDE: R + R REAR SCREEN, SEAT CUSHION AND REAR BUMPER			
B350	R + R BOOTLID		5.0	21.00
B370	R + R BOOTLID HINGES		1.0	4.20
NO NUMBER	R + R REAR NO-PLATE		1.0	4.20
G020	R + R REAR SCREEN		33.0	138.60
	INCLUDES: R + R REAR PARCEL SHELF TRIM, REAR SEAT AND SIDE TRIMS			
B410	R + R REAR BUMPER		6.0	25.20
	INCLUDES: R + R BOOT TRIMS			

Code	Description	WU	Price SGD
B420)	RENEW REAR BUMPER (REMOVED)	1.0	4.20
B410)	R + R REAR BUMPER REINFORCEMENT	1.0	4.20
B407)	RENEW RIGHT TAILLAMP	1.0	4.20
B450	R + R REAR SEAT	3.0	12.60
M010	CONDENSER AND ADD RADIATOR R + R	15.0	63.00
	INCLUDES: REFILL COOLANT		
111261)	R + R LEFT ENGINE BEARING	3.0	12.60
NO NUMBER	R + R EXHAUST SYSTEM ATTACHED PARTS	4.0	16.80
444401)	R + R POWER STEERING	6.0	25.20
	INCLUDES: DETACH + REFIT SUPPORTING JOINTS,		
	BLEED POWER STEERING		
	DOES NOT INCLUDE: ALIGN FRONT		
420018)	R + R L/FRONT WHEEL	1.0	4.20
420018)	R + R R/FRONT WHEEL	1.0	4.20
420018)	R + R WHEEL/S (ADD/WORK)	1.0	4.20
420091A	R + R L/F TYRE AND WHEEL	3.0	12.60
420091A	R + R R/F TYRE AND WHEEL	3.0	12.60
430011)	DETACH + REFIT R/FRONT UPPER CONTROL ARM	1.0	4.20
NO NUMBER	R + R FRONT HEADLAMP LEVELLING SENSOR	1.0	4.20
430201)	R + R FRONT STABILIZER	3.0	12.60
NO NUMBER	R + R FRONT AXLE CARRIER	4.0	16.80
430051)	R + R L/F LOWER CONTROL ARM	1.0	4.20
430011)	RENEW L/F UPPER SWINGING ARM	2.0	8.40
434211)	R+ R LEFT FRONT STEERING KNUCKLE	6.0	25.20
434211)	RENEW LEFT FRONT STEERING KNUCKLE	5.0	21.00
	DOES NOT INCLUDE: VEHICLE ALIGNMENT		
450251)	R + R STEERING ROD HEAD	4.0	16.80
420018)	R + R L/REAR WHEEL	1.0	4.20
420018)	R + R R/REAR WHEEL	1.0	4.20
420091A)	R + R L/R TYRE AND WHEEL	2.0	8.40
420091A)	R + R R/R TYRE AND WHEEL	2.0	8.40
370021)	R + R PROPELLER SHAFT CPL	5.0	21.00
1477	L/SIDE PANEL WORK	30.0*	126.00
1167	L/F UP W-HOUSE REINF REPAIR	20.0*	84.00
1207	L/F OUT S-MEMBER PNL REPAIR	20.0*	84.00
2227	LEFT A-PILLAR REPAIR	40.0*	168.00
2280	RIGHT B-PILLAR REPAIR	20.0*	84.00
2711	REAR PANEL REPAIR	15.0*	63.00

Labour Cost

Panel / Mechanical Labour

Hrs WU
52.90 529.0 2,221.80

Total of Labour

2,221.80

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT PEARL/MICA	WU Price SGD
	L/F WING NEW PART PAINTING	11.0
	FRT LOCK CARRIER SURFACE PAINT	4.0
	L/F PANEL SURFACE PAINT	4.0
	RIGHT FRONT DOOR NEW PART PAINTING	17.0
	R/R DOOR NEW PART PAINTING	15.0
	R/R SIDE PANEL NEW PART PAINTING	30.0

Code	Description - TWO COAT PEARL/MICA	WU	Price SGD
	L/F OUT PARK AID SEN NEW PART PAINT K1R	3.0	
	FRONT BUMPER NEW PART PAINT K1R	12.0	
	R/F DOOR OUT HANDLE NEW PART PAINT K1R	3.0	
	R/F HANDLE TRIM NEW PART PAINT K1R	3.0	
	L/F DOOR MOULDING NEW PART PAINT K1R	3.0	
	R/F DOOR MOULDING NEW PART PAINT K1R	3.0	
	L/DOOR MIRROR ASSY NEW PART PAINT K1R	3.0	
	R/DOOR MIRROR ASSY NEW PART PAINT K1R	3.0	
	R/R DOOR OUT HANDLE NEW PART PAINT K1R	3.0	
	R/R DOOR MOULDING NEW PART PAINT K1R	3.0	
	L/F SILL MOULDING NEW PART PAINT K1R	7.0	
	REAR BUMPER NEW PART PAINT K1R	13.0	
	R/R OUT PARKING SENS NEW PART PAINT K1R	3.0	
	R/OUTER SILL PANEL REPAIR PAINTING <50%	10.0	
	BONNET REPAIR PAINTING >50%	40.0	
	LEFT A-PILLAR REPAIR PAINTING >50%	11.0	
	RIGHT B-PILLAR REPAIR PAINTING >50%	14.0	
	REAR PANEL REPAIR PAINTING >50%	17.0	
	R/F OUT PARK AID SEN SURFACE PAINT PLAST.	3.0	
	L/F INNER SENSOR SURFACE PAINT PLAST.	3.0	
	R/F INNER SENSOR SURFACE PAINT PLAST.	3.0	
	R/F WING SURFACE PAINT	6.0	
	L/F UP W-HOUSE REINF SURFACE PAINT	4.0	
	L/F OUT S-MEMBER PNL SURFACE PAINT	4.0	
	L/F DOOR OUT HANDLE SURFACE PAINT PLAST.	3.0	
	L/F HANDLE TRIM SURFACE PAINT PLAST.	3.0	
	L/R DOOR SURFACE PAINT	7.0	
	L/R OUT PARKING SENS SURFACE PAINT PLAST.	3.0	
	L/R CTR PARK SENSOR SURFACE PAINT PLAST.	3.0	
	R/R CTR PARK SENSOR SURFACE PAINT PLAST.	3.0	
	L/R SIDE PANEL SURFACE PAINT	7.0	

Paint Material Per Part

Code	Description	Price SGD
0741	L/F WING NEW PART PAINTING	23.22
1017	FRT LOCK CARRIER SURFACE PAINT	4.48
1187	L/F PANEL SURFACE PAINT	1.25
1482	RIGHT FRONT DOOR NEW PART PAINTING	49.02
1782	R/R DOOR NEW PART PAINTING	39.73
3482	R/R SIDE PANEL NEW PART PAINTING	41.25
0269	L/F OUT PARK AID SEN NEW PART PAINT K1R	0.45
0283	FRONT BUMPER NEW PART PAINT K1R	58.06
1566	R/F DOOR OUT HANDLE NEW PART PAINT K1R	0.98
1586	R/F HANDLE TRIM NEW PART PAINT K1R	0.45
1685	L/F DOOR MOULDING NEW PART PAINT K1R	3.94
1686	R/F DOOR MOULDING NEW PART PAINT K1R	3.94
1737	L/DOOR MIRROR ASSY NEW PART PAINT K1R	3.94
1738	R/DOOR MIRROR ASSY NEW PART PAINT K1R	3.94
1866	R/R DOOR OUT HANDLE NEW PART PAINT K1R	0.98
1986	R/R DOOR MOULDING NEW PART PAINT K1R	2.46
2207	L/F SILL MOULDING NEW PART PAINT K1R	28.04
2583	REAR BUMPER NEW PART PAINT K1R	64.45

Paint Material Per Part

Code	Description	Price SGD
2670	R/R OUT PARKING SENS NEW PART PAINT K1R	0.49
2116	R/OUTER SILL PANEL REPAIR PAINTING <50%	8.72
0471	BONNET REPAIR PAINTING >50%	65.57
2227	LEFT A-PILLAR REPAIR PAINTING >50%	5.14
2280	RIGHT B-PILLAR REPAIR PAINTING >50%	10.67
2711	REAR PANEL REPAIR PAINTING >50%	18.17
0270	R/F OUT PARK AID SEN SURFACE PAINT PLAST.	0.37
0271	L/F INNER SENSOR SURFACE PAINT PLAST.	0.37
0272	R/F INNER SENSOR SURFACE PAINT PLAST.	0.37
0742	R/F WING SURFACE PAINT	11.21
1167	L/F UP W-HOUSE REINF SURFACE PAINT	1.74
1207	L/F OUT S-MEMBER PNL SURFACE PAINT	2.74
1565	L/F DOOR OUT HANDLE SURFACE PAINT PLAST.	0.73
1585	L/F HANDLE TRIM SURFACE PAINT PLAST.	0.37
1781	L/R DOOR SURFACE PAINT	19.17
2669	L/R OUT PARKING SENS SURFACE PAINT PLAST.	0.37
2671	L/R CTR PARK SENSOR SURFACE PAINT PLAST.	0.37
2672	R/R CTR PARK SENSOR SURFACE PAINT PLAST.	0.37
3481	L/R SIDE PANEL SURFACE PAINT	18.68

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		287.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.50	5.0	21.00
Total	10 WU/h	31.70	317.0

Material Cost - Paint

	Price SGD
New Part Painting	153.22
New Part Painting - Plastic K1R	172.20
Repair Painting	108.27
Surface-/Blend Paint	59.27
Surface Painting Plastic	3.32
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	533.88

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
0269	L/F OUT PARK AID SEN	89341 44150A1			155.00
0283	FRONT BUMPER	52119 30964			350.00
0321	L/INN BUMPER BRACKET	52116 30070			65.00
0323	L/F BUMPER SUPPORT	52536 30190			30.00
0344	FRT IMPACT ABSORBER	52611 30300			55.00
0410	GRILLE	53111 30870			220.00
0420	RADIATOR GRILLE TRIM	52711 30231			180.00
0423	UPP RAD GRILLE SEAL	53119 30210			22.00
0431	GRILLE BADGE	90975 02082			55.00

Code	Description	Part Number	Supplier	Price SGD
0561	LEFT HEADLAMP ASSY	81185 30B91		670.00
0617	H/LAMP WASHER VALVE	85208 30031		155.00
0637	L/F FOG LAMP	81221 30282		200.00
0707	L/F INDICATOR LAMP	81730 30131		26.00
0741	L/F WING	53802 30A00		310.00
0767	L/F UPPER WING MLDG	53806 30100		55.00
0841	L/WHEELHOUSE SHELL	53806 30090		105.00
0843	L/WING COVER PANEL	53828 30060		45.00
0883	L/F WHEELARCH MLDG	75872 30370		55.00
1017	FRT LOCK CARRIER	53205 30080		115.00
1187	L/F PANEL	53203 30903		150.00
1482	RIGHT FRONT DOOR	67001 30841		590.00
1553	L/DOOR MOULDING	67866 30040		35.00
1566	R/F DOOR OUT HANDLE	69210 30300A0		190.00
1586	R/F HANDLE TRIM	69217 28010A4		15.00
1685	L/F DOOR MOULDING	75072 30080		140.00
1686	R/F DOOR MOULDING	75071 30080		140.00
1737	L/DOOR MIRROR ASSY	87906 30310B0		500.00
1738	R/DOOR MIRROR ASSY	87901 30250B0		500.00
1782	R/R DOOR	67003 30620		460.00
1810	R/R DOOR SEAL	67871 30290		140.00
1816	R/DOOR MOULDING	67895 30020		30.00
1866	R/R DOOR OUT HANDLE	69210 30300A0		190.00
1878	R/R DOOR LOCK	69050 30491		350.00
1986	R/R DOOR MOULDING	75075 30080		115.00
2207	L/F SILL MOULDING	75852 30902		320.00
2583	REAR BUMPER	52159 30935		310.00
2670	R/R OUT PARKING SENS	89341 30010A1		170.00
3160	REAR SCREEN BOND KIT	PZ49I 00C1131		40.00
3161	LWR REAR SCREEN SEAL	64813 52010		0.00
3163	REAR SCREEN FIX SET	USE SINGLE PARTS		
3167	UPP REAR WINDOW	75571 30380		18.00
	MLDG			
3171	L/R WINDOW SEAL	56117 52040		18.00
3172	R/R WINDOW SEAL	56117 52040		18.00
3173	REAR SCREEN	56115 30120		0.00
	SUPPORTS			
3174	REAR SCREEN	56116 22050		0.00
	SUPPORTS			
3282	R/R MARKER LAMP	81551 30A41		310.00
3482	R/R SIDE PANEL	61611 30881		500.00
3688	R/R WHEELARCH MLDG	75873 30370		115.00
7049	L/UPPER CONTROL ARM	48630 39085		190.00
7063	L/F CONTROL ARM BUSH	48076 30030		55.00
7065	L/CARRIER JOINT	43340 39505		90.00
7071	L/LWR AXLE STEERING	48640 30290		195.00
7077	L/F SHOCK ABSORBER	48520 80174		210.00
7081	L/F STEERING KNUCKLE	43202 30020		190.00
7085	FRT H-LAMP ADJ SENS	89406 30140		155.00
7105	L/F STRUT BEARING	48680 30300		90.00
7131	L/F WHEEL HUB CPL	43560 30011		130.00
7201	L/F WHEEL	42611 30C80		750.00
7227	L/F TYRE	225/50 R 17 .. W		88.00
7245	L/F ABS SENSOR	89516 30030		150.00
7261	FRONT STABILISER	48811 30661		145.00
7269	L/F STABILISER BUSH	48815 30571		20.00

Code	Description	Part Number	Supplier	Price SGD
7270	R/F STABILISER BUSH	48815 30571		20.00
7271	L/F STABI ROD	48810 30070		55.00
7300	POWER STEERING CPL	44200 30460		2,100.00
8623	L/ENGINE MOUNTING	12361 31101		110.00
8780	FRONT ENGINE COVER	51410 30161		240.00
8911	FRT AXLE CARRIER	51201 30140		650.00
9551	L/R WHEEL	42611 30C80		750.00
9552	R/R WHEEL	42611 30C80		750.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			15,365.00
u: Used parts	Fixed Sundry Parts Price			100.00
	Total			15,465.00

Extras

Code	Description	Price SGD
1000	COMP WHEEL ALIGNMENT	60.00*
1001	MOUNT ON CAR O LINER	250.00*
7227	[E]: L/F TYRE:	0.00*
	Total Extras	310.00

Final Calculation

	SGD	SGD
Parts	15,365.00	
Fixed Sundry Parts Price	100.00	
Total Parts		15,465.00
Labour Time Base 10 WU/h		
Total 529.0 WU X 42.00 SGD/h	2,221.80	
Total of Labour		2,221.80
Total Of Extras		310.00
Paint Work Time Base 10 WU/h		
Labour Cost 317.0 WU X 42.00 SGD/h	1,331.40	
Material Cost	533.88	
Total Paint Including Material		1,865.28
Repair Cost Excludes GST		19,862.08
GST (+7.0%)		1,390.35
Repair Cost Included GST		21,252.43

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Dec 2019 Sendback Est	18 Dec 2019 13:41 \$521,836.30	20 Dec 2019 13:18 Edit Adj Rpt	\$517,057.08 Edit Estimates	\$517,057.08 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	SONG JUNSHIK, ID: G0615277K								
Vehicle Reg. No.:	SFV398R	Date of Loss:	10/12/2019 23:00 - :59 [171 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM19D205971/SFV398R/TKL		Policy/Cover Note No.:	DMPCSN3075291901 (Comprehensive)					
		Excess:	\$500.00						
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 02/01/2020]								
Driver/Custodian:	SONG JUNSHIK (/ Male), NRIC: G0615277K Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• CHINA_TAIPIING (27/12/2019): Alert - Adj Mandate Approved (\$519862.08) - SFV398R - Claim Handler: Tan Kah Leo...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SFV398R (SNM19D205971/SFV398R/TKL)

OD

Dec 10 2019 11:00PM

[SONG JUNSHIK]

Cheng Hoe Motor Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser
Assessment Reports				1 per page
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail Print
1	18/12/19 13:41	Repairer Estimates		Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	20/12/19 16:51	Adjuster Immediate Advice		Load HTM
Photos/Images				3 per page
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	23/12/19 14:27	General View		Load PDF
Documentation				1 per page
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail Print
1	18/12/19 11:41	GIA REPORT		Load PDF
2	18/12/19 13:41	Repairer's Report		Load PDF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	20/12/19 15:30	MARK ESTIMATE		Load PDF
2	20/12/19 16:38	AUDATEX		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 30px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT119022386/KVF3E2

Date: 07/01/2020

REFERENCE

Insured/Claimant: SONG JUNSHIK Policy No: DMPCSN3075291901
Date of Loss: 10/12/2019 Nature of Claim: OD Claim No: SNM19D205971/SFV398R/TKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFV398R**
Make & Model: TOYOTA LEXUS GS300 AUTO, 3.0 (A) Engine No: 3GR0083438
Reg. Date: 30/08/2005 (Man. Year: 2005) Chassis No: JTHBG96S105003721
Colour: Metallic Silver Odometer: 113438 km
Engine Capacity: 2994 cc
Market Value/New Car Price: S\$48,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50 R17 Rear Tyre Size: 215/50 R17
Front Left Side: Habilead 4 mm Rear Left Side: Habilead 4 mm
Front Right Side: Habilead 4 mm Rear Right Side: Habilead 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,097.00	12,810.00	4,287.00	25.07
Miscellaneous Items	410.00	160.00	250.00	60.98
Labour	4,329.30	4,087.08	242.22	5.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,836.30	17,057.08	4,779.22	21.89
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	21,836.30	16,557.08	5,279.22	24.18
+ GST 7.00/0.00% (S\$)	1,528.54	0.00	1,528.54	100.00
Nett Amount (S\$)	23,364.84	16,557.08	6,807.76	29.14

INSPECTION

Date of Assignment: 20/12/2019
Date Inspected: 20/12/2019 Inspected At: 10 Ang Mo Kio Industrial Park 2A #01-04
Repairer : Cheng Hoe Motor Pte Ltd
Estimated Period of Repair: 0.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(EXCLUDE CHECK ITEMS S\$2,805.00 NETT)

TOTAL LOSS ASPECT

Market Value :	\$48,000.00
OMV :	\$53,389.00
PARF Rebate (1) :	\$0
Quota Premium Paid :	\$70,454.00
COE Rebate (2) :	\$40,113.00
Total Rebate (1) + (2) = :	\$40,113.00

The total amount incurred will be Market Value \$48,000.00 minus Total Rebate \$40,113.00 = \$7,887.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 Jan 2020)
Parts: 143	TOYOTA LEXUS GS300 AUTO 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFV398R)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		17,097.00 F	*12,810.00 F
				Total Parts (S\$)	17,097.00	12,810.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	EXTRAS	310.00	60.00
2	1	SUNDRY (NECESSARY)	100.00	100.00
Sub Total (S\$)			410.00	160.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	2,343.60	2,221.80
2	SPRAY PAINTING	New	1,985.70	1,865.28
Gross Labour Cost (S\$)			4,329.30	4,087.08

Report was unsubmitted during this print-out.

< END OF ESTIMATES >