

ASS. REC. BY:

REF: CS/ASM19022343/Rlv30 Special Instructions:

SUNAVOR RasulASSIGNMENT (Office)From (Person): Kian chuan of ASM (AXM) Date/Time: 20/12/2019

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SJ85369K Insured: _____at Workshop in/s Sng Ah Tee Tel: 6268 6183of BK 3 pioneer Road north #01-18Policy No: _____ Claim No: S9M02AIOSum Insured: _____ Excess: \$2800.00Make of Veh: _____ D.O.A. 15/12/2019

(Client's Record)

CA / REV / REP. / REV 24 HRSDate/Time: 3:24pm @ 20/12/19 Person Contacted: Sumertha Vehicle: IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SJ85369K - NA/INC19011602 / 14 D.O.A. 30/06/201923/12/19 Rasul said repairer agree LS not exceeding \$700023/12/19 Revert via SMART claim31/12/19 Rece authorise repair from Kian chuan by SMART claim21/1/2020 Informed Joyce clA LS not exceeding \$7000, ex \$2800 by email

ASSIGNMENT

COE EXPIRY: 2029/30/04

From: _____ Date: _____
 Estimated Cost: _____
☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SJS 5369K
 at Workshop no: SNH AH TEG
 of 3, PIONEER ROAD NORTH #01-18
ASM (AXA)
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: 2800
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: \$39K

IDAC Accident Report Consistent? Yes or No

GIA / PR Seen Consistent? Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / ☒ REV / REP / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJS 5369K Yr Regt: 2009 / ANA
 Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Hyundai 40 AVANTE 1.6 A cc 1598Colour: Grey A/C: Insured / Std / NI / NASp Reading: 204202 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/Nr: KMH041BR94802951Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ Insured / Jammed / Leaked / Burnt orBrake: ☒ Insured / Jammed / Leaked / Burnt orModi: Nil / ☒ R/Rim / STD A/Rim orTyre Size: F: 195/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Firenza

Front

Rear

R/Bal: 6 mm R/Bal: 6 mmL/Bal: 6 mm L/Bal: 6 mmD.O.A: 15/12/19 D.O.I: 20/12/19Survey held at SNH AH TEG

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S & N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

24/2/20 @ 233pm Spoken to Kian Chuan, include supplementary parts Not Exceeding
 LS \$7000, he said to proceed

24/2/20 LS \$7000 confirmed by email (Ref 3495.99, 337)

RECEIVED 25 FEB 2020

Date/Time, File Pass to?

☐ : Preli. Report

If

☐ : Final Report

Date/Time, File Return to?

24/2 - typst

Add Fee: ☐ : Site Insp \$☐ : Interview \$☐ : Tech. Insp \$☐ : Assess \$

Report Format:

SMART claim

Lump Sum / Mileage

7000/-

Days Of Repair: 9Resurvey No. of Trip: 1

Survey Fee:

290

Transportation

3+RS 3

Meals

Other

Total

290

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 2 January 2020 11:43 AM
To: admin@sngahtee.com; Rasul (LKKAUTO); SUR
Cc: Sharon Sng
Subject: RE: OD AXA: SJS 5369K DOA:15/12/2019

Dear Joyce,

As instructed by our client, please proceed to repair the **insured vehicle SJS 5369K Not Exceeding Lump Sum Repair \$7000/- or whichever lower, (Excess \$2800/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Monday, 30 December 2019 12:44 PM
To: admin@sngahtee.com; Rasul (LKKAUTO) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: OD AXA: SJS 5369K DOA:15/12/2019

Dear Joyce,

Still pending approval from AXA.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: admin@sngahtee.com <admin@sngahtee.com>
Sent: Monday, 30 December 2019 12:34 PM

To: Rasul (LKKAUTO) <Rasul@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: OD AXA: SJS 5369K DOA:15/12/2019

Dear Rasul,

We accept the limit 7k as lump sum repair for the SJS5369K.

Please let us know any authorise repair .

Thanks

Best Regards

Joyce Tan

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



From: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Sent: Monday, December 23, 2019 11:54 AM
To: ADMIN SAT <admin@sngahtee.com>
Cc: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: SJS 5369

Hi Joyce,

As spoken, this vehicle is to be repaired as lump sum basis
Kindly take note

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Printed on Recycled Paper

Save the Earth. Print only when necessary.



Re:RE: Re:PENDING FOR APPROVAL SJS 5369K - 31/12/19

Type

🔗 Question

Message

PLS PROCEED TO AUTHORIZED REPAIRS WITHIN THE ECONOMICAL REPAIR LIMITS.

Reply

Re:PENDING FOR APPROVAL SJS 5369K

Type

🔔 Question

Message

INSURED REPORTED VEH SKIDDED, PLS CHECK THE CONDITION OF INSURED TYRES.

Reply *

Dear Kian Chuan,

According to surveyor, At the time of inspection, all the tyres of the insured vehicle were found to be in good serviceable condition with remaining tread depth of approximately 6 mm.

Best Regards,
Veron Chen

Cancel Reply

Reply Now

New Message

Type *

☒ Message

Subject *

IA SUBMITTED FOR SJS 5369K

Message *

Dear Kian Chuan

Please be informed that IA submitted. Repairer able to repair at Lump Sum Not Exceeding \$7000/. We have Not Authorize repair. Kindly let us have your approval please.Thanks Veron Chen

Cancel

Send



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564312

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 23/12/2019

Survey details

Date of loss	15/12/2019
Date of appointment	20/12/2019
Date of survey	20/12/2019
Location of survey	SNG AH TEE MOTOR PTE LTD

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SJS 5369K
Make and Model	HYUNDAI HD AVANTE 1.6A
Date of registration	24/8/20019
Excess	\$2,800
Market Value	\$37,000.00
Parf Rebate	\$29,306.00
Nett Loss	\$7,694.00

Repair details

Initial Estimate	\$8,449.99
------------------	------------

Proposed/Revised repair cost:

Parts	\$3,701.40
"Check items (Estimated)	\$2,244.00
Labour	\$3,131.49
Total	\$9,076.89
Lump Sum (Estimated)	\$7,261.51

Number of days of repair	9 days (est)
--------------------------	--------------

Remarks:

The vehicle sustained damages at the front n/s portion
and n/s rear portion

Damages Consistent
Repair Cost Economical



Service Request Details

Claim

S9M02AIO

Reference

None 

Loss Date

December 15, 2019

Report Date

Dec 17, 2019 12:00:00 AM

Request Date

December 20, 2019

Due Date

December 30, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information



Make
HYUNDAI

Model
AVANTE 1.6

Service Address

Blk 3 Pioneer Road North, , , 628457

Primary Contact/Insured

SULAIMAN NURHIDAYAT BIN
417 FAJAR ROAD, #02-403, 670417, Singapore

Claim Handler

CHAN Kian Chuan
68805444
kianchuan.chan@axa.com.sg

Additional Instructions

WS: SNG AH TEE XS: \$2,800.00 WP SURVEY DO NOT AUTHORIZE

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	088C
Vehicle Details	
Vehicle No.:	SJ55369K
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Dec 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	HD AVANTE 1.6 A
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	G4FC9U681620
Chassis No.:	KMH DU41BR9U802951
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,224.00
Original Registration Date:	24 Aug 2009
First Registration Date:	24 Aug 2009
Transfer Count:	3
Actual ARF Paid:	\$9,265.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jul 2029
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$30,512.00
COE Rebate Amount:	\$29,306.00
Total Rebate Amount:	\$29,306.00

The information contained herein is correct as at 23 Dec 2019

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	088C
Vehicle Details	
Vehicle No.:	SJ55369K
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Jan 2020
Vehicle Make:	HYUNDAI
Vehicle Model:	HD AVANTE 1.6 A
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	G4FC9U681620
Chassis No.:	KMH DU41BR9U802951
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,224.00
Original Registration Date:	24 Aug 2009
First Registration Date:	24 Aug 2009
Transfer Count:	3
Actual ARF Paid:	\$9,265.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited,
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jul 2029,
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$30,512.00
COE Rebate Amount:	\$29,150.00
Total Rebate Amount:	\$29,150.00

The information contained herein is correct as at 17 Dec 2019

OK 37,000
 29,150
 7,850
 Repair Limit (7K)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/12/2019 13:04
Date Of Accident	15/12/2019 12:30
Exact Location Of Accident	ALONG JLN ANAK BUKIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS5369K
Insured/Policyholder	
Name Of Registered Owner	NURHIDAYAT BIN SULAIMAN
NRIC No	S8317088C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94778166
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	HYUNDAI
Model	AVANTE-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA485609
Cover Note Number	

Driver

Name of Driver	RAJA FADDLY SHAH BIN RAJA MD LOKMAN
NRIC No	S9917010G
Date Of Birth	26/05/1999
Occupation	INDOOR
Date Of Driving Pass	08/03/2018
Driving Experience	1 YEAR AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94778166
Fax Number	
Contact Number	
Email Address	FADDLYSHAHH@GMAIL.COM

Address	BLK 121 PENDING RD #08-158
Postcode	670121
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - COUSIN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : RAJA MD LOKMAN BIN RAJA AZIZ GENDER: : MALE
Passenger 2	NAME: : NORLIDA BTE SWED GENDER: : FEMALE
Passenger 3	NAME: : NORASHIKIN BINTE DAYD GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT T/201912167038

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF INJURED PERSON 1

Name	RAJA FADDLY SHAH BIN RAJA MD LOKMAN
Approximate Age	
Injuries Sustain	

Injured person in which vehicle? SJS5369K

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

DETAILS OF INJURED PERSON 2

Name RAJA MD LOKMAN BIN RAJA AZIZ

Approximate Age

Injuries Sustain

Injured person in which vehicle? SJS5369K

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

DETAILS OF INJURED PERSON 3

Name NORLIDA BTE SWED

Approximate Age

Injuries Sustain

Injured person in which vehicle? SJS5369K

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

DETAILS OF INJURED PERSON 4

Name NORASHIKIN BINTE DAYD

Approximate Age

Injuries Sustain

Injured person in which vehicle? SJS5369K

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

II. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A **14 DAYS TIMEFRAME** FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report T/20191216/7038

Remark: Owner was unable to sign because owner is at the prison.

☒ Claim own policy
☐ Claim third party
☐ Claim OD / TP at other works hop
☐ For record purpose

DECLARATION

I/We declare the foregoing particulars are true in every respect.

☒ Claim own policy
☐ Claim third party
☐ Claim OD / TP at other works hop _____
☐ For record purpose

Policy No. GA485609
Insured ARYA Yeh No. STSS534K

Policyholder's Signature _____
Date & Time: _____

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name: _____
NRIC/PIN No.: _____



**SINGAPORE
POLICE FORCE**



T/20191216/7038

1 of 4

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20191216/7038

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 16/12/2019 20:48		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: RAJA FADDLY SHAH BIN RAJA MD LOKMAN			Address: APT BLK 121 PENDING ROAD #08-158 SINGAPORE 670121		
ID Type / ID No.: NRIC NO / S9917010G			Contact No.: Home/Office:		Mobile: 94778166
Nationality: SINGAPORE CITIZEN			Email: faddyshahh@gmail.com		
Sex: Male	Age: 20	Date of Birth: 26/05/1999	Type of Informant: Driver		
Race: Malay			Language: English		Institution / School Name:
Occupation: Student			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 15/12/2019 12:30	Type of Location: Bend
Location: JALAN ANAK BUKIT				
Weather: Raining		Road Surface: Wet	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume:	
Type of Collision: Self Skid			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJS5369K	Car				Slightly Damaged	3

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20191216/7038

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 4

Report No. T/20191216/7038

CONTINUATION OF REPORT

Driver:			
Name	RAJA FADDLY SHAH BIN RAJA MD LOKMAN	ID No.	S9917010G
Related Vehicle	SJS5369K (Car)	Contact No.	94778168
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger:			
Name	RAJA MD LOKMAN BIN RAJA AZIZ	ID No.	S1723977E
Related Vehicle	SJS5369K (Car)	Contact No.	91773100
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	02	Degree of Injury	Slight
Passenger:			
Name	NORLIDA BTE SWED	ID No.	S6904769F
Related Vehicle	SJS5369K (Car)	Contact No.	96218766
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	02	Degree of Injury	Slight
Passenger:			
Name	NORASHIKIN BINTE DAYD	ID No.	S8031869C
Related Vehicle	SJS5369K (Car)	Contact No.	91830959
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	02	Degree of Injury	Slight



**SINGAPORE
POLICE FORCE**



T/20191216/7035

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 4

Report No. T/20191216/7035

CONTINUATION OF REPORT

Brief Details.

On stated time and date, I was the driver of the vehicle bearing carplate number SJS5369K. I have 3 passengers on board with me and travelling at Jalan Anak Bukit.

When approaching the bend, my vehicle skidded and collided onto the wall.

Due to the accident, my passengers suffered injuries and consult a doctor and get a 2 days MC.



**SINGAPORE
POLICE FORCE**



T/20191216/7038

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

4 of 4

Report No. T/20191216/7038

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
JUREMAH BINTE AHMAD
Contact No.: 65476219

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
16/12/2019 20:48

Classification Of Case:

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North, #01-18,
628457

Insurer Reference: S9M02AIO
Repaire Reference: SJS5369K-OD AXA
Date calculated: 19/12/2019 3:20 PM

Full Report
Registration: SJS5369K-OD AXA
Printed: 19/12/2019 3:21 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	DARREN SNG	Currency:	SGD
Claim Reference:	S9M02AIO	Date of Incident:	15/12/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	HYUNDAI
Model:	AVANTE (HD)
Sub Model:	BASIS
Model Sheet Number:	30 22 50
Registration:	SJS5369K-OD AXA
VIN number:	KMH DU41BR9U802951
Odometer:	

Model Specs

FROM 07/2009	AIR CONDITIONING	FOG LAMPS	1.6 LTR 90 KW
TWO COAT METALLIC	PREPARE OFF VEHICLE		


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Time Base 10 WU/h

Price = 45.00 SGD/h



Code	Description	WU	Price SGD
NO NUMBER	ALIGN W/O ADJUST FRONT VEHICLE	6.0	27.00
86510R00	RENEW COMPLETE FRONT BUMPER INCLUDES: FRONT BUMPER, FRONT BUMPER REINFORCEMENT AND REQUIRED ATTACHED PARTS R + R AND IF NECESSARY RENEW.	6.0	27.00
NO NUMBER	RENEW FR NUMBER PLATE (REMOVED)	1.0	4.50
92000R0B	REMOVE/REFIT BOTH HEADLIGHT UNITS INCLUDES: SET HEADLIGHT BEAMS	3.0	13.50
66400R00	RENEW BONNET INCLUDES: R + R BONNET, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	6.0	27.00
79110R0B)	R + R BONNET HINGES (BONNET REMOVED)	2.0	9.00
66300R0B	R + R BOTH FRONT WINGS	13.0	58.50
NO NUMBER	R + R LEFT FRONT WING BADGE	2.0	9.00
NO NUMBER	R + R RIGHT FRONT WING BADGE	2.0	9.00
NO NUMBER	R + R FRONT PANEL	20.0	90.00
86111R00	R + R WINDSCREEN INCLUDES: R + R INTERIOR MIRROR, WIPER ARMS, WINDSCREEN FRAME COVER, ROOF STORAGE CONSOLE, SUN VISORS AND A-PILLAR TRIMS	20.0	90.00
86651R00	RENEW REAR BUMPER INCLUDES: R + R REAR BUMPER, TAIL LAMPS AND NECESSARY TRIMS, CONVERT ATTACHED PARTS, RENEW IF NECESSARY DOES NOT INCLUDE: R + R REAR BUMPER REINFORCEMENT	8.0	36.00
97606R00	R + R AIR CONDITIONING CONDENSER	10.0	45.00
NO NUMBER	R + R CONDENSER-/EVAPORATOR PIPE	5.0	22.50
97763R00	R + R COMPRESSOR-EVAPORATOR	5.0	22.50
89050R00	R + R REAR SEAT CUSHION	4.0	18.00
37110R00	R + R BATTERY	2.0	9.00
25300R00)	R + R RADIATOR INCLUDES: R + R COMPLETE RADIATOR SHROUD	7.0	31.50
21830R1G	R + R REAR ENGINE SUPPORT	5.0	22.50
NO NUMBER	R + R LEFT FRONT WHEEL	1.0	4.50
NO NUMBER	R + R RIGHT FRONT WHEEL	1.0	4.50
NO NUMBER	R + R FRONT WHEEL(S)	1.0	4.50
62410R00)	R + R FRONT AXLE CARRIER	5.0	22.50
62465R00)	R + R FRONT AXLE SUPPORT BEARING	2.0	9.00
51715R00)	R + R L/F STEERING KNUCKLE	5.0	22.50
51715R00)	RENEW L/F STEERING KNUCKLE (REMOVED) INCLUDES: R + R BRAKE DISC, WHEEL HUB AND BRAKE DISC SHIELD	4.0	18.00
54630R00)	R + R L/F STRUT	2.0	9.00
54630R00)	DISS/ASS L/F SUSPENSION STRUT REMOVED	2.0	9.00
54509R00)	R + R LEFT FRONT LOWER CONTROL ARM	2.0	9.00
57700R00)	REMOVE/REFIT STEERING BOX (WITH FRONT SUSPENSION ARMS REMOVED)	4.0	18.00
NO NUMBER	R + R L/TIE ROD	2.0	9.00

Code	Description	WU	Price SGD
NO NUMBER	(STEERING GEAR REMOVED) R + R R/TIE ROD	2.0	9.00
52910R00	(STEERING GEAR REMOVED) R + R L/F TYRE (WHEEL REMOVED) INCLUDES: BALANCE WHEEL	4.0	18.00
31150R00)	R + R FUEL TANK	4.0	18.00
NO NUMBER	DRAIN/REFILL COOLING SYSTEM	3.0	13.50
09760A00	DRAIN + REFILL AIR CONDITIONING	5.0	22.50
1201	L/F SIDE MEMBER REPAIR	5.0*	22.50
1202	R/F SIDE MEMBER REPAIR	5.0*	22.50
3481	L/R SIDE PANEL REPAIR	10 25.0*	112.50
4101	L/INNER SIDE PANEL REPAIR	15 25.0*	112.50
Labour Cost		Hrs	WU
Panel / Mechanical Labour		23.00	230.0
Alignment			
Measuring Work		0.60	6.0
Total of Labour			1,062.00

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU	Price SGD
	FRT BUMPER SUPPORT SURFACE PAINT	4.0	
	BONNET NEW PART PAINTING	24.0	
	L/F WING NEW PART PAINTING	10.0	
	R/F WING NEW PART PAINTING	10.0	
	BATTERY CARRIER SURFACE PAINT	4.0	
	L/F WHEEL NEW PART PAINTING	7.0	
	FRONT BUMPER NEW PART PAINT K1N	12.0	
	GRILLE NEW PART PAINT K1R	4.0	
	REAR BUMPER NEW PART PAINT K1N	12.0	
	L/R SIDE PANEL REPAIR PAINTING >50%	22.0	
	L/F SIDE MEMBER SURFACE PAINT	4.0	
	R/F SIDE MEMBER SURFACE PAINT	4.0	
	LEFT FRONT DOOR SURFACE PAINT	8.0	
	RIGHT FRONT DOOR SURFACE PAINT	8.0	
	R/OUTER A-PILLAR SURFACE PAINT	4.0	
	L/INNER SIDE PANEL SURFACE PAINT	5.0	

Paint Material Per Part

Code	Description	Price SGD
0340	FRT BUMPER SUPPORT SURFACE PAINT	4.23
0471	BONNET NEW PART PAINTING	78.43
0741	L/F WING NEW PART PAINTING	18.06
0742	R/F WING NEW PART PAINTING	18.06
1331	BATTERY CARRIER SURFACE PAINT	1.00
7201	L/F WHEEL NEW PART PAINTING	5.16
0283	FRONT BUMPER NEW PART PAINT K1N	53.95
0410	GRILLE NEW PART PAINT K1R	7.87
2583	REAR BUMPER NEW PART PAINT K1N	53.95

Paint Material Per Part

Code	Description	Price SGD
3481	L/R SIDE PANEL REPAIR PAINTING >50%	28.44
1201	L/F SIDE MEMBER SURFACE PAINT	3.24
1202	R/F SIDE MEMBER SURFACE PAINT	3.24
1481	LEFT FRONT DOOR SURFACE PAINT	20.17
1482	RIGHT FRONT DOOR SURFACE PAINT	20.17
2228	R/OUTER A-PILLAR SURFACE PAINT	3.74
4101	L/INNER SIDE PANEL SURFACE PAINT	5.98

Labour Cost - Paint

Factor	45.00 SGD/h	Hrs	WU	Price SGD
Time Paint			142.0	
Preparation Main Work Metal		2.50	25.0	112.50
Preparation Comp. Work Plastic		0.80	8.0	36.00
Total	10 WU/h	17.50	175.0	787.50

Material Cost - Paint

	Price SGD
New Part Painting	119.71
New Part Painting - Plastic K1R	7.87
New Part Painting - Plastic K1N	107.90
Repair Painting	28.44
Surface-/Blend Paint	61.77
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	366.99

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
0257	FRONT NUMBER PLATE	KNPL3 4W X			0.00
0283	FRONT BUMPER	865112H000	def		200.00
0287	FRONT BUMPER SPOILER	865902H000	cut		20.00
0299	FRT BUMPER AIR GRILL	865612H001	cut		35.00
0315	FRT BUMPER ABSORBER	865202H010	cut		55.00
0321	L/BUMPER MNTG REINF	865132H000	st		25.00
0322	R/BUMPER MNTG REINF	865142H000	X sul		25.00
0327	LEFT RETAINER	1491005000	na		18.00
0328	RIGHT RETAINER	1491005000	na		18.00
0340	FRT BUMPER SUPPORT	865302H010	st		115.00
0350	FRT BUMPER CLAMP KIT	USE SINGLE PARTS	na		15.00
0410	GRILLE	863502H000	cut		130.00
0471	BONNET	664002H010	bt		350.00
0475	LEFT BONNET HINGE	791102H000	bt		25.00
0476	RIGHT BONNET HINGE	791202H000	bt		25.00
0493	BONNET LOCK	811302H900	bt		25.00
0524	BONNET FRONT SEAL	864352H000	na		12.00
0561	LEFT HEADLAMP ASSY	921012H091	cut		190.00
0562	RIGHT HEADLAMP ASSY	921022H091	cut		190.00
0637	L/F FOG LAMP	922012H000	cut		80.00
0741	L/F WING	663112H022	bt		140.00

Code	Description	Part Number	Supplier	Price SGD
0742	R/F WING	663212H022	bt	140.00
0811	L/F WING BADGE	863162H000	svl X	0.00
0812	R/F WING BADGE	863162H000	svl X	0.00
0841	L/F WHEELHOUSE COVER	868112H010	can	35.00
0842	R/F WHEELHOUSE COVER	868122H010	can	35.00
0843	L/SCREW	1249306207B	can	12.00
0844	R/SCREW	1249306207B	can	12.00
1009	INNER FRT PANEL CPL	641012H000	de	250.00
1331	BATTERY CARRIER	371502H100	? can	20.00
1393	LWR WINDSCREEN COVER	861502H900	can	50.00
1423	L/COWL MOULDING	861502H910	can	16.00
1424	R/COWL MOULDING	861602H910	? can Xsvl	16.00
2583	REAR BUMPER	866102H000	de	220.00
2650	RR BUMPER CLAMP KIT	USE SINGLE PARTS	can	15.00
3281	L/R OUTER LAMP	924012H010	bro	95.00
3283	L/NUT	1227005001	can	2.00
3284	R/NUT	1227005001	can	2.00
4465	AIR CON CONDENSER	976062H010	bt	180.00
4481	COND/EVAPORATOR PIPE	977682L000	? ? Xsvl	160.00
4482	COMPR/EVAP PIPE	977642L000	? Xsvl	80.00
7023	L/F ENGINE MOUNTING	624852H000	? can Xsvl	70.00
7024	R/F ENGINE MOUNTING	624852H000	? can Xsvl	70.00
7053	L/F LWR CONTROL ARM	545002H000	? bt	110.00
7077	L/F SHOCK ABSORBER	546512H000	? bt	125.00
7081	L/F STEERING KNUCKLE	517152H000	? bt	130.00
7117	L/F WHEEL BEARING	517202H000	? can	45.00
7131	L/F WHEEL HUB	517502H000	? bt	75.00
7201	L/F WHEEL	529102H090	? Xsvl	0.00
7227	L/F TYRE	185/65 R 15	... H, punctured	0.00
7309	L/TIE ROD	565402H000	? can Xsvl	50.00
7310	R/TIE ROD	565312H000	? can	50.00
7311	L/OUTER TIE ROD BALL	568202H000	? Xsvl	40.00
7312	R/OUTER TIE ROD BALL	568202H090	? Xsvl	40.00
7755	L/RADIATOR AIR GUIDE	291352H000	can	17.00
7756	R/RADIATOR AIR GUIDE	291362H000	? can	17.00
7761	RADIATOR	253102H000	? bt	260.00
7773	LWR RADIATOR HOSE	254152H001	? Xsvl	25.00
7789	FAN SHROUD CPL	253802H060	? can	115.00
8389	AIR INTAKE HOSE	282111H000	? Xsvl	85.00
8404	AIR FILTER RESONATOR	281902H000	? Xsvl	65.00
8632	R/ENGINE MOUNTING	218100Q000	? can	90.00
8780	LWR ENG COMP COVER	291102H200	? can	30.00
9629	BATTERY	3711029200	? Xsvl	0.00
9631	BATTERY BOX	371121G000	? Xsvl	32.00
1001	FRT BUMPER	UNDERCOVER CLIP	can	15.00
1002	FRT BONNET LOCK	OUTER COVER	Xsvl	6.00
1011	ENGINE MOUNTING	FRONT	? can	70.00
1012	ENGINE MOUNTING	REAR	? can	70.00
1013	ENGINE MOUNTING	LH	? can	100.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings
Subtotal

0.00
4,835.00

Addition(+10.00%)

483.50

Total**5,318.50****Extras**

Code	Description	Price SGD
0350	[E]: FRT BUMPER CLAM P KIT: x SVL	0.00*
1000	FRT NUMBER PLATE gen ✓	35.00*
1003	COOLANT - ne ✓	20.00*
1004	BATTERY - xme ✓	200.00*150
1005	FRT TYRE LH panned 196 702	280.00*
1006	FRT RIM LH 51 ✓	180.00*
1007	TO CHECK WIRING	20 ✓ 30.00*
1008	TOP UP AIRCON GAS	30 ✓ 50.00*
1009	TO DO WHEEL ALIGNMENT an ✓	60.00*
1010	TO DO WHEEL ALIGNMENT xrepended	X 60.00*
Total Extras		915.00

Final Calculation

	HP 90010068	SGD	SGD
Parts		4,835.00	
Addition(+10.00%)		483.50	
Total Parts	9 days 4/8		5,318.50
Labour Time Base 10 WU/h	20/12/19 @1610	1,035.00	850.50
Total 230.0 WU X 45.00 SGD/h			
Alignment			
Measuring Work	EXCESS: 2800	27.00	57
Total of Labour			1,062.00
Total Of Extras	REVERT		915.00
Paint Work Time Base 10 WU/h			
Labour Cost 175.0 WU X 45.00 SGD/h	Resurvey after before repair	787.50	✓
Material Cost		366.99	✓
Total Paint Including Material			1,154.49
Repair Cost Excludes GST		10,495.99	8,449.99
GST (+7.0%)			591.50
Repair Cost Included GST			9,041.49

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LIK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be removed and is subject to final approval from Insurers Company

Acknowledged by Repairer

Signature:

Date:

Code	Description	WU	Price SGD
	(WHEEL REMOVED)		
	INCLUDES: BALANCE WHEEL		
31150R00)	R + R FUEL TANK	4.0	18.00
NO NUMBER	DRAIN/REFILL COOLING SYSTEM	3.0	13.50
09760A00	DRAIN + REFILL AIR CONDITIONING	5.0	22.50
1201	L/F SIDE MEMBER REPAIR	5.0*	22.50
1202	R/F SIDE MEMBER REPAIR	5.0*	22.50
3481	L/R SIDE PANEL REPAIR	10.0*	45.00
4101	L/INNER SIDE PANEL REPAIR	15.0*	67.50

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	18.90	189.0	850.50
Alignment			
Measuring Work	0.60	6.0	27.00
Total of Labour			877.50

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	FRT BUMPER SUPPORT SURFACE PAINT	4.0 22.50
	BONNET NEW PART PAINTING	24.0 22.50
	L/F WING NEW PART PAINTING	10.0 22.50
	R/F WING NEW PART PAINTING	10.0 45.00
	BATTERY CARRIER SURFACE PAINT	4.0 67.50
	L/F WHEEL NEW PART PAINTING	7.0
	FRONT BUMPER NEW PART PAINT K1N	12.0
	GRILLE NEW PART PAINT K1R	4.0 850.50
	REAR BUMPER NEW PART PAINT K1N	12.0
	L/R SIDE PANEL REPAIR PAINTING >50%	22.0 27.00
	L/F SIDE MEMBER SURFACE PAINT	4.0
	R/F SIDE MEMBER SURFACE PAINT	4.0 877.50
	LEFT FRONT DOOR SURFACE PAINT	8.0
	RIGHT FRONT DOOR SURFACE PAINT	8.0
	R/OUTER A-PILLAR SURFACE PAINT	4.0 10 WU/h
	L/INNER SIDE PANEL SURFACE PAINT	5.0 Price SGD

Paint Material Per Part

Code	Description	Price SGD
0340	FRT BUMPER SUPPORT SURFACE PAINT	4.23
0471	BONNET NEW PART PAINTING	78.43
0741	L/F WING NEW PART PAINTING	18.06
0742	R/F WING NEW PART PAINTING	18.06
1331	BATTERY CARRIER SURFACE PAINT	1.00
7201	L/F WHEEL NEW PART PAINTING	5.16
0283	FRONT BUMPER NEW PART PAINT K1N	53.95
0410	GRILLE NEW PART PAINT K1R	7.87
2583	REAR BUMPER NEW PART PAINT K1N	53.95
3481	L/R SIDE PANEL REPAIR PAINTING >50%	28.44
1201	L/F SIDE MEMBER SURFACE PAINT	3.24
1202	R/F SIDE MEMBER SURFACE PAINT	3.24
1481	LEFT FRONT DOOR SURFACE PAINT	20.17

Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
NO NUMBER	ALIGN W/O ADJUST FRONT VEHICLE		6.0	27.00
86510R00	RENEW COMPLETE FRONT BUMPER INCLUDES: FRONT BUMPER, FRONT BUMPER REINFORCEMENT AND REQUIRED ATTACHED PARTS R + R AND IF NECESSARY RENEW.		6.0	27.00
NO NUMBER	RENEW FR NUMBER PLATE (REMOVED)		1.0	4.50
92000R0B	REMOVE/REFIT BOTH HEADLIGHT UNITS INCLUDES: SET HEADLIGHT BEAMS		3.0	13.50
66400R00	RENEW BONNET INCLUDES: R + R BONNET, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		6.0	27.00
79110R0B)	R + R BONNET HINGES (BONNET REMOVED)		2.0	9.00
66300R0B	R + R BOTH FRONT WINGS		13.0	58.50
NO NUMBER	R + R LEFT FRONT WING BADGE		2.0	9.00
NO NUMBER	R + R RIGHT FRONT WING BADGE		2.0	9.00
NO NUMBER	R + R FRONT PANEL		20.0	90.00
86111R00	R + R WINDSCREEN INCLUDES: R + R INTERIOR MIRROR, WIPER ARMS, WINDSCREEN FRAME COVER, ROOF STORAGE CONSOLE, SUN VISORS AND A-PILLAR TRIMS		20.0	90.00
86520R00	RENEW REAR BUMPER CPL INCLUDES: REAR BUMPER, REAR LAMPS, REINFORCEMENT REAR BUMPER AND REQUIRED TRIMS REMOVE AND REFIT ATTACHED PARTS ASSEMBLE IF NECESS RENEW		8.0	36.00
97606R00	R + R AIR CONDITIONING CONDENSER		10.0	45.00
89050R00	R + R REAR SEAT CUSHION		4.0	18.00
37110R00	R + R BATTERY		2.0	9.00
25300R00)	R + R RADIATOR INCLUDES: R + R COMPLETE RADIATOR SHROUD		7.0	31.50
21830R1G	R + R REAR ENGINE SUPPORT		5.0	22.50
NO NUMBER	R + R LEFT FRONT WHEEL		1.0	4.50
NO NUMBER	R + R RIGHT FRONT WHEEL		1.0	4.50
NO NUMBER	R + R FRONT WHEEL(S)		1.0	4.50
62410R00)	R + R FRONT AXLE CARRIER		5.0	22.50
62410R00)	RENEW FRONT AXLE SUPPORT (REMOVED) INCLUDES: R + R STEERING GEAR AND FRONT STABILIZER		4.0	18.00
51715R00)	R + R L/F STEERING KNUCKLE		5.0	22.50
51715R00)	RENEW L/F STEERING KNUCKLE (REMOVED) INCLUDES: R + R BRAKE DISC, WHEEL HUB AND BRAKE DISC SHIELD		4.0	18.00
54630R00)	R + R L/F STRUT		2.0	9.00
54630R00)	DISS/ASS L/F SUSPENSION STRUT REMOVED		2.0	9.00
54509R00)	R + R LEFT FRONT LOWER CONTROL ARM		2.0	9.00
52910R00	R + R L/F TYRE		4.0	18.00

LKK Auto Consultants

#01-25 Paya Ubi Industrial Park, 51

Ubi Avenue 1

408933

Insurer Reference: S9M02AIO

Repairer Reference: SJS5369K-OD AXA

Date calculated: 21/02/2020 12:10 PM

Finalised

Full Report

Registration: SJS5369K-OD AXA

Printed: 21/02/2020 12:47 PM

Summary Information**Claim**

Location: Singapore (SG)
Printed by: KK LAU
Claim Reference: S9M02AIO
Estimated Repair Time:
Actual Repair Days:

Work Provider:
Currency:
Date of Incident:
Hire Car Start:
Hire Car End:

AXA Insurance Pte Ltd
SGD
15/12/19

Vehicle Details**Vehicle**

Manufacturer: HYUNDAI
Model: AVANTE (HD)
Sub Model: BASIS
Model Sheet Number: 30 22 50
Registration: SJS5369K-OD AXA
VIN number: KMH DU41BR9U802951
Odometer:

Model Specs

FROM 07/2009
TWO COAT METALLIC

AIR CONDITIONING
PREPARE OFF VEHICLE

FOG LAMPS


1.6 LTR 90 KW

Vehicle Condition**Vehicle Status**

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Paint Material Per Part

Code	Description	Price SGD
1482	RIGHT FRONT DOOR SURFACE PAINT	20.17
2228	R/OUTER A-PILLAR SURFACE PAINT	3.74
4101	L/INNER SIDE PANEL SURFACE PAINT	5.98

Labour Cost - Paint

Factor	45.00 SGD/h	Hrs	WU	Price SGD
Time Paint			142.0	
Preparation Main Work Metal		2.50	25.0	112.50
Preparation Comp. Work Plastic		0.80	8.0	36.00
Total	10 WU/h	17.50	175.0	787.50

Material Cost - Paint

	Price SGD
New Part Painting	119.71
New Part Painting - Plastic K1R	7.87
New Part Painting - Plastic K1N	107.90
Repair Painting	28.44
Surface-/Blend Paint	61.77
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	366.99

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
4465	AIR CON CONDENSER	976062H010		180.00	180.00
9629	BATTERY	3711029200		0.00	0.00
1331	BATTERY CARRIER	371502H100		20.00	20.00
0471	BONNET	664002H010		350.00	350.00
0524	BONNET FRONT SEAL	864352H000		12.00	12.00
0493	BONNET LOCK	811302H900		25.00	25.00
1011	ENGINE MOUNTING	FRONT		70.00	70.00
1012	ENGINE MOUNTING	REAR		70.00	70.00
1013	ENGINE MOUNTING	LH		100.00	100.00
1014	ENGINE MOUNTING	RH ca (A)		100.00	100.00
7789	FAN SHROUD CPL	253802H060		115.00	115.00
7011	FRONT AXLE SUPPORT	624052H000 ca (A)		900.00	900.00
0283	FRONT BUMPER	865112H000		200.00	200.00
0287	FRONT BUMPER SPOILER	865902H000		20.00	20.00
0257	FRONT NUMBER PLATE	KNPL3		0.00	0.00
1001	FRT BUMPER	UNDERCOVER CLIP		15.00	15.00
0315	FRT BUMPER ABSORBER	865202H010		55.00	55.00
0299	FRT BUMPER AIR GRILL	865612H001		35.00	35.00
0350	FRT BUMPER CLAMP KIT	USE SINGLE PARTS		15.00	15.00
0340	FRT BUMPER SUPPORT	865302H010		115.00	115.00
0410	GRILLE	863502H000		130.00	130.00
1009	INNER FRT PANEL CPL	641012H000		250.00	250.00
0321	L/BUMPER MNTG REINF	865132H000		25.00	25.00
1423	L/COWL MOULDING	861502H910		16.00	16.00
0637	L/F FOG LAMP	922012H000		80.00	80.00

Code	Description	Part Number	Supplier	Price SGD
7053	L/F LWR CONTROL ARM	545002H000		110.00
7077	L/F SHOCK ABSORBER	546512H000		125.00
7271	L/F STABI LINKAGE	548302H200	bt/ (A)	45.00
7081	L/F STEERING KNUCKLE	517152H000		130.00
7227	L/F TYRE	185/65 R 15 .. H		0.00
7201	L/F WHEEL	529102H090		0.00
7117	L/F WHEEL BEARING	517202H000		45.00
0841	L/F WHEELHOUSE COVER	868112H010		35.00
7131	L/F WHEEL HUB	517502H000		75.00
0741	L/F WING	663112H022		140.00
0811	L/F WING BADGE	863162H000		0.00
3283	L/NUT	1227005001		2.00
7755	L/RADIATOR AIR GUIDE	291352H000		17.00
3281	L/R OUTER LAMP	924012H010		95.00
0843	L/SCREW	1249306207B		12.00
0475	LEFT BONNET HINGE	791102H000		25.00
0561	LEFT HEADLAMP ASSY	921012H091		190.00
0327	LEFT RETAINER	1491005000		18.00
8780	LWR ENG COMP COVER	291102H200		30.00
1393	LWR WINDSCREEN COVER	861502H900		50.00
8632	R/ENGINE MOUNTING	218100Q000		90.00
0842	R/F WHEELHOUSE COVER	868122H010		35.00
0742	R/F WING	663212H022		140.00
0812	R/F WING BADGE	863162H000		0.00
3284	R/NUT	1227005001		2.00
0844	R/SCREW	1249306207B		12.00
7761	RADIATOR	253102H000		260.00
2583	REAR BUMPER	866102H000		220.00
2640	REAR BUMPER SUPPORT	866312H010	ma/ (A)	115.00
0476	RIGHT BONNET HINGE	791202H000		25.00
0562	RIGHT HEADLAMP ASSY	921022H091		190.00
0328	RIGHT RETAINER	1491005000		18.00
2650	RR BUMPER CLAMP KIT	USE SINGLE PARTS		15.00
7300	STEERING GEAR	565002H290	bt/ (A)	700.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings
Subtotal
Addition(+10.00%)

0.00
5,864.00
586.40

Total

6,450.40

Extras

Code	Description	Price SGD
0350	[E]: FRT BUMPER CLAMP KIT:	0.00*
1000	FRT NUMBER PLATE	35.00*
1003	COOLANT -	20.00*
1005	FRT TYRE LH	196.00*
1006	FRT RIM LH	150.00*
1007	TO CHECK WIRING	20.00*
1009	TO DO WHEEL ALIGNMENT	60.00*
1015	TOP UP AIRCON GAS	30.00*
Total Extras		511.00

Final Calculation

	SGD	SGD
Parts	5,864.00	
Addition(+10.00%)	586.40	
Total Parts		6,450.40
Labour Time Base 10 WU/h		
Total 189.0 WU X 45.00 SGD/h	850.50	
Alignment		
Measuring Work	27.00	
Total of Labour		877.50
Total Of Extras		511.00
Paint Work Time Base 10 WU/h		
Labour Cost 175.0 WU X 45.00 SGD/h	787.50	
Material Cost	366.99	
Total Paint Including Material		1,154.49
Repair Cost Excludes GST		8,993.39
GST (+7.0%)		629.54
Repair Cost Included GST		9,622.93
Deductions (Excludes GST)		
Repair Cost Discount (+15.00%)	-1,349.01	
Total Of Deductions (Excludes GST)		-1,349.01
Grand Total Excludes GST		7,644.38
GST (+7.0%)		535.11
Grand Total Included GST		8,179.49

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 24 February 2020 3:06 PM
To: 'Sharon Sng'; Rasul (LKKAUTO); SUR
Subject: RE: SJS5369K - AFTER PAINT & ITEMS (1)

Dear Sharon,

Confirmed Lump Sum Limit \$7k before excess \$2800 @ 9 working days.

Will submit in SMART claim shortly.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sharon Sng <sharon@sngahtee.com>
Sent: Wednesday, 19 February 2020 5:38 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: SJS5369K - AFTER PAINT & ITEMS (1)

Hi

Limit \$7k before excess \$2800

Best Regards

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



-Please note that all offer/acceptance is made without prejudice.-