

Accident Photo



Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/08/2019 16:29
Date Of Accident	05/08/2019 20:10
Exact Location Of Accident	BLK 630 ANG MO KIO AVE 4 ENTRANCE CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJB1916Y
Insured/Policyholder	
Name Of Registered Owner	MATHAVA ANBANANTHAN S/O T TIALAGASAMY
NRIC No	S1612970D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90559894
Alternative Phone No	OFFICE-90559894

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LANCER EX
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC19A00035500
Cover Note Number	

Driver

Name of Driver	MATHAVA ANBANANTHAN S/O T TIALAGASAMY
NRIC No	S1612970D
Date Of Birth	29/08/1963
Occupation	INDOOR
Date Of Driving Pass	28/03/1981
Driving Experience	38 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90559894
Fax Number	
Contact Number	OFFICE-90559894
E-Mail Address	NOEMAIL

Address	BLK 122 SERANGOON NORTH AVENUE 1 #04-177
Postcode	550122
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : SELVADURAI GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLC7034Z
Vehicle Make/Model/Colour	TOYOTA ALTIS/BLACK
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEE MING FEN EUGENE
NRIC/Passport Number	S9647701E
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorized Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders


Policyholder's Signature
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
NR/L/HR No.:

Sketch Plan #2

SKETCH PLAN



- A) SJB 19164
- B) SLC 70342

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At the motor date & time of accident 05/05/2019, 2:19pm, I was driving along Hill St. My car was in the 4th carpark, while reaching the entrance/Exit of the carpark, My lane can turn left and right, left is to Exit carpark. Upon checking that traffic was clear that there was a car ahead of me queuing to exit out from carpark, I drove to turn right. When my vehicle was almost in the lane, I stopped again to ensure no oncoming vehicle as I stationary car beside me was blocking the way while still queuing to exit when suddenly vehicle B cut over that stationary vehicle & drove towards me at fast speed & didn't stopped after collision. These changes were that right flat to row. My vehicle was stationary when happened.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

T. Mulla

Policyholder's Signature
Date & Time

T. Mulla

Driver's Signature
(If driver is not the policyholder)
Date & Time

[Signature]

Reporting Centre Personnel's Signature
Name
NEC PIN No.



CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1990
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

SGDRIVERS
PROTECTOR PLAN

M2300
COMPREHENSIVE
ORIGINAL

CERTIFICATE NO: MPC15A00035500
Agency Name: SGDRIVERS PTE LTD
Agency Code: A0000069

Chassis No: JMYSRCY2A01004249
Engine No: 4A910073211

1. Index Mark and Registration Number of Vehicle: SFB1916Y
2. Name of Policyholder: MATHAVA ANBANANTHAN S/O T TIALAGASAMY
3. Period of Insurance (both dates inclusive): 03 January 2019 to 02 January 2020

4. Person or Classes of Persons entitled to drive

- a) The Policyholder and all Named Drivers declared under the policy
b) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

5. Limitations as to use

Use for social, domestic and pleasure purposes and for the Policyholder's business. The policy does not cover use for hire or reward, tuition, driving test, race, pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

6. EXCESS APPLICABLE

MINIMUM EXCESS	SGD 100.00
SECTION 1 - INSURED/NAMED DRIVER	SGD 500.00
ADDITIONAL EXCESS OTHER THAN NAMED DRIVERS:	
SECTION 1 - AGE < 25, AGE > 70 OR DRIVING EXP < 2 YEARS OLD	SGD 3,000.00

7. Hire Purchase Company: TOKYO CENTURY LEASING (S) PTE LTD

Signed for and on behalf of ECICS Limited

AUTHORISED SIGNATORY

Important Notice:

- Policyholders are hereby warned that it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid insurance under the Act.
- On the sale of a motor vehicle, Policyholders must surrender all insurance papers issued including the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189).
- The Certificate of Insurance and the Policy will cease to be valid once the motor vehicle has been sold or transferred.
- The Payment Before Cover Warranty or Premium Payment Warranty found in the Policy must be complied with otherwise there would be no liability under the Policy and Certificate of Insurance.

Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



PAR Automotive Consultancy

Regn. No. 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0444-19-SHM

24 September 2019

Lee Seng Heng
c/o Sau Hock Motor Services
Blk 10 Ang Mo Kio Ind Park 2A #02-14
AMK AutoPoint
Singapore 568047

INVOICE No. 0444-19-SHM

Vehicle No. SLC7034Z

<u>S/NO.</u>	<u>SERVICES RENDERED</u>	<u>Amount due</u>
1	Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).	\$854.00
	Total amount payable	<u>\$854.00</u>

- Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy



PAR Automotive Consultancy

Regn. No: S2986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0444-19-SHM

24 September 2019

ACCIDENT VEHICLE SURVEY REPORT

Lee Seng Heng
c/o Sau Hock Motor Services
Blk 10 Ang Mo Kio Ind Park 2A #02-14
AMK AutoPoint
Singapore 568047

VEHICLE INFORMATION:

Vehicle Reg No.:	SLC7034Z	Odometer:	68994km
Make & Model:	Toyota Corolla Altis 1.6	Colour:	Black
Chassis number:	MR053REH10454776	Date of accident:	05/08/2019
Year of Regn.:	24/05/2016	Date inspected:	16/09/2019
Repairer at:	Sau Hock Motor Services	Date inspected (After Repair):	20/09/2019
	Blk 10 Ang Mo Kio Ind Park 2A #02-14		
	AMK AutoPoint		
	Singapore 568047		

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	6mm/Yokohama	6mm/Yokohama	205/50R16
Rear:	6mm/Yokohama	6mm/Yokohama	205/50R16

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the RH portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

Report No: 0444-19-SHM

Vehicle No: SLC7034Z

Description of part	Qty	Condition as inspected	Repairer's estimate	Our adjustment
Front door RH <i>BVC</i>	1	buckled	1,079.60	1,079.60
Front door black frame sticker RH (no 1) <i>rec</i>	1	necessary	75.10	75.10
Front door black frame sticker RH (no 2) <i>rec</i>	1	necessary	65.90	65.90
Front door checker RH <i>X (R)</i>	1	repair	150.30	0.00
Front door glass outer moulding RH <i>XNA</i>	1	necessary	172.15	172.15
Front door hinge RH - top & lower <i>X (R)</i>	2	repair	156.20	0.00
Front door inner trim board RH <i>XNA</i>	1	fractured	900.00	900.00
Front door mechanism lock RH <i>XNA</i>	1	bent	570.30	570.30
Front door outer lock handle RH <i>XNA</i>	1	distorted	141.30	141.30
Front door outer lock handle cover RH <i>SCC</i>	1	distorted	55.60	55.60
Front door outer lock handle inner bracket RH <i>X (Serviceable)</i>	1	reuse	186.70	0.00
Front door power window channel bracket RH <i>XNA</i>	1	bent	74.35	74.35
Front door power window channel bracket weatherstrip RH <i>XNA</i>	1	necessary	95.80	95.80
Front door power window regulator motor RH <i>XNA</i>	1	shorted	509.10	509.10
Front door weatherstrip RH <i>DEF</i>	1	deformed	170.10	170.10
Front fender RH <i>BVC</i>	1	buckled	656.00	656.00
Front fender emblem "Dual VVTi" RH <i>rec</i>	1	necessary	45.10	45.10
Rear bumper <i>CLT</i>	1	grazed	482.30	482.30
Rear bumper side retainer RH/LH <i>XNA</i>	2	necessary	207.00	207.00
Rear door RH <i>BVC</i>	1	buckled	1,079.60	1,079.60
Rear door black frame sticker RH (no:1) <i>rec</i>	1	necessary	75.10	75.10
Rear door black frame sticker RH (no:2) <i>rec</i>	1	necessary	65.10	65.10
Rear door checker RH <i>X (R)</i>	1	reuse	150.30	0.00
Rear door glass inner moulding RH <i>XNA</i>	1	necessary	72.50	72.50
Rear door glass outer moulding RH <i>XNA</i>	1	necessary	70.35	70.35
Rear door hinge RH/LH - top & lower <i>XNA</i>	2	repair	158.40	0.00
Rear door inner lock handle RH <i>XNA</i>	1	reuse	236.70	0.00
Rear door inner trim board RH <i>XNA</i>	1	fractured	715.30	715.30
Rear door lock striker RH <i>XNA</i>	1	bent	36.70	36.70
Rear door mechanism lock RH <i>XNA</i>	1	bent	534.10	534.10
Rear door outer lock handle RH <i>XNA</i>	1	reuse	141.10	0.00
Rear door outer lock handle cover RH <i>XNA</i>	1	reuse	48.10	0.00
Rear door power window channel bracket weatherstrip RH <i>XNA</i>	1	necessary	102.60	102.60
Rear door weatherstrip RH <i>DEF</i>	1	deformed	170.70	170.70
Rear fender RH <i>BVC</i>	1	buckled	977.70	977.70
Rear windscreen moulding <i>rec</i>	1	necessary	78.60	78.60

		Subtotal before discount	10,505.85	9,278.05
Percentage discount	0% and 25%		0.00	2,319.51
	Sub-total 1	10,505.85	6,958.54	
Front sport rim RH <i>scr</i>	1 abraded	650.00	650.00	\$600
Front tyre RH <i>cut</i>	1 abraded	350.00	350.00	\$200
Rear sport rim RH <i>scr</i>	1 abraded	650.00	650.00	\$600
Rear tyre RH <i>xnt</i>	1 abraded	350.00	350.00	
Rear windscreen sealant <i>rac</i>	1 necessary	100.00	70.00	\$40
	Subtotal before discount	2,100.00	2,070.00	
Percentage discount	0% and 0%		0.00	0.00
	Sub-total 2	2,100.00	2,070.00	
	Parts-total	12,605.85	9,028.54	

LABOUR

1. To straighten and panel beating centre pillar RH and RH frame member. To remove and refit above parts.		1,200.00	750.00	\$600
2. To putty, re-spray painting and polish affected areas.		1,600.00	1,320.00	\$1000
3. To check and rectify wiring system.		80.00	50.00	\$30
4. To remove, transfer and refit rear and front door RH components.		300.00	250.00	\$160
5. To conduct electronic wheel alignment.		200.00	150.00	\$100
6. To remove and refit 2 tyres/rims.		100.00	80.00	\$60
7. To remove and refit rear windscreen.		150.00	120.00	\$90
8. To remove and refit rear speaker board, seat cushion, roof lining, garnish, fitting and etc.		150.00	120.00	\$80
9. To rust proof affected areas.		120.00	120.00	\$100
	Labour total	3,900.00	2,960.00	
	Parts & Labour total	16,505.85	11,988.54	

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on LUMP SUM repairs is :
and the recommended number of working days for the repairs is :

\$7742.68
L/S: \$6150/=

6 repair days

\$9,500.00

7

KL
B J Loi (I Eng. MIML AIRTE)
Automotive Appraiser

List item: \$3733.42

Net item: \$1440

Labour: \$2220

Total: \$7393.42

at L/S: \$5900/=

6 repair days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ECICS LTD		Ref : CS3/ICS19013905/Fyf3s2-1	
10 EUNOS ROAD 8 SINGAPORE POST CENTRE #09-04A SINGAPORE 408600		Date : 14-01-2020	
		Code : ICS	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
Insured Veh.	SJB 1916Y	Veh. Inspected	SLC 7034Z
Policy No.	MPC19A00035500	Coverage (\$)	0.00
Claim No.	DMPC1900207H/DL	Excess (\$)	0.00
Assign From	DESMOND LEE	Assign Date	11/12/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MR053REH104547776	Colour	BLACK
Odometer	72000	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	YOKOHAMA	4 mm
L/H Front Tyre	205/55 R16	YOKOHAMA	4 mm
R/H Rear Tyre	205/55 R16	YOKOHAMA	5 mm
L/H Rear Tyre	205/55 R16	YOKOHAMA	5 mm
4. Description of Damages			
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information			
Accident Date	05/08/2019	Inspection Date	23/12/2019
Survey held at	SAU HOCK MOTOR SERVICES BLK 10 ANG MO KIO INDUSTRIAL PARK 2A (AVE 5) #02-14 AMK AUTOPOINT SINGAPORE 568047.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 7034Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT DOOR RH	REPLACED	1,079.60	1,079.60
1	FRONT DOOR BLACK FRAME STICKER RH (NO 1)	REPLACED	75.10	75.10
1	FRONT DOOR BLACK FRAME STICKER RH (NO 2)	REPLACED	65.90	65.90
1	FRONT DOOR CHECKER RH	REPAIRED SEE LABOUR	150.30	-
1	FRONT DOOR GLASS OUTER MOULDING RH	NOT CHANGED	172.15	-
2	FRONT DOOR HINGE RH - TOP & LOWER	REPAIRED SEE LABOUR	156.20	-
1	FRONT DOOR INNER TRIM BOARD RH	NOT CHANGED	900.00	-
1	FRONT DOOR MECHANISM LOCK RH	NOT CHANGED	570.30	-
1	FRONT DOOR OUTER LOCK HANDLE RH	NOT CHANGED	141.30	-
1	FRONT DOOR OUTER LOCK HANDLE COVER RH	REPLACED	55.60	55.60
1	FRONT DOOR OUTER LOCK HANDLE INNER BRACKET RH	SERVICEABLE	186.70	-
1	FRONT DOOR POWER WINDOW CHANNEL BRACKET RH	NOT CHANGED	74.35	-
1	FRONT DOOR POWER WINDOW CHANNEL BRACKET WEATHERSTRIP RH	NOT CHANGED	95.80	-
1	FRONT DOOR POWER WINDOW REGULATOR MOTOR RH	NOT CHANGED	509.10	-
1	FRONT DOOR WEATHERSTRIP RH	REPLACED	170.10	170.10
1	FRONT FENDER RH	REPLACED	656.00	656.00
1	FRONT FENDER EMBLEM "DUAL VVTI" RH	REPLACED	45.10	45.10
1	REAR BUMPER	REPLACED	482.30	482.30
2	REAR BUMPER SIDE RETAINER RH/LH	NOT CHANGED	207.00	-
1	REAR DOOR RH	REPLACED	1,079.60	981.00
1	REAR DOOR BLACK FRAME STICKER RH (NO:1)	REPLACED	75.10	75.10
1	REAR DOOR BLACK FRAME STICKER RH (NO:2)	REPLACED	65.10	65.10
1	REAR DOOR CHECKER RH	REPAIRED SEE LABOUR	150.30	-
1	REAR DOOR GLASS INNER MOULDING RH	NOT CHANGED	72.50	-
1	REAR DOOR GLASS OUTER MOULDING RH	NOT CHANGED	70.35	-
2	REAR DOOR HINGE RH/LH - TOP & LOWER	NOT CHANGED	158.40	-
1	REAR DOOR INNER LOCK HANDLE RH	NOT CHANGED	236.70	-
1	REAR DOOR INNER TRIM BOARD RH	NOT CHANGED	715.30	-
1	REAR DOOR LOCK STRIKER RH	NOT CHANGED	36.70	-
1	REAR DOOR MECHANISM LOCK RH	NOT CHANGED	534.10	-

Report Ref No. CS3/ICS19013905/Fyf3s2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR DOOR OUTER LOCK HANDLE RH	NOT CHANGED	141.10	-
1	REAR DOOR OUTER LOCK HANDLE COVER RH	NOT CHANGED	48.10	-
1	REAR DOOR POWER WINDOW CHANNEL BRACKET WEATHERSTRIP RH	NOT CHANGED	102.60	-
1	REAR DOOR WEATHERSTRIP RH	REPLACED	170.70	170.70
1	REAR FENDER RH	REPLACED	977.70	977.70
1	REAR WINDSCREEN MOULDING	REPLACED	78.60	78.60
	LESS 25% DISCOUNT		-	-1,244.48
			10,505.85	3,733.42
	SPECIAL NETT ITEMS			
1	FRONT SPORT RIM RH (SN)	REPLACED	650.00	600.00
1	FRONT TYRE RH (SN)	REPLACED	350.00	200.00
1	REAR SPORT RIM RH (SN)	REPLACED	650.00	600.00
1	REAR TYRE RH (SN)	NOT CHANGED	350.00	-
1	REAR WINDSCREEN SEALANT (SN)	REPLACED	100.00	40.00
			2,100.00	1,440.00
	LABOUR			
	TO STRAIGHTEN AND PANEL BEATING CENTRE PILLAR RH AND RH FRAME MEMBER. TO REMOVE AND REFIT ABOVE PARTS. INCLUSIVE OF THE REPAIR OF FRONT DOOR CHECKER RH, FRONT DOOR HINGE RH - TOP & LOWER AND REAR DOOR CHECKER RH.		1,200.00	600.00
	TO PUTTY, RE-SPRAY PAINTING AND POLISH AFFECTED AREAS.		1,600.00	1,000.00
	TO CHECK AND RECTIFY WIRING SYSTEM.		80.00	30.00
	TO REMOVE, TRANSFER AND REFIT REAR AND FRONT DOOR RH COMPONENTS.		300.00	160.00
	TO CONDUCT ELECTRONIC WHEEL ALIGNMENT.		200.00	100.00
	TO REMOVE AND REFIT 2 TYRES / RIMS.		100.00	60.00
	TO REMOVE AND REFIT REAR WINDSCREEN.		150.00	90.00
	TO REMOVE AND REFIT REAR SPEAKER BOARD, SEAT CUSHION, ROOF LINING, GARNISH, FITTING AND ETC.		150.00	80.00
	TO RUST PROOF AFFECTED AREAS.		120.00	100.00
			3,900.00	2,220.00
	GRAND TOTAL		16,505.85	7,393.42
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,900.00



Report Ref No. CS3/ICS19013905/Fyf3s2-1

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.