

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 23558

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1497/2019/TG
Date : 20-Dec-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Lim Kim Heong
Address : 552 Pasir Ris ST 51
#13-83
Singapore 510552
Telephone : (HP) +65 96781621
Type of Claim : Own Damage Claims
Policy No. : 1800075552-01
Vehicle No : **SGB 9029 R**
Model Code : A4 Sedan 2.0 TFSI 8W
Model / Year : 28/6/2018
Engine No : CVK 061907
Chassis No : WAUZZZF46JA170965
Mileage : 24789 KM
Date In : 19-Dec-19
Estimated By : Johnny Boo / Allan Wu
Accident Date : 19-Dec-19
Place of Accident : Carpark At Blk 552 Pasir Ris St 51

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGB 9029 R

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To tow and recover vehicle from scene of accident.	S/N \$	280.00	✓
2	To carry out first measurement test on car o-liner.	S/N \$	800.00	? photo.
3	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00	✓
4	To remove and renew aircon condenser, charged air cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and reqas.	S/N \$	1,200.00	✓
5	To remove and reinstall engine assy with gearbox assy to facillitate car o-liner repairs.	S/N \$	2,800.00	? photo.
6	To remove and reinstall front suspension assy with subframe to facillitate car o-liner repairs. Inspect for damages and renew if necessary.	S/N \$	2,400.00	? photo.
SUB TOTAL LABOUR CHARGES		:	\$ 7,960.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGB 9029 R

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
7	To place vehicle on car o-liner.	S/N \$ 2,400.00	? photo.
8	To dismantle rhs front door panel trim. To remove and reinstall rhs wing mirror assy.	S/N \$ 3,000.00	X NN
9	<i>/RH</i> To dismantle and renew front bumper, bonnet, both front fenders, rhs headlight. Cut out and reweld rhs fender support and closing element. Align both front chassis frames to specification of origin. Renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.	9.5 \$ 8,050.00	4750.
10	<i>RH</i> To respray front bumper, both front fenders, bonnet, rhs upper A-pillar, engine compartment, rhs front fender top support and rhs front door. To carry out joint selant work and stone chip treatment.	\$ 6,900.00	1650
11	To renew rhs front rim and rhs front tyre. To carry out wheel alignment.	S/N \$ 280.00	/
12	To carry out diagnostic checks	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: \$ 28,782.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBGB 9029 R

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER / Dis	\$	1,999.00
2	FRONT BUMPER FIXING PARTS / } Acc	\$	258.00
3	FRONT BUMPER SECURING STRIP /	\$	32.00
4	FRONT BUMPER GRILLE - CENTER ?	\$	178.00
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE ?	\$	191.00
6	FRONT BUMPER AIR GUIDE - RH / Acc Dis	\$	56.00
7	RADIATOR GRILLE / BR	\$	2,015.00
8	FRONT BUMPER AIR GUIDE GRILLE - LH/RH < LH x RH / RH / Mis ²	\$	665.00
9	FRONT BUMPER CARRIER ?	\$	733.00
10	FRONT BUMPER BRACKET MOUNTING - RH / Dis	\$	34.00
11	FRONT BUMPER TOP COVER / BR	\$	116.00
12	FOAM FILLER PIECE / CRA	\$	113.00
13	CAUTION SIGN STICKER / } Acc	\$	13.00
14	AIRCON STICKER /	\$	7.00
15	FRONT BUMPER LOCK CARRIER BRACKET ?	\$	125.00
16	FRONT BUMPER SUPPORT - LH / RH ?	2 \$	51.00
17	FRONT BUMPER PARKING AID SENSOR Acc ?	2 \$	462.00
18	SEAL RING / Acc	4 \$	12.00
19	FRONT BUMPER WIRING SET ?	\$	470.00
20	HORNS - LOW TONE RIGHT ?	\$	262.00
SUB TOTAL SPARE PARTS		:	\$ 7,792.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGB 9029 R

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remarks
21	SPRING SHACKLE - RH ?	\$	26.00
22	FRONT FENDER - RH / Dis	\$	700.00
23	FRONT FENDER ATTACHEMENT PARTS /	\$	183.00
24	FRONT FENDER CLOSING ELEMENT - RH /	\$	45.00
25	FRONT FENDER BRACKET - RH /	\$	32.00
26	FRONT FENDER DEFORMATION BRACKET - RH /	\$	45.00
27	FRONT FENDER BRACKET - LH/RH /	\$	29.00
28	FRONT FENDER BRACE - RH / Brc	\$	107.00
29	FRONT WHEEL HOUSING LINER - RH / R	\$	220.00
30	WHEEL HOUSING LINER ATTACHMENT PARTS / Acc.	\$	82.00
31	FRONT WHEEL SPOILER / Dis		TBC
32	FRONT FENDER TRIM PLATE / Acc	\$	33.00
33	STONE CHIP GUARD - RH /	\$	46.00
34	BONNET / BT	\$	2,554.00
35	BONNET ATTACHEMENT PARTS X NN	\$	111.00
36	IMPACT PROTECTION - CENTER / Acc	\$	25.00
37	IMPACT PROTECTION - LH/RH /	2 \$	50.00
38	FRONT FENDER LEDGE COVER - RH / BT	\$	28.00
39	FRONT FENDER PROTECTION FILM - RH / Acc.	\$	21.00
40	STRIKER - RH ?	\$	46.00
SUB TOTAL SPARE PARTS		: \$	<u><u>4,383.00</u></u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGB 9029 R

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
41	BONNET LID LOCK ?	\$ 196.00	
42	BOWDEN CABLE - CENTER ?	\$ 53.00	
43	BRACKET FOR CONNECTOR HOUSING / BR	\$ 9.00	
44	CABLE CLIP COVER ?	\$ 9.00	
45	HOOK RELEASE CABLE ?	\$ 53.00	
46	HOOK RELEASE COVER ?	\$ 12.00	
47	LID LOCK CABLE ?	\$ 67.00	
48	PLENUM CHAMBER ?	\$ 89.00	
49	FRONT FENDER LEDGE COVER - RH / BT	\$ 56.00	
50	BONNET INSULATION / Acc.	\$ 311.00	
51	FRONT LED HEADLIGHT - RH / Dis.	\$ 7,087.00	
52	POWER MODULE - RH ?	\$ 716.00	
53	CONTROL UNIT - RH ?	\$ 685.00	
54	HEADLIGHT HOSE - RH ?	\$ 32.00	
55	REPAIR KIT FOR HEADLAMP HOUSING - RH ?	\$ 120.00	
56	LIFT CYLINDER - RH / BR	\$ 192.00	
57	LIFT CYLINDER BRACKET - RH / Acc.	\$ 6.00	
58	CORRUGATED PIPE ?	\$ 83.00	
59	CORRUGATED PIPE FOR WASHER NOZZLE ?	\$ 35.00	
60	CONNECTING PLATE - RH ?	\$ 228.00	
SUB TOTAL SPARE PARTS		: \$ 10,039.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGB 9029 R

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
61	CONNECTING PLATE - RH ?	\$	197.00	
62	WHEEL HOUSING - RH / ec.	\$	54.00	
63	RADIATOR SUPPORT PANEL / CRA.	\$	928.00	
64	RADIATOR SUPPORT BRACKET / BT.	\$	69.00	
65	HOOK RELEASE CABLE ?	\$	53.00	
66	A/C CONDENSER ?	\$	568.00	
67	RADIATOR ?	\$	676.00	
68	COOLANT / ec.	4 \$	84.00	
69	RADIATOR RUBBER BUSH - LOWER ?	2 \$	17.00	
70	RADIATOR RUBBER BUSH - LOWER ?	2 \$	24.00	
71	INTERCOOLER ?	\$	535.00	
72	PRESSURE HOSE - RH ?	\$	320.00	
73	EXTERNAL TEMPERATURE SENSOR ?	\$	54.00	
74	TEMPERATURE SENSOR BRACKET ?	\$	17.00	
75	ENGINE COOLING FAN ?	\$	242.00	
76	COOLING FAN ?	\$	2,107.00	
77	RADIATOR AIR GUIDE - RH ?	\$	25.00	
78	RADIATOR AIR GUIDE - LOWER RH ?	\$	11.00	
79	RADIATOR AIR GUIDE - UPPER RH ?	\$	15.00	
80	RADIATOR AIR GUIDE - LOWER EH ?	\$	19.00	
SUB TOTAL SPARE PARTS		:	\$ 6,015.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGB 9029 R

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
81	INTAKE AIR DUCT - RH ?	\$	19.00
82	ENGINE AIR GUIDE ?	\$	48.00
83	AIR FILTER HOUSING ?	\$	339.00
84	AIR MASS METER ?	\$	533.00
85	INTAKE HOSE ?	\$	85.00
86	CLAMP ?	\$	8.00
87	FRONT FENDER - LH X	\$	700.00
88	FRONT FENDER COVER - LH X	\$	228.00
89	FENDER COVER - LH X	\$	21.00
90	STONE CHIP GUARD - LH X	\$	46.00
91	FRONT ALUMINIUM RIM - RH CT.	\$	651.00
92	RUBBER VALVE / AC.	4 \$	13.00
93	FRONT WISH BONE LINK - RH ?	\$	491.00
94	TRACK CONTROL ARM - RH ?	\$	861.00
95	FRONT UPPER CONTROL ARM GUIDE - RH ?	\$	466.00
96	FRONT UPPER CONTROL ARM - RH ?	\$	466.00
97	WHEEL BEARING HOUSING - RH ?	\$	884.00
98	BALL JOINT - RH ?	\$	175.00
99	WHEEL HUB - RH ?	\$	451.00
100	BALL BEARING - RH ?	\$	232.00
SUB TOTAL SPARE PARTS		:	\$ 6,717.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGB 9029 R

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
101	COUPLING ROD - RH ?	\$	123.00
102	DRIVE SHAFT - RH ?	\$	2,422.00
103	SHOCK ABSORBER - RH ?	\$	276.00
104	TRACH ROD - RH ?	\$	90.00
105	TIE ROD END - RH ?	\$	180.00
106	FRONT NO PLATE / MC.	\$	40.00
107	ADHESIVE SEALANT /	S/N \$	180.00
108	CAVITY WAX / } MC.	\$	140.00
109	STONE CHIP /	\$	180.00
110	FRONT TYRE - RH / wt		TBC
111	SUNDRIES ?	\$	400.00

TOTAL SPARE PARTS : \$ 38,977.00

TOTAL LABOUR CHARGES : \$ 28,782.00

GRAND TOTAL : \$ 67,759.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

12 Days.

Not Authorised.

Guo Qiang - 8288 0282

before paint photos.

20/12/19.

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant