

REC BY:

Merimay

REF:

AIG (C3/AIG 190224 30/Grb)

ASSIGNMENT

From:

Date:

20/12/19

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SGB 9029R

at Workshop m/s

Premium

of

55 ubi Road 1

Insured:

Policy No.

1800075552-01

Claims No.

Sum Insured:

Excess:

0

(Client's Record)

Make of Veh:

Vehicle In

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

\$126K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

11

days

Res.:

Yes or No

Lump Sum:

%

3 Val:

Yes or No

CA

REV

/

REP.

/

24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SGB 9029R

Yr Regn:

28 Jun 2018

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A4 2.0

C.C.

1984

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

24789

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAU8Z3F46JA170965

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

19/12/19

D.O.I.

20-12-19

Survey held at

W/S

11AM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

CoE: 59759

New car: 188016

Net: ~~65K~~ 65K.

SGB 9029R - X

23/12/19

Revert via merimen

26/12/19

Rece approved \$28,019.50 from Kok Chang by merimen

26/12/19

Check with Guo Qiang NV: \$60k

26/12/19

Informed TRuy c/A ex O by email

28/12/20

Final fig \$23,751.20 confirmed by email (Ref 52,059.12, 6990)

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair:

11

1)

☐

: Final Report

Resurvey No. of Trip:

1

Survey Fee:

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Wheel end (\$

Transportation:

\$ + RS \$

Flares

Others

TOTAL

Report Format:

Lump Sum / L.B.R. (\$

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 26 December 2019 2:02 PM
To: Claims; Admin A; SUR
Cc: (nora.khai@premiumauto.com.sg); (boojohnny@gmail.com)
Subject: RE: OD CLAIM FOR SGB 9029 R ON 19/12/2019, VEH IN

Dear TRoy,

As instructed by our client , please proceed to repair the **insured vehicle SGB 9029R (Excess \$0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

NOTE: Before paint photos for Front Bumper, Front Fender RH and Bonnet required.

AIG OIC-Azlan, Syazairdina] syazairdina.azlan@aig.com

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 26 December 2019 9:39 AM
To: Claims <claims@premiumauto.com.sg>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: OD CLAIM FOR SGB 9029 R ON 19/12/2019, VEH IN

Dear TRoy,

Pending approval from AIG, have gave them a chaser.

Once approved will send you email.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

From: Claims <claims@premiumauto.com.sg>
Sent: Thursday, 26 December 2019 8:52 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: RE: OD CLAIM FOR SGB 9029 R ON 19/12/2019, VEH IN

Dear Veron,

Any update from AIG?

Thanks

Best Regards,

TRoy Goh

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Tuesday, 24 December 2019 11:38 AM
To: Claims; Admin A; SUR
Subject: RE: OD CLAIM FOR SGB 9029 R ON 19/12/2019, VEH IN

Dear TRoy,

Pending approval from AIG.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Tuesday, 24 December 2019 11:01 AM
To: Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: RE: OD CLAIM FOR SGB 9029 R ON 19/12/2019, VEH IN

Dear All,

Any update on this?

Thanks

Best Regards,
TRoy Goh
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Claims [mailto:claims@premiumauto.com.sg]
Sent: Monday, 23 December 2019 11:39 AM
To: 'Admin A'; 'SUR'
Cc: 'Claims'
Subject: RE: OD CLAIM FOR SGB 9029 R ON 19/12/2019, VEH IN

Dear all,

Kindly assist and advise the mentioned claims for approval and who is the case handler for this case.

Thanks

Best Regards,
TRoy Goh
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Claims [<mailto:claims@premiumauto.com.sg>]

Sent: Monday, 23 December 2019 9:10 AM

To: 'Admin A'; 'SUR'

Cc: 'Claims'

Subject: RE: OD CLAIM FOR SGB 9029 R ON 19/12/2019, VEH IN

Dear all,

Survey was done by last week, herein attached the estimate repair and video footage for your next action.

Kindly assist and advise the claim status for approval.

Thanks

Best Regards,

TRoy Goh

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Claims [<mailto:claims@premiumauto.com.sg>]
Sent: Thursday, 19 December 2019 6:01 PM
To: 'Admin A'; 'SUR'
Cc: 'Claims'
Subject: OD CLAIM FOR SGB 9029 R ON 19/12/2019, VEH IN

Dear all,

Kindly assist to register this case mentioned. Herein attached with the GIA Report for your reference.

For the estimate repair will forward to you once is available.

Please arrange the survey on tomorrow 20/12/2019@Veh IN our compound.

Thanks

Best Regards,
TRoy Goh
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

View Received Message

This mail is associated with :

***SGB9029R (8314124043SG)**

OD

Dec 19 2019 8:25AM

[LIM KIM HEONG]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on **26/12/2019 13:02 PM.**

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$28019.50) - SGB9029R - Claim Handler: Azlan, Syazairdina

Approved:28019.50:Re-inspection for checked / hidden items, supplementary require with CLEAR photos upload in Merimen on the same day once vehicle dismantle parts, and re-seek mandate. Before paint photos for Front Bumper, Front Fender RH and Bonn

DOCUMENTS SUMMARY

There are no documents.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 23558

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1497/2019/TG
Date	:	20-Dec-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Lim Kim Heong
Address	:	552 Pasir Ris ST 51 #13-83 Singapore 510552
Telephone	:	(HP) +65 96781621
Type of Claim	:	Own Damage Claims
Policy No.	:	1800075552-01
Vehicle No	:	SGB 9029 R
Model Code	:	A4 Sedan 2.0 TFSI 8W
Model / Year	:	28/6/2018
Engine No	:	CVK 061907
Chassis No	:	WAUZZZF46JA170965
Mileage	:	24789 KM
Date In	:	19-Dec-19
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	19-Dec-19
Place of Accident	:	Carpark At Blk 552 Pasir Ris St 51

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGB 9029 R

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To tow and recover vehicle from scene of accident.	S/N \$	280.00	X X { an
2	To carry out first measurement test on car o-liner.	S/N \$	800.00	? photo. X { an
3	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00	✓ ✓
4	To remove and renew aircon condenser, charged air cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$	1,200.00	✓ ✓
5	To remove and reinstall engine assy with gearbox assy to facillitate car o-liner repairs.	S/N \$	2,800.00	? photo. X { an
6	To remove and reinstall front suspension assy with subframe to facillitate car o-liner repairs. Inspect for damages and renew if necessary.	S/N \$	2,400.00	? photo. X { an
SUB TOTAL LABOUR CHARGES		:	\$ 7,960.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGB 9029 R

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
7	To place vehicle on car o-liner.	S/N \$	2,400.00	photo x n n
8	To dismantle rhs front door panel trim. To remove and reinstall rhs wing mirror assy.	S/N \$	3,000.00	X n n
9	To dismantle and renew front bumper, bonnet, both front fenders, rhs headlight. Cut out and reweld rhs fender support and closing element. Align both front chassis frames to specification of origin. Renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.	9.5 \$	8,050.00	4750. ✓
10	To respray front bumper, both front fenders, bonnet, rhs upper A-pillar, engine compartment, rhs front fender top support and rhs front door. To carry out joint selant work and stone chip treatment.	\$	6,900.00	1650 ✓
11	To renew rhs front rim and rhs front tyre. To carry out wheel alignment.	S/N \$	280.00	✓
12	To carry out diagnostic checks	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 28,782.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBGB 9029 R

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER / Dis	\$ 1,999.00	1599.20
2	FRONT BUMPER FIXING PARTS X X NN	\$ 258.00	
3	FRONT BUMPER SECURING STRIP / X NN	\$ 32.00	25.44
4	FRONT BUMPER GRILLE - CENTER / X NN	\$ 178.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE / X NN	\$ 191.00	
6	FRONT BUMPER AIR GUIDE - RH / Dis	\$ 56.00	44.40
7	RADIATOR GRILLE / BR	\$ 2,015.00	1612
8	FRONT BUMPER AIR GUIDE GRILLE - LH/RH / X NN	\$ 665.00	332.50 266
9	FRONT BUMPER CARRIER / X NN	\$ 733.00	
10	FRONT BUMPER BRACKET MOUNTING - RH / Dis	\$ 34.00	27.12
11	FRONT BUMPER TOP COVER / BR	\$ 116.00	92.40
12	FOAM FILLER PIECE / CA	\$ 113.00	90.40
13	CAUTION SIGN STICKER / X	\$ 13.00	9.76
14	AIRCON STICKER / X	\$ 7.00	5.12
15	FRONT BUMPER LOCK CARRIER BRACKET / X CA	\$ 125.00	100
16	FRONT BUMPER SUPPORT - LH / RH / X	2 \$ 51.00	
17	FRONT BUMPER PARKING AID SENSOR / X	2 \$ 462.00	
18	SEAL RING / X	4 \$ 12.00	10.24
19	FRONT BUMPER WIRING SET / X NN	\$ 470.00	
20	HORNS - LOW TONE RIGHT / X NN	\$ 262.00	
SUB TOTAL SPARE PARTS		\$ 7,792.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGB 9029 R

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	SPRING SHACKLE - RH <i>X X NN</i>	\$ 26.00	
22	FRONT FENDER - RH <i>/ Dis</i>	\$ 700.00	559.60
23	FRONT FENDER ATTACHEMENT PARTS <i>X X NN</i>	\$ 183.00	
24	FRONT FENDER CLOSING ELEMENT - RH <i>/</i>	\$ 45.00	36
25	FRONT FENDER BRACKET - RH <i>/</i>	\$ 32.00	25.20
26	FRONT FENDER DEFORMATION BRACKET - RH <i>/</i>	\$ 45.00	35.60
27	FRONT FENDER BRACKET - LH/RH <i>/</i>	\$ 29.00	22.64
28	FRONT FENDER BRACE - RH <i>/ Br</i>	\$ 107.00	85.60
29	FRONT WHEEL HOUSING LINER - RH <i>/ Re</i>	\$ 220.00	175.60
30	WHEEL HOUSING LINER ATTACHMENT PARTS <i>X X NN</i>	\$ 82.00	
31	FRONT WHEEL SPOILER <i>/ Dis</i>	TBC	50.32
32	FRONT FENDER TRIM PLATE <i>/</i>	\$ 33.00	25.84
33	STONE CHIP GUARD - RH <i>/</i>	\$ 46.00	36.64
34	BONNET <i>/ BT</i>	\$ 2,554.00	2043.20
35	BONNET ATTACHEMENT PARTS <i>X NN</i>	\$ 111.00	
36	IMPACT PROTECTION - CENTER <i>/</i>	\$ 25.00	19.76
37	IMPACT PROTECTION - LH/RH <i>/</i>	\$ 50.00	39.68
38	FRONT FENDER LEDGE COVER - RH <i>/ BT</i>	\$ 28.00	22.24
39	FRONT FENDER PROTECTION FILM - RH <i>/ Acc.</i>	\$ 21.00	16.16
40	STRIKER - RH <i>X NN</i>	\$ 46.00	
SUB TOTAL SPARE PARTS		: \$	<u>4,383.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGB 9029 R

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
41	BONNET LID LOCK <i>✓</i> ☒ <i>YAN</i>	\$ 196.00	
42	BOWDEN CABLE - CENTER <i>✓</i> ☒ <i>YAN</i>	\$ 53.00	
43	BRACKET FOR CONNECTOR HOUSING <i>✓</i> ☒ <i>BR</i>	\$ 9.00	6.88
44	CABLE CLIP COVER <i>✓</i> ☒	\$ 9.00	
45	HOOK RELEASE CABLE <i>✓</i> ☒ <i>NN</i>	\$ 53.00	
46	HOOK RELEASE COVER <i>✓</i> ☒	\$ 12.00	
47	LID LOCK CABLE <i>✓</i> ☒	\$ 67.00	
48	PLENUM CHAMBER <i>✓</i> ☒	\$ 89.00	
49	FRONT FENDER LEDGE COVER - RH <i>✓</i> ☒ <i>BT</i>	\$ 56.00	44.24
50	BONNET INSULATION <i>✓</i> ☒ <i>NN</i>	\$ 311.00	
51	FRONT LED HEADLIGHT - RH <i>✓</i> ☒ <i>Dis.</i>	\$ 7,087.00	5669.60
52	POWER MODULE - RH <i>✓</i> ☒ <i>NN</i>	\$ 716.00	
53	CONTROL UNIT - RH <i>✓</i> ☒ <i>PM</i>	\$ 685.00	548
54	HEADLIGHT HOSE - RH <i>✓</i> ☒ <i>NN</i>	\$ 32.00	
55	REPAIR KIT FOR HEADLAMP HOUSING - RH <i>✓</i> ☒ <i>NN</i>	\$ 120.00	
56	LIFT CYLINDER - RH <i>✓</i> ☒ <i>BR</i>	\$ 192.00	153.20
57	LIFT CYLINDER BRACKET - RH <i>✓</i> ☒ <i>ACC.</i>	\$ 6.00	4.24
58	CORRUGATED PIPE <i>✓</i> ☒	\$ 83.00	
59	CORRUGATED PIPE FOR WASHER NOZZLE <i>✓</i> ☒ <i>NN</i>	\$ 35.00	
60	CONNECTING PLATE - RH <i>✓</i> ☒	\$ 228.00	
SUB TOTAL SPARE PARTS		: \$ 10,039.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGB 9029 R

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
61	CONNECTING PLATE - RH <i>X</i>	\$ 197.00	
62	WHEEL HOUSING - RH <i>X</i>	\$ 54.00	
63	RADIATOR SUPPORT PANEL <i>RA.</i>	\$ 928.00	<i>742</i>
64	RADIATOR SUPPORT BRACKET <i>BT.</i>	\$ 69.00	<i>54.72</i>
65	HOOK RELEASE CABLE <i>X</i>	\$ 53.00	
66	A/C CONDENSER <i>X</i>	\$ 568.00	
67	RADIATOR <i>X</i>	\$ 676.00	
68	COOLANT <i>MC.</i>	4 \$ 84.00	<i>67.20</i>
69	RADIATOR RUBBER BUSH - LOWER <i>X</i>	2 \$ 17.00	
70	RADIATOR RUBBER BUSH - LOWER <i>X</i>	\$ 24.00	
71	INTERCOOLER <i>X</i>	\$ 535.00	
72	PRESSURE HOSE - RH <i>X</i>	\$ 320.00	
73	EXTERNAL TEMPERATURE SENSOR <i>X</i>	\$ 54.00	
74	TEMPERATURE SENSOR BRACKET <i>BR.</i>	\$ 17.00	<i>13.04</i>
75	ENGINE COOLING FAN <i>X</i>	\$ 242.00	
76	COOLING FAN <i>X</i>	\$ 2,107.00	
77	RADIATOR AIR GUIDE - RH <i>X</i>	\$ 25.00	
78	RADIATOR AIR GUIDE - LOWER RH <i>X</i>	\$ 11.00	
79	RADIATOR AIR GUIDE - UPPER RH <i>X</i>	\$ 15.00	
80	RADIATOR AIR GUIDE - LOWER EH <i>X</i>	\$ 19.00	
SUB TOTAL SPARE PARTS		: \$ 6,015.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGB 9029 R

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
81	INTAKE AIR DUCT - RH	\$	19.00
82	ENGINE AIR GUIDE	\$	48.00
83	AIR FILTER HOUSING	\$	339.00
84	AIR MASS METER	\$	533.00
85	INTAKE HOSE	\$	85.00
86	CLAMP	\$	8.00
87	FRONT FENDER - LH	\$	700.00
88	FRONT FENDER COVER - LH	\$	228.00
89	FENDER COVER - LH	\$	21.00
90	STONE CHIP GUARD - LH	\$	46.00
91	FRONT ALUMINIUM RIM - RH	\$	651.00
92	RUBBER VALVE	4 \$	13.00
93	FRONT WISH BONE LINK - RH	\$	491.00
94	TRACK CONTROL ARM - RH	\$	861.00
95	FRONT UPPER CONTROL ARM GUIDE - RH	\$	466.00
96	FRONT UPPER CONTROL ARM - RH	\$	466.00
97	WHEEL BEARING HOUSING - RH	\$	884.00
98	BALL JOINT - RH	\$	175.00
99	WHEEL HUB - RH	\$	451.00
100	BALL BEARING - RH	\$	232.00
SUB TOTAL SPARE PARTS		: \$	6,717.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

12 Days.

Not Authorised.

Eric Qian - 8288 0282

before paint photos.

20/12/19.

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 23558

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1497/2019/TG
Date : 20-Dec-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Guo Qiang

11 days exclude 2 Sundays 1 PH

jb 26 Feb 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Lim Kim Heong
Address : 552 Pasir Ris ST 51
#13-83
Singapore 510552
Telephone : (HP) +65 96781621
Type of Claim : Own Damage Claims
Policy No. : 1800075552-01
Vehicle No : **SGB 9029 R**
Model Code : A4 Sedan 2.0 TFSI 8W
Model / Year : 28/6/2018
Engine No : CVK 061907
Chassis No : WAUZZZF46JA170965
Mileage : 24789 KM
Date In : 19-Dec-19
Estimated By : Johnny Boo / Allan Wu
Accident Date : 19-Dec-19
Place of Accident : Carpark At Blk 552 Pasir Ris St 51

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGB 9029 R

S/n	Nature of Jobs		Estimated Charges	Surveyor's recommendations
1	To tow and recover vehicle from scene of accident.	S/N \$	280.00	NA
2	To carry out first measurement test on car o-liner.	S/N \$	800.00	NA
3	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00	\$ 480.00
4	To remove and renew aircon condenser, charged air cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$	1,200.00	\$ 1,200.00
5	To remove and reinstall engine assy with gearbox assy to facillitate car o-liner repairs.	S/N \$	2,800.00	NA
7	To remove and reinstall front suspension assy with subframe to facillitate car o-liner repairs. Inspect for damages and renew if necessary.	S/N \$	2,400.00	NA
SUB TOTAL LABOUR CHARGES		:	<u>\$ 7,960.00</u>	<u>\$ 1,680.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGB 9029 R

S/n	Nature of Jobs		Estimated Charges	Surveyor's recommendation
				\$ 1,680.00
7	To place vehicle on car o-liner.	S/N \$	2,400.00	NA
8	To dismantle rhs front door panel trim. To remove and reinstall rhs wing mirror assy.	S/N \$	3,000.00	NA
9	To dismantle and renew front bumper, bonnet, both front fenders, rhs headlight. Cut out and reweld rhs fender support and closing element. Align both front chassis frames to specification of origin. Renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.	\$	8,050.00	\$ 4,750.00
10	To respray front bumper, both front fenders, bonnet, rhs upper A-pillar, engine compartment, rhs front fender top support and rhs front door. To carry out joint selant work and stone chip treatment.	\$	6,900.00	\$ 1,650.00
11	To renew rhs front rim and rhs front tyre. To carry out wheel alignment.	S/N \$	280.00	\$ 280.00
12	To carry out diagnostic checks	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 28,782.00	\$ 8,552.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBGB 9029 R

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		<u>S/Nett</u>	<u>Remarks</u>
1	FRONT BUMPER	\$ 1,999.00	\$ 1,599.20
2	FRONT BUMPER FIXING PARTS	\$ 258.00	
3	FRONT BUMPER SECURING STRIP	\$ 32.00	\$ 25.44
4	FRONT BUMPER GRILLE - CENTER	\$ 178.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 191.00	
6	FRONT BUMPER AIR GUIDE - RH	\$ 56.00	\$ 44.40
7	RADIATOR GRILLE	\$ 2,015.00	\$ 1,612.00
8	FRONT BUMPER AIR GUIDE GRILLE - LH/RH	2 \$ 665.00	\$ 266.00
9	FRONT BUMPER CARRIER	\$ 733.00	
10	FRONT BUMPER BRACKET MOUNTING - RH	\$ 34.00	\$ 27.12
11	FRONT BUMPER TOP COVER	\$ 116.00	\$ 92.40
12	FOAM FILLER PIECE	\$ 113.00	\$ 90.40
13	CAUTION SIGN STICKER	\$ 13.00	\$ 9.76
14	AIRCON STICKER	\$ 7.00	\$ 5.12
15	FRONT BUMPER LOCK CARRIER BRACKET	\$ 125.00	\$ 100.00
16	FRONT BUMPER SUPPORT - LH / RH	2 \$ 51.00	
17	FRONT BUMPER PARKING AID SENSOR	2 \$ 462.00	
18	SEAL RING	4 \$ 12.00	\$ 10.24
19	FRONT BUMPER WIRING SET	\$ 470.00	
20	HORNS - LOW TONE RIGHT	\$ 262.00	
SUB TOTAL SPARE PARTS		: \$ 7,792.00	\$ 3,882.08

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGB 9029 R

S/N	Parts Description	c/f	<u>Damaged Parts & Prices</u>	
			<u>S/Nett</u>	<u>Remarks</u>
				\$ 3,882.08
21	SPRING SHACKLE - RH		\$ 26.00	
22	FRONT FENDER - RH		\$ 700.00	\$ 559.60
23	FRONT FENDER ATTACHEMENT PARTS		\$ 183.00	
24	FRONT FENDER CLOSING ELEMENT - RH		\$ 45.00	\$ 36.00
25	FRONT FENDER BRACKET - RH		\$ 32.00	\$ 25.20
26	FRONT FENDER DEFORMATION BRACKET - RH		\$ 45.00	\$ 35.60
27	FRONT FENDER BRACKET - LH/RH		\$ 29.00	\$ 22.64
28	FRONT FENDER BRACE - RH		\$ 107.00	\$ 85.60
29	FRONT WHEEL HOUSING LINER - RH		\$ 220.00	\$ 175.60
30	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 82.00	
31	FRONT WHEEL SPOILER		\$ 65.40	\$ 52.32
32	FRONT FENDER TRIM PLATE		\$ 33.00	\$ 25.84
33	STONE CHIP GUARD - RH		\$ 46.00	\$ 36.64
34	BONNET		\$ 2,554.00	\$ 2,043.20
35	BONNET ATTACHEMENT PARTS		\$ 111.00	
36	IMPACT PROTECTION - CENTER		\$ 25.00	\$ 19.76
37	IMPACT PROTECTION - LH/RH	2	\$ 50.00	\$ 39.68
38	FRONT FENDER LEDGE COVER - RH		\$ 28.00	\$ 22.24
39	FRONT FENDER PROTECTION FILM - RH		\$ 21.00	\$ 16.16
40	STRIKER - RH		\$ 46.00	
SUB TOTAL SPARE PARTS		:	<u>\$ 4,448.40</u>	<u>\$ 7,078.16</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGB 9029 R

S/N	Parts Description	c/f	<u>Damaged Parts & Prices</u>	
			<u>S/Nett</u>	<u>Remarks</u>
				\$ 7,078.16
41	BONNET LID LOCK	\$	196.00	
42	BOWDEN CABLE - CENTER	\$	53.00	
43	BRACKET FOR CONNECTOR HOUSING	\$	9.00	\$ 6.88
44	CABLE CLIP COVER	\$	9.00	
45	HOOK RELEASE CABLE	\$	53.00	
46	HOOK RELEASE COVER	\$	12.00	
47	LID LOCK CABLE	\$	67.00	
48	PLENUM CHAMBER	\$	89.00	
49	FRONT FENDER LEDGE COVER - RH	\$	56.00	\$ 44.24
50	BONNET INSULATION	\$	311.00	
51	FRONT LED HEADLIGHT - RH	\$	7,087.00	\$ 5,669.60
52	POWER MODULE - RH	\$	716.00	
53	CONTROL UNIT - RH	\$	685.00	\$ 548.00
54	HEADLIGHT HOSE - RH	\$	32.00	
55	REPAIR KIT FOR HEADLAMP HOUSING - RH	\$	120.00	
56	LIFT CYLINDER - RH	\$	192.00	\$ 153.20
57	LIFT CYLINDER BRACKET - RH	\$	6.00	\$ 4.24
58	CORRUGATED PIPE	\$	83.00	
59	CORRUGATED PIPE FOR WASHER NOZZLE	\$	35.00	
60	CONNECTING PLATE - RH	\$	228.00	
SUB TOTAL SPARE PARTS		:	\$ 10,039.00	\$ 13,504.32

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGB 9029 R

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remarks
				\$ 13,504.32
61	CONNECTING PLATE - RH		\$ 197.00	
62	WHEEL HOUSING - RH		\$ 54.00	
63	RADIATOR SUPPORT PANEL		\$ 928.00	\$ 742.00
64	RADIATOR SUPPORT BRACKET		\$ 69.00	\$ 54.72
65	HOOK RELEASE CABLE		\$ 53.00	
66	A/C CONDENSER		\$ 568.00	
67	RADIATOR		\$ 676.00	
68	COOLANT	4	\$ 84.00	\$ 67.20
69	RADIATOR RUBBER BUSH - LOWER	2	\$ 17.00	
70	RADIATOR RUBBER BUSH - LOWER	2	\$ 24.00	
71	INTERCOOLER		\$ 535.00	
72	PRESSURE HOSE - RH		\$ 320.00	
73	EXTERNAL TEMPERATURE SENSOR		\$ 54.00	
74	TEMPERATURE SENSOR BRACKET		\$ 17.00	\$ 13.04
75	ENGINE COOLING FAN		\$ 242.00	
76	COOLING FAN		\$ 2,107.00	
77	RADIATOR AIR GUIDE - RH		\$ 25.00	
78	RADIATOR AIR GUIDE - LOWER RH		\$ 11.00	
79	RADIATOR AIR GUIDE - UPPER RH		\$ 15.00	
80	RADIATOR AIR GUIDE - LOWER EH		\$ 19.00	
SUB TOTAL SPARE PARTS			: \$ 6,015.00	\$ 14,381.28

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGB 9029 R

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
			\$ 14,381.28
81	INTAKE AIR DUCT - RH	\$ 19.00	
82	ENGINE AIR GUIDE	\$ 48.00	
83	AIR FILTER HOUSING	\$ 339.00	
84	AIR MASS METER	\$ 533.00	
85	INTAKE HOSE	\$ 85.00	
86	CLAMP	\$ 8.00	
87	FRONT FENDER - LH	\$ 700.00	
88	FRONT FENDER COVER - LH	\$ 228.00	
89	FENDER COVER - LH	\$ 21.00	
90	STONE CHIP GUARD - LH	\$ 46.00	
91	FRONT ALUMINIUM RIM - RH	\$ 651.00	\$ 520.80
92	RUBBER VALVE	4 \$ 13.00	\$ 9.92
93	FRONT WISH BONE LINK - RH	\$ 491.00	
94	TRACK CONTROL ARM - RH	\$ 861.00	
95	FRONT UPPER CONTROL ARM GUIDE - RH	\$ 466.00	
96	FRONT UPPER CONTROL ARM - RH	\$ 466.00	
97	WHEEL BEARING HOUSING - RH	\$ 884.00	
98	BALL JOINT - RH	\$ 175.00	
99	WHEEL HUB - RH	\$ 451.00	
100	BALL BEARING - RH	\$ 232.00	
SUB TOTAL SPARE PARTS		: \$ 6,717.00	\$ 14,912.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGB 9029 R

S/N	Parts Description		<u>Damaged Parts & Prices</u>	
			S/Nett	Remarks
		c/f		\$14,912.00
101	COUPLING ROD - RH		\$ 123.00	
102	DRIVE SHAFT - RH		\$ 2,422.00	
103	SHOCK ABSORBER - RH		\$ 276.00	
104	TRACH ROD - RH		\$ 90.00	
105	TIE ROD END - RH		\$ 180.00	
106	FRONT NO PLATE		\$ 40.00	\$40.00
107	ADHESIVE SEALANT	S/N	\$ 180.00	
108	CAVITY WAX		\$ 140.00	
109	STONE CHIP		\$ 180.00	
110	FRONT TYRE - RH		\$ 265.00	\$212.00
112	SUNDRIES		\$ 400.00	\$35.20
TOTAL SPARE PARTS			: \$ 39,307.40	\$15,199.20
TOTAL LABOUR CHARGES			: \$ 28,782.00	\$8,552.00
GRAND TOTAL			: \$ 68,089.40	\$23,751.20

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1497/2019/TG 26-Dec-19 Glory Tan 1 of 1 SGB 9029 R A4 Sedan 2.0 TFSI 8W
Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	Front LED headlight LHS	\$ 7,087.00	na
		\$ 7,087.00	
<u>Labours</u> 1	To remove and renew headlight LHS.	\$ 700.00	
	Labour total	\$ 700.00	
	Part total	\$ 7,087.00	
	TOTAL	\$ 7,787.00	

For Premium Automobiles Pte Ltd

Authorised Signature

} X MN

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 28 February 2020 10:30 AM
To: Boo seng yak; Guo Qiang (LKKAUTO); SUR; Carrine Leong; Chang Chee Sing; jayee.yap@premiumauto.com.sg
Subject: RE: FINAL REVISION - SGB9029R - OD AIG - SURVEYED 20 DEC 19

Dear Mr Boo,

Confirm repair cost of \$23,751.20 before GST @ 11 days of repairs

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Thursday, 27 February 2020 5:53 PM
To: Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Chang Chee Sing <claims@premiumauto.com.sg>; jayee.yap@premiumauto.com.sg
Subject: FINAL REVISION - SGB9029R - OD AIG - SURVEYED 20 DEC 19

Hi Guo Qiang and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$23,751.20 @ 11 days of repairs exclude 2 Sundays and 1 PH.

Your early closure is well appreciated.

Best regards - jb