

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 23245

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1489/2019/NS
Date	:	17-Dec-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Phyo Pyi Sone Khine
Address	:	Blk 203 Bukit Batok St 21 #-13-34 Singapore 650203
Telephone	:	(HP) +65 91558823
Type of Claim	:	Own Damage Claims
Policy No.	:	1900022421
Vehicle No	:	SMJ 3795 M
Model Code	:	Audi A5 S8 2.0 TFS
Model / Year	:	28/2/2019
Engine No	:	CVK 075889
Chassis No	:	WAUZZZF50KA023406
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	14-Dec-19
Place of Accident	:	Slip Road Bukit Batok Rd & Bukit Batok West Ave 5

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMJ 3795 M

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00	✓
2	To dismantle and renew front bumper, bonnet and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$	2,800.00	1000
3	To respray front bumper and bonnet.	\$	2,200.00	1100
4	To carry out diagnostic checks.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	<u>\$ 5,672.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMJ 3795 M

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remarks
1	FRONT BUMPER / de	S	2,073.00	1653.40
2	FRONT BUMPER FIXING PARTS X	S	368.00	X
3	FRONT BUMPER GRILLE - CENTRE X	S	178.00	X
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE X NN	S	207.00	X
5	FRONT BUMPER SPOILER X	S	489.00	X
6	FRONT BUMPER AIR GUIDE - LH X	S	56.00	X
7	RADIATOR GRILLE / BR.	S	2,131.00	1704.80
8	ULTRASOUND SENSOR SUPPORT - LH / RH X NN/2	S	96.00	X
9	RADIATOR GRILLE COVER - UPPER X	S	174.00	X
10	FRONT BUMPER AIR GUIDE GRILLE - LH X / lot	S	431.00	344.40
11	FRONT BUMPER FOAM FILLER PIECE / COA.	S	113.00	90.40
12	FRONT BUMPER CARRIER X NN	S	733.00	X
13	FRONT BUMPER COVER X / BR	S	116.00	✓ 52.40
14	FRONT BUMPER GUIDE SECTION - LH X NN	S	33.00	X
15	CAUTION SIGN STICKER X / fake	NEC S	13.00	✓ 10.24
16	AIRCON STICKER X	NEC S	7.00	✓ 5.36
17	LOCK CARRIER BRACKET X	S	125.00	X
18	FRONT BUMPER SUPPORT - LH / RH X	2 S	52.00	X
19	FRONT PARKING AID SENSOR - OUTER / INNER X	2 S	462.00	X
20	FRONT PARKING AID SEAL RING X NN	4 S	12.00	X
SUB TOTAL SPARE PARTS		:	\$	7,869.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMJ 3795 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	HORN - LH HIGH TONE <i>X SNN</i>	\$ 37.00	X
22	SPRING SHACKLE - LH <i>X SNN</i>	\$ 26.00	X
23	BONNET <i>/ BT</i>	\$ 2,602.00	2081.60
24	BONNET ATTACHMENT PARTS <i>X NN</i>	\$ 111.00	X
25	BONNET IMPACT PROTECTION - LH / RH / CENTRE <i>/ AC</i>	\$ 75.00	59.44
26	BONNET BOWDEN CABLE - CENTRE <i>X</i>	\$ 53.00	X
27	LED HEADLIGHT - LH <i>X</i>	\$ 7,204.00	X
28	LIFT CYLINDER - LH <i>X</i>	\$ 181.00	X
29	RADIATOR AIR GUIDE - LH OUTER <i>X</i>	\$ 28.00	X
30	RADIATOR AIR GUIDE - LH INNER <i>X</i>	\$ 15.00	X
31	RADIATOR AIR GUIDE RH OUTER <i>X</i>	\$ 28.00	X
32	RADIATOR AIR GUIDE - RH INNER <i>X</i>	\$ 15.00	X
33	RADIATOR AIR GUIDE - UPPER <i>X</i>	\$ 15.00	X
34	FRONT NO PLATE <i>/ AC</i>	S/N \$ 40.00	
35	SUNDRIES <i>X NN</i>	\$ 300.00	X

TOTAL SPARE PARTS : \$ 18,599.00

TOTAL LABOUR CHARGES : \$ 5,672.00

GRAND TOTAL : \$ 24,271.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

5 Days. 26/12/19
Guo Qiang - 82880282
before paint photos.
Not Authorised.
20/12/19

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant