

# FASTECH AUTO PTE LTD

page 1/3

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262D

Estimate : 21600

TPANG.

Vic

Date : 19.12.2019

Vehicle Num : SDV 7632S

Make/Model : TOYOTA CAMRY

Chassis/Engine no :

MROS3CK5004011750 Accident Date : 18.12.2019

Claim No : 1219-21600

Reference :

Policy No :

Qty Particular Amount SS

List Item :

1 pc	Front bonnet	\$	1,243.90	+
1 pc	Front bonnet chrome moulding	\$	246.00	+
1 pc	Front bonnet lock	\$	128.20	+
1 pc	Front bonnet lock catch	\$	55.90	+
1 pc	Front bonnet insulator	\$	258.00	+
2 pc	Front bonnet hinge @ 56.60	\$	113.20	+
2 pc	Front bonnet absorber @ 292.50	\$	585.00	+
1 pc	Front grille <i>crackd</i>	\$	510.50	✓
1 pc	Front grille logo <i>new</i>	\$	60.10	✓
1 pc	Front support panel <i>new</i>	\$	1,084.40	+
2 pc	Front head lamp assy @ 2850.00 <i>RT crackd</i>	\$	<del>5,700.00</del> 2850.00	+
2 pc	Front horn @ 146.30 <i>new</i>	\$	292.60	+
1 pc	Front bumper <i>del</i>	\$	567.70	✓
1 pc	Front bumper reinforment <i>new</i>	\$	411.40	+
2 pc	Front bumper side retainer @ 66.70 <i>new</i>	\$	133.40	✓
2 pc	Front bumper fog lamp @ 308.30	\$	616.60	+
2 pc	Front bumper fog lamp cover @ 158.70 <i>new</i>	\$	317.40	+
1 pc	Front bumper lower grille	\$	97.70	+
1 pc	Front bumper inner sponge <i>crackd</i>	\$	135.50	✓
1 pc	Front bumper lower grille chrome <i>new</i>	\$	280.50	+
1 pc	Front number plate garnish <i>crackd</i>	\$	65.80	✓
2 pc	Front bumper fog lamp cover outer rim @ 65.00 <i>new</i>	\$	130.00	+
2 pc	Front fender @ 586.30	\$	1,172.60	+
1 pc	Rear boot lid <i>Regis</i>	\$	931.30	+
1 pc	Rear boot lock	\$	892.20	+
1 pc	Rear boot lock catch	\$	51.80	+
1 pc	Rear boot centre garnish <i>new</i>	\$	393.80	+
1 pc	Rear boot centre emblem	\$	77.40	+
1 pc	Rear boot lid (Hybrid) <i>new</i>	\$	48.20	✓
1 pc	Rear boot inner board <i>new</i>	\$	499.80	+
1 pc	Rear boot emblem ( Camry ) <i>new</i>	\$	58.50	✓
		\$	17,159.40	

**FASTECH AUTO PTE LTD**

page 2/3

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262D

Estimate : 21600

Date : 19.12.2019

Vehicle Num : SDV 7632S

Make/Model : TOYOTA CAMRY

Chassis/Engine no :

Accident Date : 18.12.2019

Claim No : 1219-21600

Reference :

Policy No :

Qty	Particular	Amount S\$
<u>List Item :</u>		
1 pc	Rear boot emblem (Hybrid synergy drive) <i>3 pc</i>	\$ 48.20 ✓
1 pc	Rear boot centre emblem	\$ 77.40 ✓
2 pc	Rear boot reflector lamp @ 399.40 <i>3 pc</i>	\$ 798.80 +
2 pc	Rear boot hinge <i>2 pc</i>	\$ 243.80 +
1 pc	Rear boot rubber <i>at</i>	\$ 207.30 ✓
2 pc	Rear boot number plate lamp @ 36.70 <i>new</i>	\$ 73.40 +
2 pc	Rear tail lamp @ 689.20 <i>deleted</i>	\$ <del>842.60</del> 1,378.40
2 pc	Rear tail lamp panel @ 244.80 <i>new</i>	\$ 489.60 +
2 pc	Rear tail lamp lower bracket @ 25.20 <i>new</i>	\$ 50.40 +
1 pc	Rear end panel <i>Deleted</i>	\$ 647.30 ✓
1 pc	Rear end panel top garnish <i>Deleted</i>	\$ <del>221.30</del> 421.30
1 pc	Rear fender inner garnish @ 434.30 <i>new</i>	\$ 838.60 +
1 pc	Rear spare tyre panel top cover board <i>Not a</i>	\$ 244.80 +
1 pc	Rear bumper <i>Deleted</i>	\$ 585.70 ✓
2 pc	Rear bumper side retainer @ 103.10 <i>new</i>	\$ 206.20 ✓
1 pc	Rear bumper towing cover <i>new</i>	\$ 26.50 +
1 pc	Rear bumper reinforcement <i>Best</i>	\$ <del>455.60</del> 561.30 ✓
1 pc	Rear exhaust silencer <i>Repair</i>	\$ 981.30 +
2 pc	Rear exhaust rubber @ 60.80 <i>new</i>	\$ 121.60 +
1 pc	rear exhuast chrome tail pipe <i>Best</i>	\$ 125.00 ✓
1 pc	Rear bumper lower <del>cooling</del> cover. <i>Deleted</i>	\$ 86.30 ✓
4 pc	Rear bumper parking sensor @ 325.00 <i>2 pieces damaged</i>	\$ 1,300.00 <del>520</del>
4 pc	Rear bumper parking sensor holder @ 41.70 <i>new</i>	\$ 166.80 +
List Item Total :		\$ 26,839.40
Discount 25%		\$ 6,709.85
		\$ 20,129.55

6927.60

5195.70

# FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262D

page 3/3

Estimate : 21600

Date : 19.12.2019

Vehicle Num : SDV 7632S

Make/Model : TOYOTA CAMRY

Chassis/Engine no :

Accident Date : 18.12.2019

Claim No : 1219-21600

Reference :

Policy No :

Qty	Particular	Amount S\$
<u>Special Nett Item :</u>		
4 pc	Rear tail lamp clips @ 6.50 <i>nr</i>	\$ 26.00 ✓
12pc	Rear fender inner garnish clips @ 6.50 <i>green</i>	\$ 78.00 +
12pc	Rear boot inner board clips @ 6.50 <i>green</i>	\$ 78.00 +
1 set	Rear bumper clip <i>nr</i>	\$ <del>80.00</del> 30
1 pc	Rear number plate <i>green</i>	\$ 45.00 +
1 pc	Rear reverse camera <i>101</i>	\$ 650.00 +
1 pc	Front number plate <i>Best</i>	\$ 45.00 ✓
Special Nett Item Total :		\$ 1,002.00

Labour Charge :

To check wiring	\$ 150.00 <i>60</i>
Tuff kote	\$ 200.00 <i>60</i>
Remove and refix upholstery	\$ 160.00 <i>60</i>
Remove and replace exhaust pipe	\$ 160.00 <i>80</i>
Remove and replace reverse sensor	\$ 160.00 <i>60</i>
To remove and replace spare part and panel beating	\$ 1,800.00 <i>900</i>
To spray painting and etc	\$ 1,800.00 <i>1000</i>
Remove and refix aircon condenser and refix gas	\$ 150.00 +
Remove and refix radiator	\$ 100.00 +
Labour Charge Total :	\$ 4,680.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be received & O/E is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total Amount : \$ 25,811.55

*Adrian*  
*H/S 19/12/19.*  
*07 Days*

*Total: 7516.70*

*H/S: 6/12.*