

FASTECH AUTO PTE LTD

PAGE 1 OF 2

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Estimate : 21599

Date : 18.12.2019

Vehicle Num : GBJ 200M

Make/Model : TOYOTA HIACE

Chassis/Engine no :

Accident Date : 18.12.2019

Claim No : 1219-21599

Reference :

Policy No :

TP AIG.

Vic

JTFT+T02P/100245773

Qty	Particular	Amount S\$
<u>List Item :</u>		
1 pc	Rear boot cover <i>Dehnd</i>	\$ 2,265.00 <i>1772.70</i>
1 pc	Rear boot rubber <i>lit</i>	\$ 328.50 ✓
1 pc	Rear boot lock <i>Jamnd</i>	\$ 265.10 ✓
2 pc	Rear boot hinga @ 85.20 <i>2 pc n</i>	\$ 170.40 +
2 pc	Rear boot absorber @ 285.00	\$ 570.00 +
1 pc	Rear boot centre garnish <i>could</i>	\$ 176.50 ✓
1 pc	Rear boot inner board <i>torn</i>	\$ 515.20 <i>16530</i>
1 pc	Rear boot windscreen glass moulding <i>new</i>	\$ 1,243.60 <i>172.50</i>
1 pc	Rear boot lock actuator <i>2 pc n</i>	\$ 410.60 <i>245.30</i>
1 pc	Rear boot mirror with braket <i>new</i>	\$ 356.50 +
1 pc	Rear boot wiper motor <i>new</i>	\$ 498.50 +
1 pc	Rear boot wiper arm <i>new</i>	\$ 145.40 +
1 pc	Rear boot wiper blade <i>new</i>	\$ 89.50 +
1 pc	Rear boot emblem logo <i>2 pc n</i>	\$ 65.20 —
1 pc	Rear boot sticker toyota <i>new</i>	\$ 38.50 —
1 pc	Rear boot sticker hiace <i>new</i>	\$ 38.50 —
1 pc	Rear end panel inner <i>Regis Dentol</i>	\$ 850.00 <i>585</i>
1 pc	Rear end panel outer <i>Dented</i>	\$ 486.50 —
1 pc	Rear third brake light <i>new</i>	\$ 410.40 +
1 pc	Rear floor board panel <i>Regis</i>	\$ 2,381.40 +
1 pc	Rear bumper <i>Dehnd</i>	\$ 498.00 ✓
2 pc	Rear bumper side retainer @ 60.80 <i>new</i>	\$ 121.60 —
4 pc	Rear bumper lower support bracket @ 56.20 <i>Best</i>	\$ 224.80 <i>180</i>
2 pc	Rear number plate lamp @ 65.60 <i>new</i>	\$ 131.20 +
2 pc	Rear taillamp @ 485.00 <i>could</i>	\$ 704.60 <i>610</i>
2 pc	Rear taillamp garnish @ 109.50 <i>RA torn</i>	\$ 219.00 <i>108.50</i>
1 pc	Rear exhaust silencer <i>new</i>	\$ 825.00 +
2 pc	Rear exhaust rubber @ 58.70 <i>new</i>	\$ 117.40 +
1 pc	Rear spare tyre carrier <i>Best</i>	\$ 412.10 — <i>385</i>
1 pc	Rear boot rubber top garnish <i>Best</i>	\$ 82.70 —
2 pc	Rear fender @ 2055.60 <i>Regis</i>	\$ 4,111.20 +
2 pc	Rear fender inner board @ 365.20 <i>new</i>	\$ 730.40 +
1 pc	Rear fender air duct <i>new</i>	\$ 76.70 +
List Item Total :		\$ 19,360.00
Discount 25 %		\$ 4,840.00
		\$ 14,520.00

6286.20

4714.65

FASTECH AUTO PTE LTD

PAGE 2 OF 2

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Estimate : 21599

Date : 18.12.2019

Vehicle Num : GBJ 200M

Make/Model : TOYOTA HIACE

Chassis/Engine no :

Accident Date : 18.12.2019

Claim No : 1219-21599

Reference :

Policy No :

Qty	Particular	Amount S\$
-----	------------	------------

Special Nett Item :

1 pc	Rear wooden floor board panel	\$ 550.00 +
1 set	Rear bumper clip	\$ 50.00 - 30
1 set	Rear windscreen glass sealant	\$ 120.00 - 60
1 pc	Rear 70 KM sticker	\$ 25.00 - 15
1 set	Resersing sensor	\$ 350.00 - 200
1 set	Rear boot cover, side panel lettering	\$ 850.00 - 350
Special Nett Total :		\$ 1,945.00

Labour Charge :

To check wiring	\$ 100.00 - 30
Apply anti rust chemical	\$ 150.00 - 80
Remove & refix rear windscreen glass	\$ 150.00 - 120
Remove, refix & renew rear exhaust pipe	\$ 150.00 x
Remove & refix rear floor mat etc	\$ 120.00 x
Remove & renew reversing sensor	\$ 150.00 - 50
Labour charge knock dents on rear damage portion cut, welding & renew parts	\$ 2,500.00 - 1300
To spray paint affected portion	\$ 2,500.00 - 1300
Labour Charge Total :	\$ 5,820.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

FASTECH AUTO PTE LTD
Signature: _____

Date: _____

Total Amount : \$ 22,285.00

total: 8249.65

h/s: 66K

66K