



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
 Tel: +65 67412845 Fax No: +65 67412170
 Email: zero_gravity@singnet.com.sg
 Buss.Reg.No.: 52888887X

CC6/HGT19022444/MS3

QUOTATION

No : QT-000202

AIG ASIA PACIFIC INSURANCE PTE. LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attention: Motor Claim Department

TEL : 64193000

FAX :

Jiale

Your Ref. : SLC242K
 Vehicle No. : SLH9079E
 Make & Model : MERCEDES E200
 Chasis No. : WDD2120482A519753
 Engine No. : 27186030325151
 Accident Date : 28-11-2019
 Policy No. : 5106912668
 Date : 18-12-2019
 Page : 1 of 2

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
1	REAR BUMPER <i>Deformed</i>	1.0 PCS	1,640.00	1,640.00 ✓
2	REAR BUMPER LIP <i>Deformed</i>	1.0 PCS	520.00	520.00 ✓
3	REAR BUMPER LIP BRACKET <i>new</i>	2.0 PCS	27.00	54.00 ✗
4	BUMPER BEAM SCREW/INNER CLIPS SET <i>new</i>	1.0 SET	120.00	120.00 30
5	BUMPER CAP <i>new</i>	1.0 PCS	62.00	62.00 ✗
6	REAR BUMPER CHROME MOULDING (CENTER) <i>new</i>	1.0 PCS	182.00	182.00 ✓
7	REAR BUMPER CHROME MOULDING (SIDE)	2.0 PCS	138.00	276.00 ✓
8	BUMPER BRACKET (L/H) <i>could</i>	1.0 PCS	73.00	73.00 ✓
9	BUMPER BRACKET (R/H) <i>new</i>	1.0 PCS	73.00	73.00 ✗
10	REAR BUMPER TOP RETAINER <i>could</i>	1.0 PCS	48.00	48.00 ✓
11	BUMPER REINFORCEMENT <i>Bent</i>	1.0 PCS	413.00	413.00 ✓
12	GARNISH (EXHAUST) <i>new</i>	2.0 PCS	136.00	272.00 ✗
13	EXHAUST TAIL PIPE <i>new</i>	1.0 PCS	320.00	320.00 ✗
14	REAR END PANEL <i>Repis</i>	1.0 PCS	1,300.00	1,300.00 ✗
15	REAR END PANEL GARNISH <i>new</i>	1.0 PCS	150.00	150.00 ✗
16	REAR BOOT <i>Buckled</i>	1.0 PCS	3,100.00	3,100.00 1753
17	REAR BOOT CHROME STRIP <i>new</i>	1.0 PCS	135.00	135.00 ✗
18	REAR BOOT OUTER HANDLE <i>new</i>	1.0 PCS	265.00	265.00 ✗
19	REAR BOOT INNER TRIM BOARD <i>new</i>	1.0 PCS	325.00	325.00 ✗
20	REAR BOOT INNER TRIM BOARD CLIPS <i>new</i>	8.0 PCS	8.00	64.00 ✗
21	REAR BOOT WEATHERSTRIP <i>new</i>	1.0 PCS	185.00	185.00 ✗
22	REAR BOOT INNER LOCK <i>Dauid</i>	1.0 PCS	1,175.00	1,175.00 295
23	LOGO	1.0 PCS	57.00	57.00 ✓
24	EMBLEM "C&C"	1.0 PCS	90.00	90.00 ✓
25	EMBLEM 'E200'	1.0 PCS	86.00	86.00 ✓
26	EMBLEM '7G TRONIC'	1.0 PCS	95.00	95.00 ✓



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
Tel: +65 67412845 Fax No: +65 67412170
Email: zero_gravity@singnet.com.sg
Buss.Reg.No.: 5288887X

QUOTATION

No : QT-000202

AIG ASIA PACIFIC INSURANCE PTE. LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attention: Motor Claim Department

TEL : 64193000

FAX :

Your Ref. : SLC242K
Vehicle No. : SLH9079E
Make & Model : MERCEDES E200
Chasis No. : WDD2120482A519753
Engine No. : 27186030325151
Accident Date : 28-11-2019
Policy No. : 5106912668
Date : 18-12-2019
Page : 2 of 2

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
27	LAMP (L/H/R) <i>crack</i>	1.0 PCS	725.00	725.00 <i>652</i>
28	LAMP (REAR) (BOOT L/H) <i>new</i>	1.0 PCS	525.00	525.00 <i>X</i>
29	REVERSE SENSOR <i>Damaged</i>	1.0 PCS	286.00	286.00 <i>✓</i>
30	Discount 20 %			-2,523.20
31	SubTotal (L)			10,092.80
32	REVERSE CAMERA <i>new</i>	1.0 PCS	450.00	450.00 <i>X</i>
33	SubTotal (S)			450.00
34	PANEL BEAT & REPAIR REAR DAMAGE	1.0 X		1,000.00 <i>600</i>
35	TO PUTTY AND RE-SPRAY AFFECTED PORTION	1.0 X		900.00 <i>100</i>
36	TO PROVIDE UNDER TURFCOAT	1.0 X		180.00 <i>30</i>
37	TO TRANSFER REAR BOOT FITTING	1.0 X		180.00 <i>80</i>
38	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT	1.0 X		80.00 <i>30</i>
39	TO REMOVE REVERSE SENSOR/CAMERA	1.0 X		250.00 <i>100</i>
40	TO REMOVE AND REFIT COMPONENTS / FACILITATE THE REPAIR	1.0 X		250.00 <i>60</i>
41	SubTotal (LABOUR)			2,840.00

SINGAPORE DOLLAR THIRTEEN THOUSAND THREE HUNDRED EIGHTY TWO AND CENTS EIGHTY ONLY

E. & O.E

Total	S\$	13,382.80
Discount	S\$	0.00
Net Total	S\$	13,382.80

LKK Auto Consultants hence notify the Repairer of the following:

Customer's Signature/Co. Stamp

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

Any claim for faulty workmanship is limited solely to the rectification free of cost of such work, no claim for loss consequential or otherwise being admissible. Any objections to the validity of these charges must be made seven (7) days from the date of this invoice otherwise it is assumed that this bill is accepted as correct.

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

ZERO GRAVITY

Terms: C.O.D.

Total: 6997.50

H/s: 561C

05 Days.

561C