

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 22950

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/TP/1491/2019/TG  
**Date** : 19-Dec-19

**Vehicle IN workshop. Please arrange for survey**

**Your Insured Vehicle no : SMQ 1924 J**

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr. Lai Chong Sin  
**Address** : Blk 296 Choa Chu Kang Avenue 2  
#10-04  
Singapore 680296  
**Telephone** : HP +65 98188654  
**Type of Claim** : Third Party Claim  
**Policy No.** : PNPV2019-0005807  
**Vehicle No** : **SLZ 1847 M**  
**Model Code** : Audi A3 Sedan 1.0 TFSI 8V  
**Model / Year** : 25/4/2018  
**Engine No** : CHZ 905215  
**Chassis No** : WAUZZZ8V8J1056584  
**Mileage** : 41,067 KM  
**Date In** : 18-Dec-19  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 18-Dec-19  
**Place of Accident** : Nanyang Crescent After Pioneer Road North, At Roundabout

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLZ 1847 M

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To tow and recover vehicle from scene of accident.	S/N \$	280.00	X.
2	To carry out first measurement test on car -o liner test.	S/N \$	800.00	X
3	To remove and transfer rear parking aid. Check function.	S/N \$	280.00	✓
4	To renew rear windscreen and rhs 1/4 glass to facilliate fender renewal.	S/N \$	600.00	✓
5	To install rear windscreen solar film.	S/N \$	400.00	✓
6	To remove and transfer rhs rear door's multi lock system and power window devices. Inspect for damages.	S/N \$	280.00	✓
7	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$	1,400.00	✓
8	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbaq etc.	S/N \$	1,400.00	✓
<b>SUB TOTAL LABOUR CHARGES</b>			<b>: \$ 5,440.00</b>	

# Premium Automobiles

S5 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLZ 1847 M

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
9	To remove and reinstall exhaust system and rear suspension assembly, including rear axle. Renew accordingly.	S/N \$	2,400.00	✓
10	To remove and reinstall fuel tank assy.	S/N \$	600.00	✓
11	To place vehicle on car o-liner.	S/N \$	1,800.00	✗
12	To dismantle rear bumper, rear lid and rhs rear door. Cut out and weld rhs rear fender, rhs rear inner side panel and rhs outer wheel housing and connecting plate. Renew rear bumper and rhs rear door. Re-organise rear crash management components. Reinstall all parts removed.	\$	<del>9,800.00</del>	4000
13	To respray rear bumper, rhs rear fender, rhs rear door, rhs sill panel, door entrances, roof channel, drain panel, end panelling, rhs side inner panel and rhs outer wheel housing and connecting plate. To carry out stone chip treatment and joint sealer works.	\$	<del>7,000.00</del>	5 x 550 <del>3500</del> 3300
14	To renew rhs rear rim and carry out wheel alignment.	S/N \$	280.00	✓
15	To carry out diagnostic check.	S/N \$	192.00	✓
<b>TOTAL LABOUR CHARGES</b>			<b>: \$ 27,512.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLZ 1847 M

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
1	QUATER PANEL REAR FENDER - RIGHT <i>Distorted</i>	\$	2,110.00	✓
2	REAR WHEEL HOUSING INNER - RH <i>Ryr</i>	\$	561.00	✗
3	QUATER PANEL REAR REINFORCEMENT - RH <i>new</i>	\$	249.00	✗
4	QUATER PANEL REAR REINFORCEMENT - LOWER RH <i>new</i>	\$	176.00	✗
5	REAR WINDSCREEN <i>new</i>	\$	742.00	✓
6	PRIMER	\$	19.00	✓
7	1/4 QUATER GLASS - REAR RH <i>new</i>	\$	520.00	✓
8	REAR BUMPER <i>toin</i>	\$	1,793.00	✓
9	STICKY PAD <i>not new</i>	4 \$	21.00	✗
10	REAR BUMPER FIXING PARTS <i>new</i>	\$	175.00	✗
11	REAR BUMPER COVER - LH/RH <i>new</i>	2 \$	68.00	✗
12	REAR BUMPER GUIDE SECTION - LH/RH <i>RH 2nd</i>	2 \$	<del>29.00</del> 19.50	
13	REAR BUMPER LOCKING MECHANISM <i>new</i>	2 \$	53.00	✗
14	REAR BUMPER SPOILER <i>wt</i>	\$	216.00	✓
15	REAR REFLECTOR LIGHT - LH/RH	2 \$	75.00	✗
16	REAR LED TAIL LIGHT - OUTER RH <i>new</i>	\$	800.00	✗
17	REAR TAIL LIGHT TRIM - OUTER RH	\$	27.00	✗
18	REAR BUMPER BRACKET - LH/RH <i>RH 2nd</i>	\$	<del>50.00</del> 25	
19	REAR BUMPER GUIDE SECTION - LH/RH <i>RH 1st</i>	2 \$	<del>120.00</del> 60	
20	REAR PARKING AID SENSOR - INNER/OUTER <i>Not New</i>	4 \$	924.00	✗
<b>SUB TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 8,728.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLZ 1847 M

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
21	REAR PARKING AID SENSOR SEAL RING <i>Nil Nil</i>	4	\$ 12.00	X
22	REAR BUMPER WIRING SET <i>Nil Nil</i>		\$ 472.00	X
23	REAR VENT TRIM - RH <i>cond</i>		\$ 64.00	-
24	FUEL FILLER FLAP <i>Regis</i>		\$ 121.00	X.
25	REAR WHEEL HOUSING LINER - RH <i>ton</i>		\$ 223.00	✓
26	REAR WHEEL HOUSING LINER ATTACHMENT PARTS <i>Nil Nil</i>		\$ 81.00	X.
27	REAR DOOR - RH <i>Distal</i>		\$ 2,279.00	✓
28	REAR OUTER DOOR SEAL - RH <i>new</i>		\$ 146.00	✓
29	BONDING AGENT <i>Nil</i>		\$ 45.00	✓
30	CLEANING SOLUTION <i>Nil</i>		\$ 65.00	✓
31	APPLICATOR <i>Nil Nil</i>		\$ 7.00	X.
32	REAR DOOR ATTACHMENT PARTS <i>new</i>		\$ 117.00	+
33	REAR DOOR CATCH - RH <i>new</i>		\$ 85.00	+
34	REAR INNER DOOR SEAL - RH <i>new</i>		\$ 174.00	X
35	REAR DOOR HANDLE - RH <i>Regis</i>		\$ 331.00	+
36	REAR DOOR HANDLE COVER - RH <i>Regis</i>		\$ 47.00	+
37	REAR DOOR LUGGAGE COMPARTMENT TRIM - RH <i>new</i>		\$ 704.00	X
38	LASHING EYE - LOWER <i>new</i>	2	\$ 42.00	+
39	REAR ALUMINIUM RIM - RH <i>lit</i>		\$ 666.00	✓
40	RUBBER VALVE <i>Nil</i>	4	\$ 13.00	X.
<b>SUB TOTAL SPARE PARTS</b>			<b>\$ 5,694.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLZ 1847 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
41	REAR AXLE BEAM <i>Bent</i>	\$ 1,792.00	<input checked="" type="checkbox"/>
42	BEARING BRACKET FOR REAR AXLE <i>Not M</i>	\$ 189.00	<input checked="" type="checkbox"/>
43	REAR AXLE COVER - RH <i>Not M</i>	\$ 8.00	<input checked="" type="checkbox"/>
44	REAR WHEEL BEARING - RH <i>Dmgd.</i>	\$ 262.00	<input checked="" type="checkbox"/>
45	REAR WHEEL BEARING WITH ASSEMBLY PARTS <i>Dmgd.</i>	\$ 452.00	<input checked="" type="checkbox"/>
46	REAR GAS SHOCK ABSORBER - RH <i>Not M</i>	\$ 224.00	<input checked="" type="checkbox"/>
47	STONE CHIP GUARD - RH <i>M</i>	\$ 8.00	<input type="checkbox"/>
48	PROTECTIVE PIPE <i>M</i>	\$ 56.00	<input type="checkbox"/>
49	SHOCK ABSORBER BEARING <i>Not M</i>	\$ 94.00	<input checked="" type="checkbox"/>
50	ADHESIVE SEALANT	\$ 180.00	<input type="checkbox"/>
51	CAVITY WAX	\$ 140.00	<input type="checkbox"/>
52	STONE CHIP	\$ 180.00	<input type="checkbox"/>
53	METAL FILLER POWDER	\$ 280.00	<input type="checkbox"/>
54	REAR WINDSCREEN SEALANT	\$ 200.00	<input type="checkbox"/>
55	1/4 GLASS SEALANT	\$ 100.00	<input type="checkbox"/>
56	SUNDRIES <i>Nec</i>	\$ <del>400.00</del>	<input type="checkbox"/>

**TOTAL SPARE PARTS : \$ 18,987.00**

**TOTAL LABOUR CHARGES : \$ 27,512.00**

**GRAND TOTAL : \$ 46,499.00**

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

74.24

# Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

## Supplementary Estimate 1

GST Reg No. 19-9902271-W

<b>AIG Asia Pacific Insurance Pte Ltd</b> 78 Shenton Way #07-16 AIG Building Singapore 079120 <b>Attn: Mr. Adrian Ling - Motor Claims Dept</b> Tel: 6841 0055 - Fax: 6256 4315		<b>Estimate No.</b> <b>Date</b> <b>Service Advisor</b> <b>Pages</b> <b>Regn No</b> <b>Model No</b>	PA/OD/1491/2019/TG 20/01/2020 Glory Tan 1 of 1 SLZ 1847 M Audi A3 Sedan 1.0 TFSI 8V	
Quantity	Description		Unit Price	Amount
<u>Parts</u> 1	Rhs rear tyre <i>wt</i>	80%	\$ 270.00	\$ 216.00
<b>TOTAL</b>			<b>\$ 270.00</b>	<b>\$ 216.00</b>

For Premium Automobiles Pte Ltd

*Adrian Ling*  
*[Signature]*

\_\_\_\_\_  
Authorised Signature

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : Adrian King  
Surveyed Date : 19/12/19.  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : Not authorised, 14 Days. without undercarriage  
17 Days with undercarriage

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant