

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19022448/KKA3Q2

Date: 22/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900120193

Claimant
Vehicle No : SLT2445P **Insured Vehicle No :** GBJ6998E

Date of Loss: 15/12/2019 Nature of Claim: TP Claim No: 7782061721SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT2445P		
Make & Model:	TOYOTA C-HR HYBRID, 1.8 S CVT (A)	Engine No:	2ZR8128103
Reg. Date:	23/10/2017 (Man. Year: 2017)	Chassis No:	ZYX102047209
Colour:	Metallic Grey	Odometer:	73794 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Toyo 8 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Toyo 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,370.37	5,977.35	2,393.02	28.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,260.00	1,700.00	1,560.00	47.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,630.37	7,677.35	3,953.02	33.99
Approved Total (Overridden) (S\$)		6,100.00		
(S\$)	11,630.37	6,100.00	5,530.37	47.55
+ GST 7.00/7.00% (S\$)	814.13	427.00	387.13	47.55
Nett Amount (S\$)	12,444.50	6,527.00	5,917.50	47.55
+ Loss of Use (5.0 x S\$80.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,934.45		

INSPECTION

Date of Assignment: 17/12/2019

Date Inspected: 18/12/2019 Inspected At:

Hui Yang Motor Pte Ltd (HQ)
176 Sin Ming Drive #04-02, Sin Ming
AutoCare
Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH FENDER	Repair	781.50 FL	*- FL
2	1		*FRONT LH FENDER HTBRID EMBLEM	Necessary	85.25 FL	*85.25 FL
3	1		*FRONT LH FENDER PROTECTOR	Serviceable	374.45 FL	*- FL
4	1		*FRONT LH SIDE MIRROR	Cracked	781.50 FL	*781.50 FL
5	1		*FRONT LH SIDE MIRROR COVER	Dented / Cut	281.50 FL	*281.50 FL
6	1		*FRONT LH DOOR	Bent	1,150.20 FL	*1,109.00 FL
7	2		*FRONT LH DOOR HINGE	Repair	243.70 FL	*- FL
8	2		*FRONT LH DOOR FRAME STICKER	Necessary	362.50 FL	*362.50 FL
9	1		*FRONT LH DOOR PROTECTOR	Dented	481.50 FL	*281.85 FL
10	1		*FRONT LH DOOR INNER RUBBER	Cut	281.50 FL	*199.00 FL
11	1		*FRONT LH DOOR INNER LOCK	Repair	561.25 FL	*- FL
12	1		*FRONT LH DOOR GLASS GEAR & MOTOR	Distorted / Jammed	481.50 FL	*481.50 FL
13	1		*REAR LH DOOR	Bent	985.25 FL	*985.25 FL
14	2		*REAR LH DOOR HINGE	Repair	243.70 FL	*- FL
15	2		*REAR LH DOOR FRAME STICKER	Necessary	362.50 FL	*362.50 FL
16	1		*REAR LH DOOR PROTECTOR	Dented	381.50 FL	*280.00 FL
17	1		*REAR LH DOOR INNER LOCK	Repair	561.25 FL	*- FL
18	1		*REAR LH DOOR INNER RUBBER	Cut	182.50 FL	*182.50 FL
19	1		*REAR LH DOOR GLASS GEAR & MOTOR	Bent	481.50 FL	*481.50 FL
20	1		*REAR LH FENDER PROTECTOR	Dented	374.45 FL	*374.45 FL
21	1		*LH SIDE SKIRT	Dented / Cracked	681.50 FL	*681.50 FL
22	1		*LH SIDE SKIRT (BODY KIT)	Dented	780.00 FS	*780.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,900.50	7,709.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,530.13	1,732.45
Total Parts (\$\$)	8,370.37	5,977.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIT LH 2 DOOR GLASS	New	160.00	120.00
2	WIRING	New	120.00	20.00
3	TUFFKOTE	New	180.00	60.00
4	SPRAY PAINTING	New	1,400.00	900.00
5	LABOUR CHARGES	New	1,400.00	600.00
Gross Labour Cost (\$\$)			3,260.00	1,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >