

**BODYFIX**

NO 10 ANG MO KIO INDUSTRIAL PARK 2A #04-06  
 AMK AUTOPOINT SINGAPORE 568047  
 Tel No. : 62571289 Fax No. : 64837432  
 E-Mail : bodyfix@singnet.com.sg  
 Tax Reg. No. : 53010635C Buss. Reg. No. : 53010635C

AIG ASIA PACIFIC INSURANCE PTE LTD

Estimate : ES191219

Attention : Motor Claim Department

Date : 19/12/2019  
 Vehicle Num. : GBB 2141 D  
 Make/Model : TOYOTA HIACE-2008  
 Chassis/Eng# : KDH2010023495/1KD1817316  
 Accident Date : 14/12/2019  
 Claim No. :  
 Reference :  
 Policy No. :

| S/N | Quantity | Particular                                                                | Unit Price | Amount S\$ |
|-----|----------|---------------------------------------------------------------------------|------------|------------|
| 1.  | 1 PC     | LIST ITEMS :                                                              |            |            |
| 2.  | 2 PCS    | FRONT DOOR (RH) <i>1 pc - BT.</i>                                         |            | 1,811.90   |
| 3.  | 1 PC     | FRONT DOOR HINGES <i>1 pc</i>                                             | 92.60      | 185.20     |
| 4.  | 1 PC     | FRONT DOOR GLASS (RH) <i>X</i>                                            |            | 360.00     |
| 5.  | 1 PC     | DOOR GLASS MOULDING FRONT <i>X</i>                                        |            | 165.00     |
| 6.  | 1 PC     | POWER WINDOW MOTOR (FRONT RH) <i>X</i>                                    |            | 1,281.60   |
| 7.  | 1 PC     | POWER WINDOW REGULATOR FRONT RH <i>X</i>                                  |            | 345.00     |
| 8.  | 1 PC     | FRONT DOOR OUTER HANDLE (RH) <i>X</i>                                     |            | 145.00     |
| 9.  | 1 PC     | SIDE MIRROR (RH). <i>X</i>                                                |            | 750.00     |
| 10. | 1 PC     | HEAD LAMP (RH) <i>1 pc</i>                                                |            | 2,539.10   |
| 11. | 10 PCS   | FRONT BUMPER <i>1 pc</i>                                                  |            | 468.70     |
| 12. | 2 PCS    | FRONT BUMPER CLIPS <i>1 pc</i>                                            | 5.78       | 57.80      |
| 13. | 1 PC     | FRONT BUMPER SIDE RETAINER <i>X</i>                                       | 136.80     | 273.60     |
| 14. | 1 PC     | FRONT BUMPER LOWER GRILLE <i>X</i>                                        |            | 156.30     |
|     |          | FRONT CORNER PANEL (RH) <i>X</i>                                          |            | 268.70     |
|     |          | List TotalS\$ :                                                           |            | 8,807.90   |
| 1.  | RH -FRT  | SPECIAL NETT ITEMS :                                                      |            |            |
|     |          | DOOR STICKER <i>1 pc</i>                                                  | 15         | 100.00     |
|     |          | Special Nett Total S\$ :                                                  |            | 100.00     |
|     |          | LABOUR :                                                                  |            |            |
|     |          | RUST-PROOFING ON THE ACCIDENT AFFECTED PORTIONS                           | NN X       | 60.00      |
|     |          | LABOUR TO REPLACE ABOVE PARTS, PANEL BEAT, REPAIR & RE-ALIGN DAMAGE PARTS | 400        | 1,200.00   |

CONTINUE / ...

**BODYFIX**

NO 10 ANG MO KIO INDUSTRIAL PARK 2A #04-06  
 AMK AUTOPOINT SINGAPORE 568047  
 Tel No. : 62571289 Fax No. : 64837432  
 E-Mail : bodyfix@singnet.com.sg  
 Tax Reg. No. : 53010635C Buss. Reg. No. : 53010635C

AIG ASIA PACIFIC INSURANCE PTE LTD

Estimate : ES191219

Attention : Motor Claim Department

Date : 19/12/2019  
 Vehicle Num. : GBB 2141 D  
 Make/Model : TOYOTA HIACE-2008  
 Chassis/Eng# : KDH2010023495/1KD1817316  
 Accident Date : 14/12/2019  
 Claim No. :  
 Reference :  
 Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

SPRAY PAINT RH FRONT DOOR, FRONT BUMPER, RH CORNER  
 PANEL & OTHER AFFECTED AREAS

250 . 1,100.00

Labour Total S\$ :

2,360.00

4 Days.

Lumpsum repair.

After repair photos.

Gmo Qv8 - 82880282

15/12/19.

2087.81

20% 1650

SingDollars : Eleven Thousand Two Hundred Sixty-Seven &amp; Cents Ninety Only

E. &amp; O.E.

Total S\$ : 11,267.90

=====

for BODYFIX

LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: