

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19022450/KBA3Q2

**Date:** 26/08/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant Vehicle No :** SLR1821D **Insured Vehicle No :** SKH6859C

**Date of Loss:** 15/12/2019 **Nature of Claim:** TP **Claim No:** 4513799483SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLR1821D</b>		
Make & Model:	TOYOTA HARRIER 2.0, 2.0 PREMIUM AT AIRBAG 2WD (A)	Engine No:	3ZRB965725
Reg. Date:	02/08/2017 (Man. Year: 2017)	Chassis No:	ZSU600098861
Colour:	Metallic Pearl White	Odometer:	31197 km
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,278.00	3,529.10	1,748.90	33.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,830.00	1,370.00	460.00	25.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>7,108.00</b>	<b>4,899.10</b>	<b>2,208.90</b>	<b>31.08</b>
<b>+ GST 7.00/7.00% (S\$)</b>	497.56	342.94	154.62	31.08
<b>Nett Amount (S\$)</b>	<b>7,605.56</b>	<b>5,242.04</b>	<b>2,363.52</b>	<b>31.08</b>
<b>+ Loss of Use (6.0 x S\$90.00/day) (S\$)</b>		540.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>5,789.49</b>		
<b>Global Sum Settlement (S\$)</b>		<b>5,750.00</b>		

### INSPECTION

Date of Assignment: 18/12/2019

Date Inspected: 30/12/2019 Inspected At:

Lim Tan Motor Pte Ltd (HQ)  
Blk 176 Sin Ming Drive #03-09/10, Sin  
Ming Auto Care  
Singapore 575721

Estimated Period of Repair: 6.0 days

**Adjuster:** KENNETH KONG**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	1,395.30 FL	*1,343.00 FL
2	1		*REAR BUMPER LOWER SPOILER	Dented / Cut	369.10 FL	*369.10 FL
3	1		*REAR BUMPER RETAINER	O/S Distorted	137.92 FL	*68.97 FL
4	1		*SET REAR BUMPER SENSOR	Dented	572.46 FS	*200.00 FS
5	1		*REAR END PANEL	Repair	752.30 FL	*- FL
6	1		*REAR END PANEL GARNISH	Buckled	374.60 FL	*374.60 FL
7	1		*TAILGATE	Bent	1,565.40 FL	*1,565.40 FL
8	1		*TAILGATE LOCK	Not Necessary	961.70 FL	*- FL
9	1		*TAILGATE RUBBER	Cut	478.90 FL	*478.90 FL
10	1		*TAILGATE HARRIER EMBLEM	Necessary	86.90 FL	*86.90 FL
11	1		*REAR WINDSCREEN MOULDING	Necessary	98.60 FL	*98.60 FL
12	1		*TUBE REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,833.18</b>	<b>4,625.47</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	1,555.18	1,096.37
<b>Total Parts (\$\$)</b>	<b>5,278.00</b>	<b>3,529.10</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO PUTTY & SPRAY PAINT	New	800.00	660.00
2	TO REMOVE & REFIX REARWINDSCREEN GLASS	New	120.00	120.00
3	TO TRANSFER TAILGATE FITTING	New	80.00	60.00
4	TO ANTI-RUST	New	80.00	30.00
5	TO CHECK REAR WIRING & REPLACE SENSOR	New	50.00	50.00
6	LABOUR CHARGES	New	700.00	450.00
<b>Gross Labour Cost (\$)</b>			<b>1,830.00</b>	<b>1,370.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >