

LTM LIM TAN MOTOR

SURVEYOR NAME :	Kenneth LKK
DATE OF SURVEY :	31-12-2019
TIME OF SURVEY :	

DATE : 18-Dec-19
DATE OF ACCIDENT: 15-Dec-19
THIRD PARTY REF : SKH 6859 C / AIG

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt
1 pc	rear bumper			Bm \$ 1,395.30
1 pc	rear bumper lower spoiler			Nd / Lr \$ 369.10
2 ps	rear bumper retainer		\$ 68.96	ols DTY \$ 137.92
1 set	rear bumper sensor			\$ Nd 763.28
1 pc	rear end panel			\$ 752.30
1 pc	rear end panel garnish			Bm \$ 374.60
1 pc	tailgate			R1 \$ 1,565.40
1 pc	tailgate lock			\$. 961.70
1 pc	tailgate rubber			Cert \$ 478.90
1 pc	tailgate HARRIER emblem			M \$ 86.90
1 pc	rear windscreen moulding			M \$ 98.60
				\$ 6,984.00
	Less 25%			\$ 1,746.00
				\$ 5,238.00
1 tube	rear windscreen sealant	S.Nett		\$ M 40.00
	To putty & spray paint.			\$ 800.00
	To remove & refix rear windscreen glass.			\$ 120.00
	To transfer tailgate fitting.			\$ 80.00
	To anti-rust.			\$ 80.00
	To check rear wiring & replace sensor.			\$ 50.00
	Labour charges.	LKK Auto Consultants hence notify the Repairer of the following:		\$ 700.00
TG-ML/-	TOTAL			\$ 7,108.00
		Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		
		Acknowledged by Repairer Signature: Date:		

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel:65-64520893 Fax:65-64589127 Email: edmund@LTM.sg Website : www.LTM.sg
Co.Reg No.199307277D GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd