

Lion City rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

MsAIG Asia Pacific Insurance Pte Ltd
Date: 19/12/2019
Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLK5863T
CHASSIS NO : RU31215821
MAKE / MODEL : Honda Vezel Hybrid 1.5X CVT
DATE OF ACCIDENT : 12/12/2019
YOUR INSURED VEHICLE NUMBER :SDR988H
MILEAGE :148732 km

	<u>PARTS DeSCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	F/L headlamp X		\$2,100.00	\$2,100.00
2	F/L headlamp top bracket X		\$210.00	\$210.00
3	F/L headlamp lower bracket ?		\$210.00	\$210.00
4	F/R headlamp X		\$2,100.00	\$2,100.00
5	F/R headlamp top bracket X		\$210.00	\$210.00
6	F/R headlamp lower bracket X		\$210.00	\$210.00
7	Front bumper / dn		\$955.00	\$955.00
8	Front bumper reinforcement X		\$680.00	\$680.00
9	Front complete radiator grille assy X		\$1,590.00	\$1,590.00
LIST TOTAL S\$:				\$8,265.00
20.00% DISCOUNT S\$:				\$1,653.00
				\$6,612.00

SPECIAL NETT

1	Front bumper clips	1 SET	\$80.00	3
Special Nett Total S\$:			\$80.00	

LABOUR CHARGES

1	To check wiring system	\$100.00	X
2	To respray front bumper, support panel and front bonnet	\$900.00	200
3	To labour charge for removing front bumper and support panel out to facilitate repairs and replacement of damaged parts	\$1,250.00	200
LABOUR TOTAL S\$:		\$2,250.00	
TOTAL S\$:		\$8,942.00	
7% GST		\$625.94	
GRAND TOTAL S\$:		\$9,567.94	

Repair days - 2 days

P/P Repair

before spray photo

Sun Pm (4th)

20/12/2019

TP without prejudice

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: