



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2005484
INV Date 11/08/2020
Reference CC4/FCI19022452/Eka3n2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SLU 3026D
Insured Veh. SHA 3638R
Claim No. D19007949MFSH
Policy No. D-19092580MFSH
Accident Date 15/12/2019
Inspection Date 18/12/2019

Description	Total
Third Party Express Settlement	600.00
Subtotal	600.00
GST (7%)	42.00
Grand Total	642.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI19022452/Eka3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 11-08-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 3638R	Veh. Inspected	SLU 3026D
Policy No.	D-19092580MFSH	Coverage (\$)	0.00
Claim No.	D19007949MFSH	Excess (\$)	0.00
Assign From	RACHEL WU	Assign Date	18/12/2019

2. Vehicle Particulars & Condition

Make & Model	JAGUAR XE	c.c	1999
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	SAJAB4AG3HA956890	Colour	WHITE
Odometer	21962	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R18	PIRELLI	5 mm
L/H Front Tyre	225/45 R18	PIRELLI	5 mm
R/H Rear Tyre	225/45 R18	PIRELLI	5 mm
L/H Rear Tyre	225/45 R18	PIRELLI	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/12/2019	Inspection Date	18/12/2019
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 3026D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	COVER-BUMPER (SN)	BROKEN	1,755.20	1,579.68
1	INSERT-FOAM (SN)	NOT NECESSARY	54.20	-
1	PANEL-HOSE (SN)	NOT NECESSARY	91.80	-
1	BRACKET-FEND (SN)	NOT NECESSARY	35.00	-
1	BRACKET-FEND (SN)	NOT NECESSARY	35.00	-
1	LINER-WHEELARCH (SN)	NOT NECESSARY	329.90	-
1	JT4N13845/HEADLAMP (SN)	CUT	3,388.50	3,049.65
1	MESH-GRILLE (SN)	NOT NECESSARY	242.00	-
1	PANEL-FENDER (SN)	TO REPAIR SEE LABOUR	684.00	-
1	JT2H19105/BEAM-BUMPE (SN)	NOT NECESSARY	899.70	-
1	ADHESIVE SEALER FL2 (SN)	NOT NECESSARY	682.50	-
1	WHEEL-18" FRONT TE (SN)	NOT NECESSARY	1,501.20	-
			9,699.00	4,629.33
<u>LABOUR</u>				
	TO REPLACE FRT BUMPER HEADLAMP RH,FENDER LINER RH.FRT BUMPER BEAM,MESH GRILLE RH,FRT BUMPER FOAM,FENDER RH,REPAIR BONNET,ETC.INCLUSIVE OF THE REPAIR OF PANEL-FENDER.		3,600.00	900.00
	TO PUTTY SPRAYPAINT AND BLENDING OF PAINT ON FRT BUMPER,FENDER RH.BONNET,ETC.		4,000.00	1,600.00
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		510.00	510.00
	TO FOCUS HEADLAMP.		170.00	170.00
	TO REPLACE FRT RIM RH.	NOT NECESSARY	50.00	-
	WHEEL ALIGNMENT.	NOT NECESSARY	280.00	-
	-		-	-
	-		-	-
	-		-	-
			8,610.00	3,180.00
GRAND TOTAL			18,309.00	7,809.33



RECOMMENDED COST OF REPAIRS			7,809.33
------------------------------------	--	--	-----------------

Report Ref No. CC4/FC119022452/Eka3n2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLU 3026D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLU 3026D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

