

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5697X**AAD1912-074***Not Authorized
C/Rep & 1250h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

17 DEC 2019

SHC 5697X

VF1ABL15AUC280292

RENAULT

LATITUDE

10.12.19

III

28/11/2014

PART			LIST	
1	1	BUMPER COVER REAR	\$	<i>Bu/In</i> 561.70 ✓
2	1	BUMPER LOWER REAR	\$	<i>nd/In</i> 411.90 ✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 98.10
4	1	BUMPER BRACKET SIDE RH REAR	\$	<i>Sn</i> 82.10
5	1	BUMPER RETAINER RH REAR	\$	<i>Sn</i> 59.80
6	1	BUMPER REFLECTOR RH	\$	<i>Sn</i> 16.60
7	1	BUMPER BRACKET SIDE LH REAR	\$	<i>Sn</i> 80.80
8	1	BUMPER RETAINER LH REAR	\$	<i>Sn</i> 54.20
9	1	BUMPER REFLECTOR LH	\$	<i>Sn</i> 16.60
10	1	BUMPER BEAM REAR	\$	<i>N</i> 547.80
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>N</i> 114.50
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>N</i> 100.90
13	1	OUTER PANEL REAR (End Panel)	\$	<i>N</i> 745.80
14	1	OUTER PANEL REAR (End Panel) TRIM	\$	<i>Sn</i> 404.56
15	1	TAILLAMP RH	\$	<i>Sn</i> 313.10
16	1	TAILLAMP PANEL RH	\$	<i>N</i> 401.40
17	1	TAILLAMP LH	\$	<i>Sn</i> 401.40
18	1	TAILLAMP PANEL LH	\$	<i>N</i> 401.40
19	1	BOOT REAR	\$	<i>N</i> 1,677.20
20	1	BOOT FINISHER	\$	<i>Sn</i> 344.70
21	1	BOOT WHEATERSTRIP	\$	<i>Sn</i> 178.20
22	1	BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 277.70
23	1	BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 277.70
24	1	BOOT BADGE 'RENAULT'	\$	<i>N</i> 82.40
25	1	BOOT BADGE	\$	<i>N</i> 95.80
26	1	BOOT STRUT LH	\$	<i>Sn</i> 145.10
27	1	BOOT STRUT RH	\$	<i>Sn</i> 145.10

X

Trans-cab Auto Services Pte Ltd**AAD1912-074**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5697X

28	1	BOOT HINGE LH	\$	254.20	}
29	1	BOOT HINGE RH	\$	253.80	
30	2	BOOT RUBBER PLUG	\$	139.90	
31	2	BOOT BUFFER	\$	26.80	
32	1	BOOT LOCK LINKAGE	\$	20.60	
33	1	BOOT LOCK LINKAGE HOLDER	\$	99.50	
34	1	BOOT INNER TRIM BOARD	\$	611.00	
35	1	BOOT SWITCH	\$	113.00	
36	1	BOOT LOCK	\$	246.60	
37	1	BOOT LOCK CATCH	\$	41.70	
38	1	EXHAUST CAP REAR	\$	125.40	}
39	1	EXHAUST REAR	\$	5,263.60	
TOTAL			\$	15,232.66	
10%			\$	1,523.27	
			\$	13,709.39	

Special Nett

1	1SET	PARKING AID	\$	700.00	X
2	1SET	REAR BUMPER CLIP	\$	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00	—
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00	—
10	1	BOOT STICKER "Trans-cab"	\$	30.00	}
11	1	BOOT STICKER "6555-3333"	\$	30.00	
12	2	REAR WINDSCREEN SEALANT	\$	80.00	
13	1	WINDSCREEN MOULDING	\$	100.00	
14	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	
15	1	BOOT INNER TRIM CLIP	\$	45.00	
16	1SET	BOOT FINISHER CLIP	\$	24.20	
17	1	TAILLAMP CLIP LH	\$	5.00	}
18	1	TAILLAMP CLIP RH	\$	5.00	
19	1	Rear Bumper Protector	\$	100.00	40.00

Trans-cab Auto Services Pte Ltd**AAD1912-074**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5697X

20	1	EXHAUST MOUNTING REAR	\$	<i>nn</i>	16.00	X
21	1	EXHAUST BRACKET REAR	\$	<i>nn</i>	24.80	X
22	1SET	Rear licence plate with holder	\$	<i>nn</i>	80.00	X
TOTAL			\$		1,587.00	

TOTAL PARTS \$ 15,296.39**LABOUR**

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i>	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i>	380.00	X
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i>	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	<i>100</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i>	170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	<i>100</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		6,000.00	<i>200</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>nn</i>	170.00	X
To check steering geometry and computer wheel alignment	\$	<i>nn</i>	220.00	X
To repair and realign rear exhaust pipe.	\$	<i>nn</i>	170.00	X

Trans-cab Auto Services Pte Ltd**AAD1912-074**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5697X

To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>rm</i> 170.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>↪</i> 380.00	<i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>↪</i> 170.00	<i>X</i>
Putty and spray painting of the affected portion.	\$	6,000.00	<i>2201</i>
TOTAL	\$	14,680.00	
Over All Total	\$	29,976.39	

LUMP SUM (REPAIR DAY)***20 DAYS****2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: