

N-51 AUTOMOTIVE PTE LTD

LKK Adria

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

M/S SG LEASING PTE LTD
 15 YISHUN INDUSTRIAL ST 1 #01-08 WIN 5
 SINGAPORE 768091

TP111
 Xiao Tony

ESTIMATE

Repair Code : CLM15870
 Date in : 02/01/2020
 Vehicle Num. : GBA1197E
 Model : TOYOTA HIACE MANUAL
 Chassis/Eng# : JTFHT02P900002146/1KD1577352

Contact : 84211426 , 86664715

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>deformed</i>	1	396.00	✓ 396.00
REAR BUMPER LOWER BRACKET <i>new</i>	4	48.00	X 192.00
REAR BUMPER SIDE RETAINER L/R <i>LH x 2</i>	2	47.00	A7 94.00
REAR END PANEL (OUTER) <i>Rejis</i>	1	743.00	X 743.00
REAR LH FENDER <i>Dented</i>	1	1850.00	1452 1850.00
REAR LH FENDER AIR VENT <i>dehd</i>	1	97.00	✓ 97.00
REAR LH FENDER INNER PANEL <i>Rejis</i>	1	977.00	X 977.00
REAR LH FENDER INNER VERTICAL BRACKET <i>new</i>	2	79.00	X 158.00
REAR LH TAILLAMP <i>ct</i>	1	265.00	✓ 265.00
REAR LH TAILLAMP INNER PANEL <i>Rejis</i>	1	525.00	X 525.00
REAR LH TAILLAMP LOWER GARNISH <i>cauled</i>	1	157.00	✓ 157.00
REAR LH TAILLAMP LOWER GARNISH RETAINER <i>new</i>	1	53.00	X 53.00
REAR TAILGATE 'LOGO' EMBLEM	1	63.00	X 63.00
REAR TAILGATE WEATHER STRIP <i>2 new</i>	1	391.00	X 391.00
Subtotal before discount			5,961.00
Percentage discount 25%			1,490.25
Sub-total 1			4,470.75
REAR BUMPER CLIPS - SET <i>new</i>	1	80.00	30 80.00

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No : +65 6842 0051 Fax No : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

M/S SG LEASING PTE LTD
 15 YISHUN INDUSTRIAL ST 1 #01-08 WIN 5
 SINGAPORE 768091

Contact : 84211426 , 86664715

ESTIMATE

Repair Code : CLM15870
 Date in : 02/01/2020
 Vehicle Num. : GBA1197E
 Model : TOYOTA HIACE MANUAL
 Chassis/Eng# : JTFHT02P900002146/1KD1577352

REAR LH TAILLAMP CLIPS - SET	<i>new</i>	1	25.00	10	25.00
REAR LH TAILLAMP LOWER GARNISH CLIPS - SET	<i>new</i>	1	20.00	10	20.00
REAR TAILGATE '70KM' STICKER	<i>new</i>	1	25.00	X	25.00
Subtotal before discount					150.00
Percentage discount 0%					0.00
Sub-total 2					150.00
Parts-total					4,620.75

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	✓	80.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	50	140.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1190	500 1,000.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.		500 1,000.00
To apply anti-rust chemical on repaired and replaced panel.	60	120.00
Labour Total		2,340.00
Parts & Labour Total		6,960.75

*** This is a computer-generated document which requires no signature.***

total: 3080.50
 L/S: 2 AK. ✓
 04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: