

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MR.ZAILANI BIN ABDULLAH
BLK 223A SUMANG LANE #04-205
SINGAPORE 821223

Contact : 87665540

TP FWD.
Xiao Tony

ESTIMATE

Repair Code : CLM14802
Date in : 18/12/2019
Vehicle Num. : SLE9395H
Model : HONDA CIVIC 1.8S A
Chassis/Eng# : JHMFD16808S219871/R18A13042693

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID <i>Dented</i>	1	610.70	610.70 ✓
REAR BOOTLID 'CIVIC' EMBLEM <i>3 pc</i>	1	29.00	29.00 ✓
REAR BOOTLID 'LOGO' EMBLEM	1	76.90	76.90 ✓
REAR BOOTLID HINGES L/R <i>new</i>	2	48.60	97.20 ✓
REAR BOOTLID INNER RUBBER STOPPER L/R <i>new</i>	2	10.50	21.00 ✓
REAR BOOTLID INNER TRIM BOARD <i>new</i>	1	331.00	331.00 ✓
REAR BOOTLID MECHANISM LOCK <i>Dented</i>	1	194.50	194.50 ✓
REAR BOOTLID REFLECTOR BLACK GASKET L/R <i>3 new</i>	2	14.90	29.80 ✓
REAR BOOTLID REFLECTOR L/R	2	183.00	366.00 ✓
REAR BOOTLID WEATHER STRIP <i>new</i>	1	97.20	97.20 ✓
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	14.60	29.20 ✓
REAR END PANEL <i>Dented</i>	1	989.00	308 989.00 ✓
REAR END PANEL INNER TOP GARNISH <i>Dented</i>	1	159.00	159.00 ✓
REAR EXHAUST GASKET <i>new</i>	1	31.60	31.60 ✓
REAR EXHAUST RUBBER MOUNTING <i>new</i>	2	15.00	30.00 ✓
REAR EXHAUST SILENCER BOX <i>new</i>	1	535.00	535.00 ✓
REAR FENDER INNER TRIM BOARD L/R <i>new</i>	2	299.30	598.60 ✓
REAR TAILLAMP INNER RUBBER GASKET L/R <i>new</i>	2	15.00	30.00 ✓

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

MR.ZAILANI BIN ABDULLAH
BLK 223A SUMANG LANE #04-205
SINGAPORE 821223

ESTIMATE

Repair Code : CLM14802

Date in : 18/12/2019

Vehicle Num. : SLE9395H

Model : HONDA CIVIC 1.8S A

Chassis/Eng# : JHMFD16808S219871/R18A13042693

Contact : 87665540

REAR TAILLAMP L/R	<i>changed</i>	2	308.70	617.40	✓
REAR TAILLAMP LOWER BRACKET L/R	<i>new Bent</i>	2	13.90	27.80	✓
<i>Spore Type Panel Top Cover</i>	<i>del</i>	<i>308</i>			✓
Subtotal before discount				4,900.90	
Percentage discount 20%				980.18	
Sub-total 1				3,920.72	
REAR BOOTLID INNER TRIM BOARD CLIPS - SET	<i>new</i>	1	80.00	80.00	+
REAR BOOTLID NUMBER PLATE	<i>3 new</i>	1	25.00	25.00	+
REAR BOOTLID NUMBER PLATE HOLDER		1	50.00	50.00	x
REAR BUMPER	<i>del</i>	1	1200.00	1,200.00	880 (500)
REAR BUMPER CLIPS - SET	<i>new</i>	1	80.00	80.00	30
REAR BUMPER REVERSE SENSOR - SET	<i>del</i>	1	350.00	350.00	200
REAR END PANEL INNER TOP GARNISH CLIPS - SET	<i>new</i>	1	50.00	50.00	10
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET	<i>new</i>	2	50.00	100.00	+
REAR TAILLAMP CLIPS L/R - SET	<i>new</i>	2	25.00	50.00	20
Subtotal before discount				1,985.00	
Percentage discount 0%				0.00	
Sub-total 2				1,985.00	
Parts-total				5,905.72	

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

MR.ZAILANI BIN ABDULLAH

BLK 223A SUMANG LANE #04-205

SINGAPORE 821223

ESTIMATE

Repair Code : CLM14802

Date in : 18/12/2019

Vehicle Num. : SLE9395H

Model : HONDA CIVIC 1.8S A

Chassis/Eng# : JHMFD16808S219871/R18A13042693

Contact : 87665540

LABOUR

To Transfer Rear Bootlid Mechanism Lock Outer Handle Reflector

80.00 ~~60~~

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

100.00 ~~70~~

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

140.00 ~~60~~

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

1,200.00 ~~80~~

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

100.00 ~~80~~

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

1,000.00 ~~80~~

To apply anti-rust chemical on repaired and replaced panel.

120.00 ~~60~~

Labour Total

2,740.00

Parts & Labour Total

8,645.72

*** This is a computer-generated document which requires no signature.***

page 3



Adrian L
A/S 19/12/19
062yr

total: 4580.24

A/S: 3.61k

3.61k