



# **ZOOM AUTOWERKS PTE LTD**

130 Bedok Reservoir Road, Eunos Spring  
#08-1339 Singapore 470130  
Tel: 9450 7920  
✉ zoomautowerks@gmail.com

Vehicle Number : SLX9261K

18/12/2019

Model : TOYOTA WISH

Damaged Area: (Rear Portion Damaged)

Supplementary may be included during the cost of repair :

## **Parts / Material :**

	Quantity	
1 Rear Bumper		\$ 584.70 758.60 de ✓
2 Rear Bumper Lower Spoiler		\$ 765.80 X
3 Rear Bumper Bracket	✓ \$32.60 X 2pcs	\$ 65.20 LH - de ✓ RH X
4 Rear Bumper Retainer	✓ \$64.00 X 2pcs	\$ 128.00 LH - de ✓ RH X
5 Rear Bumper Reflector Lamp	✓ \$158.00 X 2pcs	\$ 316.00 LH - de ✓ RH X
6 Rear Bumper Clips	\$6.00 X 10pcs	\$ 60.00 30 ne ✓
7 Rear Tailgate		\$ 1,585.60 R X
8 Rear Tailgate Inner Trim Garnish		\$ 486.70 X
9 Rear Tailgate Damper	\$195.00 X 2pcs	\$ 390.00 X
10 Rear Tailgate Side Switch Sensor	\$78.00 X 2pcs	\$ 156.00 X
11 Rear Tailgate Lock		\$ 240.00 X
12 Rear Tailgate Catch		\$ 78.60 X
13 Rear Tailgate Emblem		\$ 55.00 ne ✓
14 Rear Tailgate Emblem		\$ 55.00 X Reported
15 Rear Tailgate Logo		\$ 68.00 ne ✓
16 Rear Tailgate Outer Garnish		\$ 295.80 X
17 Rear Tailgate Inner Seal		\$ 112.70 X
18 Rear Tailgate Lamp LH		\$ 415.60 X
19 Taillamp LH		\$ 566.40 686.90 one ✓
20 Rear End Panel Inner		\$ 480.00 X
21 Rear End Panel Outer		\$ 450.00 R X
22 Rear End Panel Top Trim		\$ 195.80 X
23 Rear Spare Tyre Top Trim		\$ 275.80 X
24 Rear Spare Tyre Panel		\$ 675.80 X
25 Rear Exhaust End Pipe		\$ 986.00 X
<b>Parts</b>		\$ 9,782.90 1558.70
<b>Less 25%</b>		\$ 2,445.72 1169.02
<b>Total Parts :</b>		\$ 7,337.17

## **Special Net Items :**

Rear Number Plate With Garnish	\$ 80.00 X
Rear Windscreen Glass Sealant	\$ 60.00 X
Rear End Panel Sealant	\$ 60.00 X
Rear Spare Tyre Sealant	\$ 60.00 X
Rear Exhaust GUM	\$ 80.00 X
Reverse Sensor	\$ 280.00 X
<b>Total S/N Parts :</b>	\$ 620.00

## **Labour :**

To Remove & Renew Rear Affected Accident Areas	\$ 1,200.00 600
To Putty, Spray Paint on Rear Affected Accident Areas	\$ 1,400.00 600
To Check & Re-Connect all electrical wiring	\$ 50.00 30
To Re-position Reverse Sensor	\$ 150.00 30
To Re-position Reverse Camera	\$ 150.00 X

To Transfer Rear Tailgate Trim, Garnish to assist to Facilitate Repairs	\$	150.00	X
To Remove & Install Rear Tailgate Compartment Trim To Facilitate Repairs	\$	150.00	X
To Remove & Install Rear Exhaust End Pipe	\$	250.00	X
To Rust Proof Rear Affected Areas	\$	100.00	30
To Re-Programme & Reset Diagnostic	\$	250.00	X
Total Labour :		\$	3,850.00 12 90

TOTAL PARTS : \$ 7,337.17  
 TOTAL SPECIAL NET ITEM : \$ 620.00  
 TOTAL LABOUR : \$ 3,850.00  
 TOTAL REPAIR COST : \$ 11,807.17

1169.02  
 1290  
 2459.02  
 1/5\$ 2000  
 4 days #

LKK Auto Consultants hence notify  
 the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjiah 97495749/67418434  
 Lumpsun  
 Resurvey after repair  
 4 days  
 Tanjiah C Lumpsun