

TP Claim



CO. REG. NO: 199402370D

GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhinh.com.sg

No. : 30892

Vehicle Insured : SLJ 71 A
Accident Date : 16-Nov-2019

Date : 28-Nov-2019

Our Ref : 190694 (CHINA) / QUEK

PAGE : 1

OLP SERVICE PTE LTD
Singapore

Not Withheld
6/11/19 8:15
Recovery After Pain
3 days

ESTIMATED COST OF REPAIR FOR CITROEN BERLINGO LWB 1.6L (2015) GBE3527C

1 pc LH rear bumper side cover
1 pc LH rear rim cover
1 pc LH rear rim
1 pc LH rear wheel bearing
1 pc LH rear door protector

Red/Green 240.00 ✓
Red 180.00 ✓
Red 320.00 X
NN 220.00 2X
Red 150.00 ✓

1,110.00

Less 10% : -111.00

999.00

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

570.00
-10%

400
450.00

To dismantle and check rear under-
carriage. To replace affected
portions.

513.00
+ 860.00

nn 120.00 X

To conduct rear wheel alignment
test.

80.00 *60*

To putty and respray on affected
portions.

1373.00
-20%

400
600.00

1098.40 Total : S\$ 2,249.00

Singapore Dollars Two Thousand Two Hundred and
Forty Nine Only

L/Sum \$1100/-

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.