

166:VIC

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccare.com.sg
GST:201006949C RCB NO:201006949C

not Afford
the money
take the before policy
6/11/20
5-4
4/5 = 3050

M/S : TAN SIEU LEE AMELIA
484A EAST COAST ROAD
SINGAPORE 429054

ATTN: FIRST CAPITAL

Your Ref No: TP 1219-5787
Claim Type: Third Party
Accident Date: 13/12/2019
TP Veh Reg No: SHB 4980 P

Estimate No: EST1505566
Date: 14 Dec 2019
Policy No: 2100228774
Veh Reg No: SJY6361T
Make/Model: TOYOTA WISH 2.0
AUTO
Chassis No: JTDGJ20W305003246
Engine No: 3ZRA517990
Reg. Date: 20/09/2010

Estimate Repair Cost to Vehicle No :SJY6361T

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 REAR BOOT	1080.50	1 PC	1,080.50	✓
2 REAR BOOT RUBBER	240.60	1 PC	240.60	X
3 REAR BOOT TOYOTA LOGO	60.70	1 PC	60.70	✓
4 REAR BOOT OUTER CHROME	210.50	1 PC	210.50	X
5 REAR BOOT GLASS MOULDING	241.70	1 SET	241.70	✓
6 REAR BUMPER	310.50	1 PC	310.50	✓
7 REAR BUMPER CLIPS	5.40	10 PC	54.00	✓
8 REAR BUMPER SIDE HOLDER - LH	80.50	1 PC	80.50	✓
9 REAR BUMPER SIDE HOLDER - RH	80.50	1 PC	80.50	X
10 REAR BUMPER REFLECTOR - LH	60.80	1 PC	60.80	✓
11 REAR BUMPER SENSOR - LH, RH	300.50	1 SET	300.50	2005.2
12 REAR PANEL	312.40	1 PC	312.40	✓
13 REAR PANEL TOP GARNISH	240.50	1 PC	240.50	X
			3,273.70	
		Less 25%	818.43	2,455.28
Special Net				
14 REAR BOOT DELUXE WORDING	80.0000	1 PC	80.00	✓
15 REAR BOOT BORNEO MOTORS LOGO	90.0000	1 PC	90.00	✓
16 SEALANT	20.0000	2 PC	40.00	✓
17 SPONGE TAPE	20.0000	1 PC	20.00	✓
18 REAR BUMPER SENSOR	220.0000	1 SET	220.00	X
19 REAR NUMBER PLATE WITH CASING	35.0000	1 SET	35.00	X
20 REAR BOOT REVERSE CAMERA	350.0000	1 PC	350.00	X 430
			835.00	835.00
Labour				
21 TO KNOCK OUT DENTS, CUT/WELD REAR PANEL, REMOVE, REPLACE ACCIDENT PARTS	800.0000	1 JOB	800.00	600
22 TO RESPRAY PAINT ON ACCIDENT PORTIONS	800.0000	1 JOB	800.00	750
23 TO TUFF-KOTE	100.0000	1 JOB	100.00	60
24 TO CHECK WIRING	20.0000	1 JOB	20.00	✓
25 TO REMOVE, REFIX REAR GARNISH, CARPET AND RELATED PARTS	80.0000	1 JOB	80.00	60
26 TO TRANSFER REAR BUMPER SENSOR	100.0000	1 JOB	100.00	50
27 TO REMOVE, REFIX REAR BOOT GLASS	150.0000	1 JOB	150.00	120
28 TO TRANSFER REAR BOOT	60.0000	1 JOB	60.00	✓

7720

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : TAN SIEU LEE AMELIA
484A EAST COAST ROAD
SINGAPORE 429054

ATTN: FIRST CAPITAL

Your Ref No: TP 1219-5787
Claim Type: Third Party
Accident Date: 13/12/2019
TP Veh Reg No: SHB 4980 P

Estimate No: **EST1505566**
Date: 14 Dec 2019
Policy No: 2100228774
Veh Reg No: **SJY6361T**
Make/Model: TOYOTA WISH 2.0
AUTO
Chassis No: JTDGJ20W305003246
Engine No: 3ZRA517990
Reg. Date: 20/09/2010

Estimate Repair Cost to Vehicle No :SJY6361T

Description	U/Price	Quantity	Price	Amount
			<u>S\$</u>	<u>S\$</u>
			2,110.00	2,110.00
Total				S\$ 5,400.28
Add GST @ 7%				378.02
Total Amount Payable				<u>S\$ 5,778.30</u>

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND SEVEN HUNDRED SEVENTY EIGHT AND CENTS THIRTY ONLY

For Progressive Car Care Pte Ltd

LKKAuto Consultants hence notify the Repairer of the following:

- To respray bumper/spray painting
- To display damaged part(s) and resurvey
- Repairer to refer to quotation
- To repair on a "Without Prejudice" basis
- All workmanship is to be approved
- Supply necessary parts must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

AUTHORISED SIGNATURE

P-228085
1710.71

S.N-430
L-1720
3860.71
3088

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
 GST:201006949C RCB NO:201006949C

M/S : TAN SIEU LEE AMELIA
 484A EAST COAST ROAD
 SINGAPORE 429054

Estimate No: EST1505566

Date: 07 Jan 2020

Policy No: 2100228774

Veh Reg No: SJY6361T

Make/Model: TOYOTA WISH 2.0
 AUTO

Chassis No: JTDGJ20W305003246

Engine No: 3ZRA517990

Reg. Date: 20/09/2010

ATTN: FIRST CAPITAL

Your Ref No: TP 1219-5787

Claim Type: Third Party

Accident Date: 13/12/2019

TP Veh Reg No: SHB 4980 P

Estimate Repair Cost to Vehicle No :SJY6361T

Description	U/Price	Quantity	Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair				
List Price				
1 REAR REINFORCEMENT BRACKET - LH	79.85	1 PC	79.85	
			79.85	
		Less 25%	19.96	59.89
Total				S\$ 59.89
GST Amount				S\$ 4.19
Total Amount Payable				<u>S\$ 64.08</u>

For Progressive Car Care Pte Ltd


 AUTHORIZED SIGNATURE