

First capital.

FAX : 6542 6039

MODEL : HYUNDAI i40

X	
X	
✓	
✓	
✓	
✓	
✓	
X	
X	
X	
X	
✓	
✓	
✓	
✓	
✓	
X	
X	
✓	
X	
✓	
✓	
✓	
✓	
X	
X	
X	
X	
✓	
✓	
✓	
Nett	X
Nett	✓
Nett	✓
Nett	X

SHA 7967P

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,200.00 660/-
	Spray Painting Charge			\$ 1,000.00 500/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 100.00 40/-
	Towing Charge			\$ 50.00 24
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00 80/-
	Remove/Refix Reverse Sensor			\$ 120.00 42
	Remove/Refix Fuel Tank			\$ 150.00 24
	Remove/Refix Exhaust Pipe			\$ 200.00 42
	Remove/Refix Undercarriage (RR)			\$ 200.00 150/-
	Rear Wheel Alignment			\$ 120.00 60/-
	Re-set Rear ABS System			\$ 200.00
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00 150/-
	TOTAL LABOUR			\$ 4,140.00
	ESTIMATE TOTAL			\$ 14,944.56
	18/12/2019 @ 1030hrs N/A Antine 2/5mm 6 days. 3 you LKK Auto 8			
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			