



GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676
Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500
Website: www.goldbell.com.sg
Co. Reg. No.: 198003963G

Page 1 / 1

ESTIMATE

Date	: 17-12-2019	Reg No	: SLD319T
To	: MS FIRST CAPITAL INSURANCE LIMITED	Model	: VEZEL 1.5X CVT
Attn.	:	Chassis No	: RU11112333
Office / Mobile	:	Engine No	: L15B4032337
Email	: 6 RAFFLES QUAY, SINGAPORE 048580	Quotation No.	:
Address	:	Ref. No.	:
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 16-12-2019
Attn.	: CATHERINECHONGKL	Policy No.	: D19MTPV01008493
Office / Mobile	: 97361300	Claim Type	: TP CLAIM
Email / Fax	: CatherineChongKL@goldbell.com.sg	Workshop	: 8 TUAS AVE 18
No.	:		

S/N	Part No	Description	Qty	U/Price	Net Price	Ext Price
1		TAILGATE <i>bt</i>	1	1,050.00	1,050.00	1,050.00
2		REAR BUMPER <i>de</i>	1	518.60	518.60	518.60
3		FRONT BONNET <i>bt</i>	1	892.35	892.35	892.35
4		FRONT GRILLE BASE <i>ca</i>	1	268.90	268.90	268.90
5		OUTER GANISH <i>X</i>	1	203.40	203.40	203.40
6		CHROME <i>?</i>	2	45.60	45.60	91.20
7		FRONT BUMPER <i>de</i>	1	459.80	459.80	459.80
8		FRONT HONDA EMBLEM <i>na</i>	1	95.50	95.50	95.50
9		REAR HONDA EMBLEM <i>na</i>	1	95.50	95.50	95.50
10		VEZEL EMBLEM <i>na</i>	1	55.50	55.50	55.50

PARTS TOTAL : 3,730.75

SPECIAL NETT ITEMS

1	REVERSE SENSOR ASSY <i>na</i>	1	280.00	280.00 <i>220.00</i>
2	FRONT NUMBER PLATE <i>ca</i>	1	25.00	25.00
3	SEALANT <i>na</i>	1	40.00	40.00

PARTS TOTAL: 345.00

LABOUR CHARGES

1	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	600 <i>600.00</i>
2	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC	800 <i>1180.00</i>
3	TO REMOVE AND REFIX FRONT WINDSCREEN PLUS GUM	120 <i>180.00</i>
4	SUNDRIES	30 <i>100.00</i>

FUSO

AIRMAN.

bisSAFE
STARK





GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676
Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500
Website: www.goldbell.com.sg
Co. Reg. No.: 198003963G

LABOUR TOTAL :	1,840.00
SUB-TOTAL :	5,915.75
GST @ 7% for \$ 5,915.75	414.10
GRAND TOTAL (S\$) :	6,329.85

PREPARED BY : CATHERINECHONGKL

DATE / TIME : 27/12/19 @ 11/10

SURVEYOR : Rasul

MOBILE NO : 960010068

OFFICE FAX NO :

EMAIL ADDRESS : rasul@lkkauto.com

EXCESS AMOUNT :

REPAIR TYPE : PART-BY-PART LUMPSUM

AUTHORISATION : AUTHORISED NOT AUTHORISED

RE-SURVEY : BEFORE PAINT AFTER PAINT

NO. OF DAYS : 7 days

REMARKS :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

FUSO

AIRMAN.

bisSAFE
STARS





GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg. No: 198003963G

SUPPLEMENTARY REPAIR ESTIMATE

DATE :	27/12/19	VEHICLE NO. :	SLD319T
TO :	MS FIRST CAPITAL	MODEL NO. :	VEZEL 1.5X CVT
ATTN :	INSURANCE	CHASSIS NO. :	RU11112333
OFFICE / MOBILE :	MOTOR CLAIMS	ENGINE NO. :	L15B4032337
EMAIL ADDRESS :	DEPARTMENT	REG. DATE :	
FROM :	GOLDBELL ENGINEERING	REF. NO. :	
ATTN :	MR RAMESH	D.O.A. :	16/12/19
OFFICE / MOBILE :	81578014	POLICY NO. :	D19MTPV01008493
FAX NO. :		CLAIM TYPE :	THIRD PARTY CLAIM
		WORKSHOP :	GOLDBALL PANDAN

S/N	PART NO.	DESCRIPTION	QUANTITY	PRICE
1		REAR TOOL KIT HOLDER <i>de</i>	1	\$294.97
2		FORM - BLACK		
		END PANEL <i>h</i>	1	\$535.47
PARTS TOTAL :				\$830.44

LABOUR CHARGES

1	TO CARRY OUT PANEL BEAT TO STRAIGHTERN CRAMBLED PANELS IN SPARE TYRE COMPARTMENT.	\$ 800.00 <i>400</i>
2	TO PUTTY, CEAN, SPRAY PAINT AND POLISH, ETC	\$ 400.00 ✓
3	TO APPLY SEALANT ONTO SPARE TYRE COMPARTMENT	\$ 0.00
LABOUR TOTAL :		\$ 1200.00
TOTAL :		\$ 2030.44
7% GST :		\$ 142.13
GRAND TOTAL :		\$ 2172.57

Prepared By : RAMESH

DATE / TIME : 27/12/2019 @ 11.10am

SURVEYOR : RASUL

MOBILE NO : 90010068

OFFICE FAX NO :

EMAIL ADDRESS : rasul@lkkauto.com

EXCESS AMOUNT :

REPAIR TYPE : LUMP SUM

AUTHORISATION : AUTHORISED

RE-SURVEY : AFTER PAINT

NO. OF DAYS : 7 DAYS