

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 655J**AAD1912-117***Not Authorised*
L1Png &

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

18 DEC 2019

SHF 655J

VF1ABL15AUC278397

RENAULT

LATITUDE

15.12.19

FCIL

30/6/2014

PART**LIST**

1	DOOR PANEL REAR RH	\$	<i>R</i>	758.70	X
1	ROCKER PANEL INNER GARNISH RH	\$	<i>SL</i>	466.51	X
1	ROCKER PANEL INNER RH	\$	<i>R</i>	1,024.79	X
1	ROCKER PANEL OUTER RH	\$	<i>R</i>	1,184.99	X
1	ROCKER PANEL CENTER RH	\$	<i>R</i>	990.25	X
1	FENDER PANEL REAR RH	\$	<i>Bu</i>	1,933.20	✓
1	FENDER PANEL INNER TRIM REAR RH	\$	<i>SL</i>	671.45	} X
1	WHEELARCH REAR RH	\$	<i>SL</i>	275.40	
1	AIR VENT RH	\$	<i>SL</i>	59.40	
1	FENDER INNER BOARD RH L70Y	\$	<i>SL</i>	561.40	
1	FENDER PANEL INNER REAR RH	\$	<i>R</i>	952.50	
1	CHASSIS PANEL REAR RH	\$	<i>R</i>	2,192.40	
1	BUMPER COVER REAR	\$	<i>SL</i>	561.70	} X
1	BUMPER LOWER REAR	\$	<i>SL</i>	411.90	
1	BUMPER BRACKET CTR REAR	\$	<i>SL</i>	98.10	
1	BUMPER BRACKET SIDE RH REAR	\$	<i>DIT</i>	82.10	✓
1	BUMPER RETAINER RH REAR	\$	<i>SL</i>	59.80	X
1	BUMPER REFLECTOR RH	\$	<i>SL</i>	16.60	X
1	BUMPER BEAM REAR	\$	<i>R</i>	547.80	X
1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i>	100.90	X
1	BOOT REFLECTOR LAMP RH	\$	<i>SL</i>	277.70	X
1	TAILLAMP RH	\$	<i>CM</i>	313.10	✓
1	TAILLAMP PANEL RH	\$	<i>R</i>	401.40	X
1	EXHAUST CAP REAR	\$	<i>R</i>	125.40	X
1	EXHAUST REAR	\$	<i>R</i>	5,263.60	X
1	KNUCKLE ARM REAR RH	\$	<i>B</i>	472.10	✓
1	BRAKE DISC REAR	\$		266.50	?

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 655J**AAD1912-117**

1	ABS SENSOR REAR RH	\$	<i>Sn</i> 190.50	X
1	WHEEL HUB NUT	\$	41.80	?
1	WHEEL HUB CAP	\$	<i>Not</i> 30.50	✓
1	KNUCKLE HUB+ BEARING RH	\$	<i>Me</i> 272.30	✓
1	REAR AXLE	\$	3,469.00	?
1	AXLE ARM RH	\$	69.50	?
2	REAR AXLE SPACER	\$	49.00	?
1	REAR AXLE ARM ROD	\$	69.50	?
1	LOWER ARM REAR RH	\$	543.50	?
1	AXLE SPRING ARM RH	\$	220.60	?
1	AXLE SPRING ARM BUSH UPPER	\$	42.50	?
1	AXLE SPRING ARM BUSH LOWER	\$	30.80	?
1	ABSORBER REAR	\$	217.30	?
1	ABSORBER DUST COVER REAR	\$	47.10	?
1	ABSORBER MOUNTING REAR	\$	49.40	?
1	STABILIZER BAR REAR	\$	427.90	?
1	STABILIZER LINK REAR	\$	55.20	?
1	BRAKE CALIPER REAR RH	\$	<i>Sn</i> 659.10	X
1	BRAKE HOSE REAR RH	\$	<i>Sn</i> 79.50	X
1	SUBFRAME ARM REAR	\$	<i>See</i> 198.33	X
1	RODE- LONG REAR	\$	120.16	?
TOTAL		\$	26,953.18	
10%		\$	2,695.32	
		\$	24,257.86	

Special Nett

1	REAR DOOR STICKER '6555-3333'	\$	<i>Nn</i> 80.00	X
1	FENDER INNER TRIM CLIP RH	\$	<i>Nn</i> 28.00	X
1	TAILLAMP CLIP RH	\$	<i>Nn</i> 5.00	✓
1SET	FENDER WHEELARCH REAR RH CLIP	\$	<i>Nn</i> 35.00	X
2	REAR WINDSCREEN SEALANT	\$	<i>Me</i> 80.00	<i>40Sn</i>
1	WINDSCREEN MOULDING	\$	<i>Nn</i> 100.00	X
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>Me</i> 100.00	<i>40Sn</i>
1	REAR RIGHT TYRE	\$	<i>Sn</i> 300.00	X
1	REAR RIGHT TYRE RIM	\$	380.00	?
1SET	PARKING AID	\$	<i>Sn</i> 700.00	X

Trans-cab Auto Services Pte Ltd**AAD1912-117**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 655J

1SET	REAR BUMPER CLIP	\$	<i>nn</i>	66.00	—
1SET	BUMPER BRACKET CTR CLIP	\$	<i>nn</i>	33.00	—
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	<i>nn</i>	10.00	} X
1SET	BUMPER RETAINER CLIP RH RR	\$	<i>nn</i>	20.00	
1SET	BUMPER LOWER REAR RIVET	\$	<i>nn</i>	22.00	
1SET	BUMPER LOWER REAR CLIP	\$	<i>nn</i>	66.00	
1	EXHAUST MOUNTING REAR	\$	<i>nn</i>	16.00	
1	Rear Bumper Protector	\$	<i>nn</i>	100.00	} X
1	EXHAUST BRACKET REAR L70Y	\$	<i>nn</i>	24.80	
1	Rear Right Tyre Rim Cover	\$	<i>Repair</i>	50.00	
TOTAL		\$		2,215.80	

TOTAL PARTS	\$	26,473.66
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	7,500.00	<i>600</i>
----	----------	------------

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$	<i>nn</i> 380.00	X
----	------------------	---

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	380.00	<i>100</i>
----	--------	------------

To check steering geometry and computer wheel alignment

\$	220.00	<i>60</i>
----	--------	-----------

To transfer of rear windscreen glass to facilitate bodywork repair.

\$	170.00	<i>120</i>
----	--------	------------

To transfer of Rear door fittings, attachment and perform water seepage test.

\$	<i>nn</i> 170.00	X
----	------------------	---

To transfer of Rear fender fittings, attachment and perform water seepage test.

\$	<i>nn</i> 170.00	X
----	------------------	---

Trans-cab Auto Services Pte Ltd**AAD1912-117**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 655J

To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To rust-proofing of the affected areas.	\$	170.00	<i>301</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>601</i>
Putty and spray painting of the affected portion.	\$	7,500.00	<i>4401</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00	<i>X</i>
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	380.00	<i>1801</i>
To dismantle and refit rear axle assy, remove and renewal of parts, final checking and testing.	\$	<i>nn</i> 380.00	<i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00	<i>X</i>
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>nn</i> 380.00	<i>X</i>
TOTAL	\$	18,820.00	
Over All Total	\$	45,293.66	

LUMP SUM (REPAIR DAY)~~25 DAYS~~*5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: