

INS. CASE OWNER:

CC6 / FCI190

LKK

IDAC

Surveyor:

Kenna

DOI:

12/1/19

Date / Time:

12/1/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

CHC 405E

Claim No.:

Name of Insured:

MYCMB PLC

Policy No.:

018088327 MFSH

Insured Tel No.:

HP:

Make / Model:

T-400TA

Excess Sec II :\$S

D.O.A.:

16/1/19

Place of Accident:

TONGS AVE x YISHAN

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Mr GARY WE

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SUN 2440

INSRS:
WSP:
Tel:
Liability:
RMKS:

Hui Yang

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐
	After call ltr to OI:	☐
	Authorisation To Act:	☒
	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☒
	Towing Invoice:	☐
	LTA / GIA:	☐
	Medical Bill:	☐
	PIR:	☐
	Mandate/Reject Instruction:	☒
	LOD:	☒
	Payment Breakdown Form:	☐
	Post-Repair Photos:	☐
	Others:	☐
PRELIMINARY ADVICE Date/Time:	Sent By:	Confirm by: KSC
FINALIZATION Date/Time:	Confirm with:	Confirm by: KSC
Repair Cost: 45 \$53,050.00	(4 days) Reduction: 66 %	Email ☒ Call ☐
FINAL SETTLEMENT Date/Time: 05-03-20	Confirm with: MADO	Email ☒ Call ☐
Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 27	If NO or B 28, Ass. Lia :	
Repair Cost: 45 \$53,243.50	010 ROAD ENDS TO	
Loss of Rental (LOR): \$5 292.00 (4 days) = 473		
Loss of Use (LOU): \$5 - (\$ x days)		
Loss of Income (LOI): \$5 - (\$ x days)		
LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LO ☐ (Tick only one)		
GIA/LTA Search: \$5 -		
Medical: \$5 -		
Disbursement: \$5 - (e.g. Tow/ Independent)		
Legal Cost: \$5 -		
Total: \$53,555.50	Global Sum \$5:	
FINAL PAYMENT Date/Time: 05-03-20	Confirm with: MADO	Email ☒ Call ☐
Payee 1: \$53,555.50	Name 1: HUI YANG MOTOR PTE. LTD.	
Payee 2: (Strike if N.A.) \$5	Name 2:	
Payee 3: (Strike if N.A.) \$5	Name 3:	

ASS. REC. BY:

REF: FC21

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

File pass to

40: +3.050 (RED: +3.968.38 (A/I))

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format :

Lump Sum / I.B.I. (\$) :

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS. \$

Fuel:

Others

TOTAL

Veh No:

SCN 27490

Yr Regn:

04.17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

c.c.

1787

Colour:

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading:

196260

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ZVW50

6053853

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

APUS 195/65R15

Bridges

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

16/12/19

D.O.I.

17/12/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST & Reg No. 201629438M

16/12/2019

Owner: U&G CAR LEASING

ESTIMATE TO REPAIR TOYOTA PRIUS HYBRID 1.8S A - SLN2749U

1pc	rear tailgate "PRIUS" emblem	Me \$	61.75	—
1pc	rear tailgate "HYBRID" emblem	Me \$	53.75	—
1pc	rear tailgate "TOYOTA" logo	Me \$	61.10	—
1pc	rear tailgate outer garnish	Me \$	741.35	✓
1pc	rear tailgate inner lock	Me \$	381.85	X
1pc	rear tailgate inner rubber	Me \$	281.50	X
1pc	rear tailgate inner garnish	Me \$	381.00	X
2pcs	rear taillamp lower bracket @\$121.50	Me \$	243.00	X
1pc	rear bumper	Me \$	928.35	—
2pcs	rear bumper side retainer @\$141.40	Me \$	282.80	X
2pcs	rear bumper side lamp @\$371.45.00	Me \$	742.90	X
2pcs	rear bumper side lower garnish @\$274.45	Me \$	548.90	X
1pc	rear bumper diffuser	Me \$	379.00	—
1pc	rear bumper reinforcement	Me \$	458.00	—
1pc	rear bumper towing cover	Me \$	61.00	—
1pc	rear bumper lower centre cover	Me \$	281.50	—
2pcs	rear bumper lower side cover @\$191.55	Me \$	383.10	X
1pc	rear end panel	Me \$	970.25	X
1pc	rear end panel inner garnish	Me \$	381.90	X
1pc	rear end panel sensor	Me \$	281.50	—

less 25%

\$ 7,904.50
\$ 1,976.13
\$ 5,928.38

1 set rear number plate & casing
1 set rear parking sensor

Me s.nett \$ 50.00
Me s.nett \$ 280.00

tuffkote
wiring
spray painting
labour charges
Total

Me \$ 180.00 X
\$ 180.00 2ol
\$ 1,200.00 60ol
\$ 1,200.00 30ol
\$ 9,018.38



Not Authorized
611pm 8305oh
Murray After Rain

4 days



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564311

Your ref: TBA
Our ref: CC6/FCI19022491/Keb3

Date: 23.12.2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLN2749U

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 17.12.2019 at the premises of M/s Hui Yang Motor Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	9,018.38
Revised Estimate Amount	: S\$	1,977.88
"Check" Items Amount	: S\$	5,234.21
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:
The vehicle sustained damages at the
Rear portion



Comments/Present Status:
Damages Consistent
Estimated normal period for repairs: TBA days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

辉 阳 汽 车 有 限 公 司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

16/12/2019

Owner: U&G CAR LEASING

Not Authorized
6/1/2020
Perman After Rain

ESTIMATE TO REPAIR TOYOTA PRIUS HYBRID 1.8S A - SLN2749U

1pc	rear tailgate "PRIUS" emblem	<i>Me</i>	\$	61.75	—
1pc	rear tailgate "HYBRID" emblem	<i>Me</i>	\$	53.75	—
1pc	rear tailgate "TOYOTA" logo	<i>Me</i>	\$	61.10	—
1pc	rear tailgate outer garnish		\$	741.35	?
1pc	rear tailgate inner lock	<i>Me</i>	\$	381.85	X
1pc	rear tailgate inner rubber	<i>Me</i>	\$	281.50	X
1pc	rear tailgate inner garnish		\$	381.00	?
2pcs	rear taillamp lower bracket @\$121.50		\$	243.00	?
1pc	rear bumper	<i>Me</i>	\$	928.35	—
2pcs	rear bumper side retainer @\$141.40	<i>Me</i>	\$	282.80	X
2pcs	rear bumper side lamp @\$371.45.00		\$	742.90	?
2pcs	rear bumper side lower garnish @\$274.45	<i>old?</i>	\$	548.90	
1pc	rear bumper diffuser	<i>Me</i>	\$	379.00	—
1pc	rear bumper reinforcement		\$	458.00	?
1pc	rear bumper towing cover	<i>old/Me</i>	\$	61.00	—
1pc	rear bumper lower centre cover		\$	281.50	?
2pcs	rear bumper lower side cover @\$191.55		\$	383.10	?
1pc	rear end panel		\$	970.25	?
1pc	rear end panel inner garnish		\$	381.90	?
1pc	rear end panel sensor		\$	281.50	?
			\$	7,904.50	
	less 25%		\$	1,976.13	
			\$	5,928.38	
1set	rear number plate & casing	<i>Me</i>	s.nett	\$	50.00 <i>45.50</i>
1set	rear parking sensor	<i>Me</i>	s.nett	\$	280.00 <i>200.00</i>
	tuffkote		\$	180.00	?
	wiring		\$	180.00	<i>200</i>
	spray painting		\$	1,200.00	<i>600</i>
	labour charges		\$	1,200.00	?
	Total		\$	9,018.38	

LKK Auto Consultants hereby notify the Repairer of the following:

- To return the vehicle to the repairer
- To display the vehicle to the repairer
- To display the vehicle to the repairer
- To display the vehicle to the repairer
- To display the vehicle to the repairer
- To display the vehicle to the repairer
- To display the vehicle to the repairer
- To display the vehicle to the repairer

Authorized by Repairer
Signature: _____
Date: _____



Shu Pei (LKKAUTO)

From: Aini Binte <Aini@msfirstcapital.com.sg>
Sent: Monday, 30 December 2019 10:44 AM
To: Shu Pei (LKKAUTO)
Cc: Admin A; Asher Sng (LKKAUTO); Merina Chia
Subject: FW: EXPRESS SETTLEMENT VIA LKK - Accident Involving SHC405E (MS FCI-OI) AND SLN2749U (3rd party) on 16.12.2019 (LKK REF - CC6/FCI19022491/Keb3)
Attachments: MCD619169684-SHC405E.pdf

Dear Shu Pei

O/REF: D19008085MFSH

Attached is our Insured's SAS report for your attention.

Thanks & Regards

Aini
Motor Claims Department

MS First Capital Insurance Ltd | 36 Robinson Road, City House, #16-01 Singapore 068877 | TEL: 6507 3848
Fax: 6507 3849 | Company Reg. No. 195000106C

A Member of **MS&AD** INSURANCE GROUP

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data.
Please refer to www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Caroline Cabrera <Caroline@msfirstcapital.com.sg>
Sent: Monday, December 30, 2019 9:54 AM
To: Aini Binte <Aini@msfirstcapital.com.sg>
Subject: FW: EXPRESS SETTLEMENT VIA LKK - Accident Involving SHC405E (MS FCI-OI) AND SLN2749U (3rd party) on 16.12.2019 (LKK REF - CC6/FCI19022491/Keb3)

Dear Aini,

FYNA - D19008085MFSH

Thank you & Regards,
Caroline Cabrera
Motor Claims

MS First Capital Insurance Ltd

36 Robinson Road #16-01 City House | Singapore 068877 | D: 6507 3848 | F: 6507 3849 | Reg. No. 195000106C

A member of **MS&AD** INSURANCE GROUP

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data.

Please refer to www.first-insurance.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>

Sent: Monday, December 30, 2019 9:43 AM

To: Motor Claims <MotorClaims@msfirstcapital.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Subject: RE: EXPRESS SETTLEMENT VIA LKK - Accident Involving SHC405E (MS FCI-OI) AND SLN2749U (3rd party) on 16.12.2019 (LKK REF - CC6/FCI19022491/Keb3)

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly provide us the claim reference number and a copy of your insured's GIA report for our necessary action.

Thank you.

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>

Sent: Tuesday, 24 December 2019 12:13 PM

To: Motor Claims <MotorClaims@msfirstcapital.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Subject: EXPRESS SETTLEMENT VIA LKK - Accident Involving SHC405E (MS FCI-OI) AND SLN2749U (3rd party) on 16.12.2019 (LKK REF - CC6/FCI19022491/Keb3)

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have received new assignment from 3rd party workshop, M/s Hui Yang Motor Pte Ltd and 3rd party repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly provide us the claim reference number and a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC6/FCI19022491/Kea3q2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 13-03-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 405E	Veh. Inspected	SLN 2749U
Policy No.	D-18088937MFSH	Coverage (\$)	0.00
Claim No.	D19008085MFSH	Excess (\$)	0.00
Assign From		Assign Date	17/12/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS (A)	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	ZVW506053853	Colour	METALLIC SILVER
Odometer	196260	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	APLUS	6 mm
L/H Front Tyre	195/65 R15	APLUS	6 mm
R/H Rear Tyre	195/65 R15	AGENDA	6 mm
L/H Rear Tyre	195/65 R15	AGENDA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	16/12/2019	Inspection Date	17/12/2019
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 2749U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILGATE "PRIUS" EMBLEM	NECESSARY	61.75	61.75
1	REAR TAILGATE "HYBRID" EMBLEM	NECESSARY	53.75	53.75
1	REAR TAILGATE "TOYOTA" LOGO	NECESSARY	61.10	61.10
1	REAR TAILGATE OUTER GARNISH	MTG CRACKED	741.35	741.35
1	REAR TAILGATE INNER LOCK	TO REPAIR SEE LABOUR	381.85	-
1	REAR TAILGATE INNER RUBBER	SERVICEABLE	281.50	-
1	REAR TAILGATE INNER GARNISH	SERVICEABLE	381.00	-
2	REAR TAILLAMP LOWER BRACKET @\$121.50	SERVICEABLE	243.00	-
1	REAR BUMPER	BUCKLED	928.35	928.35
2	REAR BUMPER SIDE RETAINER @\$141.40	SERVICEABLE	282.80	-
2	REAR BUMPER SIDE LAMP @\$371.45	SERVICEABLE	742.90	-
2	REAR BUMPER SIDE LOWER GARNISH @\$274.45	SERVICEABLE	548.90	-
1	REAR BUMPER DIFFUSER	BENT	379.00	379.00
1	REAR BUMPER REINFORCEMENT	BENT	458.00	458.00
1	REAR BUMPER TOWING COVER	DENTED/CUT	61.00	61.00
1	REAR BUMPER LOWER CENTRE COVER	DISTORTED/CRACKED	281.50	281.50
2	REAR BUMPER LOWER SIDE COVER @\$191.55	SERVICEABLE	383.10	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	970.25	-
1	REAR END PANEL INNER GARNISH	SERVICEABLE	381.90	-
1	REAR END PANEL SENSOR	CRACKED	281.50	281.50
	LESS 25% DISCOUNT		-1,976.13	-826.83
			5,928.37	2,480.47
SPECIAL NETT ITEMS				
1	SET REAR NUMBER PLATE & CASING(SN)	DENTED	50.00	45.00
1	SET REAR PARKING SENSOR(SN)	DENTED	280.00	200.00
			330.00	245.00
LABOUR				
	TUFFKOTE	NOT NECESSARY	180.00	-

Report Ref No. CC6/FCI19022491/Kea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WIRING.		180.00	20.00
	SPRAY PAINTING.		1,200.00	600.00
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF REAR TAILGATE INNER LOCK AND REAR END PANEL.		1,200.00	500.00
			2,760.00	1,120.00
GRAND TOTAL			9,018.37	3,845.47
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,050.00

Report Ref No. CC6/FCI19022491/Kea3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.